

**UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION  
ATOMIC SAFETY AND LICENSING BOARD**

**Before Administrative Judges:  
E. Roy Hawkens, Chair  
Dr. Paul B. Abramson  
Dr. Anthony J. Baratta**

In the Matter of: )

AmerGen Energy Company, LLC )

(License Renewal for Oyster Creek Nuclear  
Generating Station) )

) July 20, 2007

) Docket No. 50-219

**AMERGEN'S PRE-FILED DIRECT TESTIMONY EXHIBITS**

**VOLUME 1 OF 2: EXHIBITS 1-19**

**ENERCON SERVICES, INC.**

*Julien D. Abramovici, P.E.*

**Experience Summary**

- Degreed Mechanical Engineer with over 33 years of experience
- Significant experience with ASME and ANSI codes with an emphasis on ASME Sections III, VIII, and XI, and ANSI B31.1 and 31.7
- Registered Professional Engineer, New Jersey
- Multi-discipline Root Cause Evaluator
- License Renewal
- Third party reviews
- Former member of the EPRI-MRP who has dealt with the Alloy 600 Head Penetrations
- Reactor vessel internals (BWR and PWR)
- Steam Generator support
- Performed Alloy 600 Assessments for Three Mile Island and Fort Calhoun
- New plant operating license support

**Experience Description**

Since joining Enercon Services in 2000, Mr. Abramovici has been assigned to the Mt. Arlington, New Jersey office where he has worked on a multitude of diversified tasks, which included: ISI relief requests for Grand Gulf, Oyster Creek Reactor Vessel Internals and Reactor Vessel weld inspections outage support, Oyster Creek CRD leakage evaluation and repair, Fort Calhoun CRDM venting investigation, Cooper ISI and IST Programs audits, Fort Calhoun Inconel 600 assessment, Pickering Travelling Screens problems investigations, Indian Point 2 projects assessment, Three Mile Island (TMI) Steam Generator evaluation and repairs, TMI CRD head penetration repairs, GSI 191 resolutions including support to French and Spanish utilities, Oyster Creek License Renewal and many others.

Over the year, Mr. Abramovici has been involved in developing operational programs (ISI, IST, RVMS, CLRT, etc.) for new plant applications, for NuStart utility consortium. Additionally, Mr. Abramovici has provided technical input for heavy loads, steam generator, leak before break, MOV reactor head inspections and many other programs as well as subject matter expertise.

Mr. Abramovici was employed as a Senior Engineer/Consulting Engineer at GPU Nuclear's Corporate Headquarters for four years and was responsible for major plant equipment such as the reactor vessel and internals (BWR) and steam generators (PWR). He provided technical expertise on various component and system issues as well as ASME and ANSI codes, with emphasis on ASME Section III, VIII and XI, and ANSI B31.1 and 31.7. He acted as responsible or independent reviewer for 50.59 type evaluations and performed third party design verifications on multi-discipline modifications. He additionally evaluated "as found" conditions for acceptability for continued operation "as is" with minimal schedule or financial impact.

Prior to this, Mr. Abramovici held the position of Mechanical Components Manager at GPU Nuclear for two years. He was responsible for analytical support of the GPU Nuclear plant mechanical components. This activity included evaluation of component degradation mechanisms such as fatigue, corrosion, and cracking, ASME code pressure boundary calculations and heat exchanger, and rotating equipment performance. He was responsible for preparation of inspection plans and specifications for major components such as reactor internals. He reviewed inspection

data and dispositioned associated material nonconformance reports. He evaluated component failure events and performed associated root cause evaluations. He provided management and guidance to the staff in the identification of problems with the design or operation of the plant systems and components by technical expertise and knowledge of regulatory requirements. He provided management and guidance to the staff for the evaluation of engineering alternatives as well as life assurance and life extension. This included cost/benefit analysis, development of design criteria, and the establishment of work scope and schedules. He provided management and guidance for the design and/or procurement of mechanical components and review of plant operations, maintenance, surveillance practices and standards relative to these components. Large programs included underground piping, reactor vessel internals, steam generator related issues, and motor operated valves. He additionally chaired numerous design and constructability reviews.

Mr. Abramovici was part of a Plant Optimization and License Renewal (POLR) group that evaluated the adequacy of the GPUN plants for continued operation as well as license renewal. While part of this group, he participated in and reviewed the products of various industry-related groups, such as EPRI, and GE and B&W Owners Groups. His group was responsible for the plants thermal cycle monitoring and calculations revisions that may be necessary to assure continued licensing requirements compliance. After GPUN set up a License Renewal group, Mr. Abramovici and his group continued to provide support in this arena.

As Heat Exchanger and Pressure Vessel Manager with GPU Nuclear for nine years, Mr. Abramovici's responsibilities were the same as above, but limited to heat exchangers, feedwater heaters, pressure vessels, steam generators, pressurizers, reheaters, moisture separator pump, turbines, and material handling equipment.

Mr. Abramovici held similar responsibilities as Piping Engineering Manager with GPU Nuclear for one year, but these were limited to valves, piping, piping support, and material handling equipment.

While with GPU Nuclear, Mr. Abramovici additionally held various staff positions for six years. He was responsible for the nuclear steam supply system design and modifications. As System Engineer, he was responsible for the reactor coolant (primary) systems such as reactor coolant, make-up and purification, and building spray and decay heat system problem identification and resolution. He was responsible for programs related to sulfur removal from the primary loop, especially the pressurizer. He implemented the intergranular stress, corrosion, and cracking (IGSCC) at Three Mile Island Unit 1 Nuclear Generating Station. He additionally generated piping, heat exchangers, and piping supports procurement specifications.

Prior to this, Mr. Abramovici worked as Mechanical Engineer at General Dynamics Corporation's Electric Boat Division. In this position, he was responsible for design and evaluation of submarine components and systems.

#### **Education and Training**

B.S., Mechanical Engineering, City College of New York, 1973

M.S., Systems Management, University of Southern California, 1975

GPU Professional and Management Development Training Courses:

Principle Centered Leadership

Seven Habits of Highly Effective People

Time Management

Deming Management Methods

Teamwork and Leadership

Kepner-Tregoe Problem Solving and Decision Making

ASME Section XI Training

**Professional Affiliations and Licenses**

Electric Power Research Institute (EPRI):

Steam Generator Reliability Project – Technical Advisory Group

Reactor Vessel Internal Project – Repair Committee

PWR Materials Reliability Project

Registered Professional Engineer, State of New Jersey, License 24GE2674500

# JON R. CAVALLÓ, PE, PCS

**Born:** Washington, D.C. - 1946

**Education:** Pomona College  
U.S. Naval Nuclear Power School  
Northeastern University, Bachelor of Science in Engineering Technology, Cum Laude  
University of Washington, Cold Regions Engineering  
University of Colorado, Engineering Project Management  
NACE, Corrosion Prevention in Oil and Gas Production  
University of New Hampshire, Finance for the Non-Financial Manager  
Fairleigh Dickinson University, Inspection, Evaluation and Rehabilitation of Highway Bridges  
The Hartford Graduate Center, Value Engineering

**Professional Activities:** Registered Professional Engineer:  
Alaska, ME-5161 Connecticut, 14797  
Maine, 5549 Massachusetts, 30114  
New Hampshire, 8993 New Jersey, GE32609

**Certifications:**  
SSPC Protective Coatings Specialist No. 130-35-0235  
NBR Certified Nuclear Coatings Engineer No. 137

**Organizational Affiliations:**  
Member, American Society of Mechanical Engineers  
Member, American Society for Testing and Materials  
Chairman Committee D-33 (2004-2008)  
Member, National Association of Corrosion Engineers  
Director and President (2006-2007), Maine Society of Professional Engineers  
Member, Order of the Engineer  
Member, Steel Structures Painting Council  
Chairman, Northern New England Chapter (1991-1998)  
Chairman, New England Chapter (2000 - Present)  
Member, National Strategic Planning Committee (1995-1996)  
Member, Northeastern University Sigma Epsilon Rho Honor Society

**Work Experience**  
Corrosion Control Consultants & Labs, Inc. 1998 - Present (Consulting Engineering Firm)  
Vice-President  
Independent Professional Engineer 1991 - 1998  
Corrosion Engineering Consulting Services  
Sponge-Jet, Inc. 1991 - Present (Surface Cleaning Systems)  
Vice-Chairman  
S.G. Pinney & Associates, Inc. 1986-1991 (Consulting Engineering Firm)  
Northern U.S. Regional Manager (1986-1991)  
Metalweld, Inc, 1983-1986 (Industrial Coating and Lining Contractor)  
Manager, New England Division  
Project Manager, Seabrook Nuclear Power Station  
Stone & Webster Engineering Corporation, 1971-1983  
Materials Engineering Division Coordinator  
United States Navy, 1965-1971  
Viet Nam Veteran, 1965-1966  
Naval Nuclear Power Program, 1967-1971

**Scott R. Erickson**  
PMB 223  
9702 Gayton Rd.  
Richmond, VA 23238  
(804) 556-6522

**Education:** 1983 Graduate of Hutchinson Vo-Tech Institute NDE Program

**Training:** EPRI Courses, Charlotte, NC: 9/91 Level II VT1-4; 6/92: Manual Weld Overlay UT Inspection; 8/92: Manual UT Thru-Wall Sizing; 7/94 Manual UT Inspection Testing Qualification (Performance Demonstration Initiative; 12/04 Manual UT Reactor Pressure Vessel Detection Qualification;

**General Electric (GE) Course:** 1/07 Level III VT-1

**Experience:** **3/2004 to Present – Sonic Systems International.** Certified Level III in Magnetic Particle Testing (MT), Liquid Penetrant Testing (PT), Ultrasonic Testing (UT), Visual Testing (VT1-3). Job duties include Project Level III, Inservice Inspection (ISI) Coordinator, Manual PDI Piping/RPV examinations, BOP examinations (MT, PT, VT1 inspections of surfaces, VT-3 inspections of Supports, Hangers, and Snubbers (Hydraulic and Mechanical))

**5/2002 to 2/2004 – Alstom Power.** Certified Level II in MT, PT, UT. Job duties included performing NDE exams on refurbished/modified turbine components.

**10/1997 to 4/2002 – SSI.** Certified Level II in MT, PT, UT, VT1-3. Job duties included performing Inservice Inspections (ISI) / Balance of Plant (BOP) / Flow Accelerated Corrosion (FAC) examinations.

**9/1992 to 10/1997 – LMT.** Certified Level III in MT, PT, UT, VT1-3. Job duties included supervising and performing ISI and System Pressure Tests.

**2/1992 to 2/1994 – Virginia Corporation of Richmond (VCR) (Contract Employee).** Certified Level III in MT, PT, UT, Level II in VT1-3. Job duties included supervising and Performing ISI, BOP, FAC, and NSS examinations.

**10/1985 to 2/1992 – VCR.** Certified Level III in MT, PT, UT, Level II in VT1-3. Job duties included supervising outage work, writing and reviewing procedures, training and testing of employees, and performing ISI, BOP, FAC, and NSS examinations.

**4/1985 – BESTCO (for LMT). Certified Level II in MT, PT, Level I in UT. Performed ISI examinations.**

**10/1984 to 4/1985 – Branch Radiographic Labs. Certified Level II in MT, PT, Level I in UT. Job duties included performing construction NDE examinations at Hope Creek.**

**7/1984 to 10/1984 – LeHigh Testing Labs. Certified Level II in Radiographic testing (RT), MT, PT, UT. Job duties included performing manufacturing NDE Examinations.**

200 Exelon Way  
KSA 2-N  
Kennett Square, PA 19348

Work: 610-765-5958  
Cell: 610-659-6211  
Email: michael.p.gallagher@  
exeloncorp.com

# Michael P. Gallagher

---

## Professional History

1981-present	Exelon	
	VP License Renewal Projects	2006 to present
	Nuclear Review Board- PSEG	2004 to 2007
	VP Engineering & Technical Support- PSEG	2004 to 2005
	Director Licensing & Regulatory Affairs- Mid Atlantic	2001 to 2004
	BWROG Prime Representative	2001 to 2004
	Nuclear Safety Review Board Member-Exelon	2000 to 2004
	Director Operations Support- Mid Atlantic Region	2000 to 2001
	Plant Manager- Limerick	1998 to 2000
	Director of Work Management- Peach Bottom	1996 to 1998
	Director of Engineering - Limerick	1995 to 1996
	Plant Engineering Manager- Limerick	1993 to 1995
	Operations Support Manager- Limerick	1992 to 1993
	Mechanical Design Manager- Nuclear Group	1989 to 1992
	Reactor Engineering Manager- Limerick	1986 to 1989
	Startup Test Engineer- Limerick	1982 to 1986
	Engineer- Peach Bottom	1981 to 1982

## Education

1997	INPO Senior Nuclear Plant Managers Course
1988	Masters in Business Administration, Saint Joseph's University
1981	Bachelor of Chemical Engineering, Georgia Tech

## Licenses

1984-1989	Senior Licensed Operator Limerick Units 1&2
1987	Registered Professional Engineer- Pennsylvania





**Michael P. Gallagher, PE**

---

#### **Position**

Vice President License Renewal Projects

#### **Profile**

Gallagher, 48, is responsible for the overall implementation of the license renewal projects for Exelon Nuclear.

#### **Professional History**

Gallagher has 26 years experience in the nuclear industry and has held key leadership positions within Exelon Nuclear. Prior to his current position, Gallagher was Vice President Engineering and Technical Support at the PSEG Salem and Hope Creek stations responsible for performance improvements under the Exelon/PSEG Operating Services Agreement. From 2001 to 2004 Gallagher was the Director of Licensing and Regulatory Affairs responsible for compliance with Nuclear Regulatory Commission requirements. From 1998 to 2000 Gallagher was Plant Manager of the Limerick Generating Station. Gallagher also attained a USNRC Senior Reactor Operator license while at Limerick.

---

#### **Civic Involvement**

Gallagher is a member of Good Works, a Christian nonprofit organization that exists to improve the living conditions for low-income families in Chester County, PA. Since 2000, Gallagher has also participated in Habitat for Humanity blitz builds internationally and in the United States.

#### **Education**

Gallagher received his Bachelor in Chemical Engineering from Georgia Tech and Master in Business Administration from Saint Joseph's University. Gallagher is a registered professional engineer in Pennsylvania.

#### **Family**

Gallagher and his wife, Gina, have five children, Erin, Claire, Kevin, Brian and Molly.

**Barry M. Gordon, P. E.**  
Associate

**Education**

MS, Metallurgy and Material Science, Carnegie Mellon University  
BS, Metallurgy and Material Science, Carnegie Mellon University (First in Department)  
Additional courses from MIT, University of Pittsburgh and NACE in Corrosion Science

**Professional Associations and Awards**

Registered Professional Engineer, State of California – Corrosion Engineering  
Registered Corrosion Specialist – National Association of Corrosion Engineers (NACE), International Member – International Cooperative Group on Environmentally Assisted Cracking (ICG-EAC)  
Adjunct Professor, Colorado School of Mines  
Instructor Credential, California Community Colleges  
Instructor, International Atomic Energy Agency (IAEA)  
Patent No. 4,950,449 – Inhibition of Radioactive Cobalt Deposition in Water-Cooled Nuclear Reactors  
Patent No. 5,577,083 – Method and Apparatus for Electro-Protection of Piping Systems and Reactor Internals from Stress Corrosion Cracking  
Patent No. 5,590,162 – Beta Battery  
R&D Magazine's 100 award (most significant new technical products of the year) for zinc injection

**Professional Experience**

1998 to Present	Structural Integrity Associates, Inc., San José, CA Associate
1975 to 1998	GE Nuclear Energy, San José, CA Technical Expert – Corrosion Engineering Project Manager – Corrosion Technology Program Manager – Stress Corrosion Cracking
1969 to 1975	Westinghouse Electric – Bettis Atomic Power Laboratory, West Mifflin, PA Materials Engineer

**Summary**

Mr. Gordon has consulted on various LWR corrosion and material issues for over three decades with special emphasis on stress corrosion cracking (SCC). He has addressed numerous materials and corrosion problems in the LWR industry over a wide range of subjects including reactor internals, piping, fuel hardware, water chemistry transient and core flow issues, weld overlays and repairs, crack growth rate modeling, alloy selection, failure analysis, license renewal, NRC inspection relief, dry fuel storage, welding of irradiated materials, decontamination, etc.

Mr. Gordon has been the SI program manager and/or co-author of over 18 EPRI sponsored programs and reports including the landmark documents:

**B. M. Gordon**

**Page 2**

1. "Effects of Marine Environments on Stress Corrosion Cracking of Austenitic Stainless Steels – An Evaluation of the NISA and CRIEPI Spent Fuel Storage Canister Project"
2. "Effect of PWR Water Chemistry on PWSCC"
3. "BWR Water Chemistry Guideline – 2004 Revision"
4. "Technical Basis for Guidelines for Performing Weld Repairs to Irradiated BWR Internals.
5. "Guidelines for Performing Weld Repairs to Irradiated BWR Internals
6. "Interim Welding Guidelines for BWR Internals
7. "BWR Water Chemistry Guideline – 2000 Revision
8. "Technical Justification for the Extension of the Interval between Inspections for Weld Overlay Repairs"
9. "Technical Basis for Inspection Relief for BWR Internal Components with Hydrogen Injection"
10. "Full-System Decontamination of a BWR Using the LOMI Process,"

Mr. Gordon is also the SI project manager for the Yucca Mountain Project for both Bechtel SAIC and EPRI. He has conducted evaluations on the qualification of the waste package (WP) relative to long-term materials corrosion performance, weld residual stresses and long-term corrosion monitoring.

While at GE Nuclear Energy (GENE), Mr. Gordon was responsible for consultation, problem analysis and management of programs on BWR materials/environmental interactions. He developed and qualified the environmental BWR IGSCC mitigation technique, hydrogen water chemistry, prepared the EPRI decontamination guidelines for BWRs and qualified a process for BWR full-system decontamination. Mr. Gordon also co-patented a revolutionary method (GEZIP) of inhibiting radioactivity and mitigating IGSCC in nuclear reactors, a process that won *R&D Magazine's* 100 award as one of the most significant new technical products of the year.

Mr. Gordon managed multi-million dollar development programs on corrosion testing, field surveillance, failure analysis and design qualifications at GENE. He has lectured throughout the U.S., Mexico, Canada, Japan and Europe on corrosion phenomena to technical societies, regulatory agencies, utilities and vendors. He authored the highly acclaimed college accredited course (SUNY), "Corrosion and Corrosion Control in BWRs" and teaches an updated and greatly expanded "Corrosion and Corrosion Control in LWRs." Thirty US NRC personnel attended this class 2004.

Mr. Gordon has supervised senior level materials engineers and has consulted on a broad range of materials problems for other GE businesses. He also managed the materials technical exchange programs among GE, ABB, Hitachi and Toshiba. He has provided extensive litigation support to GE.

Mr. Gordon directed corrosion programs on steam generator materials and nuclear fuel cladding while at Westinghouse. He performed fieldwork on the nuclear aircraft carriers Enterprise and Nimitz and devised and qualified a new surface treatment for zirconium and hafnium alloys for corrosion and hydriding mitigation.

**Resume: DAVID GARY HARLOW**

**Personal:** Date of birth: July 18, 1951  
Place of birth: Bowling Green, Kentucky

Home address:  
149 W. Langhorne Ave.  
Bethlehem, PA 18017  
(610) 861-7471

Business address:  
Mechanical Engineering and Mechanics  
Lehigh University  
19 Memorial Drive West  
Bethlehem, PA 18015  
(610) 758-4127 (office)  
(610) 758-6224 (fax)  
dgh0@lehigh.edu

**Education:** B.A.: 1973 - Western Kentucky University; Mathematics and Physics  
M.S.: 1976 - Cornell University; Applied Mathematics  
Ph.D.: 1977 - Cornell University; Applied Probability and Stochastic Processes

**Research Interests:** Probability and statistical modeling of failure processes in materials, aluminum alloys, steels, and composites; Stochastic fracture mechanics; Stochastic differential equations and their numerical solutions; Mechanical and system reliability; Applications of stochastic processes; Applied probability modeling

**Awards:** 1973 Sigma Xi - First place; for original research at Western Kentucky University  
1973 Highest honors in Mathematics  
1973 Pi Mu Epsilon - National Mathematics Honorary Fraternity  
1973 Sigma Pi Sigma - National Physics Honor Society  
1973 Summa Cum Laude  
1985 Lehigh University Award for teaching  
1985 ASEE Summer Faculty Research Fellow - Naval Research Laboratory  
1988 NRC Research Fellowship - Naval Postgraduate School  
1992 Tau Beta Pi Teacher of the Year - Lehigh University  
2006 Pi Tau Sigma Professor of the Year - Lehigh University

**Professional Experience:**

1992- Professor; Mechanical Engineering and Mechanics; Lehigh University  
1985-1992 Associate Professor; Mechanical Engineering and Mechanics; Lehigh University  
1982-1985 Assistant Professor; Mechanical Engineering and Mechanics; Lehigh University  
1979-1982 Assistant Professor; Mechanical Engineering and Mechanics; Drexel University, Philadelphia, PA  
1977-1979 Research Associate; Sibley School of Mechanical and Aerospace Engineering; Cornell University, Ithaca, NY  
1974-1979 Adjunct Professor; Mathematical Sciences; Tompkins-Cortland Community College, Dryden, NY

*Publications:*

Refereed Articles:

1. D.G. Harlow and S.L. Phoenix, The Chain-of-Bundles Probability Model for the Strength of Fibrous Materials I: Analysis and Conjectures, *Journal of Composite Materials* 12 (1978) 195-214.
2. D.G. Harlow and S.L. Phoenix, The Chain-of-Bundles Probability Model for the Strength of Fibrous Materials II: A Numerical Study of Convergence, *Journal of Composite Materials* 12 (1978) 314-334.
3. D.G. Harlow and S.L. Phoenix, Bounds on the Probability of Failure of Composite Materials, *International Journal of Fracture* 15 (1979) 321-336.
4. D.G. Harlow, Properties of the Strength Distribution for Composite Materials, *Composite Materials: Testing and Design (Fifth Conference)*, ASTM STP 674, S.W. Tsai, Ed., American Society for Testing and Materials (1979) 484-501.
5. D.G. Harlow and S.L. Phoenix, Probability Distributions for the Strength of Composite Materials I: Two-Level Bounds, *International Journal of Fracture* 17 (1981) 347-372.
6. D.G. Harlow and S.L. Phoenix, Probability Distributions for the Strength of Composite Materials II: A Convergent Sequence of Tight Bounds, *International Journal of Fracture* 17 (1981) 601-630.
7. D.G. Harlow and S.L. Phoenix, Probability Distributions for the Strength of Fibrous Materials Under Local Load Sharing I: Two-Level Failure and Edge Effects, *Advances in Applied Probability* 14 (1982) 68-94.
8. D.G. Harlow, R.L. Smith, and H.M. Taylor, Lower Tail Analysis of the Distribution of the Strength of Load-Sharing Systems, *Journal of Applied Probability* 20 (1983) 358-367.
9. D.G. Harlow, Statistical Properties of Hybrid Composites I: Recursion Analysis, *Proceedings of the Royal Society of London A* 389 (1983) 67-100.
10. S.J. Fariborz, D.G. Harlow, and T.J. Delph, The Effects of Nonperiodic Void Spacing upon Intergranular Creep Cavitation, *Acta Metallurgica* 33 (1985) 1-9.
11. D.G. Harlow, The Pure Flaw Model for Chopped Fibre Composites, *Proceedings of the Royal Society of London A* 397 (1985) 211-232.
12. S.J. Fariborz, C.-L. Yang, and D.G. Harlow, The Tensile Behavior of Intraply Hybrid Composites I: Model and Simulation, *Journal of Composite Materials* 19 (1985) 334-354.
13. T.-S. Liu, R.J. Fields, D.G. Harlow, and T.J. Delph, Statistical Observations of Creep Cavitation in AISI Type 304 Stainless Steel, *Scripta Metallurgica* 19 (1985) 299-304.
14. S.J. Fariborz, D.G. Harlow, and T.J. Delph, Intergranular Creep Cavitation with Time-Discrete Stochastic Nucleation, *Acta Metallurgica* 34 (1986) 1433-1441.
15. S.H. Johnson, D.G. Harlow, and J.S. Yoon, Time Optimal Multistage Controllers for Nonlinear Continuous Processes, *Journal of Dynamic Systems and Measurement Control Transactions ASME* 108 (1986) 240-247.
16. S.J. Fariborz and D.G. Harlow, The Tensile Behavior of Intraply Hybrid Composites II: Micromechanical Model, *Journal of Composite Materials* 21 (1987) 856-875.

17. T.-S. Liu, D.G. Harlow, and T.J. Delph, Stereological Analysis of Creep Cavities on Polished Surfaces, *Metallography* 21 (1988) 55-76.
18. T.-S. Liu, R.J. Fields, S.J. Fariborz, D.G. Harlow, and T.J. Delph, Experimental Observations and Analysis of Creep Cavitation in AISI 304 Stainless Steel, *Acta Metallurgica* 36 (1988) 2481-2491.
19. D.G. Harlow, The Effect of Proof-Testing on the Weibull Distribution, *Journal of Materials Science* 24 (1989) 1467-1473.
20. R.C. Dobbyn, J. Farris, D.G. Harlow, T.J. Delph, and R.J. Fields, Insitu Imaging of Creep Cavities by Synchrotron Microradiography, *Scripta Metallurgica* 23 (1989) 623-625.
21. J.P. Farris, J.D. Lee, D.G. Harlow, and T.J. Delph, On the Scatter in Creep Rupture Times, *Metallurgical Transactions A* 21A (1990) 345-352.
22. D.G. Harlow and S.L. Phoenix, Approximations for the Strength Distribution and Size Effect in an Idealized Lattice Model of Material Breakdown, *Journal of the Mechanics and Physics of Solids* 39 (1991) 173-200.
23. D. Xiao, D.G. Harlow, and T.J. Delph, Numerical Solutions of the Random Paris-Erdogan Equation, *Engineering Fracture Mechanics* 40 (1991) 227-231.
24. D.G. Harlow and T.J. Delph, The Numerical Solution of Random Initial-Value Problems, *Mathematics and Computers in Simulation* 33 (1991) 243-258.
25. D. Xiao, J.E. Yukich, D.G. Harlow, and T.J. Delph, A Simplified Probabilistic Model of the Growth of Creep Cavitation, *Philosophical Magazine A* 65 (1992) 71-84.
26. D.G. Harlow and T.J. Delph, Solutions of Random Initial Value Problems, *Proceedings of the International Union of Theoretical and Applied Mechanics: Symposium on Nonlinear Stochastic Mechanics* (July 1-5, 1991) Eds. Bellomo, N. and Cascatti, F., Springer-Verlag, (1992) 273-283.
27. D.G. Harlow and J.E. Yukich, Empirical Process Methods for Classical Fiber Bundles, *Stochastic Processes and Their Applications* 44 (1993) 141-158.
28. R.P. Wei and D.G. Harlow, Materials Considerations in Service Life Prediction, *Applied Mechanics Reviews* 46 (1993) 190-193; Part of *Aging of Energy Production and Distribution Systems*, edited by M.M. Carroll and P.D. Spanos, ASME Book AMR128, 1992.
29. D.G. Harlow and R.P. Wei, A Mechanistically Based Approach to Probability Modeling for Corrosion Fatigue Crack Growth, *Engineering Fracture Mechanics* 45 (1993) 79-88.
30. D.G. Harlow and R.P. Wei, Probability Approach for Prediction of Corrosion and Corrosion Fatigue Life, *AIAA Journal* 32 (1994) 2073-2079.
31. R.P. Wei, D. Masser, H. Liu, and D.G. Harlow, Probabilistic Considerations of Creep Crack Growth, *Materials Science and Engineering A* 189 (1994) 69-76.
32. J.R. Cockman, R.J. Fields, T.J. Delph, and D.G. Harlow, Spatial Statistics of Creep Cavities, *Modelling and Simulation in Materials Science and Engineering* 3 (1995) 187-200.
33. D.G. Harlow and T.J. Delph, A Computational Probabilistic Model for Creep-Damaging Solids, *Computers and Structures* 54 (1995) 161-166.

34. P.J. Laumakis and D.G. Harlow, Probability Failure Modeling of Woven Fiber Networks, *Textile Research Journal* 65 (1995) 254-264.
35. H. Liu, M. Gao, D.G. Harlow, and R.P. Wei, Grain Boundary Character, and Carbide Size and Spatial Distribution in a Ternary Nickel Alloy, *Scripta Metallurgica et Materialia* 32 (1995) 1807-1812.
36. D.G. Harlow and R.P. Wei, Probability Modeling for the Growth of Corrosion Pits, *Structural Integrity in Aging Aircraft AD-47 ASME* (1995) 185-194.
37. P.J. Laumakis and D.G. Harlow, Asymptotic Approximations Used in Probabilistic Failure Modeling of Woven Fiber Networks, *Textile Research Journal* 65 (1995) 731-738.
38. D.G. Harlow, Reliability Modeling Based on Fatigue Crack Growth, *International Journal of Mathematical Education in Science and Technology* 27 (1996) 447-454.
39. D.G. Harlow, H.-M. Lu, J.A. Hittinger, T.J. Delph, and R.P. Wei, A Three Dimensional Model for the Probabilistic Intergranular Failure of Polycrystalline Arrays, *Modelling and Simulation in Materials Science and Engineering* 4 (1996) 261-279.
40. N.R. Cawley and D.G. Harlow, Spatial Statistics of Particles and Corrosion Pits in 2024-T3 Aluminum Alloy, *Journal of Materials Science* 31 (1996) 5127-5134.
41. M. Gao, S. Chen, D.G. Harlow, and R.P. Wei, Preferential Coarsening of  $\gamma''$  Precipitates in Inconel 718 During Creep, *Metallurgical and Materials Transactions* 27A (1996) 3391-3398.
42. P.J. Laumakis and D.G. Harlow, Designing a Model of a Platform Crane, *The Journal of Undergraduate Mathematics and Its Applications* 17 (1996) 397-414.
43. D.G. Harlow and T.J. Delph, A Probabilistic Model for Creep-Fatigue Failure, *Journal of Pressure Vessel Technology* 119 (1997) 45-51.
44. D.G. Harlow, Statistical Properties of Hybrid Composites: Asymptotic Distributions for Strain, *Reliability Engineering and System Safety* 56 (1997) 197-208.
45. J.T. Gliniak, D.G. Harlow, and T.J. Delph, A Probabilistic Model for the Growth of Creep Cracks, *Engineering Fracture Mechanics* 57 (1997) 25-40.
46. D.G. Harlow and R.P. Wei, A Probability Model for the Growth of Corrosion Pits in Aluminum Alloys Induced by Constituent Particles, *Engineering Fracture Mechanics* 59 (1998) 305-325.
47. J. Park and D.G. Harlow, Statistical Modeling of Interfacial Damage of Polymer Encapsulated Microelectronic Devices, *International Journal of Microcircuits and Electronic Packaging* 21 (1998) 171-176.
48. J. Rawers and D.G. Harlow, Understanding the Tensile Failure of Hot-Pressed Nanostructured Powder Compacts, *Journal of Materials Engineering and Performance* 8 (1999) 35-45.
49. D.G. Harlow and R.P. Wei, Probabilities of Occurrence and Detection of Damage in Airframe Materials, *Fatigue and Fracture of Engineering Materials and Structures* 22 (1999) 427-436.
50. J. Park, D.G. Harlow, and H.F. Nied, Characterization of Interfacial Adhesion Damage Induced by Accelerated Life Testing, *IEEE CPMT Transactions on Advanced Packaging* 23 (2000) 100-107.
51. D.G. Harlow and T.J. Delph, Creep Deformation and Failure: Effects of Randomness and Scatter, *Journal of Engineering Materials and Technology* 122 (2000) 342-347.

52. D.G. Harlow and R.P. Wei, Materials Aging and Structural Reliability, *International Journal of Materials and Product Technology* 16 (2001) 304-316.
53. J. Park, D.G. Harlow, and H.F. Nied, Growth Kinetics of Interfacial Damage: Epoxy Coating on a Generic Dual In-Line Package, *IEEE Transactions on Components and Packaging Technology* 24 (2001) 482-492.
54. D.G. Harlow and R.P. Wei, Probability Modeling and Statistical Analysis of Damage in the Lower Wing Skins of Two Retired B-707 Aircraft, *Fatigue and Fracture of Engineering Materials and Structures* 24 (2001) 523-535.
55. D.G. Harlow and R.P. Wei, A Critical Comparison between Mechanistically Based Probability and Statistically Based Modeling for Materials Aging, *Materials Science and Engineering A323* (2002) 278-284.
56. D.G. Harlow, Applications of the Fréchet Distribution Function, *International Journal of Materials and Product Technology* 17 (2002) 482-495.
57. J. Park and D.G. Harlow, Interfacial Degradation of Epoxy Coated Silicon Nitride, *IEEE Transactions on Components and Packaging Technologies* 25 (2002) 470-477.
58. P.J. Laumakis and D.G. Harlow, Structural Reliability and Monte Carlo Simulation, *International Journal of Mathematical Education in Science and Technology* 33 (2002) 377-387.
59. R.P. Wei and D.G. Harlow, Corrosion Enhanced Fatigue and MSD, *AIAA Journal* 41 (2003) 2045-2050.
60. D.G. Harlow, The Effect of Statistical Variability in Material Properties on Springback, *International Journal of Materials and Product Technology* 20 (2004) 180-192.
61. R.P. Wei and D.G. Harlow, Mechanistically Based Probability Modeling, Life Prediction and Reliability Assessment (invited Topical Review), *Modeling and Simulation in Materials Science and Engineering* 13 (2005) R33-R51.
62. D.G. Harlow, Probability Versus Statistical Modeling: Examples from Fatigue Life Prediction, *International Journal of Reliability, Quality and Safety Engineering* 12 (2005) 1-16.
63. D.G. Harlow, R.P. Wei, T. Sakai, and N. Oguma, Crack Growth Based Probability Modeling of S-N Response for High Strength Steel, *International Journal of Fatigue* 28 (2006) 1479-1485.
64. D.G. Harlow, The Effect of Randomness in Complex Models, (to appear).
65. D.G. Harlow, P.K. Liaw, W.H. Peter, G. Wang, and R.A. Buchanan, An Approach To Modeling The S-N Behavior Of Bulk-Metallic Glasses, *Intermetallics* (to appear).
66. D.G. Harlow, M.Z. Wang, and R.P. Wei, Statistical Analysis Of Constituent Particles In 7075-T6 Aluminum Alloy, *Metallurgical and Materials Transactions* (to appear).
67. D.G. Harlow, Particle Statistics in Aluminum Alloys, *International Journal of Reliability, Quality and Safety Engineering* (to appear).
68. D.G. Harlow, Probabilistic Property Prediction, *Engineering Fracture Mechanics* (to appear).
69. D.G. Harlow, Data Fusion and Modeling for Fatigue Crack Growth Prediction, *Reliability and Robust Design in Automotive Engineering, 2007*, SAE International, Warrendale, PA, (April 2007) 459-464.



70. R.P. Wei, C. Miller, Z. Huang, G.W. Simmons, and D.G. Harlow, Mechanical and Chemical Aspects of Oxygen Enhanced Crack Growth in Nickel-Based Superalloys, (submitted).
71. D.G. Harlow and R.P. Wei, Probability Modeling and Material Microstructure, (submitted).

Nonrefereed Articles:

1. D.G. Harlow, *Probabilistic Models for the Tensile Strength of Composite Materials*, Ph.D. Dissertation, Cornell University, Ithaca, N.Y., 1977.
2. D.G. Harlow, Statistical Aspects of the Tensile Strength of Composite Materials, *Proceedings I.C.C.M. #2*, B.R. Noton, Ed., The Metall. Soc. AIME, (1978) 44-60.
3. D.G. Harlow and S.L. Phoenix, Tight Bounds for the Probability Distribution of the Strength of Composites, *Fracture of Composite Materials*, Proceedings Sec. USA-USSR Symposium, Mar. 9-12, 1981, G.C. Sih and V.P. Tamuzs, Eds., Martinus Nijhoff Pub., The Hague, (1982) 17-27; also published in Russian in a companion volume.
4. D.G. Harlow, Statistical Properties of Hybrid Composites, *Recent Advances in Engineering Mechanics and Their Impact on Civil Engineering Practice*, W.F. Chen and A.D.M. Lewis, Eds., ASCE, New York, (1983) 499-502.
5. D.G. Harlow (contributor), *Engineering Statistics Exam File*, Engineering Press, Inc., San Jose, CA (1985).
6. A. Kehagias, S.H. Johnson, and D.G. Harlow, Time Optimal Trajectory Tracking for Strongly Nonlinear Systems, *Engineering Science Preprints 23rd Ann. Meeting Soc. Engineering Science*, Aug. 25-27, 1986.
7. S.J. Fariborz, J.P. Farris, D.G. Harlow, and T.J. Delph, Some Stochastic Aspects of Intergranular Creep Cavitation, *Proceedings International Seminar on High Temperature Fracture Mechanisms and Mechanics*, EGF 6, (Oct. 1987) Ed. P. Bensussan, Mechanical Engineering Publications, London, 1990, 163-176.
8. D.G. Harlow and R.P. Wei, A Probabilistic Approach to Life Prediction for Corrosion Fatigue Crack Growth, (keynote lecture) *Life Prediction of Corrodible Structures*, NACE, Kauai, HA, Nov. 5-8, 1991.
9. R.P. Wei and D.G. Harlow, A Mechanistically Based Approach to Life Prediction for Corrosion and Corrosion Fatigue of Airframe Materials, *Proceedings International Workshop on Structural Integrity of Aging Airplanes*, Atlanta, GA, Mar. 31-Apr. 2, 1992.
10. R.P. Wei and D.G. Harlow, A Mechanistically Based Approach for Predicting Corrosion and Corrosion Fatigue Life, *Proceedings of the 17th Symposium of the International Committee on Aeronautical Fatigue*, A.F. Blom, ed., Stockholm, (June 9-11, 1993) 347-366.
11. D.G. Harlow and R.P. Wei, A Dominant Flaw Probability Model for Corrosion and Corrosion Fatigue, *Corrosion Control Low Cost Reliability: Proceedings of the 12th International Corrosion Congress*, Houston, 5b, Sept. 19-24, 1993, 3573-3586.
12. G.S. Chen, M. Gao, D.G. Harlow, and R.P. Wei, Corrosion and Corrosion Fatigue of Airframe Aluminum Alloys, *FAA/NASA International Symposium on Advanced Structural Integrity Methods for Airframe Durability and Damage Tolerance*, NASA Conference Publication 3274, Langley Research Center, Hampton, VA, Sept. 1994, 157-173.
13. R.P. Wei and D.G. Harlow, A Mechanistically Based Probability Approach for Life Prediction, *Proceedings of International Symposium on Plant Aging and Life Prediction of Corrodible Structures*, Sapporo, Japan, May 15-18, 1995, 47-57.

14. D.G. Harlow, N.R. Cawley, and R.P. Wei, Spatial Statistics of Particles and Corrosion Pits in 2024-T3 Aluminum Alloy, *Proceedings of the 15th Canadian Congress of Applied Mechanics*, B. Tabarrok and S. Dost, Eds., Victoria, BC, May 28-June 2, 1995, 116-117.
15. D.G. Harlow and T.J. Delph, A Probabilistic Formulation for Creep-Fatigue Failure Analysis, (keynote lecture) *Computational Mechanics '95: Theory and Applications, Proceedings of the International Conference on Computational Engineering Science*, S.N. Atluri, G. Yagawa, and T.A. Cruse, Eds., Mauna Lani, HI, July 30 - August 3, 1995, 1152-1157.
16. R.P. Wei, M. Gao, and D.G. Harlow, Corrosion and Corrosion Fatigue Aspects of Aging Aircraft, *Proceedings of the Air Force 4th Aging Aircraft Conference*, U.S. Air Force Academy, Colorado Springs, July 9-11, 1996, 225-250.
17. N.R. Cawley, D.G. Harlow, and R.P. Wei, Probability and Statistics Modeling of Constituent Particles and Corrosion Pits as a Basis for MSD Analysis, *Proceedings of the FAA-NASA Symposium on the Continued Airworthiness of Aircraft Structures*, C.A. Bigelow, Ed., Atlanta, August 28-30, 1996, DOT/FAA/AR-97/2, II, July 1997, 531-542.
18. D.G. Harlow and T.J. Delph, Randomness in Creep Deformation and Failure, *Creep and Fracture of Engineering Materials and Structures*, J.C. Earthman and F.A. Mohamed, Eds., The Materials, Metals, and Materials Society, Warrendale, PA, 1997, 361-370.
19. J. Park, D.G. Harlow, and H.F. Nied, The Development of a Methodology to Statistically Characterize the Interfacial Damage of Microelectronic Devices, *Proceedings of the 8<sup>th</sup> Korean-American Scientists and Engineers Association*, Northeast Regional Conference, Rutgers University, New Brunswick, March 21-22, 1997, 52-56.
20. J. Park, D.G. Harlow, and H.F. Nied, Statistical Modeling of Interfacial Damage of Nonhermetically Sealed Electronic Devices: Development and Application of the Methodology for Statistical Observations and Analysis, *Proceedings of the 30<sup>th</sup> International Symposium on Microelectronics*, International Microelectronics and Packaging Society, Reston, VA, October 12-16, 1997, 557-562.
21. R.P. Wei, C. Li, D.G. Harlow, and T.H. Flournoy, Probability Modeling of Fatigue Crack Growth and Pitting Corrosion, *ICAF97: Fatigue in New and Aging Aircraft*, vol. 1, R. Cook and P. Poole, Eds, (Edinburgh, June 16-20, 1997) Engineering Material Advisory Services Ltd., London, 1998, 197-214.
22. R.P. Wei and D.G. Harlow, Aging of Airframe Materials: From Pitting to Cracking, *First Joint DoD/FAA/NASA Conference on Aging Aircraft*, Ogden, UT, July 8-10, 199 (CD)7.
23. D.G. Harlow and R.P. Wei, Probabilistic Aspects of Aging of Airframe Materials: Damage Versus Detection (invited paper), *Third Pacific Rim International Conference on Advanced Materials and Processes (PRICM 3)*, M.A. Imam, R. DeNale, S. Hanada, Z. Zhong, and D.N. Lee, Eds, The Minerals, Metals and Materials Society Honolulu, HA, July 12-16, 1998, 2657-2666.
24. D.G. Harlow and R.P. Wei, Aging of Airframe Materials: Probability of Occurrence versus Probability of Detection, *Second Joint NASA/FAA/DOD Conference on Aging Aircraft*, NASA/CP-1999-208982/PART1 Williamsburg, VA, August 31 - September 3, 1998, 275-283.
25. R.P. Wei and D.G. Harlow, Corrosion and Corrosion Fatigue of Aluminum Alloys – An Aging Aircraft Issue, *Seventh International Fatigue Conference, Fatigue '99*, Beijing, People's Republic of China, June 8-12, 1999 (CD).
26. R.P. Wei and D.G. Harlow, Probabilities of Occurrence and Detection, and Airworthiness Assessment, *ICAF99 Symposium on Structural Integrity for the Next Millennium*, J.L. Rudd and R.M. Bader, eds, Bellevue, WA, July 12-16, 1999, 445-463.

27. D.G. Harlow, L.D. Domanowski, E.J. Dolley, and R.P. Wei, Probability Modeling and Analysis of J-STARS Tear-down Data from Two B707 Aircraft, *Third Joint FAA/DoD/NASA Conference on Aging Aircraft*, Albuquerque, NM, September 20-23, 1999, (CD).
28. J. Park and D.G. Harlow, Interfacial Degradation of Epoxy Coated Silicon Nitride, *50<sup>th</sup> Electronic Components and Technology Conference*, Las Vegas, NE, May 21-24, 2000 (CD).
29. D.G. Harlow, S.V. Oshkai, and R.P. Wei, Impact of Pitting Corrosion and Corrosion Fatigue Crack Growth Spectrum-Load Fatigue Life, *Fourth Joint DoD/FAA/NASA Conference on Aging Aircraft*, St. Louis, MO, May 15-18, 2000 (CD).
30. D.G. Harlow and R.P. Wei, Materials Aging and Structural Reliability, *2000 Proceedings for the Sixth ISSAT International Conference on Reliability and Quality in Design*, Orlando, FL, August 9-11, 2000 (invited paper), 1-6.
31. D.G. Harlow and R.P. Wei, Life Prediction – The Need for a Mechanistically Based Probability Approach, *Key Engineering Material: Probabilistic Methods in Fatigue and Fracture*, 200 (2001) 119-138; *2000 ASME International Mechanical Engineering Congress and Exposition*, Orlando, FL, November 5 – 10, 2000 (invited paper).
32. D.G. Harlow and R.P. Wei, The Disparity Between Mechanistic and Empirical Modeling of Variability in Materials Damage Processes, *Fifth Annual FAA/Air Force/NASA/Navy Workshop on the Application of Probabilistic Methods to Gas Turbine Engines*, Cleveland, OH, June 11 – 13, 2001 (CD).
33. R.P. Wei, M.C. Latham, and D.G. Harlow, Nature and Statistical Distribution of Damage in the Lower Wing Skin of a 24-Year-Old B707-321B Aircraft, *ICAF 2001: Design for Durability in the Digital Age*, J. Rouchon, ed., Toulouse, France, June 25 – 29, 2001, 469483.
34. D.G. Harlow and R.P. Wei, A Critical Comparison between Mechanistically Based and Statistically Based Probability Modeling, *ICAF 2001: Design for Durability in the Digital Age*, J. Rouchon, ed., Toulouse, France, June 25 – 29, 2001, 1085-1095.
35. D.G. Harlow, Applications of the Frechet Distribution Function, *Seventh ISSAT International Conference on Reliability and Quality in Design*, Washington, DC, August 8-10, 2001, 80-85.
36. D.G. Harlow and R.P. Wei, Spatial Statistics of Particle Clusters and Modeling of Pitting Corrosion, *10<sup>th</sup> International Congress of Fracture*, Honolulu, HA, December 3 – 7, 2001 (CD – invited paper).
37. R.P. Wei and D.G. Harlow, Corrosion Enhanced Fatigue and MSD, *43<sup>rd</sup> AIAA/ASME/ASCE/AHS/ASC Structures, Structural Dynamics, and Materials Conference: Structural Integrity Issues and Method for Aging Aircraft*, Denver, CO, April 22-25, 2002 (CD – invited paper).
38. R.P. Wei and D.G. Harlow, Aging Aircraft and Life-Cycle Engineering and Management of Engineered Systems, *Proceedings of the 8<sup>th</sup> International Fatigue Congress*, Volume 1/5 Stockholm, Sweden, June 2-7, 2002, A.F. Blom, ed., Engineering Materials Advisory Services Ltd., West Midlands, UK, 2002, 71 – 78.
39. D.G. Harlow and R.P. Wei, Mechanistically Based Probability Modeling and Reliability Analysis, *Proceedings of the 8<sup>th</sup> International Fatigue Congress*, Volume 3/5 Stockholm, Sweden, June 2-7, 2002, A.F. Blom, ed., Engineering Materials Advisory Services Ltd., West Midlands, UK, 2002, 1509 – 1518.
40. D.G. Harlow, The Effect of Statistical Variability in Material Properties on Springback, *Eighth ISSAT International Conference on Reliability and Quality in Design*, Anaheim, CA, August 7-9, 2002, 261 – 266.

41. D.G. Harlow and R.P. Wei, Linkage Between Safe-Life and Crack Growth Approaches for Fatigue Life Prediction, *Materials Lifetime Science and Engineering, Proceedings of a Symposium Sponsored by the Structural Materials Division of The Minerals, Metals, and Materials Society*, San Diego, CA, March 2-6, 2003, P.K. Liaw, et al., eds, TMS, Warrendale, PA, 2003, 3 – 8 (invited paper).
42. R.P. Wei and D.G. Harlow, Materials Aging, Prognostics, and Life-Cycle Engineering and Management, *2003 TMS Annual Meeting, Materials Prognosis: Integrating Damage-State Awareness and Mechanism-Based Prediction: Role of Probabilistics in Prognostics*, March 2-6, San Diego, CA (CD – invited).
43. R.P. Wei and D.G. Harlow, Impact of Pitting Corrosion on the Evolution and Distribution of Fatigue Damage in Aircraft Structures: Model Predictions versus Observations, *NACE-International Corrosion Conference*, San Diego, CA, March 16-21, 2003 (to appear – invited).
44. R.P. Wei and D.G. Harlow, Materials Aging and Structural Reliability – A Case for Science Based Probability Modeling, *International Conference on Advanced Technology in Experimental Mechanics*, Tokyo, Japan, September 10 – 12, 2003 (to appear – keynote).
45. D.G. Harlow, The Effect of Randomness in Complex Models, *Ninth ISSAT International Conference on Reliability and Quality in Design*, Honolulu, HA, August 6-8, 2003, 284-288.
46. D.G. Harlow, Probability Versus Statistical Modeling: Examples from Fatigue Life Prediction, *Fifth Japan Conference on Structural Safety and Reliability*, Tokyo, November 26-28, 2003 (keynote) 1 – 14.
47. D.G. Harlow, Error Management, *Tenth ISSAT International Conference on Reliability and Quality in Design*, Las Vegas, NV, August 5-7, 2004, 158-162.
48. D.G. Harlow, R.P. Wei, T. Sakai, and N. Oguma, Crack Growth Based Probability Modeling of S-N Response, *Very High Cycle Fatigue - 3*, Kyoto and Shiga, Japan, September 16-19, 2004 (plenary lecture), 542-552.
49. R.P. Wei and D.G. Harlow, Science based probability modeling and life cycle engineering and management, *2<sup>nd</sup> International Conference on Environment Induced Cracking of Metals*, Banff, Canada, September 20-24, 2004 (invited plenary lecture), (to appear).
50. D.G. Harlow, Probabilistic Property Prediction, *11<sup>th</sup> International Conference on Fatigue*, Turin, Italy, March 20-25, 2005 (invited), (CD).
51. Robert P. Wei, D. Gary Harlow, and David Muench, Corrosion/Corrosion Fatigue and Material Prognosis, *23<sup>rd</sup> ICAF Symposium on "Structural Integrity of Advanced Aircraft and Life Extension for Current Fleets – Lessons Learned in 50 Years after the Comet Accidents"*, ICAF 2005, Hamburg, Germany, 8-10 June 2005, (to appear).
52. D.G. Harlow, Statistical Analysis of Constituent Particles in 7075-T6 Aluminum Alloy, *Eleventh ISSAT International Conference on Reliability and Quality in Design*, St. Louis, MO, August 4-6, 2005, 280-284.
53. N. Birbilis, M.K. Cavanaugh, R.G. Buchheit, D.G. Harlow, R.P. Wei, Understanding Damage Accumulation upon AA7075-T651 Used in Airframes from a Microstructural Point of View, *Proceedings of the Symposium: Applications of Materials Science to Military Systems*, MS&T, Pittsburgh, PA. 2005.
54. D.G. Harlow, Spatial Statistics of Particles and Pitting Corrosion in Aluminum Alloys, *Multiscale Damage Related to Environment Assisted Cracking: Fracture Mechanics and Applications*, G.C. Sih, S.T. Tu, and Z.D. Wang, eds, East China University of Science and Technology, China, 2005, 269-272.
55. D.G. Harlow, Pitting Corrosion: The Role of Clusters of Particles, *Twelfth ISSAT International Conference on Reliability and Quality in Design*, Chicago, IL, August 3-5, 2006, 177-181.

56. D.G. Harlow, Data Fusion and Science Based Modeling: A Technique for Very High Cycle Fatigue Predictions, VHCF-4, 2007, (invited, to appear).

Patent:

R.A. Marshall and D.G. Harlow, A Method of Separating the Three Major Types of Blood Cells from a White Blood Cell Histogram; 5,040,112 US patent application serial number 281,250 filed 12/7/88, issued 8/13/91; BIC - 1353 USA; Canadian Patent Number 2,001,728 issued 5/20/97.

D.G. Harlow and R.S. Dise, Method for Installing Blind Threaded Inserts; filed 4/6/04, patent pending.

Conference Presentations:

1. D.G. Harlow, Water Quality of the Barren River, *A.A.A.S. Symposium* Philadelphia, December, 1971.
2. W.G. Buckman, D.W. Cook, and D.G. Harlow, The Detection of Ultraviolet and Visible Radiation by Using the Thermoluminescence of Materials, *Health Physics Society Symposium* 16th Meeting, 1971.
3. D.G. Harlow and W.G. Buckman, Luminescent Properties of  $\text{CaF}_2:\text{Eu}$ , *Amer. Phys. Soc.* 39th Meeting, November 16-18, 1972.
4. D.G. Harlow, Statistical Aspects of the Tensile Strength of Intra-Ply Hybrid Composites, *Ninth U.S. National Congress of Applied Mechanics*, Cornell University, June 24, 1982.
5. D.G. Harlow, Statistical Properties of Hybrid Composites (invited), *Aerospace Technical Conference, SAE*, Washington D.C., October 1986.
6. S.L. Phoenix and D.G. Harlow, A Percolation Model for the Failure of Discontinuous Fiber Composites, *The Society of Rheology*, Santa Monica, January 18-21, 1987.
7. S.L. Phoenix, C.C. Kuo, and D.G. Harlow, Statistical Modelling of the Static Strength and Lifetime of Fiber-Reinforced Composites, *American Physical Society* New Orleans, March 21-25, 1988.
8. S.L. Phoenix, D.G. Harlow, and R.L. Smith, Approximations for the Strength Distribution and Size Effect in an Idealized Lattice Model of Material Breakdown, *American Physical Society* March 1990.
9. D.G. Harlow, Recursive Techniques for Modelling Breakdown in Idealized Lattice Structures with Applications to Discrete and Continuous Distributions for Element Strength (keynote), *Percolation Models of Material Failure*, Cornell University, Ithaca, NY, June, 1990.
10. T.J. Delph and D.G. Harlow, Numerical Solutions of Random Initial Value Problems, *Nonlinear Stochastic Systems*, Torino, Italy, July, 1991.
11. R.P. Wei and D.G. Harlow, A Mechanistically Based Probability Approach to Life Prediction for Corrosion and Corrosion Fatigue of Airframe Materials, *International Workshop on Structural Integrity of Aging Airplanes*, Atlanta, April 1, 1992.
12. D.G. Harlow, The Effects of Random Size and Position of Creep Cavities in a Bicrystal, *Society of Engineering Science* 29th Annual Meeting, La Jolla, CA, September 14-16, 1992.
13. D.G. Harlow and R.P. Wei, Corrosion and Fatigue of Aluminum Alloys: Chemistry, Micromechanics, and Reliability, *Workshop on Aging Aircraft Research*, Atlanta, April 27-28, 1993.

14. D.G. Harlow and R.P. Wei, A Probability Model for Predicting Corrosion and Corrosion Fatigue Life of Aluminum Alloys, *Conference on Extreme Value Theory and Its Applications*, Gaithersburg, MD, May 2-7, 1993.
15. R.P. Wei and D.G. Harlow, A Mechanistically Based Probability Approach for Life Prediction: Mechanics and Materials Science, *First SES-ASME-ASCE Joint Meeting*, Charlottesville, VA, June 6-9, 1993.
16. T.J. Delph and D.G. Harlow, A Computational Probabilistic Model for Creep-Damaging Solids, *IUTAM Symposium on Probabilistic Structural Mechanics*, San Antonio, June 7-10, 1993.
17. R.P. Wei, D. Masser, and D.G. Harlow, A Probability Model for Creep Crack Growth, *TMS/AMS Symposium*, Pittsburgh, October 17-21, 1993.
18. J.A. Hittinger, D.G. Harlow, and T.J. Delph, Simulation of Time-Dependent Intergranular Failure in Three-Dimensional Polycrystalline Arrays, *Materials Research Society Spring Meeting*, San Francisco, April 4-8, 1994.
19. J.T. Gliniak, D.G. Harlow, and T.J. Delph, A Microscopic Model for the Probabilistic Growth of Creep Cracks, *Twelfth U.S. National Congress of Applied Mechanics*, Seattle, June 26 - July 1, 1994.
20. D.G. Harlow, G. Chen, and R.P. Wei, A Probability Model for Pitting Corrosion in Aluminum Alloys, *Twelfth U.S. National Congress of Applied Mechanics*, Seattle, June 26 - July 1, 1994.
21. G.S. Chen, M. Gao, C. Iwashita, H.W. Liu, D.G. Harlow, and R.P. Wei, Grain Boundary Orientation and Carbide Distribution in Ni-18Cr-18Fe Alloy Polycrystals and Bicrystals, *TMS Fall Meeting*, Rosemont, IL, October 2-6, 1994.
22. R.P. Wei, M. Gao, and D.G. Harlow, Pitting Corrosion in Aluminum Alloys: Experimentation and Modeling, *Air Force 3rd Aging Aircraft Conference*, Wright-Patterson AFB, Ohio, September 26-28, 1995.
23. D.G. Harlow, H.-M. Lu, J.A. Hittinger, T.J. Delph, and R.P. Wei, A Three Dimensional Model for the Probabilistic Intergranular Failure of Polycrystalline Arrays, *ASME Mechanics and Materials Conference*, Johns Hopkins, Baltimore, June 12-14, 1996.
24. D.G. Harlow and T.J. Delph, Probabilistic Methods for Creep Deformation and Failure, *ASME Mechanics and Materials Conference*, Johns Hopkins, Baltimore, June 12-14, 1996.
25. J. Park, D.G. Harlow, and H.F. Nied, Statistical Modeling of Interfacial Damage: Development of Methodology, *TECHON '96*, Phoenix, AZ, September 12-14, 1996.
26. R.P. Wei, and D.G. Harlow, Mechanistically Based Probabilistic Considerations of Creep Crack Growth, *Joint FAA/USAF Workshop on Probabilistic Methods for Gas Turbine Engines*, Dayton, OH, October 8-9, 1996.
27. D.G. Harlow, The Effect of Statistical Variability in Material Properties on Springback Predictability, *AeroMat'97: 8th Annual Advanced Aerospace Materials and Processes Conference*, Williamsburg, VA, May 12-15, 1997.
28. J. Rawers, R. Krabbe, N. Duttlinger, and D.G. Harlow, Statistical Study of Nanostructured Material Properties, *TMS: 1997 Materials Week*, Indianapolis, IN, September 14-18, 1997.
29. R.P. Wei and D.G. Harlow, Aging of Airframe Materials: From Pitting to Cracking, *Symposium on Problems in Mechanics and Applied Mathematics, In honor of Professor Fazil Erdogan*, Bethlehem, PA, June 28-30, 1998.

30. D.G. Harlow and R.P. Wei, Corrosion and Corrosion Fatigue in Airframe Materials: Probability of Occurrence Versus Probability of Detection, *Materials Research Society Fall 1998 Meeting: Aging of Engineered Systems with Focus on Aircraft*, Boston, MA, November 30-December 4, 1998.
31. J. Park, D.G. Harlow, and H.F. Nied, Characterization and Evolution of Interfacial Damage in Microelectronic Devices Induced by Accelerated Life Testing, *ASME Mechanics and Materials Conference*, Virginia Tech, Blacksburg, June 27-30, 1999.
32. D.G. Harlow and R.P. Wei, Mechanistically Based Probability Modeling: Intergranular Failure of Three Dimensional Polycrystalline Arrays (invited talk), *Naval Materials by Design*, ONR, Washington D.C., January 6-7, 2000.
33. R.P. Wei and D.G. Harlow, Materials Aging and Life Cycle Design and Management, *AeroMat'00*, Bellevue, WA, June, 2000.
34. D.G. Harlow, Mechanistic Versus Empirical Modeling (invited talk), *DARPA AIM Uncertainty Workshop*, Annapolis, MD, August, 27-28, 2001.
35. D.G. Harlow, Mechanistically Based Probability Models Versus Experimentally Based Statistical Models for Life Prediction (invited talk), *Workshop on Materials in Design*, AFOSR, Tampa, FL, April 10-12, 2002.
36. D.G. Harlow and T.M. Pollock, Modeling the Variability in Strength in a Turbine Disk, *14<sup>th</sup> US National Congress of Theoretical and Applied Mechanics*, Blacksburg, VA, June 23-28, 2002.
37. R.P. Wei and D.G. Harlow, Prognostics Workshop, Washington, D.C., July 17 – 18, 2002.
38. D.G. Harlow, Bayesian Analysis for Error Incorporated with Science Based Modeling for Yield Strength, *DARPA Workshop on Accelerated Insertion of Materials*, Evanston, IL, November 13, 2003.
39. D.G. Harlow, Bayesian Analysis for Science Based Error Modeling for Yield Strength, *DARPA Workshop on Accelerated Insertion of Materials*, San Diego, CA, February 2 – 3, 2004.
40. D.G. Harlow, Science Based Model Tuning with Limited Data, *20<sup>th</sup> Annual General Meeting of the Steel Research Group*, Evanston, IL, March 22 – 23, 2004.
41. Robert P. Wei and D. Gary Harlow, “Materials Aging, Prognosis, and Life Cycle Engineering and Management”, AFOSR Workshop on Damage Prognosis of Metallic Materials, Washington, DC, 28-30 June 2004.
42. D.G. Harlow, G.B. Olson, and J.J. Schirra, Probabilistic Modeling and Data Fusion, *Materials Science & Technology 2004; The Accelerated Implementation of Materials & Processes*, New Orleans, LA, September 26 – 29, 2004.
43. D.S. Muench, G. Kacprzynski, M.J. Roemer, R.P. Wei, and D.G. Harlow, Adaptive Prognosis Applied to Corrosion Fatigue, *Materials Science & Technology 2004; The Accelerated Implementation of Materials & Processes*, New Orleans, LA, September 26 – 29, 2004.
44. D.G. Harlow and M.Z. Wang, Statistical Analysis of Constituent Particle Distributions in 7056-T651, *DARPA Prognosis Meeting*, Sedona, AZ, February 8 – 11, 2005.
45. D.G. Harlow, P.K. Liaw, W. Peter, G. Wang, and R.A. Buchanan, An Approach to Modeling the S-N Behavior of Bulk-Metallic Glasses, *2005 TMS Annual Meeting & Exhibition; Symposium on Bulk Metallic Glasses*, San Francisco, February 13 – 17, 2005.

46. R.P. Wei, D.G. Harlow, M.Z. Wang, R.G. Buchheit, and N. Birbilis, Modeling of Localized Corrosion and Corrosion Fatigue Damage Accumulation, *DARPA Prognosis Meeting*, Sedona, AZ, February 8 – 11, 2005.
47. D.G. Harlow, Spatial Statistics Of Particle Clusters And Modeling Of Pitting Corrosion, *Eighth U.S. National Congress on Computational Mechanics (USNCCM8)*, Austin, TX, July 25 – 27, 2005 (invited).
48. N. Birbilis, R.G. Buchheit, R.P. Wei, D.G. Harlow, and M. Wang, Predicting Corrosion and Corrosion Fatigue in AA7075-T651 used in Airframes, NACE, 2005.
49. R.P. Wei, D.G. Harlow, M.Z. Wang, R. Buchheit, and N. Birbilis, On the Need for Mechanistically Based Modeling in Life Prediction and Reliability Analysis, *EUROCORR 2005*, Lisboa, Portugal, September 4 – 8, 2005 (invited, plenary).
50. R.P. Wei, D.G. Harlow, and R. Buchheit, Mechanistically Based Probability (MBP) Modeling In Design, Fleet Management and Sustainment, *AF Aging Aircraft Technical Interchange Meeting (TIM)*, Tinker AFB, OK, October 18 – 19, 2005 (invited).
51. D.G. Harlow, Mechanics Based Probability Modeling for Minimum Life Estimation of S-N Data, *TMS 2006 135<sup>th</sup> Annual Meeting & Exhibition; A Symposium in Honor of Art McEvily's 80<sup>th</sup> Birthday*, San Antonio, March 12 – 16, 2006.
52. D.G. Harlow, Modeling Pitting Corrosion Induced by Clusters of Particles, *15<sup>th</sup> U.S. National Congress of Theoretical and Applied Mechanics*, Boulder, CO, June 25-30, 2006 (invited).
53. D.G. Harlow, M.-Z. Wang, and R.P. Wei, Probability Modeling to Reflect The Influence of Microstructure, *Materials Damage Prognosis and Life Cycle Engineering*, Snowmass, CO, July 24-28, 2006 (invited).

Technical Reports:

1. D.G. Harlow, R.L. Smith, and H.M. Taylor, The Asymptotic Distribution of Certain Long Composite Cables, Technical Report No. 384, School of Operations Research and Industrial Engineering, Cornell University, Ithaca, NY, Aug. 1978.
2. D.G. Harlow, D. Wei, and J. Keverian, Development of a Reliability, Availability, and Maintainability (RAM) System for the Narrow Strip Production (NSP) Process (proprietary), Kennecott/Chase Brass and Copper, Aug. 1982.
3. D.G. Harlow, Reliability Analysis for the F-18 Main Landing Gear (proprietary), McDonnell Douglas Technical Report, Fall 1985.
4. D.G. Harlow and E.M. Wu, Antenna Wire Reliability (proprietary), NADC Technical Report, Fall 1987.
5. D.G. Harlow, Separation of Three Populations of White Blood Cells from a Histogram (proprietary), Baker Instruments, Spring 1988.
6. D.G. Harlow, Statistical Sampling Plan for the Oyster Creek Drywell Vessel (proprietary), GPU Nuclear, Fall 1990.
7. D.G. Harlow, Reliability Functions for Composite Materials Models, USN/NPS, Report N62271-90-M-2999, Spring 1991.
8. D.G. Harlow and R.P. Wei, A Probability Approach for Prediction of Corrosion and Corrosion Fatigue Life, *Airworthiness Assurance R&D Branch - 1995 Research Accomplishments*, FAA, Atlantic City, 1995, 45-46.



9. D.G. Harlow, N.R. Cawley, and R.P. Wei, Spatial Statistics of Particles and Corrosion Pits in 2024-T3 Aluminum Alloy, *Airworthiness Assurance R&D Branch - 1995 Research Accomplishments*, FAA, Atlantic City, 1995, 47.
10. R.P. Wei and D.G. Harlow, Corrosion and Corrosion Fatigue of Airframe Materials, U.S. Department of Transportation, Federal Aviation Administration, DOT/FAA/AR-95/76, February, 1996.
11. R.P. Wei and D.G. Harlow, Corrosion and Corrosion Fatigue of Airframe Materials: Final Report, U.S. Department of Transportation, Federal Aviation Administration, DOT/FAA/AR-00/22, July, 2000.

*Contracts and Grants:*

Principal or Co-principal Investigator:

Water Quality of the Barren River, NSF, 1972.

A Probabilistic Model for Fibrous Materials, NSF, 1980 - 1982.

Structural Reliability Characterization of Short Fiber Reinforced Plastics, General Motors Technology Center, (with A. Wang) 1981.

Development of a Reliability, Availability, and Maintainability System for Narrow Strip Processing, Chase Brass Company, (with J. Keverian) 1981 -1982.

Practical Robot Control Laws from the Theory of Dynamical Cell-to-Cell Mappings, NSF, (with S.H. Johnson) 1984 - 1986.

Fundamentals of Automated Inference, ONR/ASEE - NRL, (with P. Mast) 1985.

Reliability of the F18 Landing Gear, McDonnell Douglas Corporation - MDRL, 1985.

Investigations of Creep Cavitation in Type 304 Stainless Steel, DOE, (with T.J. Delph) 1985 - 1986.

An Experimental and Analytical Investigation into the Statistics of Creep Rupture, NSF, (with T.J. Delph) 1986 - 1988.

Antenna Wire Reliability, NADC, (with E.M. Wu) 1987.

Reliability and Durability Analysis of Cables, NRC/ONR - NPS, (with E.M. Wu) 1988 - 1989.

Reliability without Hermeticity: Task 4.4.3 Develop Models for Reliability Predictions, MCC/USAF, (with R. Jaccodine, D. Jaffe, and many others) 1991 - 1993.

Environmental and Stochastic Aspects of Creep Crack Growth, NSF (with R.P. Wei, T.J. Delph, M. Gao, and D. Dwyer) 1991 - 1995.

Corrosion and Corrosion Fatigue of Airframe Materials, FAA (with R.P. Wei, M. Gao, and R.D. Granata) 1992 - 1999.

Corrosion and Fatigue of Aluminum Alloys: Chemistry, Micromechanics and Reliability, AFOSR (with R.P. Wei and M. Gao), 1993 - 1996.

Mechanistically Based Temperature and Relative Humidity Reliability Model, MCC, 1993 - 1994.

Study of Fundamentals of Adhesion, Manufacturing, and Reliability of Organic Chip Attachment Adhesives and Process, SRC (with R.A. Pearson and others), 1994 - 1996.

Moisture Induced Subcritical Crack Growth at Coating Interfaces, SRC (with H.F. Nied and R.A. Pearson), 1996 - 1999.

Corrosion and Fatigue of Aluminum Alloys: Chemistry, Micromechanics and Reliability, AFOSR (with R.P. Wei), 1998 - 2000.

Airworthiness Assurance Center of Excellence, FAA, participant as an affiliate member, 1997 - 1999.

Visteon - Reliability, PA Department of Community and Economic Development, (with H.F. Nied and others), 2000 - 2002.

IGERT Formal Proposal: Environmental/Mechanical Interactions and Effects on the Integrity of Structural Materials, NSF (partnership with University of Tennessee, Knoxville), 2000 - 2004.

Accelerated Insertion of Materials (AIM) - Rotor Components, DARPA/DSO (partnership with Pratt & Whitney, and others), 2001 - 2004.

Northrop Grumman Corporation, Modeling for Corrosion and Corrosion Fatigue, DARPA, 2003 - 2008.

Data Fusion and Scientifically Based Modeling, USAF, 2006.

*Probability and Statistics Teaching:*

Undergraduate:

- Statistics
- Probability
- Engineering Reliability
- Advanced Mechanical Design - Mechanical Reliability

Graduate:

- Applied Stochastic Processes
- Mechanical Reliability
- Random Vibrations
- Probability Models in Mechanics
- Stochastic Control
- System Identification
- Nondeterministic Models in Engineering

**Jon C. Hawkins**  
**Non-Destructive Examination Inspector**  
**Peach Bottom Atomic Power Station**

***Current Certifications***

- Level III Ultrasonic Testing (UT) – 15 years
- Level III Visual Testing (VT) – 15 years
- Level III Magnetic Particle Testing (MT)
- Level III Liquid Penetrant Testing (PT)
- NDE Instructor Certified
- PDI Ultrasonic Certified in RPV, Bolting & Overlay

***Previous Certifications***

- Level II Radiographic Film Interpretation (RTI)
- EPRI IGSCC Ultrasonic Certified

***Experience***

- 1978 to 1980: NDE Level I & Level II RT film Interpreter
  - International Union of Operating Engineers: Pipeline Radiography (several company's and locations)
- 1981 to 1986: Limerick Nuclear Generating Station Unit # 1,
  - Pre Service Inspection (PSI) Level II UT, VT, MT, PT
- 1986 to 1991: Limerick Nuclear Generating Station Unit # 2,
  - Pre Service Inspection (PSI) Lead L/II UT, VT, MT, PT
- 1991 to 1992: PECO Level II NDE Inspector
- 1992 to Present: PECO / Exelon NDE Level III NDE Inspection Specialist
  - Currently- Peach Bottom Atomic Power Station NDE Level III / Project Manager
  - PBAPS NDE Project Manager since 2001
- 2006 1R21 Oyster Creek Outage: Performed and Supervised Visual and Ultrasonic thickness readings of the drywell shell.

***UT and VT Training***

- EPRI, Level III Visual Inspection, 160 hrs
- PECO, VT-1, VT-2, VT-3 Visual Inspection, 40 hrs
- PECO, VT-1C, VT-3C Visual Inspection (IWE/IWL), 40 hrs
- EPRI, UT of High Energy Piping, 40 hrs
- EPRI, UT IGSCC Detection, 80 hrs

- EPRI, UT IGSCC Sizing, 40 hrs
- Sperry school for NDE, UT Weld Inspection, 40 hrs
- ASNT, UT Refresher course, 40 hrs
- PECO, NDE Instructor Training, 40 hrs

## RESUME

EDWIN W. HOSTERMAN, P.E.  
Mechanical/Nuclear Engineer

### HOME ADDRESS

45 Clearview Drive  
Mertztown, PA 19539  
(610) 682-4256  
e-mail address: ehosterman@ceinetworks.com

### BUSINESS ADDRESS

Exelon Nuclear  
200 Exelon Way  
Kennett Square, PA  
(610) 765-5947  
e-mail address: edwin.hosterman@exeloncorp.com

### REGISTRATION

Professional Engineer-Pennsylvania, Certificate No.  
PE-031089-E

### EDUCATION

Bachelor of Science, Nuclear Engineering, Pennsylvania State  
University, 1977  
Masters of Business Administration, Temple University, 1983

### PRESENT EMPLOYMENT

Exelon Nuclear , December 2000 to present  
Kennett Square

#### Position:

Senior Staff Engineer

#### Responsibilities Include:

Corporate subject matter expert for heat exchangers, condensers and feedwater heaters as well as Corporate Program Owner for the Generic Letter 89-13 program. Developed Standard heat exchanger testing analysis methodology for Safety Related heat Exchangers. Responsible for formulating long term asset management strategies for condensers, feedwater heaters and buried piping. Has prepared corporate standards for the maintenance and testing of Balance of Plant heat exchangers, condenser air in-leakage testing and water in-leakage testing. Prepared Corporate standard specification for replacement feedwater heaters. Has also functioned as the Corporate Thermal Performance program manager. Prepared PEPSE model of the Limerick Generating station.

### PREVIOUS EMPLOYMENT

Senentec Inc., and Hosterman Engineering, Inc. January 1999 to  
December 2000

PECO Nuclear Co.  
Limerick Generating Station

#### Position:

Consulting Engineer

#### Responsibilities Include:

- Reviewed design Calculations as part of the Limerick Calculation Improvement Project
- Prepared design packages for the replacement of Service Water system valves during the 2RO5 refueling outage
- Provided installation support for the ECCS Suction Strainer modification

- Prepared room temperature analysis for various rooms at the Peach Bottom Atomic Power Station, in support of the Fire Safe Shutdown modifications
- Prepared blowdown and room pressurization analysis in support of the Limerick Reactor Water Cleanup pump replacement.

**PREVIOUS EMPLOYMENT**

Apollo Consulting  
Pa. Power and Light Co. August 1998 to Jan. 1999

Position: Consulting Engineer

**Responsibilities Included:**

- Prepared calculations to provide the design basis for the process flow diagrams for the HPCI, RCIC, RWCU, Core Spray, RHR and Control Rod Drive systems as part of Licensing basis project.

**PREVIOUS EMPLOYMENT**

PECo Energy Company, March 1992 to August 1998

Position: Senior Engineer

**Responsibilities Included:**

- Lead Responsible Engineer for the Emergency Service Water (ESW) and Residual Heat Removal Service Water Systems (RHRSW).
- Program owner for the Generic Letter 89-13 program for both the Limerick and Peach Bottom Stations.
- Developed PECO's heat exchanger testing program and a methodology for statistically analyzing test data.
- Responsible for all hydraulic analysis to support system modifications and system flow balancing at both the Peach Bottom and Limerick Generating Stations.
- Developed transient temperature models for the ECCS pump rooms at both Limerick and Peach Bottom. These models have been used to reanalyze the effects of a DBA LOCA on room temperatures as well as evaluating the effects of pipe breaks on reactor building temperatures.
- Re-evaluated all heat loads served by the ESW and RHRSW systems and Ultimate Heat Sink for both Limerick and Peach Bottom. This re-evaluation reduced the need for testing and cleaning of heat exchangers at the stations and reduced the post accident UHS temperature at Limerick.
- Provided consulting services regarding heat exchanger repairs and maintenance instructions for both Limerick and Peach Bottom.
- Served as the Lead Engineer for several major modifications, in charge of conceptual and final designs, material procurement and installation support. Modifications included:
  - a) Install crosstie lines between the ESW and RHRSW systems at Limerick to facilitate on-line lining of approximately 3000 ft of buried piping.
  - b) Design and install corrosion monitoring racks to monitor the condition of the Service Water and ESW systems at Peach Bottom.
  - c) Install Radiation Monitors on the High Pressure Water System at Peach Bottom.
  - d) Designed and installed a heat exchanger simulator to monitor the condition of the RHR heat exchanger at Limerick. This system allowed the Limerick units to operate for a whole refueling cycle following the discovery of severe pitting in the RHR heat exchanger tube bundle. This allowed the planned replacement of the heat exchangers to be performed without requiring an extended refueling outage. The estimated savings to PECO for this modification were 85 - 87 million dollars.



Responsibilities Included:

- Lead System Engineer for HPCI and RCIC systems
- Lead Mechanical System Engineer for the plant fire protection and liquid and solid radioactive waste treatment systems.
- Lead Mechanical Engineer for programmatic concerns such as high energy line break analysis, several nuclear piping and system design reviews for compliance with the ASME III piping codes, modifications to mitigate the effects of an Anticipated Transient Without Scram and personnel radiation exposure minimization.

**PREVIOUS EMPLOYMENT**

Bechtel Power Corporation, May 1979 to April 1983

Major Assignment:

Senior Field Engineer  
May 1979 to April 1983  
1100 MW BWR, Limerick Generating Station  
Pottstown, PA

**PREVIOUS EMPLOYMENT**

Burns & Roe, Inc., June 1977 to April 1979

Major Assignment:

Mechanical/ Nuclear Engineer  
June 1977 to April 1979  
Nuclear Analysis Group  
Oradell, N.J.



**Martin McAllister**  
**Oyster Creek Nuclear Generating Station**  
Route 9, Forked River, New Jersey 08731

**Current Certifications**

Level III Ultrasonic Testing (UT)  
Level III Magnetic Particle Testing (MT)  
Level III Liquid Penetrant Testing (PT)  
Level III Visual Testing (VT)  
NDE Instructor Certified  
PDI Ultrasonic Certified

**Previous Certifications**

Level II Radiography Testing (RT)  
AWS/CWI Visual Inspector  
IGSCC Ultrasonics Certified

**Experience**

1978 to 1991

NDE Level II Inspector / Supervisor

Construction of Susquehanna Steam Electric Station and Limerick Generating Station

1991 to Present

Oyster Creek Nuclear Generating Station, Currently- Station NDE Level III

**Specific drywell liner experience:**

Performed ultrasonic thickness readings of the Drywell liner shell from 1991-1994 and supervised exams (both VT and UT) from 1994 to present.

Certified as Level III UT over 13 yrs.

Certified as Level III VT over 9 yrs.

**Training - UT and VT only**

A.W. Beattie Tech School – Nuclear / Metallurgy / NDE – Diploma 1978, 170 hrs NDE

AWS, CWI Visual Inspection, 40 hrs

EPRI, Level III Visual Inspection, 40 hrs

GPUN, VT-1, VT-2, VT-3 Visual Inspection, 56 hrs

EPRI, UT of High Energy Piping, 40 hrs

EPRI, UT IGSCC Detection, 40 hrs

EPRI, UT IGSCC Sizing, 40 hrs

Magnaflux, UT Weld Inspection, 40 hrs

ASNT, UT Inspection, 40 hrs

EPRI, NDE Instructor Training, 40 hrs

**AHMED M. OUAOU, PE**

1103 Shadow Wood Drive  
Downingtown, PA 19935

(484) 947-3765

**SUMMARY**

Registered professional engineer with extensive, diversified experience in civil/structural design, stress analysis, plant and construction support, and licensing. Areas of expertise include:

<i>License Renewal</i>	<i>Civil/structural Design and Analysis</i>	<i>Design Basis Documents</i>
<i>Configuration control</i>	<i>Dynamic Qualification of Equipment</i>	<i>Design Review/Assessment</i>
<i>Project Management</i>	<i>Process and procedure development</i>	<i>Licensing Documents Update</i>

**PROFESSIONAL EXPERIENCE**

**License Renewal Experience:**

**Three Mile Island Nuclear Station Unit 1**

03/2007 – Present

- Developed ASME Section XI, Subsection IWE, IWL, IWF, and Structures Monitoring aging management programs. The documents provide technical basis for the adequacy of TMI-1 aging management activities to support the extended period of operation.
- Supported scoping of structures and development of aging management reviews on an advisory role.

**Oyster Creek Generating Station License Renewal Application**

11/2003 – 03/2007

- Civil/Structural lead for Oyster Creek (OC) license renewal application.
- Performed scoping, screening, and aging management reviews for OC structures
- Prepared aging management program (AMPs) basis documents and aging management review technical basis documents.
- Evaluated Oyster Creek AMPs for consistency with NUREG-1801 AMPs
- Developed Oyster Criteria for scoping of systems and structures to meet 10 CFR 54.4 (a)(2), and NRC Staff Interim Staff Guidance (ISG-09).
- Prepared civil/structural sections of the Oyster Creek license renewal application
- Prepared position papers and project level instructions for performing scoping, screening, and aging management review of systems and structures.
- Presented scoping and screening methodology of Oyster Creek structures and 10 CFR 54.4 (a)(2) scoping to the NRC scoping and screening methodology audit team.
- Supported the NRC AMP/AMR audit team and interfaced with the Staff and its consultants to resolve AMP and AMR questions and issues
- Prepared response to RAIs and interfaced with NRC Staff to resolve technical issues.
- Prepared presentation for, and supported the ACRS Subcommittee review of the OC drywell corrosion issue.
- Participated in industry review of the draft NUREG-1801 Rev. 1
- Member of NEI Civil/Structural Working Group team.
- Provided technical support to the drywell corrosion issue legal team.

**Browns Ferry License Renewal Application**

07/2003 – 11/2003

- Performed scoping and screening of Browns Ferry structures
- Review AMRs prepared by TVA consultants

**Peach Bottom License Renewal Application**

04/2001 – 06/2003

- Performed scoping, screening, and aging management reviews for Peach Bottom structures and selected mechanical systems.
- Wrote civil/structural sections of the application

- Prepared response to RAIs and interfaced with NRC Staff to resolve technical issues identified during its review of the LRA
- Participated in ACRS Subcommittee hearings and responded to ACRS member's questions related to structures.
- Reviewed and commented on NUREG-1801 Rev.0.
- Participated in industry peer review of Hatch, ANO-1, and Dresden/Quad LRAs.

### **Construction and Plant Support Experience**

#### **Limerick Generating Station**

1998 -2001

Design and review the design of plant modifications for technical adequacy

Develop engineering strategy for resolving Thermo-Lag raceway encapsulation deficiencies identified in NRC Generic Letter 92-08

#### **Maine Yankee Power Station**

- Review open items for nuclear safety significance, equipment reliability, licensing commitments, and recommend their implementation strategy prior to restart from NRC Shutdown Order.
- Assess Maine Yankee's Corrective Action Program for compliance to 10 CFR 50 Appendix B requirements.

#### **Peach Bottom Atomic Power Station.**

Assess a pressure vessel for stress and fatigue Code requirements. Prepare a summary report for the client on the available design margin. Develop a specification to assess Motor Operated Valves for maximum thrust/torque. Design structural modifications for pump intake structures. Prepare procurement documents and installation work packages for modifications.

### **PECO ENERGY COMPANY, Philadelphia, PA**

#### **Site Support Engineer**

1993 - 1996

Responsible for the design, procurement, and planning of plant modifications. Resolved Nonconformance Reports, and Engineering Change Requests. Resolved configuration control issues. Worked with plant operations and maintenance to improve plant equipment and systems performance.

- Designed modifications to structures, and equipment to enhance plant safety, performance, and improve productivity. These changes in conjunction with other plant initiatives reduced Power Plant refueling outage length from 120 days to 22.8 days. Set world record.
- Considered a subject matter expert on dynamic qualification and design of structures and equipment.
- Designed reactor cavity stair tower. The tower is considered a first in the US nuclear industry. Its use reduces refueling outage critical path time by 4 hours. The design was selected by the company for submittal as a candidate for 1995 Power Industry "Innovative Design Idea" Award.

#### **Branch Manager, Processes and Procedures, Wayne, PA**

1990 - 1993

Responsible for planning, developing, and implementing engineering processes, policies, directives, and procedures. Resolved configuration issues associated with Peach Bottom power plant shutdown. Managed work performed by consultants and contractors.

### **BECHTEL POWER CORPORATION, San Francisco, CA**

#### **Project Engineer**

1989 - 1990

Responsible for scope, cost, and schedule of the \$8.4 million design turnover project from the Bechtel to the client. Managed multi-discipline group activities associated with the turnover.

**Site Project Manager**

1988 - 1989

Responsible for establishing and staffing site project manager's office that is recognized as the focal point for all engineering requests. Coordinated engineering activities to ensure prompt support of critical construction, maintenance, and operations activities. Managed design and installation of modifications.

**Resident Project Engineer**

1987 - 1988

- Managed a multi-discipline engineering team responsible for Limerick construction support.

**Engineering Group Supervisor**

1981 - 1987

- Directed and provided technical direction for up to 60 engineers responsible for civil/structural design and assessment of Susquehanna Steam Electric Station, and Limerick Generating Nuclear Station structures and commodities.

**Structural Design Experience:**

1977 - 1980

- Designed steel, reinforced concrete, and masonry wall structures for Susquehanna, Limerick, Peach Bottom, Trojan, and Midland nuclear power plants.
- Performed static and dynamic analysis using SAP, ANSYS, and STRUDL computer codes.
- Performed finite element analysis to evaluate Susquehanna Steam Electric Station, and Limerick Generating Nuclear Station Mark II containments for BWR Mark II containment hydrodynamic loads.
- Designed and evaluated structures and equipment for Design Basis Accident Loads.
- Developed test plans and evaluated dynamic testing of Category I equipment and structures.
- Developed Project Specification for assessing Seismic Category III/II Items.
- Developed masonry design criteria and standard details specific to nuclear plant structures.
- Developed response to NRC IE Bulletins 79-02, 79-14, and 80-11.

**Engineer, Mining and Metals Division**

1974 - 1977

Responsible for the design of concrete and steel structures for two \$100 million dollar projects. Designed tanks, hoppers, conveyor towers and pipe racks. Prepared conceptual designs and plant layout for industrial project. Prepared cost estimates, and bid packages that resulted in job awards to the company.

**EDUCATION**

B.S. - Civil Engineering, University of Nevada at Reno  
Graduate courses in Civil Engineering, University of California, Long Beach  
Registered Professional Engineer, PA, CA

## Resume of John F. O'Rourke

### Present Position

Senior Project Manager, License Renewal, Exelon Nuclear, Kennett Square

### Previous Positions

June 11, 1973

Joined the Philadelphia Electric Company as an Assistant Engineer in the Power Plant Services Section of the Mechanical Engineering Division

November 4, 1974

Transferred to Power Plant Design Section, Mechanical Engineering Division

June 5, 1976

Engineer, Power Plant Design Section

April 20, 1981

Appointed as Group Leader, Piping and Pipe Supports, Power Plant Design Section

May 26, 1984

Senior Engineer, Power Plant Design Section

June 23, 1984

Appointed as Branch Head, Plant Design and Metallurgy (formerly Fossil Steam Supply) Branch, Power Plant Design Section

March 22, 1986

Appointed as Supervising Engineer and Branch Head, Nuclear Services Branch, Power Plant Services Section

October 31, 1987

Appointed as Manager, Corporate Nuclear Quality (formerly Quality Support) Division, Nuclear Quality Assurance

December 1, 1989

Appointed as Manager, Limerick Quality Division, Nuclear Quality Assurance

May 18, 1992

Appointed as Acting Projects Division Manager, Limerick Generating Station (until Dec. 31, 1992)

April 1, 1993

Appointed Senior Manager, Design Engineering, Site Engineering, Limerick Generating Station.

November 18, 1996

Appointed Manager, Procedures Branch, Nuclear Engineering Division,  
Chesterbrook.

May 27, 1997

Appointed Manager, Engineering Assurance and Procedures Branch,  
Nuclear Engineering Division, Chesterbrook.

October 18, 1999

Appointed Manager, Mechanical Branch, Nuclear Engineering Division,  
Chesterbrook

October 20, 2000

Appointed Senior Manager, Mechanical Branch, Mid-Atlantic Regional  
Operating Group, Engineering Division, Exelon Nuclear, Kennett Square

July 28, 2003

Appointed Assistant Site Engineering Director for the Oyster Creek  
Generating Station

September 4, 2006

Assigned to License Renewal Project, Exelon Nuclear, Kennett Square as a  
Senior Project Manager for Oyster Creek and Salem/Hope Creek activities

## Work Assignments

2006 – Present

Assigned to License Renewal Project for Oyster Creek to assist with completion of Oyster Creek activities including NRC Safety Evaluation Report review/comments, ACRS Meetings preparation/execution including preparing and delivering presentations to the ACRS Subcommittee and Full Committee, Re-Analysis of Oyster Creek drywell (Project Manager) and the Evaluation of the Oyster Creek Refueling Cavity Liner leakage (Project Manager). Appointed as the Senior Project Manager to manage all aspects of the Salem/Hope Creek License Renewal Project under contract to PSEG.

2003 – 2006

Responsible, along with the Director, for the management and leadership of the Engineering Department at Oyster Creek. Acts as Director, when the Director is away from the site, and as Senior Manager, Design and Plant Engineering (positions combined into Asst. Director position under Single Site Staffing Initiative). Develops and manages the Engineering Department budget. Provides the site single point of contact for Configuration Management activities and leadership and management of design and modification related activities for the site, including capital and expense projects/checkbook. Chairs the Design Subcommittee of the Plant Health Committee and the Curriculum Review Committee. Provides the site management sponsorship, interface and oversight for License Renewal technical activities (application, program and technical basis documents, audits, training, site engineering support, etc.). Acting Director from April, 2006 thru June, 2006

1999 - 2003

Responsible for high-end technical support, consultation and mentoring to the site Design Engineering and Plant Engineering organizations in the areas of accident analysis, thermal-hydraulic analysis, diesels, heat exchangers and condensers, structural/dynamic qualification, finite element analysis, HVAC/compressors, turbines and pumps. Responsible for developing strategic plans for the Regional Operating Group in the Mechanical and Structural areas. Responsible for Program management for selected programs (e.g., Dynamic Qualification). Completed transitioning TMI and Oyster Creek support from Parsippany including training and qualification of personnel, staffing and software support. Provided outage support for Limerick as the MSRV Modification "Make-It-Happen" Manager. Continuing as the lead for the Design Change Process Team as the Engineering organizations develop a process ownership approach to Engineering processes. Also, continuing as the lead for the Configuration Management strategy and as the Custodial Team Leader for the PIMS ECR Module. Provided support for MWROG with their implementation of Passport and for the implementation of PIMS at TMI and Oyster Creek.

1996 - 1999

Responsible for the common procedure activities (Administrative, Engineering, Modifications) within the Nuclear Group. This includes

providing leadership for improvement initiatives and for the former Document Steering Committee. On May 27, 1997, the Engineering Assurance Branch was merged with the Procedures Branch providing the added responsibility for the technical assessment of engineering and configuration management activities throughout the Nuclear Group. This activity as well as the procedure activities directly support Nuclear Engineering Division's role as the PECON Design Authority. Outage support for the Limerick refueling outages provided via assignments as Engineering Duty Manager and MSIV and MSRV Modifications "Make-It-Happen" Manager. During the Nuclear Group Project to develop PassPort as a replacement for PIMS, acted as the Implementation Team Leader for the Engineering module which included working with British Energy counterparts to design a completely new module. Appointed as the lead for the Design Change Process Team and the lead for the Information Technology and Configuration Management strategies. Worked with TMI personnel to develop the appropriate application of technical assessment activities for TMI. Acted as a peer evaluator for an INPO Assistance visit to Fitzpatrick.

1993 - 1996

Responsible for ensuring timely, high quality, day-to-day station support for resolution of Design Engineering issues and for the design of engineering projects (small modifications, minor physical changes, design equivalent changes, etc.). Responsible for ensuring configuration control is maintained, facilitating the removal of organizational and cultural barriers impacting Design Engineering's performance, interfacing with on-site customers and Peach Bottom and Chesterbrook counterparts. Outage support for Limerick refueling outages provided via assignments as the Shift Outage Director, Engineering Duty Manager and MSIV Modification "Make-It-Happen" Manager.

1992

Responsible for managing activities within the Limerick Projects Division which included the Outage Section, Materials Management, Regulatory and the Modifications Group. Responsibilities included business planning and cost control (Both Projects Division and Limerick Quality Division under budget in 1992)

1989 - 1993

Responsible for the independent oversight (i.e. Single point accountability) of all Quality activities at Limerick Generating Station. Activities include auditing, inspections, surveillances, monitoring and reviews. Significant activities included reduction in contractor personnel, initiation of formal divisional self-assessment activities, budget compliance, and "customer" interface.

1987-1989

Responsible for the independent oversight of Corporate Nuclear Group organizations (i.e., Single point accountability for oversight of Nuclear Engineering and Nuclear Services Departments quality activities) for work performed under the PBAPS and LGS Operational Quality Assurance



Plans. Also responsible for all vendor audit/surveillance activities, security screening auditing, QATTS technical support, PBAPS/LGS FSAR (Chapter 17) and Quality Assurance Plans preparation/revision and NQA Procedure and Budget coordination. Served as the Acting PBAPS Quality Manager in 1989 during the absence for training purposes of the current Quality Manager. This assignment included heavy HR and OD interface as well as training in MARC, Interaction Management and Managing Organizational Change. Also, changing culture in the Nuclear Group and in NQA and downsizing of NQA required significant management attention.

#### 1986-1987

Responsible for design activities associated with various systems that support nuclear plant operations, i.e., Diesel generators, Air and Nitrogen Systems, Gaseous Radwaste Systems, PASS, CAC, Containment, etc. This required interfacing with the plant staffs as the "customer" focal point for resolution of system operating problems. Also served as ERDP (Engineering & Research Department Procedures) Task Force Chairman during this period which required extensive interface with the Quality Assurance organizations.

#### 1975-1986

Responsible for piping and pipe support design activities. This required working closely with plant staff personnel during the investigation and resolution of piping/pipe support problems. It also included reviewing operating data to identify plant conditions that might have caused the problems. Frequent plant inspections were made during this period.

Appointed as Group leader for all piping and pipe support design activities for nuclear and fossil plants in April, 1981. Appointed as Branch head, Plant Design and Metallurgy Branch (formerly Fossil Steam Supply Branch) in June, 1984 responsible for nuclear and fossil piping and pipe support design activities, nuclear and fossil valve design activities and fossil steam supply systems.

Significant activities performed during this period included:

- Project Manager, Peach Bottom Unit 2 Recirculation/RHR Piping Replacement. The majority of the management of the field activities was done via full time site presence working in close concert with the contractor and the plant technical/outage staff.
- Project Engineer, Eddystone Unit 1 main steam piping replacement.
- Project Engineer, Peach Bottom torus attached piping modifications associated with Mark I containment program. These activities required frequent on-site presence.
- Project Engineer, I.E. Bulletin 79-14 field inspections and modifications.

1974-1979

Responsible for the design of modifications related to the Offgas Systems at the Peach Bottom Atomic Power Station. This included the review/investigation of operating difficulties with the System which required plant staff interface and field inspections.

1973-1974

Responsible for various fossil plant projects, such as equipment replacements and preparation of waste water permits.

### Educational Background

Bachelor of Science in Mechanical Engineering, Drexel University, 1973, *cum laude*

Master of Science in Mechanical Engineering, Drexel University, 1975

Master of Science in Engineering Management, Drexel University, 1983

Professional Engineer, Commonwealth of Pennsylvania, 1976

Penn State Executive Management Program, 1989

PECO Quality Management Training, 1991, 1992, 1993

Senior Reactor Operators (SRO) Certification at Limerick, 1991

Three Mile Island Unit 1 Systems Training, 1999

### Professional Activities

American Society of Mechanical Engineers, Philadelphia Section

Member 1974 to 1997, held various committee chairmanships and officer positions, Section Chairman 1983-1984

American Nuclear Society, Delaware valley Section

Member 1977 to 1993

American Society for Quality Control

Member 1988 to 1993

Delaware Valley Engineers' Week Committee

Vice-Chairman 1985-88, Secretary 1988-89, Chairman, Engineer of the Year Election Committee 1989

Edison Electric Institute Quality Assurance Committee

Alternate Philadelphia Electric representative for the NQA General Manager

and Vice-Chairman of the Nuclear Sub-Committee, 1988 to 1993

Institute of Nuclear Power Operations (INPO) Peer Evaluator, 1997

Updated 4/4/07

**Fred Polaski**  
**License Renewal Manager, Exelon Nuclear**  
200 Exelon Way  
Kennett Square, Pennsylvania 19348

***Experience***

- Over 36 years experience in engineering and management with Philadelphia Electric, PECO and Exelon
- 1971-1996: Held various positions in nuclear engineering and management, mostly at Peach Bottom Atomic Power Station:
  - System Engineer
  - Maintenance Engineer
  - Lead Reactor Engineer
  - Outage Manager
  - Assistant Superintendent Operations during Peach Bottom restart
  - Senior Project Manager
  - Manager Independent Safety Engineering Group
- 1978: Earned Senior Reactor Operator's License on Peach Bottom Atomic Power Station
- 1996: PECO project manager for the NEI/NRC/Utility Demonstration Project on Implementation of NEI 95-10 and Part 54.
- 1996 to 2005: Member and Vice Chair of the Electric Power Research Institute (EPRI) LCM Subcommittee, Chair of BWROG License Renewal Committee
- 1996 to present: Member of NEI License Renewal Task Force and License Renewal Working Group
- 1998: Project Director for Peach Bottom License Renewal project
- 2000-present: Exelon License Renewal Manager responsible for
  - Peach Bottom License Renewal Project - new license issued, May 2003
  - Dresden – Quad Cities License Renewal Project – new license issued, October 2004
  - Oyster Creek License Renewal Project
  - TMI 1 License Renewal Project
  - Planning for future license renewal projects within Exelon
  - Participant in Peer Reviews for several license renewal applications
  - Member of the License Renewal Assessment Board for Beaver Valley Nuclear Power Station application.

- Member various other industry groups on license renewal and LCM: EPRI MRP committee on Environmentally Assisted Fatigue, Member of the License Renewal Assessment Board for the Beaver Valley License Renewal Application, NEI License Renewal Electrical and Mechanical Working Groups, Westinghouse Owner's Group License Renewal Committee.

***Education***

- University of Delaware 1971 Bachelor's of Mechanical Engineering, with High Honors

**Francis H. Ray**  
**Engineering Programs Manager**

Oyster Creek Nuclear Generating Station  
Route 9, Forked River, NJ 08731

***Experience***

Over 26 years of experience in the Nuclear Industry.

December 2006-Present: Oyster Creek Nuclear Generating Station: Manager,  
Engineering Programs.

- Responsible for the day-day supervision of the program owners who implement the Regulatory driven Engineering Programs, which include the ASME In-Service Inspection (ISI) and drywell monitoring programs.
- Responsible for overseeing implementation of all license renewal commitments including those associated with the drywell shell integrity and inspection program.

January 2004 – December 2006: Oyster Creek Nuclear Generating Station: Manager,  
Mechanical / Structural Design

- Responsible for the day-to-day supervision of the Mechanical / Structural Design Engineering Branch whose primary activities included support of plant operations, configuration control, margin management, proactively defend the plant design and licensing basis, modifications, and ownership of a number of Aging Management Programs associated with the Oyster Creek Nuclear Generating Station License Renewal Application, including the drywell shell and related inspections and commitments.
- Supported NRC license renewal audits and inspections at the Oyster Creek Nuclear Generating Station in 2006.

June 1999 – January 2004: PECO / Exelon Nuclear at the Limerick Generating Station:  
Senior Mechanical / Structural Design Engineer

- Subject matter expert for piping and support design, structural bolting, ASME Code and Code Case interpretations associated with evaluations of ASME piping flaws due to corrosion.

September 1980 – June 1999: Stone and Webster Engineering Corporation (SWEC),  
Cherry Hill, NJ

- Over 18 years of extensive design experience in the civil and mechanical engineering disciplines associated with numerous nuclear power plants under construction (e.g. Nine Mile Point 2, RiverBend, Comanche Peak, Fermi 2, and Shoreham) and several licensed Operating plants (e.g. Peach Bottom Atomic Power Station, Limerick Generating Station, Three Mile

Island, RiverBend, Nine Mile Point 2, and Browns Ferry Nuclear Plant - Unit 2).

- Received extensive training in all aspects of design in BWR and PWR power plant design, construction, and maintenance.

***Publication***

“Cost Effective In Situ Small Bore Piping Qualification for Vintage Power Plants”, ASME Pressure Vessel and Piping Division Conference, San Diego, Ca. (TP No. 91-50)

***Education***

Bachelor of Science, Civil Engineering, University of Pittsburgh, 1980

**Peter Tamburro**  
**Programs Engineer**  
**Oyster Creek Nuclear Generating Station**

**Office Phone: (609) 971-4141**

**EXPERIENCE**

2007 to present - Programs Engineer, AmerGen LLC, Oyster Creek Nuclear Generating Station, Forked River, NJ 08731. Maintain the following Oyster Creek Programs: Drywell Material Condition Program, Open Cycle Cooling Water Piping, and the Underground Piping Program. The purpose of these programs is to ensure that these systems will perform their function.

1999 to 2006 - Mechanical Design Engineer, AmerGen LLC, Oyster Creek Nuclear Generating Station, Forked River, NJ 08731

Responsibilities included: designing and managing modifications; resolving construction problems related to modifications; evaluating component failures; analyzing and correcting problems related to system and equipment degradation; and support engineering activities during scheduled and unscheduled outages.

Activities include developing: design criteria, installation and procurement specifications, construction sketches, and overseeing development of construction drawings. Examples of modification completed successfully are: installation of the 2004 DBT security systems, installation of various large piping systems such ESW, Service Water and Fuel Oil Transfer Lines.

Provided engineering support to troubleshoot and modify plant equipment, to avoid or recover from unscheduled outages. Performed and documented evaluations that support continued plant operation. Provided input to management with regard to economic justification for funding future projects and modifications.

Responsible to ensure that UT inspection were performed in the upper drywell regions and visual inspections were performed in the sandbed region per plant commitments.

1991 to 1999 - Mechanical Engineer, GPU Nuclear Corporation (GPUNC), Oyster Creek Nuclear Generating Station, Forked River, NJ 08731

Responsibilities included: to support engineering activities during scheduled and unscheduled outages and to serve as an interface between plant and corporate engineering.

Activities include developing: design criteria, installation and procurement specifications, construction sketches, and overseeing development of construction drawings. This also includes following successful modifications in the field and disposition of field changes: replacement of a 2000 GPM fire protection pumphouse; rerouting of large bore piping and valves; installing HVAC equipment and process chillers; excavations to repair leaking underground Service Water lines; and installing temperature, pressure, flow and radiation instrumentation.

Provided engineering support to trouble shoot and modify plant equipment, to avoid or recover from unscheduled outages. Performed and documented evaluations that support continued plant operation. Developed heat exchanger monitoring programs. Provided input to management with regard to economic justification for funding future projects and modifications.

Also involved in a cross-disciplinary committee which "re-engineered" the project management process at GPUNC. Key person in specifying software for the new process.

1986 to 1991 - Mechanical System Engineer, GPUNC, 100 Interpace Parkway, Parsippany, NJ 07054

Member of the corporate engineering staff: responsibilities for both the Oyster Creek and Three Mile Island Unit #1 Nuclear Power Plants included: evaluating system problems and component failures; monitoring system parameters; analyzing, defining, and correcting problems related to system degradation; and design of plant modifications.



## **Peter Tamburro**

Performed and documented evaluations that supported regulatory Technical Specification revisions, and justifications for continued plant operation. This included calculations, technical reports, and responses to audits. Performed numerous studies and reviews related to system and component heat transfer capabilities and plant capacity improvements, including overall effects on plant heat rates. Member of the GPUNC Thermal Performance Committee whose purpose was to overview lost capacity issues and pursue corrective actions. Designed plant modifications for both plants and then followed construction in the field.

Major contributor to the Oyster Creek drywell corrosion abatement program. Responsibilities included defining requirements for an inspection program of the drywell pressure vessel. Coordinated inspection data reduction, performed and documented analysis, and reported results to upper management and the Nuclear Regulatory Commission.

1982 to 1988 - Plant Analysis Engineer, GPUNC, Parsippany, 100 Interpace Parkway, NJ 07054

Responsibilities involved developing and maintaining the Plant Thermal Performance and Availability Monitoring Programs for both the Oyster Creek and Three Mile Island Unit #1 Nuclear Power Plants. This involved developing and refining calculations, procedures, and methods for determining plant inefficiencies and loss generation. Developed thermal performance code models of both plants. These models have been a foundation for GPUNC thermal performance monitoring programs at both plants. Model outputs were used for the development of replica simulators of both plants.

Another responsibility was to review, for applicability to GPUNC plants, descriptions of adverse events which occurred in the nuclear industry. If applicable, it was my responsibility to implement action that would reduce the possibility for the events from occurring at GPUNC.

It was also my responsibility was to assist in the development of a SCRAM Frequency Reduction Program for GPUNC. The program established methods which reduced the number of unnecessary reactor trips at Oyster Creek. Participated for GPUNC on a nuclear industry committee which exchanged lessons learned.

1980 to 1982 - Mechanical Test Engineer, Newport News Shipbuilding & Drydock Company, Newport News, Virginia

Mechanical system testing of two A4W type nuclear power plants on the CVN-70 aircraft carrier.

### **EDUCATION**

B.S. in Chemical Engineering from Clarkson University, Potsdam, NY (May 1980).

M.S. in Computer Science from Fairleigh Dickinson University, Teaneck, NJ (October 1986).

Professional Engineer, State of New Jersey, 1986.

AmerGen Energy Company, LLC  
200 Exelon Way  
Kennett Square, PA 19348

www.exeloncorp.com

An Exelon Company

10 CFR 50  
10 CFR 51  
10 CFR 54

2130-05-20159

July 26, 2005

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Oyster Creek Generating Station  
Facility Operating License No. DPR-16  
NRC Docket No. 50-219

**Subject:** Application for Renewed Operating License – Reformatted CD-ROM

**References:** Letter from C. N. Swenson (AmerGen Energy Company, LLC) to U. S. NRC  
“Application for Renewed Operating License” dated July 22, 2005

AmerGen Energy Company, LLC (AmerGen) submitted an application for the renewal of the operating license for the Oyster Creek Generating Station (OCGS) pursuant to U. S. Nuclear Regulatory Commission (NRC) regulations 10 CFR 50, 51 and 54 in the above referenced letter.

For clarity, the enclosed CD-ROM is being provided in a revised electronic file format that is intended to resolve issues with image resolution and embedded fonts. It is solely an administrative reformatting. Specifically, Enclosure 2 is a single compact disc (CD), formatted in a manner that is consistent with “Guidance for Electronic Submissions to the Commission”, referenced in the *Federal Register* on October 10, 2003 (68 FR 58826). This CD contains files suitable for entry into the NRC's record retrieval system, ADAMS.

It is not practicable to provide fully text searchable files for Appendices B, C, D and E of the Environmental Report since they contain copies of documents and graphics that must be scanned as image files. Thus, AmerGen also is providing a paper copy of the complete Oyster Creek Generating Station “Application for Renewed Operating License” in Enclosure 3 (four volumes).

Inasmuch as this submittal only involves administrative changes to the electronic formatting, the Application for Renewed Operating License submitted by letter dated July 22, 2005, remains operative.

If you have any questions, please contact Fred Polaski, Manager License Renewal, at 610-765-5935.

A114

July 26, 2005  
Page 2

Respectfully,



Pamela B. Cowan  
Director – Licensing and Regulatory Affairs  
AmerGen Energy Company, LLC

Enclosures:   1. Affidavit  
                  2. CD-ROM labeled “Oyster Creek Generating Station, License Renewal Application, July 2005, Reformatted CD-ROM ”  
                  3. Oyster Creek Generating Station, License Renewal Application (four volume paper copy)


cc:   Regional Administrator, USNRC Region I, without enclosures  
      NRC Project Manager, NRR – License Renewal, Safety, without enclosures  
      NRC Project Manager, NRR – License Renewal, Environmental, without enclosures  
      USNRC Senior Resident Inspector, OCGS, without enclosures  
      Bureau of Nuclear Engineering, New Jersey Department of Environmental Protection, without enclosures  
      File No. 05040

STATE OF PENNSYLVANIA )  
CHESTER COUNTY )  
IN THE MATTER OF: )  
AMERGEN ENERGY COMPANY (AmerGen), LLC ) Docket Number  
Oyster Creek Generating Station ) 50-219


SUBJECT: Application for Renewed Operating License – Reformatted CD-ROM

AFFIDAVIT

I affirm that the content of this transmittal is true and correct to the best of my knowledge, information, and belief.

  
\_\_\_\_\_  
Pamela B. Cowan  
Director – Licensing and Regulatory Affairs  
AmerGen Energy Company, LLC

Subscribed and sworn to before me, a Notary Public in and  
for the State above named, this 26<sup>th</sup> day of  
July, 2005

  
\_\_\_\_\_  
Notary Public

COMMONWEALTH OF PENNSYLVANIA  
Notarial Seal  
Viva V. Gallimore, Notary Public  
Kennett Square Boro, Chester County  
My Commission Expires Oct. 6, 2007  
Member, Pennsylvania Association Of Notaries

---

**Enclosure 2 consists of one CD-ROM labeled "Oyster Creek Generating Station, License Renewal Application, July 2005, Reformatted CD-ROM" containing the following 3 files:**

**01-LRA.pdf; 5,025 KB; publicly available**

**02-ER(TOC-Chap9).pdf; 14,027 KB; publicly available**

**03-ER(Appendix A-F).pdf; 40,194 KB; publicly available**

**LICENSE RENEWAL APPLICATION**

**OYSTER CREEK GENERATING STATION**

**DOCKET No. 50-219**

**Facility Operating License No. DPR-16**

## 2.4.1 Primary Containment

### System Purpose

The Primary Containment Structure is comprised of the primary containment, containment penetrations, and internal structures. The structure is enclosed by the Reactor Building, which provides secondary containment, structural support, shielding, shelter, and protection, to the containment and components housed within, against external design basis events.

The primary containment is a General Electric Mark I design and consists of a drywell, a pressure suppression chamber, and a vent system connecting the drywell and the suppression chamber. It is designed, fabricated, inspected, and tested in accordance with the requirements of the ASME Boiler and Pressure Vessel Code, Section VIII, and Nuclear Code Cases 1270N-5, 1271N and 1272N-5. The containment is safety related, classified Seismic Class 1 structure.

The drywell is a steel pressure vessel, in the shape of an inverted light bulb, with a spherical lower section and a cylindrical upper section. The lower spherical section is embedded externally in the reinforced concrete foundation and covered internally by a fill slab at the bottom of the drywell. The top portion of the drywell vessel consists of a steel head that is removed during refueling operations. The head is bolted to the drywell flange and is sealed with a double seal arrangement. Access into the drywell is through a personnel airlock/equipment hatch, with two mechanically interlocked doors, and other access hatches. The drywell houses the reactor pressure vessel, the reactor coolant recirculation system, safety relief valves, electromatic relief valves (EMRVs), branch connections of the reactor primary system, containment drywell spray header, and internal structures discussed below. The drywell shell and the enclosing reactor building concrete are separated by an air gap to allow for differential thermal expansion between the shell and the concrete during any mode of plant operation.

The pressure suppression chamber is a toroidal shaped, steel pressure vessel encircling the base of drywell. The suppression chamber, commonly called the torus, is partially filled with demineralized water and includes internal steel framing, and access hatches. The suppression chamber is mounted on support structures that transmit loads to the reactor building foundation. Major components inside the suppression chamber include Emergency Core Cooling Systems (ECCS) suction strainers, which are connected to the ECCS suction header located outside the chamber, torus spray header, and Y-Quenchers.

The vent system consists of ten circular vent lines, which form a connection between the drywell and the pressure suppression chamber. The lines enter the suppression chamber through penetrations provided with expansion bellows and join into a common header contained within the air space of the suppression chamber. The header discharge is through 120 downcomer pipes, which terminate below the water level in the torus. The header and the downcomer pipes are supported from the suppression chamber shell.

The primary containment is provided with a vacuum breaker system to equalize the pressure between the drywell and the suppression chamber, and between the suppression chamber and the reactor building. The vacuum breaker system assures that the external design pressure limits of the two chambers are not exceeded.

The primary containment is penetrated at several locations by piping, instrument lines, ventilation ducts, and electric leads. The penetrations consist of sleeves welded to drywell vessel or suppression chamber and are of two general types. Those required to accommodate thermal movements; and those, which experience relatively little thermal stress. Penetrations required to accommodate thermal movements are provided with expansion bellows.

Internal structures consist of a fill slab, reactor pedestal, biological shield wall and its lateral support, and structural steel. The fill slab is reinforced concrete placed in the bottom of the drywell to provide a working base for supporting the reactor pedestal and other structures and components inside the drywell.

The reactor pedestal is a reinforced concrete cylinder with an outside diameter of 26 feet. The pedestal provides structural support to the reactor pressure vessel, the biological shield wall, and floor framing. The biological shield wall extends above the reactor pedestal and is a composite steel, concrete cylinder with an inside diameter of approximately 21 feet. The wall is framed with steel columns covered with steel plate on each face and filled partly with normal density concrete and partly with high-density concrete. The top of the wall is capped with a steel plate and laterally braced to the drywell vessel.

Structural steel includes floor framing steel for the platforms inside the drywell, and a catwalk inside the suppression chamber. It also includes miscellaneous steel inside the containment such as grating, ladders, connection plates; electrical cable trays, and electrical conduits.

The purpose of the primary containment is to accommodate, with a minimum of leakage, the pressures and temperatures resulting from the break of any enclosed process pipe; and thereby, to limit the release of radioactive fission products to values, which will insure offsite dose rates well below 10CFR100 guideline limits. It also provides a source of water for ECCS and for pressure suppression in the event of a loss-of-coolant accident. The primary containment and internal structures also provide structural support to the reactor pressure vessel, the reactor coolant systems, and other safety and nonsafety related systems, structures, and components housed within. The biological shield wall provides the added function of radiation shielding to maintain drywell environment within equipment qualification parameters.

Included in the evaluation boundary of the Primary Containment are the drywell, drywell head, suppression chamber, vent lines, downcomers, drywell and suppression chamber penetrations, vent line bellows, drywell penetration bellows, personnel air lock/equipment and other hatches, pressure retaining bolting, thermowells, and internal structures listed above.

Not included in the evaluation boundary of the Primary Containment are safety relief valves and EMRVs, EMRV discharge lines, Y-Quenchers, drywell and torus spray headers, vacuum breakers, ECCS suction strainers and header, downcomer bracing, suppression chamber (torus) supports, and other component supports. These components are separately evaluated with their respective license renewal systems. That is, safety relief valves, EMRVs, EMRV discharge lines, and Y-Quenchers are evaluated with Main Steam System. Drywell and torus spray headers, and ECCS suction strainers and header are evaluated with the Containment Spray System. Vacuum breakers are evaluated with the Containment Vacuum Breakers System. Downcomer bracing, suppression chamber supports, and other component supports are evaluated with the Component Supports Commodity Group.



For more detailed information, see UFSAR Sections 3.8 and 6.2

Reason for Scope Determination

The Primary Containment meets the scoping requirements of 10 CFR 54.4(a)(1) because it is a safety-related structure which is relied upon to remain functional during and following design basis events. It meets 10 CFR 54.4(a)(2) because failure of nonsafety related portions of the structure could prevent satisfactory accomplishment of function(s) identified for 10 CFR 54.4(a)(1). It also meets 10 CFR 54.4(a)(3) because it is relied upon in the safety analyses and plant evaluations to perform a function that demonstrates compliance with the Commission's regulations for fire protection (10 CFR 50.48), ATWS (10 CFR 50.62), and Environmental Qualification (10 CFR 50.49). The Primary Containment is not relied upon in the safety analyses and plant evaluations to perform a function that demonstrates compliance with Station Blackout (10 CFR 50.63).

System Intended Functions

1. Controls the release of fission products to the secondary containment in the event of design basis loss-of-coolant accidents (LOCA) so that off site consequences are within acceptable limits. (10 CFR 54.4(a)(1))
2. Provides sufficient air and water volumes to absorb the energy released to the containment in the event of design basis event so that pressure is within acceptable limits. (10 CFR 54.4(a)(1))
3. Provides a source of water for core spray, containment spray, and condensate transfer systems. (10 CFR 54.4(a)(1))
4. Provides physical support, shelter, and protection for safety related systems, structures, and components (SSCs). 10 CFR 54.4(a)(1)
5. Provides physical support, shelter, and protection for nonsafety related systems, structures, and components (SSCs) whose failure could prevent satisfactory accomplishment of function(s) identified for 10 CFR 54.4(a)(1). 10 CFR 54.4(a)(2)
6. Relied upon in safety analyses or plant evaluations to perform a function that demonstrates compliance with the commission's regulations for Anticipated Transients without Scram (10 CFR 50.62). 10 CFR 54.4(a)(3)
7. Relied upon in safety analyses or plant evaluations to perform a function that demonstrates compliance with the commission's regulations for Fire Protection (10 CFR 50.48). 10 CFR 54.4(a)(3)
8. Relied upon in safety analyses or plant evaluations to perform a function that demonstrates compliance with the commission's regulations for Environmental Qualification (10 CFR 50.49). 10 CFR 54.4(a)(3)

UFSAR References

3.8  
6.2

License Renewal Boundary Drawings

LR-JC-19702

**Table 2.4.1      Primary Containment  
Components Subject to Aging Management Review**

Component Type	Intended Functions
Access Hatch Covers	Pressure Boundary
Beam Seats	Structural Support
Biological Shield Wall - Concrete	Shielding
Biological Shield Wall - Lateral Support	Structural Support
Biological Shield Wall - Liner Plate	Structural Support
Biological Shield Wall - Structural Steel	Structural Support
Cable Tray	Structural Support
Class MC Pressure Retaining Bolting	Pressure Boundary
Concrete embedment	Structural Support
Conduits	Enclosure Protection
	Structural Support
Downcomers	Pressure Boundary
Drywell Head	Pressure Boundary
	Structural Support
Drywell Penetration Bellows	Pressure Boundary
Drywell Penetration Sleeves	Pressure Boundary
	Structural Support
Drywell Shell	Pressure Boundary
	Structural Support
Drywell Support Skirt	Structural Support
Liner (Sump)	Leakage Boundary
Locks, Hinges, and Closure Mechanisms	Pressure Boundary
	Structural Support
Miscellaneous Steel (catwalks, handrails, ladders, platforms, grating, and associated supports)	Structural Support
Panels and Enclosures	Enclosure Protection
	Structural Support
Penetration Closure Plates and Caps (spare penetrations)	Pressure Boundary
Personnel Airlock/Equipment Hatch	Pressure Boundary
Reactor Pedestal	Structural Support
Reinforced Concrete Floor Slab (fill slab)	Enclosure Protection
	Structural Support
Seals, Gaskets, and O-rings	Pressure Boundary
Shielding Blocks and Plates	Shielding
Structural Bolting	Structural Support
Structural Steel (radial beams, posts, bracing, plate, connections, etc.)	Structural Support
Suppression Chamber Penetrations	Pressure Boundary
	Structural Support
Suppression Chamber Ring Girders	Structural Support
Suppression Chamber Shell	Pressure Boundary

Suppression Chamber Shell	Structural Support
Suppression Chamber Shell Hoop Straps	Structural Support
Thermowells	Pressure Boundary
Vent Header Deflector	HELB Shielding
Vent Jet Deflectors	HELB Shielding
Vent line bellows	Pressure Boundary
Vent line, and Vent Header	Pressure Boundary

The aging management review results for these components are provided in

Table 3.5.2.1.1 Primary Containment

-Summary of Aging Management Evaluation

Table 3.0-2 – Oyster Creek External Service Environments

Oyster Creek Environment	Description	Equivalent NUREG-1801 Environment
Adverse localized Environment	Environment, which could exist in limited plant areas caused by heat, radiation, moisture or voltage in the presence of oxygen. Used for electrical insulation only.	Adverse Localized Environment
Aggressive Environment <sup>1</sup>	Ground water and raw water environments are considered aggressive if pH < 5.5, or chlorides > 500 ppm, or sulfates > 1500 ppm.	Aggressive Environment
Boiler Treated Water <sup>2</sup>	Deminerlized water subject to chemistry controls recommended by the boiler manufacturer. Water chemistry controls are implemented through plant procedures.	Treated Water
Closed Cooling Water	Treated water subject to water chemistry controls recommended in EPRI TR-107396, "Closed Cooling Water Chemistry Guidelines."  Closed Cooling Water includes Reactor Building Closed Cooling Water (RBCCW), and Turbine Building Closed Cooling Water (TBCCW).	Closed cycle cooling water
Closed Cooling Water < 140°F <sup>3</sup>	Closed cooling water below the temperature threshold for SCC in austenitic stainless steel components.	Closed cycle cooling water
Concrete	Embedded or Encased in concrete	Concrete

<sup>1</sup> This environment is not an exact match of aggressive environment defined in NUREG-1801, Table IX.D. However it is an exact match of the aggressive environment used in NUREG-1801 AMR tables, for example line Item III.A3-4 (T-05).

<sup>2</sup> This environment is not an exact match of the environment defined in NUREG-1801 because water chemistry is controlled to different guidelines. However for aging management review considerations it is considered equivalent.

<sup>3</sup> This environment is not an exact match of environments defined in NUREG-1801; however it is bounded by the listed equivalent NUREG-1801 environment

**Table 3.0-2 – Oyster Creek External Service Environments**

Oyster Creek Environment	Description	Equivalent NUREG-1801 Environment
Containment Atmosphere	This environment is inert with nitrogen to render the atmosphere non-flammable by maintaining the oxygen content below 4% by volume. The average normal temperature inside the drywell is 139°F, with a humidity range of 20-40%. The upper elevations (above elev. 95') of the drywell could be exposed to higher temperatures, up to 256°F. For bolting this environment includes potential leakage of treated water, steam, or raw water.	Air – Indoor Uncontrolled Air with Reactor Coolant Leakage Air with Steam or Water Leakage
Dry Gas	Nitrogen	Gas Air, Dry
Encased	Applies to components encapsulated in steel, or aluminum. Encased components are inaccessible, and not exposed to air, water, or other environments.	Environment not in NUREG-1801
Fuel Oil	Diesel oil used for the combustion engines and heating boilers.	Fuel Oil
Indoor Air	Air in a sheltered environment, other than containment atmosphere. Air temperature range is 65°F - 140°F and the humidity is 100% maximum. For bolting this environment includes potential leakage of treated water, steam, sodium pentaborate, or raw water.	Air – indoor Uncontrolled Air with Reactor Coolant Leakage Air with Steam or Water Leakage
Lubricating Oil	Low to medium viscosity hydrocarbons used for lubrication of rotating equipment.	Lubricating Oil
Outdoor Air	Outdoor air environment is subject to local weather conditions. The mean temperature range is 23.7°F - 84°F and the average annual precipitation is approximately 42 inches.	Air - Outdoor

**Table 3.0-2 – Oyster Creek External Service Environments**

Oyster Creek Environment	Description	Equivalent NUREG-1801 Environment
Raw Water – Fresh Water	<p>Fresh raw water is drawn from either a deep well or from the Fire Pond Dam. Water taken from the deep wells is processed in the pretreatment facility and used for domestic water or treated further and used as Demineralized water and for make up to the condensate storage and transfer system.</p> <p>Fresh water drawn from the Fire Pond Dam is untreated and is used for fire suppression and to the circulating water and service water pumps seals, and dilution pump oil coolers. Recent chemistry results show that the pH = 4.8, chlorides = 12 ppm, and sulfates = 6 ppm.</p>	Raw Water
Raw Water – Salt Water	<p>Raw salt water is drawn from Barnegat Bay, which receives salt water from the Atlantic Ocean and fresh water runoff from streams, which border it on the western shore, including Oyster Creek and Forked River. Recent tests of water samples taken at the Intake Structure and Canal showed that the pH = 7.9, Chlorides = 14659 ppm, and Sulfates 1419 ppm. The average monthly water temperature range is 37°F in the winter and 80°F in summer.</p>	
Soil	<p>External environment for structures and components buried in soil. Buried structures and components may be exposed to groundwater if they are located below the local ground water elevation. Site groundwater has been tested and determined non-aggressive to concrete.</p>	Soil
Steam	<p>Steam that is subject to BWR water chemistry controls</p>	Steam

**Table 3.0-2 – Oyster Creek External Service Environments**

Oyster Creek Environment	Description	Equivalent NUREG-1801 Environment
Treated Water	Treated water is demineralized water and is the base water for all clean systems. Depending on the system, this demineralized water may require additional processing. Treated water can be deaerated, include corrosion inhibitors, biocides, or some combination of these treatments. Treated water is subject to BWR water chemistry controls. Treated water includes reactor grade water, spent fuel pool water, torus water, and demineralized water.	Treated water
Treated Water < 140°F <sup>1</sup>	Treated Water below the temperature threshold for SCC in austenitic stainless steel components.	Treated water
Treated Water > 482°F	Treated water above thermal embrittlement threshold for CASS components.	Treated water > 482°F
Water – flowing	Water that is refreshed, thus having larger impact on leaching of calcium hydroxide from concrete structures.	Water - flowing
Water - standing	Water that is stagnant and un-refreshed, thus possibly resulting in increased ionic strength of solution up to saturation	Water - standing

<sup>1</sup> This environment is not an exact match of environments defined in NUREG-1801; however it is bounded by the listed equivalent NUREG-1801 environment

**AmerGen**<sup>SM</sup>

Michael P. Gallagher, PE  
 Vice President  
 License Renewal Projects

Telephone 610.765.5958  
 www.exeloncorp.com  
 michael.p.gallagher@exeloncorp.com

An Exelon Company

AmerGen  
 200 Exelon Way  
 KSA/2-E  
 Kennett Square, PA 19348  
 2130-06-20437

10 CFR 50  
 10 CFR 51  
 10 CFR 54

December 8, 2006

U. S. Nuclear Regulatory Commission  
 ATTN: Document Control Desk  
 Washington, DC 20555  
 Attention: Mr. Michael A. Junge  
 Mail Stop: T2E26

Oyster Creek Generating Station  
 Facility Operating License No. DPR-16  
NRC Docket No. 50-219

**Subject:** Submittal of Information to ACRS Plant License Renewal Subcommittee Related to AmerGen's Application for Renewed Operating License for Oyster Creek Generating Station (TAC No. MC7624)


**Reference:** AmerGen Letter to NRC, "Change to Timing for Submittal of Information to ACRS Plant License Renewal Subcommittee Related to AmerGen's Application for Renewed Operating License for Oyster Creek Generating Station (TAC No. MC7624)," dated November 1, 2006

In accordance with the Reference letter, AmerGen hereby submits information to the Advisory Committee on Reactor Safeguards (ACRS) Plant License Renewal Subcommittee related to AmerGen's application for renewal of the Oyster Creek Generating Station (OCGS) operating license. This information is intended to assist the Subcommittee in its preparation for a meeting being scheduled for January 2007 between the Subcommittee, the NRC Staff and AmerGen.

Contained within the Enclosure is a detailed discussion of the primary containment drywell corrosion issue history, which includes information learned during the October 2006 refueling outage. Numerous source documents are referenced in the discussion, and these are provided as part of the Enclosure.

If you have any questions regarding this information, please contact Fred Polaski at 610-765-5935.

Respectfully,



Michael P. Gallagher  
 Vice President, License Renewal  
 AmerGen Energy Company, LLC


A114



**Enclosure: Oyster Creek License Renewal Project, Drywell Monitoring Program – Information for ACRS Subcommittee**

**cc: NRC Director (Acting), License Renewal, w/o Enclosure  
Regional Administrator, USNRC-Region I, w/o Enclosure  
NRC Project Manager, NRR - License Renewal, Safety, w/Enclosure  
ACRS Staff Lead – Cayetano Santos, w/Enclosure (15 copies)  
NRC Project Manager, NRR - License Renewal, Environmental, w/o Enclosure  
NRC Project Manager, OCGS, Part 50, w/o Enclosure  
NRC Senior Resident Inspector, OCGS, w/o Enclosure  
New Jersey Bureau of Nuclear Engineering, w/o Enclosure  
Oyster Creek File No. 05040**

**Oyster Creek  
License Renewal Project  
Drywell Monitoring Program**



**Information for ACRS Subcommittee**

**December 8, 2006**

---

**Enclosure - Table of Contents**

**Section 1 - Introduction to the Information Package (2 pages)**

**Section 2 - Oyster Creek Drywell Corrosion Timeline (2 pages)**

**Section 3 - Oyster Creek Drywell General Description (9 pages)**

**Section 4 - Water Leakage onto the Exterior Surface of the Drywell Shell (7 pages)**

**Section 5 - The Upper Regions of the Drywell (21 pages)**

**Section 6 - Corrosion of the Outer Drywell Shell in the Sandbed Region (48 pages)**

**Section 7 - Embedded External Drywell Shell (7 pages)**

**Section 8 - Interior Embedded Drywell Shell (4 pages)**

**Section 9 - Reference Index (3 pages)**

**References**

This package of historical information and 2006 outage information is being provided to the ACRS Subcommittee reviewing the License Renewal Application for Oyster Creek. The purpose of the information is to respond to questions that were raised at the ACRS Subcommittee meeting on October 3, 2006 concerning the corrosion of the drywell shell and to update the Subcommittee on the results of recent inspection activities. This package is meant to help the ACRS members understand the information that the NRC staff has already reviewed over the course of weeks of audits and inspections. As such, the information set forth in this package consists of documents and responses to questions that were available to the NRC staff during the NRR AMR and AMP audits in January and February 2006, during the NRC Region 1 inspection in March 2006, in response to NRC RAIs during the review of the Oyster Creek License Renewal Application, in docketed correspondence between GPUN or AmerGen and the NRC, and in documents reviewed by NRC Region 1 during the 2006 refueling outage. The information provided also includes some historical information that serves as the basis or support for documents that were reviewed by the NRC.

Although the information included in this package has been available to the NRC, AmerGen has in many cases formatted the information differently in order to address some of the questions asked by ACRS members. For example, the NRC staff may have reviewed numerical data on drywell shell corrosion provided in a table. In this document, however, AmerGen prepared a graphical representation of the data to show how the drywell shell corrosion rate has changed with time up to and including data obtained during the 2006 refueling outage and including the margin that is available.

The information being provided by AmerGen is organized into the following five primary areas of interest dealing with the corrosion on the surfaces of the Oyster Creek drywell shell:

- Leakage of water onto the drywell shell external surface during refueling outages. (Section 4)
  - Includes a summary of significant events related to water leakage, information on the historic identification and evaluation of reactor cavity liner defects, historic troubleshooting and repairs to the reactor cavity trough area, and actions in place to minimize, detect and assess the impact of any leakage going forward.
- The Upper Regions of the drywell. (Section 5)
  - Includes information on periodic UT measurements taken from the inside of the drywell, the process to determine the locations monitored, and the random sampling confirmation of the monitored locations.
- The Sandbed Region. (Section 6)
  - This includes information on historical and recent UT thickness readings, the early 1990s General Electric buckling analysis, and early 1990s preparing and coating of the external surface of the drywell shell.

- The embedded part of the drywell shell exterior. (Section 7)
  - Includes information on environmental conditions for the embedded part of the shell located below the sandbed region.
- The embedded part of the drywell shell interior. (Section 8)
  - Includes information on construction, required shell thicknesses and environmental conditions for the embedded part of the shell that is inside the drywell

Information in each topic area is presented somewhat differently. Topics 1, 4 and 5 are generally narrative in nature presenting historical and technical information, with references to supporting documents. Topics 2 and 3 provide both a narrative presentation of the topic, and include UT measurement data that support AmerGen's understanding of and position on corrosion of the outer surface of the drywell shell.

The information on each of the five topics references many source documents, all of which are included in this package. Some of the references include the detailed inspection results.

In addition to these 5 topics, the package also includes a timeline that shows the sequence of relevant events, starting with the first discovery of water in the sand bed drains in 1980 up to and including the inspections performed during the refueling outage in October 2006. Also, the package includes a section on the general description of the Oyster Creek drywell, with associated drawings and figures.

1969	Begin Oyster Creek plant operation.
1980	Water identified coming from sand bed drains.
1980, 83, 86, and 89	Investigation into source of water leaking from sandbed drains, and the leakage path.
1986	<ul style="list-style-type: none"> <li>• 2 trenches excavated in the floor inside the containment to gain access to the inside of the drywell shell at an elevation corresponding to a lower portion of the sandbed region (Bays 5 &amp; 17).</li> </ul>
1986 to 89	<ul style="list-style-type: none"> <li>• Corrosion monitoring of the drywell shell from the inside to establish and characterize the extent of corrosion.</li> <li>• 19 grid locations inside the drywell at Elev. 11' 3" established for monitoring corrosion in the sandbed region with UT measurements.</li> <li>• Approximately 1,000 UT points taken circumferentially around the inside of the drywell shell.</li> <li>• 12 representative grid locations selected from the 1,000 points for continued monitoring of the upper drywell area.</li> <li>• Core samples taken at 9 locations of the drywell shell.</li> </ul>
1988	<ul style="list-style-type: none"> <li>• Cathodic protection system installed on drywell shell.</li> <li>• Sand removal from the sandbed region started.</li> <li>• Repairs made to reactor cavity concrete trough to improve drainage.</li> <li>• Visual and UT inspections in trenches.</li> </ul>
1990	UT thickness measurements of the drywell shell taken at 57 randomly selected locations to confirm the 12 grid locations identified previously for monitoring were representative of the leading corrosion locations. One additional location added to the original 12.
1992	<ul style="list-style-type: none"> <li>• Cathodic protection system removed because it was not effective in preventing corrosion.</li> <li>• Sand removal from the sandbed regions completed.</li> <li>• External surface of the drywell shell in the sand bed region cleaned.</li> <li>• 125 UT readings taken to confirm minimum thickness locations from the external surface.</li> <li>• Epoxy coating applied to the external surface of the drywell shell in the sandbed region.</li> <li>• Surface of the concrete floor in the sandbed regions finished with epoxy and sealed against the drywell shell.</li> <li>• UT of the sandbed region from inside the drywell at 19 grid locations at Elevation 11' 3".</li> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations.</li> </ul>
1994	<ul style="list-style-type: none"> <li>• UT of the sand bed region from inside the drywell at 19 grid locations at Elevation 11' 3".</li> <li>• Visual inspection of epoxy coating on outside of drywell in the sand bed region (Bays 3 &amp; 11).</li> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations.</li> </ul>
1996	<ul style="list-style-type: none"> <li>• UT of the sand bed region from inside the drywell at 19 grid locations at Elevation 11' 3", but some data appeared anomalous.</li> <li>• Visual inspection of epoxy coating on outside of drywell in the sand bed region (Bays 11 &amp; 17).</li> </ul>

	<ul style="list-style-type: none"> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations.</li> </ul>
2000	<ul style="list-style-type: none"> <li>• Visual inspection of epoxy coating on outside of drywell in the sand bed region (Bays 1 &amp; 13).</li> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations.</li> </ul>
2004	<ul style="list-style-type: none"> <li>• Visual inspection of epoxy coating on outside of drywell in the sand bed region (Bays 1 &amp; 13).</li> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations.</li> </ul>
2005	Oyster Creek License Renewal Application submitted to the NRC on July 22, 2005.
2006	<ul style="list-style-type: none"> <li>• Visual inspection of epoxy coating on outside of drywell in the sand bed region in all 10 bays.</li> <li>• Visual inspection of the caulk seal at the junction between the sand bed region floor and the drywell shell in all 10 bays.</li> <li>• UT readings at 19 grid locations in the sand bed region from inside the drywell at Elevation 11'-3".</li> <li>• UT readings at 106 locally thinned areas (previously inspected in 1992) from outside the drywell in the sand bed region.</li> <li>• Visual inspections and UT readings of the drywell shell in the two trenches inside the drywell including additional excavation in the Bay 5 trench.</li> <li>• UT readings at two grid locations each at two transition plate locations from inside the drywell (Elevations 23'-6" and 71'-6").</li> <li>• UT readings from the inside of the drywell shell at the 13 grid locations in the upper elevations to confirm low corrosion rates or no observable corrosion.</li> <li>• Boroscopic examination of reactor cavity trough drain line and all 5 sand bed drain lines.</li> <li>• Monitored the Sandbed Regions drains for leakage.</li> <li>• Monitored the Reactor cavity trough drain for leakage.</li> <li>• Repaired/modified areas internal to the drywell to minimize the potential for water intrusion into the area between the embedded drywell shell and the drywell concrete floor.</li> </ul>

The Oyster Creek primary containment is a General Electric Mark I design, with a drywell, suppression chamber, and a vent system connecting the drywell and the suppression chamber. It is designed, fabricated, inspected, and tested in accordance with the requirements of the ASME Boiler and Pressure Vessel Code, Section VIII, and Nuclear Code Cases 1270N-5, 1271N, and 1272N-5.

The drywell is a steel pressure vessel, in the shape of an inverted light bulb, with a spherical section and a cylindrical section (See Figures 1 thru 4) located inside the Reactor Building. The Reactor Building Foundation floor is a 10 ft thick reinforced concrete mat. The bottom elevation of the mat is minus 29' 6" and its top elevation is minus 19' 6" (See Figure 4). There is a waterproof membrane at the bottom of the mat that extends up the outside of the exterior walls to an Elevation of 5' 0". The concrete pedestal that supports the drywell is located at the center of the mat. The Torus Room completely surrounds this concrete pedestal with a floor elevation of minus 19' 6" (top of mat). The drywell shell has a bottom elevation of 2' 3".

The spherical section of the drywell was supported on a 39-foot diameter continuous steel skirt during construction (See Figures 4 & 7). The area within the skirt was filled with concrete and the floor inside the bottom of the sphere (drywell floor) was poured up to elevation 10' 3". The reactor support structure (pedestal) sits on top of the drywell floor (See Figure 5). The area within the reactor pedestal provides access for Control Rod Drive exchanges and is typically referred to as the Sub-Pile Room. The room also contains the drywell sump and a drainage trough that collects any leakage within the drywell. The Sub-Pile Room floor is raised at the center and slopes toward the drainage trough. Leakage outside the Sub-Pile Room, in the drywell, is directed to the drainage trough through 4 holes in the reactor pedestal equally spaced around the circumference. A concrete curb is installed around the perimeter of the drywell floor (See Figure 4 & 5) to prevent any water that collects on the floor from coming in contact with the drywell shell. The curb is removed in two locations where two trenches (Figure 3) were excavated in the floor in 1986 to allow UT thickness measurements to be taken below the floor. A moisture barrier was added at the junction of the curb and the drywell shell and inside the trenches during the 2006 refueling outage to prevent water and moisture intrusion into the embedded drywell shell.

Outside the drywell support skirt and the spherical section, concrete was poured in contact with the sphere up to elevation 8' 11". At this point, the concrete was stepped back 15" radially up to elevation 12' 3" and later filled with sand (sandbed region), refer to Figures 5 & 7 for details. The purpose of the sandbed was to provide a cushion to smooth the transition of the shell plate from a condition of fully embedded between two concrete masses to a free-standing condition. The sandbed region was provided with five drains designed to allow drainage of any water that may enter the region.

Above the sandbed region, the drywell shell is closer to the reactor building concrete shield wall. The outer surface of the drywell shell and the shield wall are separated by a gap filled with compressible material. After construction completion, this material was



compressed by heating and pressurizing the drywell to provide the gap required for free expansion of the drywell under design basis loads and postulated events.

At the top of the Reactor Building concrete shield wall, a concrete trough is located below the reactor cavity seal to collect any water that might leak from the reactor cavity during refueling outages. This trough is equipped with a drain line designed to direct any leakage to the Reactor Building equipment drain tank and prevent it from entering the gap between the drywell shell and the Reactor Building concrete shield wall (See Figure 6).





FIGURE 1 - PRIMARY CONTAINMENT CROSS-SECTION



PL THK = DESIGN NOMINAL THICKNESS

FIGURE 2 - DRYWELL ELEVATION





FIGURE 3 - DRYWELL BAYS



### LOWER DRYWELL- SANDBED, TRENCH & SUMP



ELEVATION LOOKING WEST  
FIGURE 5




FIGURE 6 - REACTOR CAVITY TROUGH DRAIN




FIGURE 7



The following discussion addresses water leakage onto the exterior surface of the Oyster Creek drywell shell. Part I, below, provides a historic overview of information about water leakage prior to the October 2006 outage. The discussion in Part II summarizes prior commitments made by AmerGen aimed at preventing leakage onto the shell, monitoring for such leakage and performing corrective actions if leakage occurs. Part III sets forth information discovered and analyzed as a result of the October 2006 outage. Overall conclusions about the drywell, AmerGen's performance of associated commitments, and continued drywell operability during the proposed twenty-year renewal term are summarized in Part IV.

### **I. Historical Background**

Water leakage onto the exterior of the Oyster Creek drywell shell over a period of years, in combination with an historically degraded sand bed region drainage system, created a condition that was conducive to corrosion of the exterior surface of the drywell shell. The previous owner/operator of Oyster Creek conducted extensive troubleshooting and repairs to determine and address the leakage and the corrosive effects of that leakage onto the drywell shell. As part of its license renewal activities, AmerGen has reviewed previous actions and instituted new measures (see Section II below) to ensure that leakage will be minimized and monitored, and that corrective actions will be implemented to ensure the drywell continues to perform its intended functions throughout the proposed twenty-year period of extended plant operation.

In addition, drywell commitments for license renewal are embedded in a formal AmerGen tracking system that includes specific work tasks, thereby ensuring timely implementation of the commitments and effective management oversight. Therefore, AmerGen is confident that the measures put into place to prevent and monitor leakage, in conjunction with the implementation of drywell shell visual and ultrasonic testing aging management program activities, will protect the shell such that it continues to perform its intended functions throughout the proposed period of extended operation.

#### **A. Chronology of Significant Events (Also see Timeline, Section 2)**

- 1980 – Water was observed coming from the sand bed drains. As part of the original design, these drains had been filled with sand during plant construction. The sand was restrained at the outlet with a 100-mesh stainless steel screen (0.006 inch opening). The intent was to prevent loss of sand from the sand bed region through the drain lines, yet allow drainage of water.
- 1980, 1983 and 1986 refueling outages - Extensive investigations were performed to identify the source of water and the leakage path. Results of the investigations indicated that:
  - Leakage was observed (from the sand bed drains) during refueling outages;

- Leakage was not attributed to the reactor cavity metal trough drain line gasket or the refueling bellows seal (See Figure 6 of Section 3 of this Enclosure).

The reactor cavity metal trough drain line gasket leak was ruled out as the primary source of water observed in the sand bed drains because there was no clear leakage path to the gap between the drywell shell and reactor building concrete shield wall (i.e., drywell expansion gap). Any gasket leakage would be minor and would be collected in the concrete trough below the gasket. Also, inspections concluded that the refueling bellows (seals) were not the source of water leakage. The bellows were repeatedly tested using helium (external) and air (internal) without any indication of leakage. Furthermore, any minor leakage from the refueling bellows would be collected in the same concrete trough as would collect water from the gasket. The concrete trough is equipped with a drain line that would direct any leakage to the reactor building equipment drain tank and prevent it from entering the drywell expansion gap (Ref [13], Attachment III).

- Leakage was attributed to through-wall cracks in the reactor cavity liner attributed to mechanical damage and to fatigue (Ref [13], Attachment III); and
- The leakage path was from the reactor cavity, to the concrete trough (later found to have been degraded – see Section C below) and through the drywell expansion gap down to the sandbed region within the reactor building (See Figure 6 of Section 3 of this Enclosure).
- Between 1988 and 1993, multiple mitigating actions were taken to address the corrosion problem. These actions included (Ref [32], page 9):
  - Cleared the former sand bed region drains of sand and corrosion products to improve drainage.
  - Replaced reactor cavity metal trough drain gasket, which was found to be leaking (See Figure 6 of Section 3 of this Enclosure).
  - Removed water from the sand bed region.
  - Installed a cathodic protection system in bays with greatest wall thinning. Subsequent UT thickness measurements in these bays showed that the system was not effective in reducing the rate of corrosion and the system was removed from service in 1992.
  - Removed sand from the sand bed region to break up the galvanic cell (Ref [46]).
  - Removed corrosion products from the external side of the drywell shell in the sand bed region.

- Upon sand removal, the sand bed concrete floor was found to be cratered and unfinished. The concrete floor was repaired, finished and coated to permit proper drainage of the sand bed region (Refer to Section 7 of this Enclosure for details).
- Applied an epoxy caulk seal at the junction of the drywell shell and the sand bed concrete floor to prevent intrusion of moisture into the drywell shell embedded in concrete (Refer to Section 6 of this Enclosure for details).
- Applied a multi-layered epoxy protective coating to the exterior surfaces of the drywell shell in the sand bed region (i.e., one pre-primer coat, and two top coats). (Refer to Section 6 of this Enclosure for details).
- Applied stainless steel type tape and strippable coating to the reactor cavity during refueling outages to seal cracks in the stainless steel liner, in order to limit leakage from the reactor cavity. (Note that the steel tape was applied to larger cavity liner cracks and then the strippable coating was applied over the entire liner surface that would be (otherwise) wetted.)
- Confirmed that the reactor cavity concrete trough drain line was not clogged (See Figure 6 of Section 3 of this Enclosure)

#### B. Discovery and Evaluation of Cavity Liner Defects

In 1987, defects in the reactor cavity liner were documented and evaluated in material nonconformance report MNCR 87-240 (Ref [49]). These defects consisted of through-wall and surface indications detected by non-destructive examination of the liner near weld joints. The purpose of the cavity liner is to facilitate filling the reactor cavity with water for refueling activities.

The defects do not pose problems except when the reactor cavity is filled with water during refueling outages. If no preventive action is taken, the defects allow water to leak behind the liner and run down into the reactor cavity concrete trough. If the flow rate exceeds the capacity of the two-inch trough drain, then water would back up into the drywell expansion gap and drain onto the outside of the drywell shell.

Safety Evaluation 328257-002 was generated in 1988 with the purpose of addressing the adequacy of the design and the safety impact of installation of a temporary barrier on the OC Reactor Cavity Pool to prevent leakage of water during refueling operation (Ref 6, pages 7 - 13). In it, two major options were considered - weld repair of the liner and a temporary barrier over the entire cavity liner. The weld repair option had the following drawbacks: (a) there were too many defects in the liner; (b) weld repair of these defects would produce large residual stresses and warping of the liner, and (c) if weld repairs were implemented, the repair areas would eventually fail due to the same mechanism, in the future. Therefore, the temporary barrier option of metal tape and strippable coating was chosen for the repair (Ref [6], page 6).

**C. Reactor Cavity Concrete Trough Area Testing and Repairs**

As a result of observations of water leaking from concrete biological shield penetrations and sand bed drain lines during refueling outages in the early 1980s, numerous troubleshooting and repair activities were implemented over several years. These included:

- Air and helium leak testing of the bellows seal in the bottom of the reactor cavity (no leakage detected) and cavity drain line (no significant leakage found),
- Leak testing and some minor repairs to reactor cavity liner welds,
- Further pressure testing of the bellows (no leakage detected) at a later outage,
- Liquid penetrant testing of the cavity "steps" upon which the cavity shield plugs are placed (no indications detected), and
- Air purge testing of the drain line that channels refueling cavity leakage away from the gap between the drywell shell and concrete drywell shield wall (drain line did not appear to be restricted).

During the 1986 refueling outage, the drain line from the refueling cavity metal trough was inspected and the drain line gasket was found to have leaks, and was replaced. Additional leak tests were performed on the bellows during the 1986 outage and no leaks were detected (Ref [1], Attachment 2, pages 2-1 and 2-2).

During the 1986 refueling outage, camera inspections identified that the lip of the reactor cavity concrete trough was not sufficient to assure that water would not enter the area between the concrete shield wall and drywell shell. (Ref [5], page 3). Prior to reactor cavity flooding for the 1988 refueling outage, repairs were made to the concrete trough to rectify the condition. These repairs were determined to be effective based on visual inspections for leakage during the 1988 outage.

As noted previously, the mitigating features described above were implemented between 1988 and 1993. For the strippable coating, a latex coating was used at first. This latex coating had (a) stringent surface preparation requirements; (b) long curing time; and (c) lack of strength to absorb mechanical abuse during refueling. Accordingly, it was not applied during the 1994 and 1996 refueling outages. Discontinuation was also prompted by the fact that sand had been removed from the sand bed region and drainage in the area was improved during the 1994 outage. However, the observed water leakage during the 1996 outage prompted investigation and use of a more durable barrier. InstaCote ML-2 coating barrier was effectively used on the reactor cavity during the 1998 outage. (Ref [28], page 6). Strippable coating has also been applied to the reactor cavity in all refueling outages since 1998.

## II. Summary of IWE Program Elements Related to Water Leakage

The following is a summary of Oyster Creek's commitments related to preventing and monitoring for water leakage onto the exterior surface of the drywell shell. These are captured within the ASME Section XI, Subsection IWE Aging Management Program. These committed actions were performed during the 2006 refueling outage and will be performed during refueling outages in the future, including during the period of extended operation. For further details on these commitments, see Ref [39], Enclosure 2.

- Strippable coating, as discussed above in Section C, is applied to the reactor cavity liner surface prior to filling the reactor cavity with water for refueling activities.
- Periodic verification (once per refueling cycle) that the reactor cavity trough drain is functional (clear).
- Periodic monitoring (when reactor cavity is flooded) of reactor cavity trough drain for leakage.
- Daily visual monitoring of drywell sand bed drains for leakage during refueling outages when the reactor cavity is flooded. If leakage is detected, AmerGen will determine the source of leakage and investigate and address the impact of leakage on the drywell shell, including verification of the condition of the drywell shell coating and moisture barrier (seal) in the sand bed region and performance of UT examinations of the shell in the upper regions. UTs will also be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred. UT results will be evaluated per the existing program. Any degraded coating or moisture barrier will be repaired. These actions will be completed prior to exiting the associated outage.
- Quarterly visual monitoring of the sand bed drains for leakage during plant power operation. If leakage is identified, then the source of water will be investigated, corrective actions taken or planned as appropriate. In addition, if leakage is detected, the following items will be performed during the next refueling outage:
  - Inspection of the drywell shell coating and moisture barrier (seal) in the affected bays in the sand bed region
  - UTs of the upper drywell region consistent with the existing program
  - UTs will be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred
  - UT results will be evaluated per the existing program

Any degraded coating or moisture barrier will be repaired.

- When the sand bed region drywell shell coating inspection is performed, the seal at the junction between the sand bed region concrete and the embedded drywell shell will be inspected per the Protective Coatings Program.

Through these commitments, AmerGen will minimize any water leakage through the reactor cavity liner that may occur during refueling outages, and prevent or minimize water from reaching the external surface of the drywell shell. These commitments were made with the expectation that corrosion of the external surface of the drywell shell will be minimized, thus maximizing the margin remaining above the design-required thicknesses of the drywell shell.

### III. Findings and Analysis from the 2006 Outage

During the 1R21 (October 2006) refueling outage, AmerGen implemented its commitments related to preventing water from reaching the outer surface of the drywell shell and monitoring for evidence of water leakage. The results of these activities were successful. Based on daily observations of sandbed drain water collection bottles and upon numerous visual reports from the sand bed region, no water leakage onto the exterior surface of the drywell shell during 1R21 was evident and no corrective actions related to water leakage onto the shell were required (Ref [47]).

The reactor cavity was coated with a strippable coating prior to flooding the cavity for refueling activities. A small amount of leakage (approximately 1 gallon per minute (GPM)) was observed coming from the cavity trough drain line during the time period when the refueling cavity was flooded. Daily observations of the cavity trough drainage confirmed a steady stream of approximately 1 GPM during this period. Because this small amount of leakage did not exceed the drainage capacity of the trough, no water would have leaked onto the exterior surface of the drywell shell. The minor leakage was discharged to the plant's radwaste system as designed.

Specifically, AmerGen performed the following actions during the October 2006 refueling outage to prevent or minimize water leakage onto the exterior of the drywell shell. These activities are consistent with commitments made in AmerGen Letter 2130-06-20358 (Ref [39]).

- Applied a strippable coating to the reactor cavity liner prior to flooding the cavity for refueling activities.
- Verified that the reactor cavity trough drain was clear prior to flooding the reactor cavity for refueling activities.
- Monitored the trough drain for leakage daily while the cavity was flooded with water. Documented results identified only a steady "pencil stream" of water coming from the trough drain, indicating, as expected, that the leakage was being handled by the cavity trough drain system, keeping water away from the drywell shell.

- Inspected the five sand bed drain lines to verify they were clear; removed some debris from two of the drain lines.
- Inspected the five poly collection bottles associated with the sand bed drains on a daily basis. Documented results identified no leakage observed coming from the sand bed drains.
- Verified no water on the concrete floor in any of the ten bays of the sand bed region through visual inspection.
- Inspected the seal at the junction between the sand bed region floor and drywell shell in all 10 bays. The inspection revealed the seal at this junction to be in good condition with no repairs required.

#### IV. Conclusion

Oyster Creek historically experienced water leakage onto the external surface of the drywell shell as described in Section I above. Various investigative and corrective activities have been performed to understand the issue and prevent water from continuing to drain onto the shell during refueling activities.

As part of the License Renewal process, AmerGen has established specific commitments within the formal Exelon Passport commitment tracking system to ensure license renewal commitments, including those addressing water leakage onto the drywell shell external surface (described in Section II above), are implemented. In addition, the recurring tasks, preventive maintenance activities, and surveillance procedures that are used to implement these commitments are annotated such that it is clear from looking at them that the subject actions are associated with commitments made to the NRC. In this way, there are formal controls to ensure awareness and oversight of the activities and to ensure that commitments are implemented.

The inspections performed during the 2006 refueling outage (1R21) confirm that the license renewal-related committed actions for leakage prevention and monitoring prevented water from reaching the external surface of the drywell shell. AmerGen has committed to perform these preventive/monitoring actions in future refueling outages, with the objective of preventing water leakage onto the drywell shell exterior. In addition, commitments are in place to investigate and address any leakage onto the shell exterior, should it occur.

This set of actions, aimed at preventing water from reaching the external surface of the drywell shell, serve as an additional level of assurance beyond that provided by performing and trending drywell shell thickness measurements and conducting visual inspections of the epoxy coating in the sand bed region (also part of the IWE Aging Management Program), that corrosion is not impacting the ability of the drywell to perform its design functions.

The following discussion addresses upper drywell corrosion at the Oyster Creek Generating Station. Part I, below, provides an overview of information pre-dating the October 2006 outage. The discussion in Part II sets forth information discovered and analyzed as a result of the October 2006 outage. Overall conclusions about the upper drywell, and its continued operation during the proposed twenty-year renewal term, are summarized in Part III.

## I. Historic Summary and Past Findings

Outer drywell shell corrosion was first identified at Oyster Creek in the late 1980's. As explained in the Section 4 of this Enclosure, water intrusion into the gap between the drywell shell and the drywell shield wall was determined to be the source of the water, which created the corrosive environment. Corrective actions have been taken to mitigate corrosion in the upper region of the outer drywell shell. These actions have effectively reduced the rate of corrosion to a negligible amount in the upper region as demonstrated by UT thickness measurements (Ref [32], Table 1). In 1991, Oyster Creek and its consultants performed stress and buckling analyses considering all design basis loads and load combinations (Ref [15], Ref [16]). The results of these analyses indicate that the minimum measured drywell shell thickness satisfies ASME Section III Requirements.

### A. Original Inspection Plan (1986 - 1992)

Inspections using UT thickness measurements were conducted during refueling outages and outages of opportunity between 1986 and 1989 to establish and characterize the extent of corrosion of the outer drywell shell. The initial UT measurements were not based on a sampling process. Instead the measurements were taken in areas that correspond to locations where water leakage was observed from the sand bed region drains. The UT measurements were then expanded around the drywell perimeter and vertically into the upper drywell to establish locations affected by corrosion. Approximately 1000 ultrasonic (UT) thickness measurements were taken at various elevations to access extent/scope of corrosion around the drywell perimeter and vertically to establish locations affected by corrosion and to identify the thinnest areas (Ref [4b], Ref [4c], Ref [4d]). Based on the results of the above-mentioned 1000 UT measurements, Oyster Creek continued to monitor 12 grid locations at elevations 50' 2" and 87' 5", that would be representative of the upper drywell shell condition. In addition, core samples of the drywell shell were taken at upper drywell region locations, believed to be representative of general corrosion, to confirm UT results (Ref [7]).

In addition to the above mentioned core samples of the drywell shell, the impact of Firebar-D on the drywell shell corrosion was discussed in a General Electric report (Ref [3]). Section 2.1.3.2 of the GE report discusses the material and Section 6.2.1 discusses the impact. The report concluded that the lack of  $\gamma\text{-Fe}_2\text{O}_3$  in the oxide on the core plug surface/crust, the relative low amount of Mg in the sand samples and the absence of corrosion at the 51' elevation level suggest that the role of Firebar-D in the degradation of the OC drywell corrosion phenomena is not significant.



In 1990, a third elevation, 51' 10", was added to the scope of inspection after it was determined that the supplied plate thickness is slightly less than the adjacent 50' 2" plate. For each of the three elevations, sets of 49 UT measurements, spaced approximately 1" apart within a 6"x6" area, were taken from inside the drywell around the entire perimeter of each elevation. The 6"x6" area with one inch spacing results in a 7x7 grid of points located on one inch centers. These are identified as 49 point UT grid locations.

Engineering evaluation of the UT results concluded that monitoring of 12 upper drywell grid locations within these three elevations would represent the outer drywell shell condition and provide reasonable assurance that significant corrosion would be detected prior to a loss of an intended function. This is because the 12 grid locations were selected considering the degree of drywell shell thinning and the minimum required thickness to satisfy ASME stress requirements. Seven of the locations are at elevation 50' 2", three locations are at elevation 87' 5", and two locations are at elevation 51' 10" (Ref [31]). These locations are inspected from the inside of the drywell shell on a frequency of every other refueling outage.

#### **B. Sampling Plan Justification and Confirmation - Augmented Inspection Plan (1990 - 1995)**

In response to an NRC Staff concern regarding whether the inspected locations represent the condition of the entire drywell, in 1990 a new random UT inspection plan (also known as the augmented inspection) was prepared (Ref [11]). The plan was based on a non-parametric statistical approach using attribute sampling that assumes no prior knowledge of the distribution of corrosion above the sand bed region (Ref [12]). The plan consisted of random UT testing of 60 drywell shell plates. 57 plates were included in the inspection plan because three plates were inaccessible for inspection. On each plate, 49 point UT measurements were made on one 6"x6" area. Acceptance criteria were that the mean and local thickness of the shell equal or exceed the required minimum thickness plus a corrosion allowance necessary in order to reach the next inspection.

Inspection results using the new random inspection plan confirmed that previously monitored locations bound the condition of the drywell above the sand bed region, except one location at elevation 60' 10". This elevation was added to elevations 50' 2", 51' 10", and 87' 5" and all four elevations have been monitored on the frequency of every other refueling outage since 1992 (Ref [31], Ref [32]).

The augmented inspection plan, the original inspection plan, and justification for sampling techniques and statistical methodology were submitted to the NRC on November 26, 1990 (Ref [14]). In its Safety Evaluation dated November 1, 1995, the Staff noted that the licensee provided a table of UT measurement results from the Fall 1994, 15<sup>th</sup> refueling outage inspection. This table shows the locations of the measurements, the nominal as-constructed thickness, the minimum as-measured thickness, the ASME Code required thickness and the corrosion margin available at the time. The Staff found the current program based on the submitted information acceptable.

The current ongoing inspection plan is described in Oyster Creek specification IS-328227-004 (Ref [41]). The current inspection results are provided in Tables 1 and 2.

## II. Confirmatory Actions During the October 2006 Outage

During the 2006 refueling outage (1R21), UT thickness measurements were taken at the 4 elevations (50' 2", 51' 10", 60' 10", and 87' 5") discussed above in accordance with the Oyster Creek ASME Section XI, Subsection IWE aging management program. The results of the UT thickness measurements indicated that no statistically observable corrosion is occurring at elevations 51' 10", 60' 10" and 87' 5". A single grid location (Bay 15 -23) of the elevation 50' 2" continues to experience minor corrosion at a rate of 0.66 mils/yr. The corrosion rate for the elevation 87' 5" is now statistically insignificant and this elevation can be considered as no longer undergoing statistically observable corrosion (Ref [47]), however it will continue to be monitored.

In addition, UT measurements were taken on 2 locations (bay #15 and bay #17) at elevation 23' 6" where the circumferential weld joins the bottom spherical plates and the middle spherical plates. This weld joins plates that are 1.154" thick to the plates that are 0.770" thick. These two bays were selected because they are among those that have historically experienced the most corrosion in the sandbed region. At each location, 49 UTs over a 6"x6" area grid were taken above the weld on the 0.770" thick plate and 49 UTs over a 6"x6" area grid were taken below the weld on the 1.154" thick plate. The minimum average thickness measured on the 0.770" thick plate is 0.766" and 1.160" on the 1.154" thick plate. The minimum measured local thickness on the 0.770" thick plate is 0.628" and on the 1.154" thick plate is 0.867". The minimum measured general and local thickness on each plate meets the minimum thickness required to satisfy ASME stress requirements with an adequate margin (Ref [47]).

UT measurements were also taken on 2 locations (bay #15 and bay #19) at elevation 71' 6" where the circumferential weld joins the transition plates (referred to as the knuckle plates) between the cylinder and the sphere. This weld joins the knuckle plates (2.625" thick) to the cylinder plates (0.640" thick). These two bays were selected because they also have historically experienced the most corrosion in the sandbed region. At each location, 49 UTs over a 6"x6" area grid were taken above the weld on the 0.640" thick plate and 49 UTs over a 6"x6" area grid were taken below the weld on the 2.625" thick plate. The minimum measured average thickness on the 0.640" thick plate is 0.624" and 2.530" on the 2.625" thick plate. The minimum measured local thickness on the 0.640" thick plate is 0.449" and 2.428" on the 2.625" thick plate. The minimum measured general and local thickness on each plate meets the minimum thickness required to satisfy ASME stress requirements with an adequate margin (Ref [47]).

The above information identified during the recent outage has confirmed the condition of the upper drywell as described in previous submittals. AmerGen thus concluded that outer drywell shell corrosion at Oyster Creek is being effectively managed both during the current and proposed renewed terms of plant operation. The monitored locations under the current term were subject to extensive UT measurements conducted over several years. NRC Staff found the sampling methodology to identify these locations, and the results of inspections, acceptable for the current term.

### III. Conclusion

In conclusion, Oyster Creek has conducted extensive examinations of the OCNGS upper drywell to identify the cause of drywell corrosion, employed a sampling process, quantified the extent of outer drywell shell thinning due to corrosion, and assessed its impact on the drywell structural integrity. Inspection results for the upper region are provided in Table 2. A summary of the upper region outer drywell shell corrosion rates and margins and the associated reference source documents are provided on Table 1. A summary of corrosion rates of UT measurements taken in the upper drywell every 4 years through year 2006 is provided below:

- There is no statistically observable ongoing general corrosion at three elevations (51' 10", 60' 10", and 87' 5")
- Based on statistical analysis, one location at elevation 50' 2" is undergoing a minor general corrosion rate of 0.66 mils per year
- The drywell corrosion inspection program will ensure sufficient margin will be maintained through 2029

Therefore, AmerGen has concluded that upper drywell corrosion at Oyster Creek is effectively managed, both during the current and proposed renewed term of plant operation. The upper drywell region is not experiencing statistically observable corrosion, except a single location that continues to experience minor corrosion at a rate of 0.66 mils/yr. When this monitored corrosion rate is projected through the year 2029, sufficient margin exists to acceptance criteria.

Table 1

Drywell Shell Thickness and Minimum Available Thickness Margins are provided below:

Drywell Region (Elevation monitored)	Nominal Design Thickness, mils (Ref [40])	Minimum Measured Thickness, mils (Ref [21], Ref [25], Ref [31], Ref [47])	Minimum Required Thickness, mils Acceptance Criteria (Ref [43], Ref [15])	Minimum Available Thickness margin, mils
Cylindrical (87' 5")	640	604	452	152
Upper Sphere (51' 10", 60' 10")	722	676	518	158
Middle Sphere (50' 2")	770	678	541	137

**Conclusions:**

**Summary of Corrosion Rates of UT measurements taken every 4 years through year 2006 (Ref [47])**

- There is no statistically observable ongoing general corrosion at three elevation (51' 10", 60' 10", and 87' 5")
- Based on statistical analysis, one location at elevation 50' 2" is undergoing a minor general corrosion rate of 0.66 mils per year
- The drywell corrosion inspection program will ensure sufficient margin will be maintained through 2029

For illustrations of the margins of monitored locations in upper drywell see attached Key Plan and Graphs 1-13.

Table 2

Monitored Elevation	Location	Minimum Required Thickness, inches	Average Measured Thickness <sup>1,2A</sup> , inches											Projected Thickness in 2029	
			1987	1988	1989	1990	1991	1992	1993 <sup>a</sup>	1994	1996	2000	2004		2006
Elevation 50' 2"	Bay 5-D12	0.541"				0.743 0.745 0.748	0.742 0.745 0.748	0.747 0.747		0.741	0.748	0.741	0.743	0.747	No Observable Ongoing Corrosion
	Bay 5-5H					0.761 0.761	0.755 0.758 0.760	0.759 0.759		0.754	0.757	0.754	0.756	0.760	No Observable Ongoing Corrosion
	Bay 5-5L					0.706 0.703	0.703 0.705 0.706	0.703 0.702		0.702	0.705	0.706	0.701	0.705	No Observable Ongoing Corrosion
	Bay 13-31H					0.762 0.779	0.760 0.758 0.765	0.765 0.763		0.759	0.766	0.762	0.758	0.762	No Observable Ongoing Corrosion
	Bay 13-31L					0.687 0.684	0.689 0.678 0.688	0.685 0.688		0.683	0.690	0.682	0.693	0.678	No Observable Ongoing Corrosion
	Bay 15-23H					0.758 0.764	0.762 0.762 0.765	0.767 0.763		0.758	0.760	0.758	0.757	0.749	0.720
	Bay 15-23L					0.726 0.726	0.726 0.729 0.725	0.726 0.724		0.728	0.724	0.729	0.727		

Monitored Elevation	Location	Minimum Required Thickness, Inches <sup>1</sup>	Average Measured Thickness <sup>2,3</sup> , inches											Projected Thickness in 2029	
			1987	1988	1989	1990	1991	1992	1993 <sup>4</sup>	1994	1996	2000	2004		2006
Elevation 51' 10"	Bay 13-32H	0.518" (6)				0.716	0.715 0.715 0.720	0.717 0.717		0.714	0.715	0.715	0.713	0.715	No Observable Ongoing Corrosion
	Bay 13-32L					0.686	0.683 0.683 0.682	0.683 0.678		0.680	0.684	0.679	0.687	0.685	No Observable Ongoing Corrosion
Elevation 60' 10"	Bay 1-50-22	0.518"							0.693	0.711	0.693	0.689	0.693	0.691	No Observable Ongoing Corrosion
Elevation 87' 5"	Bay 9-20	0.452"	0.619	0.622 0.620	0.619	0.620	0.614 0.612	0.629 0.614		0.613	0.613	0.604	0.612	0.617	No Observable Ongoing Corrosion
	Bay 13-28		0.643	0.641 0.642	0.645	0.643	0.635 0.629	0.641 0.637		0.640	0.636	0.635	0.640	0.642	No Observable Ongoing Corrosion
	Bay 15-31		0.638	0.636 0.636	0.638	0.642	0.628 0.627	0.631 0.630		0.633	0.632	0.628	0.630	0.633	No Observable Ongoing Corrosion


## Notes:

1. The average thickness is based on 49 Ultrasonic Testing (UT) measurements performed at each location.
2. Multiple inspections were performed in the years 1988, 1990, 1991, and 1992.
3. The 1993 elevation 60' 10" Bay 5-22 inspection was performed on January 6, 1993. All other locations were inspected in December 1992.
4. Accuracy of Ultrasonic Testing Equipment is plus or minus 0.010 inches.
5. Reference SE-000243-002 (Ref [26]).



# 1. Upper Drywell Corrosion Trend and Margin

Elevation 50' 2" Bay 5 - D12




Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils



## 2. Upper Drywell Corrosion Trend and Margin

Elevation 50' 2" Bay 5 - 5H




Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty  $\pm 10$  Mills

### 3. Upper Drywell Corrosion Trend and Margin

Elevation 50' 2" Bay 5 - 5L




Source: Averaged Data - AmerGen Letter 2130-08-20428 dated December 3, 2006  
Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty  $\pm 10$  Mils

### 4. Upper Drywell Corrosion Trend and Margin

Elevation 50' 2" Bay 13 - 31H




Source: Averaged Data - AmerGen Letter 2130-06-20428 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-167-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

### 5. Upper Drywell Corrosion Trend and Margin


Elevation 50' 2" Bay 13 - 31L



Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

### 6. Upper Drywell Corrosion Trend and Margin Elevation 50' 2" Bay 15 - 23H




Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty  $\pm$  10 Mils

### 7. Upper Drywell Corrosion Trend and Margin


Elevation 50' 2" Bay 15 - 23L



Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

### 8. Upper Drywell Corrosion Trend and Margin Elevation 51' 10" Bay 13 - 32H




Source: Averaged Data - AmerGen Letter 2130-06-20428 dated December 3, 2006  
Raw Data - AmerGen Calculation C-1302-167-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

### 9. Upper Drywell Corrosion Trend and Margin

Elevation 51' 10" Bay 13 - 32L




Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-167-E310-037, Rev 2

Instrument Uncertainty  $\pm 10$  Mils




### 10. Upper Drywell Corrosion Trend and Margin Elevation 60' 10" Bay 1 - 50 - 22



Source: Averaged Data - AmerGen Letter 2130-08-20426 dated December 3, 2006  
Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

### 11. Upper Drywell Corrosion Trend and Margin Elevation 87' 5" Bay 9 - 20




Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

## 12. Upper Drywell Corrosion Trend and Margin



Elevation 87' 5" Bay 13 - 28



Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-187-E310-037, Rev 2

Instrument Uncertainty ± 10 Mils

**13. Upper Drywell Corrosion Trend and Margin**  
 Elevation 87' 5" Bay 15 - 31



Source: Averaged Data - AmerGen Letter 2130-06-20426 dated December 3, 2006  
 Raw Data - AmerGen Calculation C-1302-167-E310-037, Rev 2

Instrument Uncertainty  $\pm$  10 Mils

The following discussion addresses corrosion of the Oyster Creek outer drywell shell in the sanded region. Part I, below, provides an overview of historic information pre-dating the October 2006 outage. The discussion in Part II sets forth information discovered and analyzed as a result of the October 2006 outage. Overall conclusions about the drywell, and its continued operation during the proposed twenty-year renewal term, are summarized in Part III.

#### I. Historical Summary and Past Findings

In the 1980's, the Oyster Creek containment drywell experienced wall thinning in the sandbed region caused by water in contact with the outer drywell shell. Beginning in 1986, corrective actions were implemented to monitor, mitigate or reduce the rate of corrosion, which was initially estimated to vary from negligible in certain bays to 39 mils/year at the thinnest location in bay 13 (Ref [10]). The corrective actions were effective in reducing accelerated corrosion as evidenced by the decline in the rate of corrosion starting in 1990 (see Attachment 1).

Beginning in 1986, UT thickness measurements were taken at elevation 11'3" from the interior of the drywell shell in each bay using a 6"x6" template every refueling outage and outage of opportunity. The template is centered on points determined by UT thickness measurements taken between 1983 and 1986 to be thinnest location in each bay. The points were marked on the shell to ensure that the same location is examined each time (See Attachment 2).

Analysis and trending of UT thickness data collected between 1986 and 1992 showed that thinning of the shell was not uniform and varied within a bay and from one bay to another. The measured average thickness in some bays (1,3,5,7,15) is nearly equal to the plate original nominal thickness of 1154 mils. In other bays, the nominal thickness is reduced significantly, with bay 19 having the thinnest area of 800 mils. In all cases, the average thickness is greater than 736 mils, which is required to satisfy ASME Code buckling stress requirements.

As shown in Table-1 below, the thinnest average measured area in each bay has adequate thickness margin in addition to the ASME Code safety factor of 2 for refueling load combination and 1.67 for post accident load combination (Ref [32]). As explained in Part II, below, AmerGen took UT thickness measurements during the October 2006 refueling outage to confirm the margin remains within the calculated uncertainty listed in Table-6.

**Table-1. Minimum Available Thickness Margin**

Bay No.	1	3	5	7	9	11	13	15	17	19
Minimum Available Margin, mils	365	439	432	397	256	84	101	306	74	64

Corrosion mitigating actions in the sand bed region were completed in 1992, when the sand was completely removed from the region, followed by removal of corrosion products, and preparation of the shell surface for the epoxy coating. Prior to applying the coating, the entire surface of the sandbed area was visually inspected to validate UT thickness measurements, previously made from inside the drywell, and to identify local areas thinner than the minimum required average general thickness of 736 mils. 125 local areas were identified by visual inspection as areas that could be potentially thinner than 736 mils (See Table-2). UT thickness measurements of the 125 locations identified 20 locally thinned areas less than the minimum required general thickness of 736 mils, but greater than analyzed local criteria of 536 mils (the minimum required to withstand buckling), and 490 mils local criteria developed in accordance with ASME Code requirements (the minimum required to withstand design pressure).

Following the UT inspections discussed above, the outer drywell shell surface in the sandbed region was coated with a multi-layered epoxy coating system designed for moisture environment. The sandbed region floor also was repaired to improve drainage of the region and the junction of the embedded outer drywell shell with the sandbed region concrete floor was sealed to prevent moisture intrusion into the embedded outer drywell shell.

Analysis of UT thickness measurements conducted in 1992 and 1994 showed that corrosion of the outer drywell shell in the sandbed region had been arrested. UT thickness measurements taken in 1996 also indicated that corrosion in the outer drywell shell had been arrested. Some of the 1996 data contained anomalies that are not readily justifiable but the anomalies did not significantly change the results (Ref [37]). Between 1996 and the October 2006 outage, UT thickness measurements had not been taken; instead the epoxy coating in selected bays was inspected every other refueling outage.

Coating inspections conducted in 1994 (Bays 11, 3), 1996 (Bays 11, 17), 2000 (Bays 1, 13), and 2004 (Bays 1, 13) showed that the coating was in good condition and there were no indications that the outer drywell shell was undergoing further corrosion (Ref [34]). Furthermore, the periodic UT thickness measurements of the shell in the upper regions of the drywell that are not coated with epoxy can be used conservatively as an indicator of the condition of the outer drywell shell in the sandbed region. The 2004 and 2006 upper region UT results showed that the highest general corrosion rate is less than 1 mil/year.

A detailed discussion of the various historic activities follows:

**A. Initial Corrective Actions**

Upon discovery of water in the sandbed region in 1980, corrective actions were initiated to a) determine the source of water leakage, b) establish if corrosion is occurring by taking UT thickness measurements, and c) assess the impact of corrosion on the drywell structural integrity.

**1. Source of Water Leakage Into the Sand Bed Region**

Extensive examination and testing of potential water sources concluded that water found in the sandbed region was from the refueling cavity during refueling outages. Cracks were identified in the reactor cavity stainless steel liner that permitted water to leak from the cavity, collect in an improperly functioning concrete trough below the cavity seals, and enter the gap between the outer drywell shell and the reactor building concrete. Once water entered the gap, it flowed down to the sandbed region. The water collected and was retained in the sandbed region in part as a result of unfinished concrete floor in some bays and clogged sandbed drains. Refer to the section 4 of this Enclosure for additional details.

**2. Initial Ultrasonic Testing (UT) Thickness Measurements**

Initial UT thickness measurements were made in 1983 from inside the drywell, through paint, above the concrete floor level (elev. 10' 3") in the bays that corresponded to where water was observed coming from sandbed drains. The measurements indicated that the drywell shell was thinner than expected. The accuracy of these measurements was questioned because the readings were taken through paint. As a result, calibration tests were conducted to evaluate the impact of the paint on the UTs. The test results indicated that UT measurements through paint overestimated the actual thickness by 0.3% for a 5-mil coating and 1.5% for a 10-mil coating. For this reason, the paint was removed at the inspection locations and a new set of UT measurements was taken from inside the drywell in 1986. The new UT readings continued to indicate that the drywell shell was thinner in those sand bed bays. (Ref [7])

The scope of the UTs was expanded to include several areas near the drywell floor adjacent to the sandbed region (elevation 11' 3"). The new readings also indicated that the drywell shell was thinner than expected. (Ref [7])

As a result of the 1986 UT readings, a program was initiated to obtain detailed measurements in order to determine the extent and characterization of the thinning. Where thinning was detected, additional measurements were made in a cross pattern to determine the extent of the thinning. After the cross pattern was completed, the lowest reading at each location was used to expand the UT readings to a 6"x6" grid on 1" center with the lowest reading at the center of the grid. Approximately

560 total UT measurements were made in the ten bays at locations shown in drawing 3E-SK-S-85 (Ref [4a]). In 1986, as part of an ongoing effort at the Oyster Creek Generating Station to investigate the impact of water on the outer drywell shell, concrete was excavated at two locations inside the drywell (referred to as trenches) to expose the drywell shell below the Elevation 10' 3" concrete floor level to allow ultrasonic (UT) measurements to be taken to characterize the vertical profile of corrosion in the sand bed region outside the shell. The trenches (approximately 18" wide) were located in Bays 5 and 17 with the bottom of the trenches at approximate elevations 8' 9" and 9' 3" respectively (The elevation of the sand bed region floor outside the drywell is approximately 8' 11"). A total of 579 UT thickness measurements were taken inside the 2 trenches. The measurements inside the 2 trenches showed that the reduction in shell thickness below the drywell concrete floor level (Elev. 10' 3") is no greater than indicated above the floor level (Ref [7], Ref [4a], Ref [8], Ref [47])

Additional UT thickness measurements were taken at the plate-to-plate welds under the vent lines and the vent opening reinforcement plates. These areas were given extra consideration on the basis that material sensitized by welding may have been attacked by a corrosion mechanism with greater potential for damage or cracking. The readings did not detect wall thinning or cracks at these locations (Ref [7]).

### 3. UT Thickness Data Statistical Analysis Prior to 2006

The following steps have been performed to test and analyze the UT measurement data for those locations where 6"x6" grid data has been taken at least three times. The results of the analysis yield the measured average general thickness ( $\pm$  standard error), F-Ratio, which was used to determine if corrosion was occurring, and the upper 95% confidence interval was used after corrosion was identified. See Table-5, Table-6, and Attachment 1 for the results of the analysis. The steps are:

- Edit each 49-point data set by setting all invalid points to "missing". Invalid points are those that are declared invalid by the UT operator or are at a plug (i.e., core sample) location.
- Perform a Univariate Analysis of each 49 point data set to ensure that the data is normally distributed.
- Calculate the mean thickness and variance of each 49-point data set.
- Perform an Analysis of Variance F-test to determine if there is a significant difference between the means of the data sets.
- Using the mean thickness values for each 6"x6" grid, perform linear regression analysis over time at each location



- Perform F-test for significance of regression at the 5% level of significance.
- Calculate the ratio of the observed F value to the critical F value at 5% level of significance. The result of this test indicates whether or not the regression model is more appropriate than the mean level.
- Calculate the coefficient of determination ( $R^2$ ) to assess how well the regression model explains the percentage of total error and thus how useful the regression line will be as a predictor
- Determine if the residual values for the regression equations are normally distributed.
- Calculate the y-intercept, the slope and their respective standard errors. The y-intercept represents the fitted mean thickness at time zero, the slope represents the corrosion rate, and the standard errors represent the uncertainty or random error of the two parameters. Calculate the upper 95% one-sided confidence interval about the computed slope to provide an estimate of the maximum probable corrosion rate at 95% confidence after corrosion was identified.
- When the corrosion rate is not statistically significant compared to random variations in the mean thickness, the slope and confidence interval slope computed in the regression analysis still provides an estimate of the corrosion rate, which could be masked by the random variations.
- Use the chi-square goodness-of-fit test results to determine if low thickness measurements are significant pits. If the measurement deviates from the mean thickness by three standard deviations, it is to

Table 3 - Core Sample Thickness Evaluation

Sample No.	Location (Bay No.)	Pre-removal UT Average thickness, mils	Post-removal Measured Average Thickness, mils
1	19C	815	825
2	15A	1170	1170
3	17D	840	860
4	19A	830	847
5	11A	860	885
6	11A	1170	1190
7	19A	1140	1181

Source: Ref [1]

In summary, extensive UT readings of drywell shell thickness were taken inside the drywell to establish areas of largest wall thinning between 1986 and 1992. UT measurements were also taken in 2 trenches excavated in the drywell concrete floor to establish the vertical profile of corrosion in the sandbed region in 1986 and in 1988. The measurements showed that corrosion in the sandbed region below the drywell floor level, elevation 10' 3", was no greater than the corrosion measured at the floor level. UT measurements taken from outside the drywell after removing the sand in 1992 (discussed in section C.1 below) confirmed this observation. Thus locations selected inside the drywell for repetitive UT measurements represented the condition of the entire sandbed region.

#### 5. Initial Analysis to Assess Impact of Corrosion on the Drywell Structural Integrity and Operability.

A detailed engineering analysis was conducted in 1987, assuming a corroded thickness of 700 mils. The analysis concluded that, with sand in place and conservatively assuming the thickness was reduced to 700 mils, the drywell was capable of performing its intended function and that the containment is operable (Ref [2]).

#### B. Other Corrective Actions Taken in Response to UT Measurements

As a result of significant wall thinning and accelerated rate of corrosion in the sandbed region (bays 11, 13, 17, and 19), Oyster Creek initiated additional corrective actions in 1987 to assess the impact on corrosion on the drywell intended function, and minimize the rate of corrosion. These included but were not limited to: a) an initial analysis to determine if the containment was operable, b) actions to minimize the potential for water intrusion into the affected area, c) actions to effect removal of any water that might intrude into the affected area, d) installation of a cathodic protection system in 2 bays, e) taking UT measurements every refueling outage and outage of opportunity, and f) trending the UT results. Refer to (Ref [32]) for additional details.

**1. Corrective Actions to Minimize the Rate of Corrosion**

Beginning in 1988, the strippable coating was applied to reactor cavity walls to minimize water leakage during the refueling outages. Leakage monitoring, implemented later, confirmed that this coating is effective in minimizing the water intrusion into the sandbed region. See section 4 of this Enclosure for additional details.

UT thickness measurements taken through 1988 showed that the corrosion rate of the outer drywell shell in the sandbed region continued to increase (see Attachment 1). Also the rate of corrosion in the bays where the cathodic protection system was installed showed no improvement. It was then concluded that the most effective way to mitigate corrosion was to remove the sand and corrosion products, and apply a protective coating to the outer drywell surface in sandbed region. Refer to section C.1 below for details of the coating. (Ref [9], Ref [32]).

**2. Engineering Analysis Performed to Establish the Minimum Required Thickness With Sand Removed**

An engineering analysis, based on ASME Code requirements, was conducted in the early 1990's to establish the minimum required general thickness without sand for both pressure and buckling stress (Ref [15], Ref [16], Ref [32]). The analysis was based on a partial finite element model (36-degree slice - Fig. 1) of the drywell. Loads and load combinations were in accordance with the original design basis requirements as follow: (Ref [16])

**CASE I - INITIAL TEST CONDITION**

Deadweight + Design Pressure (62 psi) + Seismic (2 x DBE)

**CASE II - FINAL TEST CONDITION**

Deadweight + Design Pressure (35 psi) + Seismic (2 x DBE)

**CASE III - NORMAL OPERATING CONDITION**

Deadweight + Pressure (2 psi external) + Seismic (2 x DBE)

**CASE IV - REFUELING CONDITION**

Deadweight + Pressure (2 psi external) + Water Load +  
Seismic (2 x DBE)

**CASE V - ACCIDENT CONDITION**

Deadweight + Pressure (62 psi @ 175°F or 35 psi @ 281°F) +  
Seismic (2 x DBE)

**CASE VI - POST ACCIDENT CONDITION**

Deadweight + Water Load @ 74°F + Seismic (2 x DBE)

Note: Subsequent to this analysis GE developed Oyster Creek plant specific accident pressure, approved in accordance with Technical Specification Amendment 165 (Ref [46])

The results of the analysis showed that the minimum required thickness was controlled by buckling and that a general thickness of 736 mils will satisfy ASME Code requirements with a safety factor of 2 against buckling for the controlling operating load combination (Case IV - refuelling condition), and 1.67 safety factor for accident flooding load combination (Case V - Accident condition). See Table 4 below for additional details). (Ref [32]).

Local areas where the thickness was less than the general 736 mils were evaluated based on 490 mils local acceptance criteria (Ref [42]). The local acceptance criteria of 490 mils was confined to an area less than  $2\frac{1}{2}$ "<sup>1</sup> in diameter experiencing primary membrane + bending stresses based on ASME B&PV Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular, NE-3213.10 limits the meridional distance between openings without reinforcement to  $2.5 \times$  (square root of Rt). Also Paragraph NE-3335.1 only applies to openings in shells that are closer than two times their average diameter.

A review of all the 1992 UT data presented in Appendix D of calculation C-1302-187-5320-024 (Ref [42]) indicated that all thicknesses in the drywell sand bed region exceeded the required pressure thickness by a substantial margin. Therefore, the requirements for pressure reinforcement specified in the previous paragraph were not required for the very local wall thickness evaluation presented in Calculation C-1302-187-5320-024 (Ref [42]).

Reviewing the stability analyses provided in both the GE Report 9-4 (Ref [16]) and the GE Letter Report Sand Bed Local Thinning and Raising the Fixity Height Analysis (Ref [22]) and recognizing that the plate elements in the sand bed region of the model are 3" x 3" it was clear that the circumferential buckling lobes for the drywell were substantially larger than the  $2\frac{1}{2}$ "<sup>1</sup> diameter for very local wall areas. This, combined with the local reinforcement surrounding these local areas, indicated that these areas would have no impact on the buckling margins in the shell. It was also clear from the GE Letter Report (Ref [22]) that a uniform reduction in thickness of 27% to 0.536" over a one square foot area would only create a 9.5% reduction in the load factor and theoretical buckling stress for the whole drywell resulting in the largest reduction possible. In addition, to the reported result for the 27% reduction in wall thickness, a second buckling analysis was performed for a wall thickness reduction of 13.5% over a

<sup>1</sup> In some evaluations 2" diameter is conservatively used to define very local areas instead of  $2\frac{1}{2}$ "


one square foot area which only reduced the load factor and theoretical buckling stress by 3.5% for the whole drywell resulting in the largest reduction possible. To bring these results into perspective, a review of the NDE reports indicated there were 20 UT measured areas in the whole sand bed region that had thicknesses less than the 0.736 inch thickness used in GE Report 9-4 (ref [16]) which cover a conservative total area of 0.68 square feet of the drywell surface with an average thickness of 0.703" or a 4.5% reduction in wall thickness. Therefore, to effectively change the buckling margins on the drywell shell in the sand bed region, a reduced thickness would have to cover approximately one square foot of shell area at a location in the shell that is most susceptible to buckling with a reduction in thickness greater than 25%. GE analysis concluded that the buckling of the shell was unaffected by the distance between the very local wall thicknesses; in fact, these local areas could be contiguous provided their total area did not exceed one square foot and their average thickness was greater than the thickness analyzed in the GE Letter Report (Ref [22]) and provided the methodology of Code Case N284 was employed to determine the allowable buckling load for the drywell. Furthermore, all of these very local wall areas were centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the sand bed region, which is located at the midpoint between two vents. (Ref [35], [32], [16])

Table 4 - Buckling Analysis Summary

	Load Combination	
	CASE IV - REFUELING CONDITION	CASE V - ACCIDENT CONDITION
Service Condition	Design	Level C
Thickness used in Analysis, mills	736	736
Factor of Safety Applied	2.00	1.67
Applied Compressive Meridional Stress (ksi)	7.59	12.0
Allowable Compressive Meridional Stress (ksi)	7.59	12.93
Actual Buckling Safety Factor <sup>1</sup>	2.00	1.80

Source: Ref [16]

<sup>1</sup> The actual buckling safety factor is greater than 2.00 and 1.80 since the minimum measured general thickness is greater than 0.736 inches.



**Fig. 1 - Drywell Analysis ANSYS Finite Element Model**

**C. Final Corrective Actions (early 1990's)**

The corrective actions, implemented in early 1993, included removal of sand from the sandbed region, performance of additional UT inspections on the outside of the drywell shell to confirm the results of measurements previously taken from the inside, and application of epoxy coating to the exterior surface of the drywell to protect it from further corrosion.

1. Removal of the sand was initiated in 1988 and completed in 1992. The surface of the outer drywell shell was cleaned in preparation for coating (Ref [19]). Before the coating was applied, inspection of the outer drywell shell in all 10 sandbed bays was conducted. 125 UT measurements were taken in local areas suspected by visual inspection to be less than the minimum required general thickness of 736 mils. Of the 125 UT thickness measurements, 20 were determined to be less than 736 mils, but greater than the analyzed local thickness of 536 mils. The locally thinned areas were evaluated using criteria provided in ASME Section III, Subsection NE3213.10 and found acceptable (Ref [32], [35]). See Table 2.

**Table 2 – UT Thickness Measurement of Locally Thinned Areas Taken from Outside The Drywell In the Sandbed Region.**

Location	1992 UT Measurements			2006 UT Measurements		
	No. of UT	Number of UT < 736 mils	Thickness in mils	No. of UT	Number of UT < 736 mils	Thickness in mils
Bay 1	23	9	700, 710, 705, 700, 680, 690, 714, 724, 726	23	10	710, 690, 665, 680, 731, 669, 711, 722, 719, 712
Bay 3	8	0		8	0	
Bay 5	8	0		7	0	
Bay 7	7	0		5	0	
Bay 9	10	0		10	0	
Bay 11	8	1	705	8	1	700
Bay 13	29	9	672, 722, 718, 655, 618, 718, 728, 685, 683	15	6	708, 658, 602, 704, 669, 666
Bay 15	11	1	722	11	0	
Bay 17	11	1	720	10	1	681
Bay 19	10	0		9	0	
Total	125	21		106 <sup>1</sup>	18	

Source: Ref [42], Ref [47]

<sup>1</sup> The locally thinned areas prepared for UT measurements in 1992 were measured in 2006. However the inspection team was able to locate only 106 points instead of 125.

## 2. Coating of the Outer Drywell Shell in the Sandbed Region:

In 1992 the outer drywell shell was coated with a DEVOE Epoxy system, comprised of one coat of DEVOE 167 Rust Penetrating Sealer followed by two coats of Devran 184 epoxy coating (see attachment 3, Ref [19])

The DEVOE coating system was selected based on anticipation of less than ideal surface preparation of the outer drywell shell due to the confined space of the sandbed region. It was designed for application on surfaces prepared by hand cleaning tools to remove loose rust, mill scale, and other detrimental foreign matter in accordance with Steel Structures



Paint Council surface Preparation Specification No. 2 (SSPC-SP2). (Ref [17])

The Pre-Prime DEVOE 167 Sealer penetrates through rusty surfaces and provides a means of reinforcing rusty steel substrates and thus insures adhesion of the Devran 184. The sealer was recommended by its manufacturer for use in areas where, due to restrictions or economics, blasting or a thorough hand cleaning was not feasible. (Ref [17])

The Devran 184 epoxy coating was designed for coating of tank bottoms, including water tanks, fuel tanks, and selected chemical tanks. (Ref [17])

Before the coating was used, a set of tests was performed outside the sandbed using a mock-up of the sandbed space and lighting. The purpose of these tests was to establish and qualify the painting process considering the limited space and visibility in the sandbed region. Each set of tests was performed on rusted carbon steel test panels that were prepared using tools to resemble as closely as possible the expected condition of the drywell exterior surface. To further simulate the condition of the drywell exterior, the test panels were cleaned with DEVOE DevPrep 88 cleaner and then washed with high-pressure water (Ref [20])

DEVOE Pre-Prime 167 and Devran 184 coatings were applied to the test panel surfaces using brushes and rollers. The wet and dry film thickness of each coat was measured and used to determine the expected ranges of the coating thickness for the drywell exterior surface. Tests were performed to determine if holidays or pinholes were present in the coatings. (Ref [20])

### 3. Repair of Sandbed Floor to Improve Drainage

The unfinished floor in the sandbed regions was built up using the same epoxy that was used to coat the shell, and reshaped to allow drainage through the sandbed floor drain of any water that may leak into the region. At that time, the joint between the sandbed floor and the external drywell shell was sealed with a caulk compatible with the epoxy coating to prevent any water from coming in contact with any portion of the drywell shell embedded below the level of the sandbed floor. See Section 7 of this Enclosure for additional information.

### 4. Validation of Corrective Actions Effectiveness

UT inspections of the sandbed region were conducted in 1992, 1994, and 1996 from inside the drywell. The results of these inspections showed that the corrective actions had been effective in arresting corrosion of the outer drywell shell in the sand bed region. (See Table-6). After 1996, additional UT measurements were not taken in the sandbed region; instead, the epoxy coating in critical bays was inspected for cracking, flaking, blistering, peeling, discoloration, and other signs of distress. Inspections conducted in 1994 (Bays 3, 11), 1996 (Bays 11, 17), 2000 (Bays 1, 13), and 2004 (Bays 1,13) show that the coating was in good

condition and there were no indications that the outer drywell shell was undergoing further corrosion (Ref [34]). Furthermore the periodic UT thickness measurements of the shell in the upper regions of the drywell could be used conservatively as an indicator of the condition of the outer drywell shell in the sandbed region. This was because the operating environment was similar in the sandbed region and the upper region of the drywell and the shell in the upper region does not have an epoxy coating. The 2004 upper region UT results showed that the highest corrosion rate is less than 1 mil/year.

**Table 5 – Sandbed Region Drywell Shell 95% Confidence Level Average Thickness<sup>1</sup>**

Bay	Loc	Dec-86	Feb-87	Apr-87	May-87	Aug-87	Sep-87	Jul-88	Oct-88	Jun-89	Sep-89	Feb-90	Apr-90	Mar-91	May-91	Nov-91	May-92	Sep-92	Sep-94	Sep-96	Oct-2006
1D									1115										1101	1151	1122
3D									1178										1184	1175	1180
5D									1174										1168	1173	1185
7D									1135										1136	1138	1133
9A									1155										1157	1155	1154
9D		1072							1021	1054	1020	1026	1022	993	1008	992	1000	1004	992	1008	993
11A				919	905	922	905	913	888	881	892	881	870	845	844	833	842	825	820	830	822
11C	Btm				917	954	916	906	891	877	891	870	865	858	863	856	882	859	850	883	855
	Top				1046	1109	1079	1045	1009	1016	1005	952	977	982	1002	964	1010	970	982	1042	958
13A		919							905	883	883	862	853	855	853	849	865	858	837	853	846
13D	Btm								962				932	909	901	900	931	906	895	933	904
	Top													1072	1049	1048	1088	1055	1037	1059	1047
13C																		1149	1140	1154	1142
15A									1120										1114	1127	1121
15D		1089							1056	1060	1061	1059	1057	1060	1050	1042	1065	1058	1053	1066	1053
17A	Btm	999							957	965	955	954	951	935	942	933	948	941	934	997	935
	Top	999							1133	1130	1131	1128	1128	1131	1129	1123	1125	1125	1129	1144	1122
17D			922		895	891	895	878	862	857	847	836	829	825	829	822	823	817	810	848	818
17/19	Btm								982	1019	1131	990	986	975	969	954	972	976	963	967	964
	Top								1004	999	955	1010	1006	987	982	971	990	989	975	991	972
19A			884		873	859	858	849	837	829	825	812	808	817	803	803	809	800	806	815	807
19B					898	892	888	864	857	826	845	840	837	853	844	846	847	840	824	837	848
19C					901	888	888	873	856	845	845	831	825	843	823	822	832	819	820	854	824

<sup>1</sup> Source: Ref 47

**Table 6 – Minimum Available Thickness Margin Based on Minimum 95% Confidence Level Average Thickness.  
(Thickness in mils)**

Location		Pre-1992	May 1992 <sup>1</sup>	Sept 1992		1994 <sup>2</sup>		1996 <sup>3</sup>		2006 <sup>4</sup>		Min. Required	Nominal Thick.	Margin
				Thick	Std Error	Thick	Std Error	Thick	Std Error	Thick	Std Error			
1D		1115				1101	± 10.0	1151	± 13.6	1122	± 8.4	736	1154	365
3D		1178				1184	± 4.9	1175	± 7.5	1180	± 5.7			439
5D		1174				1168	± 2.6	1173	± 2.2	1185	± 2			432
7D		1135				1136	± 4.3	1138	± 5.9	1133	± 6.5			397
9A		1155				1157	± 4.5	1155	± 4.8	1154	± 4.2			418
9D		992	1000	1004	± 10.0	992	± 10.4	1008	± 10.6	993	± 11.2			256
11A		833	842	825	± 8.2	820	± 7.7	830	± 8.7	822	± 8.0			84
11C	Bot	856	882	859	± 6.4	850	± 4.5	883	± 7.4	855	± 4.5			114
	Top	952	1010	970	± 23.8	982	± 23.4	1042	± 21.4	958	± 24.7			216
13A		849	865	858	± 9.6	837	± 7.8	853	± 8.8	846	± 8.2			101
13D	Bot	900	931	906	± 9.0	895	± 8.2	933	± 9.6	904	± 8.9			159
	Top	1048	1088	1055	± 14.1	1037	± 13.6	1059	± 11.2	1047	± 13.7			196
13C		932		1149	± 1.9	1140	± 3.8	1154	± 3.2	1142	± 3.1			196
15A		1120				1114	± 16.3	1127	± 10.8	1121	± 16.8			378
15D		1042	1065	1058	± 8.7	1053	± 9.0	1066	± 8.5	1053	± 8.9			308
17A	Bot	933	948	941	± 11.8	934	± 10.7	997	± 10.7	935	± 10.5			197
	Top	999	1125	1125	± 7.2	1129	± 6.8	1144	± 11.1	1122	± 7.2			263
17D		822	823	817	± 9.2	810	± 9.5	848	± 8.9	818	± 9.5			74
17/19 Frame	Top	954	972	976	± 4.8	963	± 4.9	967	± 6.0	964	± 4.8			218
	Bot	955	990	989	± 6.3	975	± 7.8	991	± 6.2	972	± 5.9			219
19A		803	809	800	± 8.4	806	± 9.9	815	± 9.6	807	± 8.9	64		
19B		826	847	840	± 8.7	824	± 7.8	837	± 9.5	848	± 8.6	88		
19C		822	832	819	± 11.0	820	± 10.5	854	± 11.8	824	± 11.3	83		

1. Source – Reference 21
2. Source – Reference 25
3. Source – Reference 27
4. Source – Reference 31, 47

Note: Shaded cells indicate thickness value used to conservatively calculate the margin

**II. 2006 Confirmatory Actions**

During the 2006 refueling outage (1R21), AmerGen performed UT of the drywell shell in the sandbed region from inside the drywell, at the same 19 grid locations where UT was performed in 1992, 1994, and 1996. Location of the UT grid is centered at elevation 11' 3" in an area of the drywell shell that corresponds to the sandbed region. The 2006 UT measurements were made in accordance with the enhanced Oyster Creek ASME Section XI, Subsection IWE (B1.27) Aging Management Program. The data was statistically analyzed using the methodology described in section 3 to determine the 95% confidence level mean thickness. The results of the statistical analysis of the 2006 UT data were compared to the 1992, 1994 and 1996 data statistical analysis results. Some of the 1996 data contained anomalies that are not readily explained, but the anomalies did not significantly change the results. The comparison confirmed that corrosion on the exterior surfaces of the drywell shell in the sandbed region has been arrested.

Analysis of the 2006 UT data, at the 19 grid locations indicates that the minimum measured 95% confidence level mean thickness in any bay is 807 mils (bay #19A). This is compared to the 95% confidence level minimum measured mean thickness in bay #19 of 806 mils and 800 mils measured in 1994 and 1992 respectively. Considering the instrument accuracy of  $\pm 10$  mils these values are considered equivalent. Thus no statistically observable corrosion has occurred since 1992 and the minimum drywell shell mean thickness at the grid locations remains greater than 736 mils as required to satisfy the worst case buckling analysis, and the minimum available margin of 64 mils for any bay reported prior to taking 2006 UT thickness measurements remains bounded. (Ref [47])

In its statistical analysis of drywell corrosion data, AmerGen has used the F-ratio test as part of its method to determine whether there is ongoing corrosion. In analysis of the data from this outage, AmerGen determined that different statistical treatment of the data would be appropriate to estimate bounding corrosion rates in the sandbed region. Using this updated statistical test of the data, AmerGen cannot statistically confirm that the sandbed region has a corrosion rate of zero. This is because of the high variance in UT data within each 49-point grid (standard within a range of deviation 60 to 100 mils), the relatively limited number of data sets that have been taken and the time frame over which data has been collected since the sand was removed in 1992. The high variance in UT data within the grids is a result of the drywell exterior surface roughness caused by corrosion that occurred prior to 1992. However, AmerGen continues to believe that corrosion of the exterior surface of the drywell shell in the sandbed region has been arrested as evidenced by little change in the mean thickness of the 19 monitored (grid) locations and the observed good condition of the epoxy coating during the 2006 inspection.

In addition to the UT measurements at the 19 grid locations, a total of 294 UT thickness measurements were taken in the bay #5 trench and 290 measurements were taken in the bay #17 trench during the 2006 refueling outage. The computed mean thickness value of the drywell shell taken within the two trenches is 1074 mils for bay #5 and 986 mils for bay #17. These values,

when compared to the 1986 mean thickness values of 1112 mils for the bay #5 trench and 1024 mils for the bay #17 trench, indicated that wall thinning of approximately 38 mils has taken place in each trench since 1986. Engineering evaluation of the results concluded that considering that the exterior surface of bay #5 had experienced a corrosion rate of up to 11.3 mils/yr between 1986 and 1992 and the exterior surface of bay #17 had experienced a corrosion rate of up to 21.1 mils/yr in the same period, the 38 mils wall thinning measured in 2006 is due to corrosion on the exterior surface of the drywell between 1986 and 1992. (Ref [47])

Additionally the 95% confidence level minimum computed drywell shell mean thickness based on 2006 UT measurements within the two trenches is greater by a margin of 250 mils than the minimum required thickness of 736 mils for buckling. Also this margin is significantly greater than the minimum computed margin at other monitored locations outside the trenches (64 mils). Individual points within the two trenches met the local thickness acceptance criterion of 490 mils for pressure computed based on ASME Section III, Subsection NE, Class MC Components, Paragraph NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE 3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The individual points also met a local buckling criterion of 536 mils previously established by engineering analysis. (Ref [47])

The above UT thickness measurements were supplemented by additional UT measurements taken at 106 points from outside the drywell in the sandbed region, distributed among the ten bays. The locations of these measurements were established in 1992 as being the thinnest local areas based on visual inspection of the exterior surface of the drywell shell before it was coated. The thinnest location measured in 2006 is 602 mils versus 618 mils measured in 1992. The difference between the two measurements does not necessarily mean a wall thinning of 16 mils has taken place since 1992. This is because the 2006 UT data could not be compared directly with the 1992 data due to the difference in UT instruments and measurement technique used in 2006, and the uncertainty associated with precisely locating the 1992 UT points. A review of the 2006 data for the 106 external locations indicated that the measured local thickness is greater than the local acceptance criteria of 0.490" for pressure and 536 mils for local buckling. (Ref [47])

As stated above, the 2006 UT data of the locally thinned areas (106 points) could not be correlated directly with the corresponding 1992 UT data. This is largely due to using a more accurate UT instrument and the procedure used to take the measurements. In addition the inner drywell shell surface could be subject to some insignificant corrosion due to water intrusion onto the embedded shell (see discussion below). For these reasons the Oyster Creek ASME Section XI, Subsection IWE Program (B.1.27) will be further enhanced to require UT measurements of the locally thinned areas in 2008 and periodically during the period of extended operation. (Ref [47])

During the 2006 refueling outage (1R21), AmerGen conducted VT-1 inspections of the epoxy coating in all ten bays in accordance with ASME Section XI, Subsection IWE, and AmerGen's Protective Coating Monitoring and Maintenance Program. These inspections would have documented any flaking, blistering, peeling, discoloration, and other signs of degradation of the coating. The VT-1 inspections found the coating to be in good condition with no degradation.

Based on these VT-1 inspections, AmerGen has confirmed that no further corrosion of the drywell shell is occurring from the exterior of the epoxy-coated sandbed region. Monitoring of the coating in accordance with the ASME Section XI, Subsection IWE and AmerGen's Protective Coating Monitoring and Maintenance Program will continue to ensure that the drywell shell maintains its intended function during the period of extended operation. (Ref [47])

**A. Aging Management Program for the Extended Period of Operation:**

AmerGen is committed to a comprehensive aging management program to ensure that significant corrosion is detected and corrected prior to impacting the intended functions of the drywell (Ref [47]). The program elements for the sandbed region include:

1. A strippable coating will be applied to the reactor cavity liner to prevent water intrusion into the gap between the drywell shield wall and the drywell shell during periods when the reactor cavity is flooded.
2. The reactor cavity seal leakage trough drains and the drywell sand bed region drains will be monitored for leakage during refueling outages and during the plant operating cycle:
  - The sand bed region drains will be monitored daily during refueling outages. If leakage is detected, procedures will be in place to determine the source of leakage and investigate and address the impact of leakage on the drywell shell, including verification of the condition of the drywell shell coating and moisture barrier (seal) in the sand bed region and performance of UT examinations of the shell in the upper regions. UTs will also be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred. UT results will be evaluated per the existing program. Any degraded coating or moisture barrier will be repaired. These actions will be completed prior to exiting the associated outage.
  - The sand bed region drains will be monitored quarterly during the plant operating cycle. If leakage is identified, the source of water will be investigated, corrective actions taken or planned as appropriate. In addition, if leakage is detected, the following items will be performed during the next refueling outage:
    - o Inspection of the drywell shell coating and moisture barrier (seal) in the affected bays in the sand bed region
    - o UTs of the upper drywell region consistent with the existing program

- o UTs will be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred
  - o UT results will be evaluated per the existing program. Any degraded coating or moisture barrier will be repaired
3. The Inservice Inspection (ISI) Program will be enhanced to require inspection of 100% of the epoxy coating every 10 years during the period of extended operation. These inspections will be performed in accordance with ASME Section XI, Subsection IWE. Performance of the inspections will be staggered such that at least three bays will be examined every other refueling outage. Inspection of the coating is accomplished through the Protective Coating Monitoring and Maintenance Program (B.1.33)
  4. When the sand bed region drywell shell coating inspection is performed, the seal at the junction between the sand bed region concrete and the embedded drywell shell will be inspected
  5. The reactor cavity seal leakage concrete trough drain will be verified to be clear from blockage once per refueling cycle.
  6. UT thickness measurements will be taken from outside the drywell in the sandbed region during the 2008 refueling outage on the locally thinned areas examined during the October 2006 refueling outage. The locally thinned areas are distributed both vertically and around the perimeter of the drywell in all ten bays such that potential corrosion of the drywell shell would be detected.
  7. Starting in 2010, drywell shell UT thickness measurements will be taken from outside the drywell in the sandbed region in two bays per outage, such that inspections will be performed in all 10 bays within a 10-year period. The two bays with the most locally thinned areas (bay #1 and bay #13) will be inspected in 2010. If the UT examinations yield unacceptable results, then the locally thinned areas in all 10 bays will be inspected in the refueling outage that the unacceptable results are identified.
  8. Perform visual inspection of the drywell shell inside the trench in bay #5 and bay #17 and take UT measurements inside these trenches in 2008 at the same locations examined in 2006. Repeat (both the UT and visual) inspections at refueling outages during the period of extended operation until the trenches are restored to the original design configuration using concrete or other suitable material to prevent moisture collection in these areas.

After each inspection, UT thickness measurements results will be evaluated and compared with previous UT thickness measurements. If unsatisfactory results are identified, then additional corrective actions will be initiated, as necessary, to ensure the drywell shell integrity is maintained throughout the period of extended operation (Ref [47]).



**III. Conclusion**

Corrosion of the Oyster Creek outer drywell shell has been investigated since the early 1980's. Corrective actions, implemented beginning in 1986, have arrested corrosion. AmerGen conducted UT thickness inspections of the shell in the sandbed region in 2006 (1R21) to confirm corrosion has been arrested in the outer drywell shell. The results showed that corrosion of the exterior drywell shell has been arrested. AmerGen also conducted VT-1 inspections of the epoxy coating in all ten bays in accordance with ASME Section XI, Subsection IWE, and AmerGen's Protective Coating Monitoring and Maintenance Program. The VT-1 inspections found the coating to be in good condition with no degradation.

Engineering analysis of the drywell using a conservative uniform general thickness of 736 mils for the entire sandbed region concluded that the drywell meets its design requirements during the current term with adequate margin.


AmerGen is committed to implementing a comprehensive aging management program during the extended period of operation to preserve the existing margin. The program is designed to detect, mitigate, and correct drywell shell degradations. These activities provide reasonable assurance that wall thinning of the drywell will be detected and corrected prior to impacting the intended function of the drywell.

**ATTACHMENT 1**

**GRAPHICAL PRESENTATION OF SANDBED DATA**


**Source of data for the graphs:  
Ref. [21], Ref [25], Ref [27], Ref [31], and Ref [47]**

**Figure 1. Sandbed Bay # 1D**




Source: Raw Data - AmerGen Calculation C-1302-187-5300-021, C-1302-187-5300-028, C-1302-187-8610-030

**Figure 2. Sandbed Bay #3D**




**Figure 3. Sandbed Bay # 5D**




Source: Raw Data - Amergen Calculation C-1302-187-5300-021, C-1302-187-5300-028, C-1302-187-8610-030

Date

**Figure 4. Sandbed Bay # 7D**




**Figure 5. Sandbed Bay # 9A**




Source: Raw Data - Amergen Calculation C-1302-187-5300-021, C-1302-187-5300-028, C-1302-187-8610-030

**Figure 6. Sandbed Bay # 9D**








**Figure 7. Sandbed Bay #11A**



**Figure 8. Sandbed Bay #11C  
Top**




**Figure 9. Sandbed Bay #11C  
Bottom**




Source: Raw Data - Amergen Calculation C-1302-187-5300-021, C-1302-187-5300-028, C-1302-187-8610-030 Date (\*Maximum calculated rate -22.4mils/yr 4/91, C-1302-187-5300-011 Rev.1)

**Figure 10. Sandbed Bay #13A**



**Figure 11. Sandbed Bay #13D  
Top**




Source: Raw Data - Amergen Calculation C-1302-187-5300-021, C-1302-187-5300-028, C-1302-187-8610-030


Date

**Figure 12. Sandbed Bay #13 D  
Bottom**


1154 Mil Nominal Shell Plate Thickness



**Figure 13. Sandbed Bay # 13C**




**Figure 14. Sandbed Bay # 15A**




Source: Raw Data - Amergen Calculation C-1302-187-5300-021,  
 C-1302-187-5300-028, C-1302-187-8610-030




**Figure 15. Sandbed Bay #15 D**




**Figure 16. Sandbed Bay #17A  
Top**




**Figure 17. Sandbed Bay #17A  
Bottom**




**Figure 18. Sandbed Bay #17D**




**Figure 19. Sandbed Bay #17/19  
Frame Top**




**Figure 20. Sandbed Bays # 17/19  
Frame Bottom**



**Figure 21 Sandbed Bay # 19A**




**Figure 22. Sandbed Bay #19 B**






**Figure 23. Sandbed Bay # 19C**

1154 Mil Nominal Shell Plate Thickness



**ATTACHMENT 2**

**LOCATION OF UT MEASUREMENTS**



**Attachment 3 – Sandbed Region Epoxy Coating Specification**

<b>DEVOE Epoxy Coating System</b>	<ul style="list-style-type: none"> <li>• Pre-Prime 167 (Epoxy Primer)</li> <li>• Devran 184 (Epoxy paint)</li> <li>• Demat 124S (Epoxy caulk)</li> <li>• DevPrep 88 (Cleaner)</li> </ul>
<b>Service Life</b>	The specification requirement for ideal service life is at least 20 years. However, it was recognized that practical coatings may require maintenance sooner than 20 years. The service life is determined by periodic inspection to ensure degradations are detected and corrected before failure of the coating.
<b>Environmental Conditions</b>	<ul style="list-style-type: none"> <li>• The coating is qualified for temperature Up 250 degree F</li> <li>• Wetting &amp; Drying</li> </ul>
<b>Abrasion Resistance</b>	<ul style="list-style-type: none"> <li>• The material should be sufficiently abrasion resistant to avoid damage from video cameras, temperature probes, radiation monitors, and other similar devices.</li> </ul>
<b>Adhesion</b>	<ul style="list-style-type: none"> <li>• The coating should remain intact and attached to the drywell for the full range of general operating conditions and for the expected light abrasion during inspections and maintenance</li> </ul>
<b>Direct Impact Resistance</b>	<ul style="list-style-type: none"> <li>• The coating should remain intact and attached to the drywell for the full range of general operating conditions and for the expected light abrasion during inspections and maintenance</li> </ul>
<b>Weathering Resistance</b>	<ul style="list-style-type: none"> <li>• N/A. The area to be coated is not exposed to weathering or direct light</li> </ul>
<b>Decontaminability</b>	<ul style="list-style-type: none"> <li>• N/A</li> </ul>
<b>Thermal Conductivity</b>	<ul style="list-style-type: none"> <li>• N/A</li> </ul>
<b>Maintenance</b>	<ul style="list-style-type: none"> <li>• Periodic inspection to determine if maintenance is required</li> </ul>
<b>Repairability</b>	<ul style="list-style-type: none"> <li>• Repairable in the limited access area using equipment available on site</li> </ul>
<b>Color</b>	<ul style="list-style-type: none"> <li>• Color or tint for one coat should provide a good visual contrast with previous coat or substrate</li> <li>• Light gray to provide good light reflectance and easy detection of surface contamination and color changes indicating deterioration, and to make the need to repair a damaged or abraded area more evident</li> </ul>
<b>Gamma Radiation</b>	<ul style="list-style-type: none"> <li>• DEVOE coatings have not been tested for resistance to gamma radiation. Degradation due to exposure to Gamma radiation is determined by periodic inspection.</li> </ul>

Source: Ref [19]

This discussion addresses the embedded external Oyster Creek drywell shell ("embedded shell"). Part I, below, provides an overview of commitment information regarding the embedded shell prior to the October 2006 outage. The discussion in Part II sets forth information discovered and analyzed as a result of the October 2006 outage. Overall conclusions about the embedded shell, and continued performance of its intended function during the proposed twenty-year renewal term, are summarized in Part III.

A question regarding the embedded shell was posed to AmerGen at a June 1, 2006 NRC public meeting, and later documented in Ref [36]:

**"Inspection of Inaccessible Regions:**

It is not clear to the NRC whether the junction between the 1.154 inch plate and the 0.676 inch plate at the elevation 6 foot 10 1/4 inches is represented in the UT sampling plan. This area is below the bottom of the sand-pocket area, and is in contact with the concrete alkaline environment. However in the past, before sealing of the junction between the steel and the concrete, this area would have been subjected to the same type of contaminated water as the drywell shell in the sand-pocket area. The NRC considers this junction to be an area for possible corrosion. The NRC requested the applicant to incorporate this area in the sampling plan or justify why it should not be part of the sampling plan."

In October 2006, the ACRS License Renewal Subcommittee also asked about possible corrosion in the embedded region and AmerGen's confidence that corrosion there would be no greater than in the sandbed region, due to the inability to inspect the shell embedded in the concrete. (Ref [44], Pages 84 & 85)

In answer to these inquiries, AmerGen provides the historical information in Part I of this document.

**I. Historical Summary - The Embedded Shell**

The condition of the embedded shell was communicated in a response to the NRC dated June 20, 2006 (Ref [37]):

**"Response:**

A review of the drywell construction and fabrication details shows that the drywell skirt is welded to the 1.154 inch thick plate below the sand bed floor before the end of the 1.154" thick plate. This thick plate is welded to the 0.676" plate at elevation 6 foot 10 1/4 inches. One of the purposes of the skirt, which is also now embedded in concrete, was to support the drywell during construction. The presence of the skirt prevents moisture intrusion into the 0.676" plate. Reference Figure 7 in Section 3 of this Enclosure.

Both the 1.154" thick plate and the 0.676" thick plate are embedded in concrete and are inaccessible for inspection as recognized by ASME Section XI, Subsection IWE-1232 and NRC Guidance (NUREG-1801 Rev. 1) for license renewal. These documents credit pressure testing performed in accordance with 10 CFR Part 50 Appendix J, Type A test, for managing aging effects of inaccessible portions of the drywell shell. NUREG-1801 and Ref [30] indicate that corrosion of embedded steel is not significant if the following conditions are satisfied:

1. Concrete meeting the specifications of ACI 318 or 349 and the guidance of 201.2R was used for the containment shell or liner.
2. The concrete is monitored to ensure that it is free of cracks that provide a path for water seepage to the surface of the containment shell or liner.
3. The moisture barrier, at the junction where the shell or liner becomes embedded, is subject to aging management activities in accordance with ASME Section XI, Subsection IWE requirements.
4. Water ponding on the containment concrete floor are not common and when detected are cleaned up in a timely manner."

The Response also indicated:

"The corrosion of the drywell shell in the sand bed region was caused by the moisture trapped in the sand bed due to water leakage into the region. The source of leakage was determined to be the reactor cavity, which is filled with demineralized water during refueling outages. The water passed over the Firebar-D coating that was applied to the drywell shell to allow for formation of the required seismic gap between the drywell shell and the encircling concrete shield wall. The Firebar-D material is a magnesium oxychloride compound. The drywell was erected onsite and exposed to salt air environment during construction, which could also introduce contaminants to the sandbed environment. Chemistry test results on wet sand conducted in 1986 indicated that the leachate from the moist sand had a pH of 8.46 and contained only 45 ppb chlorides and <17 ppb sulfates.

As noted in Ref [30], this water is not aggressive to concrete since the pH is greater than 5.5, the chlorides are less than 500 ppm and sulfates are less than 1500 ppm. This means that the wetted concrete environment will provide a high pH environment that will protect the embedded shell from corrosion. Additionally, the corrosion rates calculated for the carbon steel plugs removed from the drywell shell in the sand bed region were comparable to carbon steel exposed to typical waters over a similar temperature range. While an increase in the salinity and impurity of the water will increase the kinetics of the corrosion reaction by increasing the electrolyte conductivity and can alter the form of corrosion experienced by steel (e.g., from general corrosion to pitting corrosion), impurities such as chloride and sulfate are not fundamentally involved in the corrosion anodic and cathodic reactions. In fact, increasing the salinity of the water decreases the dissolved oxygen content of the water and, thus, reduces the concentration of cathodic reactant present for the corrosion reaction." (Ref [37])

The removal of the sand from the sandbed region in 1992 afforded the first opportunity to inspect the sandbed floor and evaluate its condition. There were a number of bays in which the sandbed floor was noted as being unfinished (i.e., the floor lacked a smooth surface with appropriate slope that would direct any water entering the sandbed region away from the drywell shell to the drain). This was documented in Update 10 (4/97) to the Oyster Creek FSAR, Section 3.8.2.8 (Drywell Corrosion) (Ref [46]).

The condition of the sandbed floor also was noted in a May 5, 1993 meeting between GPU Nuclear Corporation and the NRR Staff on the Oyster Creek Drywell Corrosion Mitigation Program (Ref [24]). The presentation slides used during that meeting identified the sandbed floor in some bays to be "cratered with some craters adjacent to the shell. A few craters were big, about 12-13 feet long, 12-20 inches deep and 8-12 inches wide." AmerGen believes that the small quantity, low velocity and non-aggressive chemistry of the water that entered the sandbed region while the sand was present could not have eroded concrete to the extent identified and, therefore, the craters have existed since original construction. (Ref [48])

Several corrective actions were implemented to mitigate corrosion of the drywell shell. These mitigative actions were designed to minimize water intrusion into the sand bed region, provide for an effective drainage of the region in the event of water leakage, and monitor the drains to detect leakage. (See Sections 4 & 6 of this Enclosure). Specifically, as part of the corrosion mitigation activities performed in 1992, the outer shell of the drywell was cleaned and then coated with an epoxy coating including portions of the shell below the current level of the sandbed floor in those bays where the floor was unfinished. The unfinished floors in the sandbed regions were then built up using the same epoxy that was used to coat the shell, and reshaped to allow drainage through the sandbed floor drain of any water that may leak into the region. At that time, the joint between the sandbed floor and the external drywell shell was sealed with a caulk compatible with the epoxy coating to prevent any water from coming in contact with any portion of the drywell shell embedded below the level of the sandbed floor. (Ref [19], Section 6.12).

## II. Confirmatory Actions During The 2006 Outage

AmerGen visually inspected the sandbed regions in all 10 bays during the 2006 outage. As part of these inspections, the integrity of the epoxy floor and the caulk sealant between the external drywell shell and the floor of the sandbed region were inspected. No degradation of the caulking between the coated drywell shell and the epoxy coating on the sand bed regions floors was observed. Accordingly, no repairs were required. (Ref [47])

AmerGen observed in 8 of 10 bays separation/cracking of the floor epoxy coating. These areas had no impact on the exterior drywell shell epoxy coating or the caulk seal between the drywell shell and the sand bed floors because the cracks were in areas of the floor away from the shell. The separation/cracking was repaired prior to the conclusion of the October, 2006 outage.

The 1.154 inch thick plate of the external drywell shell between the embedded support skirt and the floor of the sandbed region likely experienced some historical corrosion. However, AmerGen expected such corrosion to be bounded by the corrosion in the non-embedded regions due to the formation of a thin protective oxide passive film over the shell from the highly alkaline concrete. (Ref [29]). During the October 2006 outage, AmerGen implemented a commitment to inspect the drywell shell from the inside of the drywell in two trenches excavated in 1986 in the concrete floor (Discussed in more detail in Section 8 of this Enclosure). An additional portion of one of the trenches was further excavated to expose a small portion of the drywell shell that had, up until October 2006, been embedded in concrete on both sides. An average thickness of 1.113 inches was ultrasonically measured which, when compared with a nominal wall thickness of 1.154 inches, indicates an average total wall loss of 41 mils since construction in the late 1960s (approximately 40 years). AmerGen assumes that the majority of this wall loss occurred from the exterior of the shell and prior to 1992 (Ref [47]), when the sand and standing water was removed from the sandbed region. However, assuming that the 41 mils wall loss occurred over the first 40 years, and that there is an ongoing corrosion of about 1 mil per year, there is still adequate margin for the proposed 20-year period of extended operation.

For the reasons stated below, the exterior of the 0.676 inch thick plate embedded in the concrete below the attachment point of the steel support skirt has been protected from contact with water on the outside of the drywell shell and, therefore, likely did not (and does not now) experience corrosion. The weld that attaches the skirt to the drywell shell is continuous around the exterior of the drywell shell preventing water on the exterior of the drywell from continuing into the 0.676 inch plate region. Although there are cutouts in the skirt to facilitate initial construction, these cutouts are at least 2 feet below the attachment weld. Notes on installation drawings indicate that other openings in the skirt were closed as concrete placement proceeded. For water on the outside of the shell to contact the 0.676 inch plate, it would need to migrate downward through the concrete, through the opening in the skirt and then over two feet upward to the shell. The water on the outside of the shell that may have entered the space between the exterior drywell shell and the sandbed floor prior to the joint being caulked lacks the driving force (including wicking) necessary to navigate such a tortuous path through the concrete.

Also, although the bottom of the drywell is below the level of the groundwater table, it is not credible that groundwater could have migrated through the concrete under this portion of the shell and caused external corrosion in the 0.676 inch plate. The Reactor Building Foundation floor is a 10 ft thick reinforced concrete slab. The bottom elevation of the slab is minus 29' 6" and its top elevation is minus 19' 6". There is a waterproof membrane at the bottom of the mat that extends up the outside of the exterior walls to an elevation of 5' 0". The concrete pedestal that supports the Containment shell is located at the center of the mat. The containment shell is spherical in shape at the base and has a bottom elevation of 2' 3". The Torus Room completely surrounds this concrete pedestal with a floor elevation of minus 19' 6" (top of mat). (A more detailed description of the drywell is provided in Section 3 of this Enclosure)

In order for ground water to reach the lowest point of the containment shell it would need to penetrate the waterproof membrane then migrate through the 10 ft concrete mat then



migrate through the pedestal concrete. Since there is no waterproofing on this interior concrete pedestal, or other interior walls, any water contained or migrating in the pedestal would seek the path of least resistance and flow into the Torus Room. This path would be through the concrete itself or along construction joints in the pedestal. If water was able to make its way along the path outlined above, and actually reach the base of the containment shell, the Torus Room would be flooded. There are sumps in the basement of the Reactor Building that collect any water in leakage and would prevent significant accumulation of water in the Torus Room.

Periodic testing of the drywell integrity is required by 10CFR50, Appendix J. In particular, the Type A test measures the containment system overall integrated leakage rate and must be conducted under conditions representing design-basis loss-of-coolant accident containment peak pressure. The most recent Appendix J, Type A test of the drywell shell (Nov. 2000) confirmed the integrity of the shell in the embedded region and satisfied all Code acceptance criteria.

### III. Conclusions

From the above discussion, the conclusions are as follows:

- The corrosion of the external embedded drywell shell is bounded by the corrosion in the sandbed region. This is a reasonable conclusion for two primary reasons:
  1. The carbon steel in the embedded region is in contact with high pH concrete that allows the creation of a passive film on the steel surface. That is, the presence of abundant amounts of calcium hydroxide and relatively small amounts of alkali elements, such as sodium and potassium, gives concrete a very high alkalinity (e.g., pH of 12 to 13). In fact, thermodynamic calculations reveal no corrosion of iron (steel) above pH 10 at room temperature.
  2. Uniform corrosion will tend to occur when some surface regions become anodic for a short period, but their location and that of the cathodic regions constantly change. For example, general corrosion/rusting of mild steel will occur when there is a uniform supply of oxygen available across the surface of the steel and there is a uniform distribution of defects in the oxide film as is usually the case in the non-protective films formed on unalloyed steel. In the absence of areas of high internal stress (e.g., cold-worked regions) or segregated zones (e.g., non-uniform distributions of sulfide inclusions), a number of anodic regions will develop across the surface. Some areas will become less active while new anodic regions become available. Therefore, overall attack takes place at a number of anodic sites whose positions may change, leading to general rusting across the surface.

If the supply of oxygen is not uniform across a surface, then any regions that are depleted in oxygen will become anodic as the case of moist sand in contact with the drywell steel. The remainder of the drywell surface including the embedded steel has oxygen available to it and therefore acts as a large cathodic area. When the cathodic area is larger, local attack will occur in the

smaller anodic region. This phenomenon is referred to as differential aeration.

Therefore, due to the creation of a differential aeration cell, the adjacent carbon steel in contact with the moist sand bed acts as an anode that sacrifices itself to the benefit of the steel in the embedded region. That is, the corrosion of the sand cushion steel preferentially corrodes as galvanically coupled to the embedded steel." (Ref [37])

- "Craters" identified in the sandbed region floors when the sand was initially removed were created during initial construction (pre-1969). (Ref [48])
- Measures taken to prevent water from entering the sandbed region and any further water intrusion into the area between the concrete and the external drywell shell are effective because they preclude "two of the four necessary fundamental parameters necessary for any form of corrosion to occur, an electrolyte, (i.e., moisture) and the cathodic reactant (i.e., oxygen), while only the lack of one fundamental parameter is sufficient to prevent corrosion. Sealing off the embedded steel prevents refreshment of moisture in the embedded region." (Ref [37]) The ultrasonic measurements taken during the October, 2006 outage of a section of the drywell shell previously embedded on both sides since initial construction indicate the effectiveness of preventive measures in that, on average, in excess of 96% of the nominal wall remains in the embedded portion of the drywell shell immediately below the sandbed region.
- Any oxygen trapped by the caulk sealant would most likely have been consumed and a thin protective oxide passive film would have been formed from contact with the highly alkaline concrete thereby minimizing further corrosion because "residual moisture will not support any subsequent corrosion once all the dissolved oxygen is consumed in the cathodic corrosion reaction. The cessation of the corrosion reaction will occur regardless of the presence of contaminants that may be dissolved in the water (e.g., chloride, sulfate, etc.) since although these impurities can affect the kinetics of the corrosion reaction, they do not participate in the cathodic reduction reaction. Once the cathodic reaction is stopped, corrosion is stopped. Intermittent wetting and aeration of the embedded steel would produce only minimal additional corrosion." In addition, "[t]he presence of concrete in contact with the embedded steel will mitigate corrosion even if sufficient moisture and oxygen are available due to the spontaneous formation of a thin protective oxide passive film on the embedded steel surface in the highly alkaline solution of the concrete. As long as this film is not disturbed, it will keep the steel passive and protected from corrosion." (Ref [37])
- The sandbed floor was reshaped in 1992 to route water to the sandbed drains and away from the drywell shell and caulk sealant.
- Continued inspections of the caulk sealant have confirmed its integrity.

- Appendix J, Type A testing confirmed the integrity of the drywell shell in the embedded region.

\*In summary, AmerGen has extensively investigated drywell corrosion, including the embedded shell. A review of plant operating and industry experience indicates that corrosion of embedded steel in concrete is not significant because it is protected by the high alkalinity in concrete. Corrosion could only become significant if the concrete environment is aggressive. Historical data shows that the environment in the sand bed region is not aggressive, and thus any water in contact with the embedded shell is not aggressive. The data also shows that corrosion of the drywell shell in the sand bed region is due to galvanic corrosion and impurities such as chlorides and sulfates are not fundamentally involved in the corrosion anodic and cathodic reactions. Thus, only limited corrosion would be anticipated for the drywell embedded shell

AmerGen has also committed to a comprehensive drywell corrosion-monitoring program for the period of extended operation. The program includes mitigative measures to prevent water intrusion into the sand bed region. The sand bed region concrete floor is sealed with epoxy coating. The junction between the sand bed region concrete floor and the drywell shell was sealed in 1992 to prevent moisture from impacting the embedded shell. Thus, additional significant corrosion of the embedded shell is not expected because of lack of moisture and depleted oxygen. AmerGen is committed to taking specific corrective actions, described in item 3 of Enclosure 1 to Ref. [39], prior to exceeding any design requirements, if water leakage is detected in the sand bed region drains.

For all of the above reasons, the corrosion rate for the embedded drywell shell is less than the corrosion rate of the sand bed region of the drywell shell. Also, direct monitoring of the drywell shell in the sand bed region adequately bounds any corrosion in the drywell embedded shell." (Ref [37])

This discussion addresses the potential for corrosion of the interior surface of the drywell shell that is embedded in the concrete floor inside the drywell (i.e., below the concrete floor at Elevation 10' 3"). See Figure 4 in Section 3 of this Enclosure. This area includes the shell behind the concrete curb at the edge of the concrete floor. All elevations of the interior drywell shell were presumed to be coated with primer (except those areas to be embedded in concrete) that was applied following fabrication of the material to protect the steel prior to and during installation.

Part I, below, provides an overview of historic information pre-dating the October 2006 outage. The discussion in Part II sets forth information discovered and analyzed as a result of the October 2006 outage. Overall conclusions about the drywell, and its continued operation during the proposed twenty-year renewal term, are summarized in Part III.

### I. Historical Summary

The drywell is described in Section 3 of this Enclosure. Figure 1 (Section 3) shows a cross-section of the drywell. Figure 4 (Section 3) shows an elevation view of the construction of the drywell foundation including the configuration of the Torus Room. Figure 5 (Section 3) provides the details of the drywell floor including the drainage trough located in the area under the reactor vessel (referred to as the Sub-Pile Room). The two areas addressed in this discussion are the embedded portions of the 1.154" thick section internal to the drywell and the 0.676" thick section at the bottom of the drywell all of which is embedded internally (See Figure 4 in Section 3). Section 6 of this Enclosure identifies the minimum required average general thickness of the 1.154" thick section as 0.736". Since the 0.676" thick section is completely encased in concrete, it is only required to contain the maximum drywell pressure (44 psig) and is not required to withstand buckling or membrane stresses. The minimum required thickness for this section required due to the maximum drywell pressure is 0.479" per Reference [42].

In 1986, as part of an ongoing effort at the Oyster Creek Generating Station to investigate the impact of water on the outer drywell shell, concrete was excavated at two locations inside the drywell (referred to as trenches) to expose the drywell shell below the Elevation 10' 3" concrete floor level to allow ultrasonic (UT) measurements to be taken to characterize the vertical profile of corrosion in the sand bed region outside the shell. The trenches (approximately 18 inches wide) were located in Bays 5 and 17 (See Figure 3 in Section 3 of this Enclosure) with the bottom of the trenches at Elevations 8' 9" and 9' 3" respectively (The elevation of the sand bed region floor outside the drywell is approximately 8' 11").

Following UT examinations in 1986 and 1988, the exposed shell in the trenches was prepped and coated and the trenches were filled with Dow Corning 3-6548 silicone RTV foam covered with a protective layer of promatic low density silicone elastomer to the height of the concrete floor (Elevation 10' 3"). At that time, it was expected that these materials would prevent water that might be present on the drywell concrete floor from entering the trenches. Before the 2006 outage (discussed in Part II below), these materials had not been removed from the trenches since 1988.

During the preparation of a response to an NRC question (Ref [33]) during the Aging Management Review Audit, an internal memo was identified that indicated the intermittent presence of water in the two trenches inside the drywell. This was not an expected condition. That memo, dated January 3, 1995 was referenced in a 1996 Structural Walkdown Report but was not entered into the Corrective Action Process and was not considered as Operating Experience input to the Aging Management Program reviews.

Based on activities performed under the Structures Monitoring Program and IWE Inspection program, and the reviews performed in support of the License Renewal Application, the water on the drywell floor and potentially inside the trenches was previously considered a temporary outage condition and not an operating environment for the embedded shell. However, in its response to an NRC Aging Management Review Audit question (Ref [33]), AmerGen committed to inspect the condition of the drywell interior shell in the trench areas and to evaluate any identified degradations prior to entering the period of extended operation (Commitment 27.5 in Ref. [39]). The results of these inspections and associated corrective actions are described in Section II below.

## II. Confirmatory Actions During the October 2006 Refueling Outage

As noted above, AmerGen planned visual and ultrasonic (UT) inspections of the drywell shell in the trench areas during the 2006 refueling outage. The filler material in the trenches was removed and water was identified in the trenches (Bay 5 had 5 inches of standing water and Bay 17 had dampness but no standing water). (Ref: [47]) This condition was entered into the Corrective Action Process.

The presence of water in the trenches was indicative of water beneath the drywell floor surface, being in contact with both the drywell shell and drywell concrete. Following removal of the water from the trenches, visual inspections and UT measurements were performed in each trench. AmerGen has concluded (Ref: [47]) that most of the material loss occurred between 1986 and 1992 when sand and water remained in the sandbed region located adjacent to the exterior of the drywell shell and significant corrosion of the external shell was known to have occurred.

The following additional corrective/confirmatory actions related to the discovery of water in the trenches were taken during the October, 2006 Refueling Outage (Details may be found in Reference [47] transmitting a supplement to the License Renewal Application):

- Walkdowns, drawing reviews, tracer testing and chemistry samples were performed to identify the potential sources of water in the trenches.
- An engineering analysis was performed to evaluate the impact of the water on the drywell shell integrity.
- Field repairs/modifications were implemented to mitigate/minimize future water intrusion into the area between the shell and the concrete floor. These repairs/modifications consisted of (1) Repair of the trough concrete in the area under the reactor vessel to prevent water from potentially migrating through the concrete and reaching the drywell shell, (2) Caulking the interface between the

drywell shell and the drywell concrete floor/curb to prevent water from reaching the embedded shell and (3) Grouting/caulking the concrete/drywell shell interface in the trench areas.

- Additional concrete was removed from the Bay 5 trench to expose an additional 6 inches of drywell shell to allow visual inspection and UT measurements to be performed in the area of the shell that had been embedded in concrete (on both sides) until the 2006 outage.

### III. Conclusions

An engineering evaluation of the Oyster Creek Inner drywell shell condition was prepared by a structural engineer and reviewed by an industry corrosion expert and independent third-party expert to determine the impact of the as-found water on the continued integrity of the drywell shell. The evaluation utilized water chemical analysis, visual inspections and UT examinations to conclude that the measured water chemistry values and the lack of any indications of rebar degradation suggest that the protective passive film established during concrete installation at the embedded steel/concrete interface is still intact and significant corrosion of the interior embedded drywell shell would not be expected as long as this barrier

metal lost based on a current average thickness measurement of 1.113" versus a nominal plate thickness of 1.154" is only 0.041" (total wall loss for both inside and outside of the drywell shell). Although no continuing corrosion is expected, but conservatively assuming that a similar wall loss could occur between now and the end of the period of extended operation, a margin of 336 mils to the 0.736" required wall thickness would exist. Using a similarly conservative approach for the 0.676" embedded bottom head plate (0.479" required thickness for pressure retaining capability only as noted above) provides a margin of 115 mils to the end of the period of extended operation.

The engineering evaluations summarized above confirmed that the condition identified during the 2006 outage will not impact safe operation during the next operating cycle. Also, a conservative projection (noted above) of wall loss for the 1.154 and 0.676 inch thick embedded shell sections indicates that margin is provided in both sections through the period of extended operation.

Although a basis is established that ongoing corrosion of the shell embedded in concrete should not be expected and repairs/modifications have been performed to limit or prevent water from reaching the internal surface of the drywell shell, AmerGen has now established that the existence of water in contact with the internal surface of the drywell shell and concrete at and below the floor elevation will be assumed to be a normal operating environment. Therefore, aging management reviews have now been performed and new aging management activities are being specified to confirm that corrosion that could impact the ability of the drywell shell to perform its design functions for the period of extended operation is appropriately managed (Details may be found in Ref. [47]).

Ref. No.	Document	Document Date
	<b>VOLUME 1</b>	
1	Letter 5000-86-1116, GPU to NRC, Oyster Creek Drywell Containment with attached SE No. 000243-002 Rev. 0	12/18/86
2	Restart Analysis Report - Drywell Analysis Sand Transition Zone	2/9/87
3	GE Report No. 87-178-003, GE report "Corrosion Evaluation of the Oyster Creek Drywell" Rev. 1	3/6/87
4	Drawings a) 3E-SK-S-85, Drywell Plan Elev. 11' - 3" 1986 Plots b) 3E-SK-S-89, Ultrasonic Testing Drywell Level 50' 2" & 87' 5" c) 3E-SK-M-275, Ultrasonic Testing Drywell Level 50' 2" March 1990 d) 3E-SKM-358, Ultrasonic Testing Drywell Level 51' 10" April 1990	12/16/86 10/16/87 4/8/90 12/27/90
5	Memo, Oyster Creek Reactor Cavity Leakage	1/28/88
6	SE No. 328257-002, Temporary Repair of Reactor Cavity	10/19/88
7	TDR-851, Rev 0, Assessment of Oyster Creek Drywell Shell	12/27/88
8	Calculation C-1302-187-5300-005, "Statistical Analysis of Drywell Thickness Data Thru 12-31-88" Rev. 0	1/31/89
9	TDR-948, "Statistical Analysis of Drywell Thickness Data," Revision 1	2/1/89
10	Calculation C-1302-187-5300-011, "Statistical Analysis of Drywell Thickness Data Thru 4/24/90"	6/13/90
	<b>VOLUME 2</b>	
11	IS-402950-001, "Functional Requirement for Augmented Drywell Inspection," Rev. 0	10/4/90
12	TDR-1027, "Design of a UT Inspection Plan for the Drywell Containment Using Statistical Inference Methods," Rev. 1	11/1/90
13	Letter 5000-90-1995, GPU to NRC, Oyster Creek Drywell Containment	12/5/90
14	Letter, GPU to NRC, Oyster Creek Drywell Containment, dated November 26, 1990	11/26/90
15	Calculation GE Index 9-3 "An ASME Section VIII Evaluation of Oyster Creek Drywell for Without Sand Case Part 1 Stress Analysis"	2/91
16	Calculation GE Index 9-4 "An ASME Section VIII Evaluation of Oyster Creek Drywell for Without Sand Case Part 2 Stability Analysis"	2/91




Ref. No.	Document	Document Date
17	MPR Report 1275, Selection of Candidate Coatings and Steel Cleaning/Preparation Methods for the Oyster Creek Drywell Exterior in the Sand Bed Area	3/10/92
18	MPR-TP-83161-001, Test Plan for Qualifying the Painting Process for the Exterior Surface of the Drywell, Rev. 2	6/19/92
19	OC-MM-402950-010, "Cleaning and Coating the Drywell Exterior in the Sand Bed Area," Rev. 0	7/29/92
20	MPR Report 1322 - Results of Painting Process Qualification Tests for the Drywell Exterior in the Sand Bed Area at Oyster Creek, Rev. 0	8/7/92
<b>VOLUME 3</b>		
21	Calculation C-1302-187-5300-021, "Statistical Analysis of Drywell Thickness Data Thru May 1992" Rev. 0	8/26/92
22	Letter from H.S. Mehta (GE) to Dr. S. Tumminelli (GPU), "Sandbed Local Thinning and Raising the Fixity Height Analyses (Line Items 1 and 2 in Contract # PC-0391407)"	12/11/92
23	SE No. 402950-011, "Clean and Coat Drywell Ext. in Sand Bed," Revision 2	1/5/93
24	NRC Letter, "Summary of May 5, 1993, Meeting with GPU Nuclear Corporation (GPUN) to Discuss Matters Related to the Oyster Creek Drywell Corrosion Mitigation Program	5/17/93
25	Calculation C-1302-187-5300-028, "Statistical Analysis of Drywell Thickness Data Thru September 1994" Rev. 0	12/2/94
26	SE No. 000243-002, "Drywell Steel Shell Plate Thickness Reduction," Rev. 14	8/2/95
27	Calculation C-1302-187-8610-030, "Statistical Analysis of Drywell Thickness Data Thru September 1996" Rev. 1	7/12/00
28	SE No. 320006-003, Application of Strippable Coating on Equipment Pool & Rx Cavity Liner, Rev. 2	8/16/00
29	S. Jaggi, H. Böhni and B. Elsener, "Macrocell Corrosion of Steel in Concrete - Experiments and Numerical Modeling," paper presented at Eurocorr 2001, Riva di Gardi, Italy	10/1/01
30	EPRI 1002950, "Aging Effects for Structures and Structural Components (Structural Tools), Revision 1	8/03
31	Calculation C-1302-187-E310-037, Revision 2 (includes raw data)	6/10/05

Ref. No.	Document	Document Date
	<b>VOLUME 4</b>	
32	Letter 2130-06-20289, Response to RAI 4.7.2-1	4/7/06
33	Response to NRC Aging Management Review Inspection Team Question No. AMR-164	4/19/06
34	Response to NRC Aging Management Review Inspection Team Question No. AMP-071	4/20/06
35	Response to NRC Aging Management Review Inspection Team Question No. AMP-210	4/20/06
36	NRC Letter, Summary of June 1, 2006 Meeting	6/9/06
37	Letter 2130-06-20353, Supplemental Information Related to the Aging Management Program for the Oyster Creek Drywell Shell, Associated with AmerGen's License Renewal Application	6/20/06
38	Letter 2130-06-20354, Updated FSAR Supplement Information Supporting the Oyster Creek Generating Station License Renewal Application	6/23/06
39	Letter 2130-06-20358, Additional Information Concerning FSAR Supplement Supporting the Oyster Creek Generating Station License Renewal Application	7/7/06
40	Letter 2130-06-20360 (CB&I drawing 9-0971 sheet 1)	7/7/06
41	IS-328227-004, "Functional Requirements for Drywell Containment Vessel Thickness Examination," Rev. 13	9/15/06
42	Calculation C-1302-187-5320-024, "OC Drywell Ext. UT Evaluation in Sandbed," Revision 1	9/21/06
43	Calculation C-1302-243-5320-071, Revision 2, "Drywell Thickness Margins"	9/21/06
44	ACRS Subcommittee Transcript Excerpts	10/3/06
45	Letter 2130-06-20414, AmerGen Response to Open Items Associated with the NRC Draft Safety Evaluation for the Oyster Creek Generating Station Application for License Renewal	10/20/06
46	Oyster Creek FSAR Section 3.8.2.8	Rev. 14
47	Letter 2130-06-20426, Information from October 2006 Refueling Outage Supplementing AmerGen Energy Company, LLC (AmerGen) Application for a Renewed Operating License for Oyster Creek Generating Station	12/3/2006
48	MNCR 92-0188, Sandbed Floor	12/28/92
49	MNCR 87-0240, Cavity Liner Defects	11/2/87

# AmerGen<sup>SM</sup>


An Exelon Company

APPLICANT'S EXH. 4




# AmerGen<sup>SM</sup>

An Exelon Company





An Exelon Company




KEY PLAN

# AmerGen<sup>SM</sup>


An Exelon Company


## LOWER DRYWELL/SANDBED REGION DETAIL C



# AmerGen<sup>SM</sup>

DRYWELL TO REACTOR CAVITY SEAL DETAIL 'B'









**Michael P. Gallagher, PE**  
 Vice President  
 License Renewal Projects

Telephone 610.765.5958  
 www.exeloncorp.com  
 michael.p.gallagher@exeloncorp.com

An Exelon Company

AmerGen  
 200 Exelon Way  
 KSA/2-E  
 Kennett Square, PA 19348

10 CFR 50  
 10 CFR 51  
 10 CFR 54

2130-07-20464  
 February 15, 2007

U. S. Nuclear Regulatory Commission  
 ATTN: Document Control Desk  
 Washington, DC 20555

Oyster Creek Generating Station  
 Facility Operating License No. DPR-16  
NRC Docket No. 50-219

**Subject:** Additional Commitments Related to the Aging Management Program for the Oyster Creek Drywell Shell, Associated with AmerGen's License Renewal Application (TAC No. MC7624)

- References:**
1. January 18, 2007 Meeting Between ACRS License Renewal Subcommittee, AmerGen Energy Company, LLC and NRC Staff, related to License Renewal of Oyster Creek Generating Station
  2. February 1, 2007 Meeting Between Full ACRS, AmerGen Energy Company, LLC and NRC Staff related to License Renewal of Oyster Creek Generating Station
  3. ACRS Letter Dated February 8, 2007, Describing the Outcome of the February 1, 2007 ACRS Review of the Oyster Creek Generating Station License Renewal Application

In the Reference 1 meeting, AmerGen Energy Company, LLC (AmerGen) presented detailed information related to the condition of and aging management program activities for the primary containment drywell shell, as part of AmerGen's efforts to renew the operating license for the Oyster Creek Generating Station (OCGS). The Subcommittee identified several specific issues related to the drywell shell structural analysis and certain aspects of the program proposed by AmerGen to manage aging of the drywell shell for the extended period of operation.

During the full ACRS review of the Oyster Creek License Renewal Application (LRA) in the Reference 2 meeting, AmerGen presented its proposed responses to the issues identified by the Subcommittee in the January 18, 2007 meeting. In its February 1<sup>st</sup> presentation, AmerGen made three additional commitments to address these previous Subcommittee items. This letter documents these commitments.

In addition, AmerGen is making a commitment to perform the full scope of drywell sand bed region inspections, consistent with what was performed during the 2006 refueling outage, on a frequency of every other refueling outage. AmerGen believes that this commitment is

A114

responsive to a recommendation made by NRC Staff at the February 1, 2007 ACRS meeting, which was endorsed by the ACRS in its February 8, 2007 letter to the NRC Chairman.


The details of these four new commitments are provided in the Enclosure to this letter. The ASME Section XI, Subsection IWE Primary Containment Inspection aging management program (commitment 27) is modified to include these new commitments, and to clarify the effect of these new commitments on previously made IWE program commitments.

If you have any questions, please contact Fred Polaski, Manager License Renewal, at 610-765-5935.

I declare under penalty of perjury that the foregoing is true and correct.

Respectfully,

Executed on 02-15-07



Michael P. Gallagher  
Vice President, License Renewal  
AmerGen Energy Company, LLC

Enclosure: Regulatory Commitments

cc: Regional Administrator, USNRC Region I  
USNRC Project Manager, NRR - License Renewal, Safety  
USNRC Project Manager, NRR - License Renewal, Environmental  
USNRC Project Manager, NRR - Project Manager, OCGS  
USNRC Senior Resident Inspector, OCGS  
Bureau of Nuclear Engineering, NJDEP  
File No. 05040

## ENCLOSURE – REGULATORY COMMITMENTS

The following table identifies additions being made to item #27 of the License Renewal Commitment List, Table A.5 of the Oyster Creek LRA. Four commitments are being added to the ASME Section XI, Subsection IWE Primary Containment Inspection Program as part of this submittal. These new commitments are numbered to sequentially follow the commitments made in previous LRA correspondence as part of the IWE Inspection Program. The full set of commitments made as part of the IWE Program is repeated here for convenience. **Bold font** is used to highlight new information.

In addition, clarifications are made to certain previously made IWE Program commitments to indicate 1) commitments that were completed during the 2006 refueling outage and 2) the effects, if any, of the new commitments on the scope or frequency of previously made commitments. Again, **bold font** is used to highlight information introduced in this submittal.

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
27) ASME Section XI, Subsection IWE	<p>Existing program is credited. The program will be enhanced to include:</p> <ol style="list-style-type: none"> <li>1. Ultrasonic Testing (UT) thickness measurements of the drywell shell in the sand bed region will be performed on a frequency of every 10 years, except that the initial inspection will occur prior to the period of extended operation and the subsequent inspection will occur two refueling outages after the initial inspection, to provide early confirmation that corrosion has been arrested. The UT measurements will be taken from the inside of the drywell at the same locations where UT measurements were performed in 1996. The inspection results will be compared to previous results. Statistically significant deviations from the</li> </ol>	A.1.27	<p>Prior to the period of extended operation</p> <p>Prior to the period of extended operation <b>(completed during 2006 refueling outage); then every other refueling outage thereafter</b></p>	Section B.1.27

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>1992, 1994, and 1996 UT results will result in corrective actions that include the following:</p> <ul style="list-style-type: none"> <li>• Perform additional UT measurements to confirm the readings.</li> <li>• Notify NRC within 48 hours of confirmation of the identified condition.</li> <li>• Conduct visual inspection of the external surface in the sand bed region in areas where any unexpected corrosion may be detected.</li> <li>• Perform engineering evaluation to assess the extent of condition and to determine if additional inspections are required to assure drywell integrity.</li> <li>• Perform operability determination and justification for operation until next inspection.</li> </ul> <p>These actions will be completed prior to restart from the associated outage.</p> <p><b>Note: The frequency for the inspections described in commitment 1 (above) has been changed to every other refueling outage, in accordance with commitment 21 of the IWE Inspection Program.</b></p> <p>2. A strippable coating will be applied to the reactor cavity liner to prevent water intrusion into the gap between the drywell shield wall and the drywell shell during periods when the reactor cavity is flooded.</p>		<p>Refueling outages prior to and during the period of extended operation</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>3. The reactor cavity seal leakage trough drains and the drywell sand bed region drains will be monitored for leakage.</p> <ul style="list-style-type: none"> <li>• The sand bed region drains will be monitored daily during refueling outages. If leakage is detected, procedures will be in place to determine the source of leakage and investigate and address the impact of leakage on the drywell shell, including verification of the condition of the drywell shell coating and moisture barrier (seal) in the sand bed region and performance of UT examinations of the shell in the upper regions. UTs will also be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred. UT results will be evaluated per the existing program. Any degraded coating or moisture barrier will be repaired. These actions will be completed prior to exiting the associated outage.</li> <li>• The sand bed region drains will be monitored quarterly during the plant operating cycle. If leakage is identified, the source of water will be investigated, corrective actions taken or planned as</li> </ul>		<p>Periodically</p> <p>Daily during refueling outages</p> <p>Quarterly during non-outage periods</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>appropriate. In addition, if leakage is detected, the following items will be performed during the next refueling outage:</p> <ul style="list-style-type: none"> <li>• Inspection of the drywell shell coating and moisture barrier (seal) in the affected bays in the sand bed region</li> <li>• UTs of the upper drywell region consistent with the existing program</li> <li>• UTs will be performed on any areas in the sand bed region where visual inspection indicates the coating is damaged and corrosion has occurred</li> <li>• UT results will be evaluated per the existing program</li> </ul> <p>Any degraded coating or moisture barrier will be repaired.</p> <p>4. Prior to the period of extended operation, AmerGen will perform additional visual inspections of the epoxy coating that was applied to the exterior surface of the Drywell shell in the sand bed region, such that the coated surfaces in all 10 Drywell bays will have been inspected at least once. In addition, the Inservice Inspection (ISI) Program will be enhanced to require inspection of 100% of the epoxy coating every 10 years during the period of</p>		<p>Prior to the period of extended operation (completed during 2006 refueling outage); then every other refueling outage thereafter</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>extended operation. These inspections will be performed in accordance with ASME Section XI, Subsection IWE. Performance of the inspections will be staggered such that at least three bays will be examined every other refueling outage.</p> <p><b>Note: The scope and frequency for the inspections described in commitment 4 (above) has been changed to all 10 bays every other refueling outage, in accordance with commitment 21 of the IWE Inspection Program.</b></p> <p>5. A visual examination of the drywell shell in the drywell floor inspection access trenches will be performed to assure that the drywell shell remains intact. If degradation is identified, the drywell shell condition will be evaluated and corrective actions taken as necessary. In addition, one-time ultrasonic testing (UT) measurements will be taken to confirm the adequacy of the shell thickness in these areas. Beyond these examinations, these surfaces will either be inspected as part of the scope of the ASME Section XI, Subsection IWE inspection program or they will be restored to the original design configuration using concrete or other suitable material to prevent moisture collection in these areas.</p> <p><b>Note: Commitment 5 (above) is supplemented by</b></p>		<p>Prior to the period of extended operation (completed during 2006 refueling outage)</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p><b>commitments 16 and 20 of the IWE Inspection Program.</b></p> <p>6. The coating inside the torus will be visually inspected in accordance with ASME Section XI, Subsection IWE, per the Protective Coatings Program. The scope of each of these inspections will include the wetted area of all 20 torus bays. Should the current torus coating system be replaced, the inspection frequency and scope will, as a minimum, meet the requirements of ASME Section XI, Subsection IWE.</p> <p>7. AmerGen will conduct UT thickness measurements in the upper regions of the drywell shell every other refueling outage at the same locations as are currently measured.</p> <p>8. The IWE Program will be credited for managing corrosion in the Torus Vent Line and Vent Header exposed to an Indoor Air (External) environment.</p> <p>9. During the next UT inspections to be performed on the drywell sand bed region (reference AmerGen 4/4/06 letter to NRC), an attempt will be made to locate and evaluate some of the locally thinned</p>		<p>Every other refueling outage prior to (completed during 2006 refueling outage) and during the period of extended operation</p> <p>Every other refueling outage prior to (completed during 2006 refueling outage) and during the period of extended operation</p> <p>Prior to the period of extended operation (completed during 2006 refueling</p>	



ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>areas identified in the 1992 inspection from the exterior of the drywell. This testing will be performed using the latest UT methodology with existing shell paint in place. The UT thickness measurements for these locally thinned areas may be taken from either inside the drywell or outside the drywell (sand bed region) to limit radiation dose to as low as reasonably achievable (ALARA).</p> <p><b>Note: Commitment 9 (above) is supplemented by commitments 14 and 21 of the IWE Inspection Program.</b></p> <p>10. AmerGen will conduct UT thickness measurements on the 0.770 inch thick plate at the junction between the 0.770 inch thick and 1.154 inch thick plates, in the lower portion of the spherical region of the drywell shell. These measurements will be taken at four locations using the 6"x6" grid. The specific locations to be selected will consider previous operational experience (i.e., will be biased toward areas that have had corrosion or leakage). These measurements will be performed prior to the period of extended operation and repeated at the second refueling outage after the initial inspection, at the same location. If corrosion in this transition area is greater than areas monitored in the upper drywell, UT inspections in the transition area will be performed on the same frequency as those in the</p>		<p>outage); then every other refueling outage thereafter</p> <p>Prior to the period of extended operation and two refueling outages later</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>upper drywell (every other refueling outage).</p> <p>11. AmerGen will conduct UT thickness measurements in the drywell shell "knuckle" area, on the 0.640 inch thick plate above the weld to the 2.625 inch thick plate. These measurements will be taken at four locations using the 6"x6" grid. The specific locations to be selected will consider previous operational experience (i.e., will be biased toward areas that have had corrosion or leakage). These measurements will be performed prior to the period of extended operation and repeated at the second refueling outage after the initial inspection, at the same location. If corrosion in this transition area is greater than areas monitored in the upper drywell, UT inspections in the transition area will be performed on the same frequency as those in the upper drywell (every other refueling outage).</p> <p>12. When the sand bed region drywell shell coating inspection is performed (item 27, commitments 4 and 21), the seal at the junction between the sand bed region concrete and the embedded drywell shell will be inspected per the Protective Coatings Program.</p> <p><b>Note: The frequency for the inspections described in commitment 12 (above) has been changed to every other refueling outage, in</b></p>		<p>Prior to the period of extended operation and two refueling outages later</p> <p>Prior to the period of extended operation (completed during 2006 refueling outage); then every other refueling outage thereafter</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>accordance with commitment 21 of the IWE Inspection Program.</p> <p>13. The reactor cavity concrete trough drain will be verified to be clear from blockage once per refueling cycle. Any identified issues will be addressed via the corrective action process.</p> <p>14. UT thickness measurements will be taken from outside the drywell in the sandbed region during the 2008 refueling outage on the locally thinned areas examined during the October 2006 refueling outage. The locally thinned areas are distributed both vertically and around the perimeter of the drywell in all ten bays such that potential corrosion of the drywell shell would be detected.</p> <p><b>Note: The frequency for the inspections described in commitment 14 (above) has been changed to every other refueling outage, in accordance with commitment 21 of the IWE Inspection Program.</b></p> <p>15. Starting in 2010, drywell shell UT thickness measurements will be taken from outside the drywell in the sandbed region in two bays per outage, such that inspections will be performed in all 10 bays</p>		<p>Once per refueling cycle</p> <p>During the 2008 refueling outage and every other refueling outage thereafter</p> <p>All 10 bays will be inspected during the 2008 refueling outage and every other</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>within a 10-year period. The two bays with the most locally thinned areas (bay #1 and bay #13) will be inspected in 2010. If the UT examinations yield unacceptable results, then the locally thinned areas in all 10 bays will be inspected in the refueling outage that the unacceptable results are identified.</p> <p><b>Note: The scope and frequency for the inspections described in commitment 15 (above) have been changed to all 10 bays every other refueling outage, in accordance with commitment 21 of the IWE Inspection Program.</b></p> <p>16. Perform visual inspection of the drywell shell inside the trenches in bay #5 and bay #17 and take UT measurements inside these trenches in 2008 at the same locations examined in 2006. Repeat (both the UT and visual) inspections at refueling outages during the period of extended operation until the trenches are restored to the original design configuration using concrete or other suitable material to prevent moisture collection in these areas.</p> <p><b>Note: Commitment 16 (above) is supplemented by commitment 20 of the IWE Inspection Program.</b></p>		<p>refueling outage thereafter.</p> <p>During the 2008 refueling outage and subsequent refueling outages until trenches are restored to original configuration</p>	

ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>17. Perform visual inspection of the moisture barrier between the drywell shell and the concrete floor/curb, installed inside the drywell during the October 2006 refueling outage, in accordance with ASME Section XI, Subsection IWE during the period of extended operation.</p> <p>18. AmerGen will perform a 3-D finite element structural analysis of the primary containment drywell shell using modern methods and current drywell shell thickness data to better quantify the margin that exists above the Code required minimum for buckling. The analysis will include sensitivity studies to determine the degree to which uncertainties in the size of thinned areas affect Code margins. If the analysis determines that the drywell shell does not meet required thickness values, the NRC will be notified in accordance with 10 CFR 50 requirements.</p> <p>19. AmerGen will perform an engineering study to investigate cost-effective replacement or repair options to eliminate or reduce reactor cavity liner leakage.</p> <p>20. AmerGen is committed to perform visual and UT inspections of the drywell shell in the inspection trenches in drywell bays 5 and 17 during the</p>		<p>In accordance with ASME Section XI, Subsection IWE</p> <p>Prior to the period of extended operation</p> <p>Prior to the period of extended operation</p> <p>Every refueling outage until trenches are restored</p>	


ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	<p>Oyster Creek 2008 refueling outage (see commitment 16 of AmerGen's IWE Program (Item 27), made in its letter 2130-06-20426). AmerGen will extend this commitment and also perform these inspections during the 2010 refuelling outage. In addition, AmerGen will monitor the two trenches for the presence of water during refueling outages. Visual and UT inspections of the shell within the trenches will continue to be performed until no water is identified in the trenches for two consecutive refuelling outages, at which time the trenches will be restored to their original design configuration (e.g., refilled with concrete) to minimize the risk of future corrosion.</p> <p>21. Perform the full scope of drywell sand bed region inspections prior to the period of extended operation and then every other refueling outage thereafter. The full scope is defined as:</p> <ul style="list-style-type: none"> <li>• UT measurements from inside the drywell (commitment 1)</li> <li>• Visual inspections of the drywell external shell epoxy coating in all 10 bays (commitment 4)</li> <li>• Inspection of the seal at the junction between the sand bed region concrete and the embedded drywell shell (commitment</li> </ul>		<p>During the 2008 refueling outage and every other refueling outage thereafter. If the analysis being performed under commitment 18 above establishes increased margin, or if ongoing inspections continue to demonstrate that drywell shell</p>	

February 15, 2007

Enclosure

Page 13 of 13


ITEM NUMBER	COMMITMENT	UFSAR SUPPLEMENT LOCATION (LRA APP. A)	ENHANCEMENT OR IMPLEMENTATION SCHEDULE	SOURCE
	12) • UT measurements at the external locally thinned areas inspected in 2006 (commitments 9 and 14)		corrosion has been sufficiently arrested, the period between inspections may be increased to minimize personnel radiation exposure.	




**"TRAY" FRONT VIEW**

SCALE: 2" = 1'-0"





"TRAY"  
ISOMETRIC VIEW



**AmerGen**<sup>SM</sup>

Michael P. Gallagher, PE  
Vice President  
License Renewal Projects

Telephone 610.765.5958  
www.exeloncorp.com  
michaelp.gallagher@exeloncorp.com

An Exelon Company  
10 CFR 50  
10 CFR 51  
10 CFR 54

AmerGen  
200 Exelon Way  
KSA/2-E  
Kennett Square, PA 19348  
2130-06-20426  
December 3, 2006

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Oyster Creek Generating Station  
Facility Operating License No. DPR-16  
NRC Docket No. 50-219

**Subject:** Information from October 2006 Refueling Outage Supplementing AmerGen Energy Company, LLC (AmerGen) Application for a Renewed Operating License for Oyster Creek Generating Station (TAC No. MC7624)

- References:**
1. AmerGen's "Application for Renewed Operating License," Oyster Creek Generating Station, Letter 2130-05-20135, dated July 22, 2005
  2. AmerGen's "Response to NRC Request for Additional Information, dated March 10, 2006, Related to Oyster Creek Generating Station License Renewal Application (TAC No. MC7624)," Letter 2130-06-20289, dated April 7, 2006
  3. AmerGen's "Supplemental Information Related to the Aging Management Program for the Oyster Creek Drywell Shell, Associated with AmerGen's License Renewal Application (TAC No. MC7624)," Letter 2130-06-20353, dated June 20, 2006
  4. AmerGen's "Additional Information Concerning FSAR Supplement Supporting the Oyster Creek Generating Station License Renewal Application (TAC No. MC7624)," Letter 2130-06-20358, dated July 7, 2006

In References 1 through 4, AmerGen provided detailed information describing aging management reviews, aging management programs and commitments for future actions associated with the primary containment drywell shell, as part of its license renewal application (LRA) for the Oyster Creek Generating Station (Oyster Creek). In its recently completed Oyster Creek refueling outage, AmerGen performed many of the drywell shell inspection activities that it had committed to perform prior to the period of extended operation.

Per 10 C.F.R. § 54.21, this submittal serves to update the LRA and the other referenced submittals with the results of the 2006 outage activities. For ease of review, various sections of the original LRA and related responses to NRC requests for additional information (RAIs) have been updated to reflect the latest information. To a great extent, the information learned during this outage confirmed the condition of the drywell as described in previous submittals.

A114

However, as a result of performing planned inspections of the internal surface of the drywell shell in the trenches excavated in the concrete floor in 1986, AmerGen identified an environment/material/aging effect combination that was not included in the LRA. Aging management reviews of this combination have been performed and, as a result, AmerGen has identified additional aging management activities that will be included in aging management programs associated with the drywell.

The Enclosure to this letter more fully describes these reviews and resultant aging management activities. Updates to the affected portions of the LRA are provided, including a revision to the License Renewal Commitment List (LRA Appendix A, Section A.5). The Commitment List update clearly indicates the activities that are being added as part of this submittal.

AmerGen has performed a review to determine whether any additional aspects of the LRA require updating, given the recent identification of a new environment requiring evaluation in support of license renewal. Based on its review, AmerGen concludes that there are no additional revisions required to the LRA. This review has been documented in the corrective action program.

In addition, a consolidated summary of key drywell-related inspections conducted during the outage, with a summary of the results, is provided in the Enclosure.

If you have any questions, please contact Fred Polaski, Manager License Renewal, at 610-765-5935.

I declare under penalty of perjury that the foregoing is true and correct.

Respectfully,

Executed on 12/03/2006

  
Michael P. Gallagher  
Vice President, License Renewal  
AmerGen Energy Company, LLC

Enclosure: LRA Supplemental Information, Post-2006 Refueling Outage

cc: Regional Administrator, USNRC Region I, w/ Enclosures  
USNRC Project Manager, NRR - License Renewal, Safety, w/Enclosures  
USNRC Project Manager, NRR - License Renewal, Environmental, w/o Enclosures  
USNRC Project Manager, NRR - Project Manager, OCGS, w/o Enclosures  
USNRC Senior Resident Inspector, OCGS, w/ Enclosures  
Bureau of Nuclear Engineering, NJDEP, w/Enclosures  
File No. 05040

**Enclosure**

**License Renewal Application  
Supplemental Information  
Post-2006 Refueling Outage**

**Oyster Creek Generating Station  
License Renewal Application (TAC No. MC7624)**

**Note: Bold font has been used to designate additions made by this  
submittal to previously submitted documents.**

**Monitoring and Maintenance Program.** These inspections would have documented any flaking, blistering, peeling, discoloration, and other signs of degradation of the coating. The VT-1 inspections found the coating to be in good condition with no degradation.

Based on these VT-1 inspections, AmerGen has confirmed that no further corrosion of the drywell shell is occurring from the exterior of the epoxy-coated sandbed region. Monitoring of the coating in accordance with the ASME Section XI, Subsection IWE and AmerGen's Protective Coating Monitoring and Maintenance Program will continue to ensure that the drywell shell maintains its intended function during the period of extended operation.

Also during the 2006 refueling outage (1R21), AmerGen performed UT of the drywell shell in the sandbed region from inside the drywell, at the same 19 grid locations where UT was performed in 1992, 1994, and 1996. Location of the UT grid is centered at elevation 11'-3" in an area of the drywell shell that corresponds to the sandbed region. The 2006 UT measurements were made and statistically analyzed in accordance with the enhanced Oyster Creek ASME Section XI, Subsection IWE (B1.27) Aging Management Program. The results of the statistical analysis of the 2006 UT data were compared to the 1992, 1994 and 1996 data statistical analysis results (see below). Some of the 1996 data contained anomalies that are not readily justifiable but the anomalies did not significantly change the results. The comparison confirmed that corrosion on the exterior surfaces of the drywell shell in the sandbed region has been arrested.

Analysis of the 2006 UT data, at the 19 grid locations, indicates that the minimum measured 95% confidence level mean thickness in any bay is 0.807" (bay #19). This is compared to the 95% confidence level minimum measured mean thickness in bay #19 of 0.806" and 0.800" measured in 1994 and 1992 respectively. Considering the instrument accuracy of  $\pm 0.010$ " these values are considered equivalent. Thus the minimum drywell shell mean thickness at the grid locations remains greater than 0.736" as required to satisfy the worst case buckling analysis, and the minimum available margin of 64 mils for any bay reported prior to taking 2006 UT thickness measurements remains bounded.

In addition to the UT measurements at the 19 grid locations, a total of 294 UT thickness measurements were taken in the bay #5 trench and 290 measurements were taken in the bay #17 trench during the 2006 refueling outage. The computed mean thickness value of the drywell shell taken within the two trenches is 1.074" for bay #5 and 0.986" for bay #17. These values, when compared to the 1986 mean thickness values of 1.112" for the bay #5 trench and 1.024" for the bay #17 trench, indicated that wall thinning of approximately 0.038" has taken place in each trench since 1986. Engineering evaluation of the results concluded that considering that the exterior surface of

bay #5 had experienced a corrosion rate of up to 11.3 mils/yr between 1986 and 1992 and the exterior surface of bay #17 had experienced a corrosion rate of up to 21.1 mils/yr in the same period, the 0.038" wall thinning measured in 2006 is due to corrosion on the exterior surface of the drywell between 1986 and 1992.

Additionally the 95% confidence level minimum computed drywell shell mean thickness based on 2006 UT measurements within the two trenches is greater by a margin of 250 mils than the minimum required thickness of 0.736" for buckling. Also this margin is significantly greater than the minimum computed margin outside the trenches (64 mils). Individual points within the two trenches met the local thickness acceptance criterion of 0.490" for pressure computed based on ASME Section III, Subsection NE, Class MC Components, Paragraph NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE 3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The individual points also met a local buckling criterion of 0.536" previously established by engineering analysis.

The above UT thickness measurements were supplemented by additional UT measurements taken at 106 points from outside the drywell in the sandbed region, distributed among the ten bays. The locations of these measurements were established in 1992 as being the thinnest local areas based on visual inspection of the exterior surface of the drywell shell before it was coated. The thinnest location measured in 2006 is 0.602" versus 0.618" measured in 1992. The difference between the two measurements does not necessarily mean a wall thinning of 0.016" has taken place since 1992. This is because the 2006 UT data could not be compared directly with the 1992 data due to the difference in UT instruments and measurement technique used in 2006, and the uncertainty associated with precisely locating the 1992 UT points. A review of the 2006 data for the 106 external locations indicated that the measured local thickness is greater than the local acceptance criteria of 0.490" for pressure and 0.536" for local buckling.

As stated above, the 2006 UT data of the locally thinned areas (106 points) could not be correlated directly with the corresponding 1992 UT data. This is largely due to using a more accurate UT instrument and the procedure used to take the measurements, which involved moving the instrument within the locally thinned area in order to locate the minimum thickness in that area. In addition the inner drywell shell surface could be subject to some insignificant corrosion due to water intrusion onto the embedded shell (see discussion below). For these reasons the Oyster Creek ASME Section XI, Subsection IWE Program (B.1.27) will be further enhanced to require UT measurements of the locally thinned areas



Michael P. Gallagher, PE  
 Vice President  
 License Renewal Projects

Telephone 610.765.5958  
 www.exeloncorp.com  
 michael.p.gallagher@exeloncorp.com

An Exelon Company  
 10 CFR 50  
 10 CFR 51  
 10 CFR 54

AmerGen  
 200 Exelcn Way  
 KSA/2-E  
 Kennett Square, PA 19348  
 2130-06-20290  
 April 7, 2006

U. S. Nuclear Regulatory Commission  
 ATTN: Document Control Desk  
 Washington, DC 20555

Oyster Creek Generating Station  
 Facility Operating License No. DPR-16  
NRC Docket No. 50-219

**Subject:** Response to NRC Request for Additional Information, dated March 10, 2006,  
 Related to Oyster Creek Generating Station License Renewal Application  
 (TAC No. MC7624)

**Reference:** "Request for Additional Information for the Review of the Oyster Creek Nuclear  
 Generating Station, License Renewal Application (TAC No. MC7624)," dated  
 March 10, 2006

In the referenced letter, the NRC requested additional information related to Sections B.1.12,  
 B.2.3, 2.3, and 3.3 of the Oyster Creek Generating Station License Renewal Application (LFA).  
 Enclosed are the responses to this request for additional information.

If you have any questions, please contact Fred Polaski, Manager License Renewal,  
 at 610-765-5935.

I declare under penalty of perjury that the foregoing is true and correct.

Respectfully,

Executed on

04-07-06

Michael P. Gallagher  
 Vice President, License Renewal  
 AmerGen Energy Company, LLC

Enclosure: Response to 03/10/06 Request for Additional Information

cc: Regional Administrator, USNRC Region I, w/o Enclosure  
 USNRC Project Manager, NRR - License Renewal, Safety, w/Enclosure  
 USNRC Project Manager, NRR - License Renewal, Environmental, w/o Enclosure  
 USNRC Project Manager, NRR - OCGS, w/o Enclosure  
 USNRC Senior Resident Inspector, OCGS, w/o Enclosure  
 Bureau of Nuclear Engineering, NJDEP, w/Enclosure  
 File No. 05040

A114

**Enclosure**

**Response to 3/10/06 Request for Additional Information  
Oyster Creek Generating Station  
License Renewal Application (TAC No. MC7624)**

**RAI B.1.12-1  
RAI B.2.3-1  
RAI 2.3.1.6-1  
RAI 2.3.1.7-1  
RAI 3.3.2.1.16-1  
RAI 2.3.3.36-1**



### Corrosion in the sand bed region

The high rate of corrosion in the sand bed region was attributed to galvanic corrosion of the drywell shell caused by water retained in the sand because of lack of proper drainage. To reduce the corrosion rate, Oyster Creek initiated several corrective actions as described in item (c) below. Evaluation of these corrective actions concluded that the most effective action to reduce corrosion rate is to remove the sand from sand bed region and protect the drywell shell from additional corrosion by applying a protective coating.

Location of the UT measurements was not based on a sampling process. Instead the locations were based on UT measurements taken at all accessible locations that correspond to the sand bed region from inside the drywell to establish the thinnest area. After sand was removed in 1992, and prior to coating the shell, thickness measurements were taken in each of the 10 bays, from outside the drywell, to establish the minimum general and local thickness of the thinned shell. The measurements from inside the drywell showed that the minimum general thickness of the sand bed region is 0.800 inches, and the minimum local thickness is 0.618 inches. The measurements from outside the drywell in the sand bed region showed that the minimum general thickness is generally greater than 0.800 inches. There were local areas where the thickness is less than 0.800 inches. However the minimum average thickness in these areas is greater than 0.736 inches, which is required for satisfying ASME Code requirements. The minimum local thickness measured from outside the sand bed region is 0.603 inches. Considering measurement and instrument accuracies, it is concluded that locations examined from inside the drywell represent the condition of the sand bed region.

The results of these measurements and subsequent analysis, which considered all design basis loads and load combinations, confirmed that the "as found" condition of the drywell shell thickness satisfies ASME Section III minimum thickness requirements. Additional thickness measurements taken at all accessible locations (total of 19) from inside the drywell in 1992, 1994, and 1996 show no corrosion, or no significant corrosion (see Table -2). In addition, inspection of the protective coating on exterior surfaces of the drywell shell in the sand bed region, every other refueling outage, shows no degradation of the coating or the underlying shell.

### Corrosion of the upper region, above the sand bed region

Based on the results of approximately 1000 UT measurements, Oyster Creek continued to monitor elevations 50'-2", and 87'-5" in the regions above the sand bed region. A third elevation, 51'-10", was added to the scope of inspection after it was determined that the supplied plate thickness is slightly less than the adjacent 50'-2". For each elevation, UT measurements spaced approximately 1" within a 6"x6" array were taken from inside the drywell around the entire perimeter of each elevation. Engineering evaluation of the UT results concluded that monitoring of 12 locations would represent the drywell shell condition and provide reasonable assurance that significant corrosion would be detected prior to a loss of an intended function. This is because the 12 locations were selected considering the degree of drywell shell thinning and the minimum required thickness to satisfy ASME stress requirements. The locations are, 7 locations 50'-2", 3 locations at

elevation 87'-5", and 2 locations at elevation 51'-10". These locations are inspected from the inside of the drywell shell on a frequency of every other refueling outage.

In response to NRC Staff concern regarding whether the inspected locations represent the condition of the entire drywell, in 1990 GPU prepared a new random UT inspection plan (also known as augmented inspection) designed to address the concern. The plan was based on a non-parametric statistical approach using attribute sampling that assumes no prior knowledge of the distribution of corrosion above the sand bed region. It consisted of random UT testing of 57 plates using the 6"x6" grid. Acceptance criteria are that the mean and local thickness of the shell equals or exceeds the required minimum thickness plus a corrosion allowance necessary in order to reach the next inspection.

Inspection results using the new random inspection plan confirmed that previously monitored locations bound the condition of the drywell above the sand bed region; except one location at elevation 60'-10". This elevation was added to elevations 50'-2", 51'-10", and 87'-5" and monitored on the frequency of every other refueling outage since identified in 1992.

The augmented inspection plan, the original inspection plan, and justification for sampling techniques and statistical methodology were submitted to the NRC on November 26, 1990. In its Safety Evaluation dated November 1, 1995, the Staff noted that the licensee provided a table of UT measurement results from the 15<sup>th</sup> refueling outage inspection. This table shows the locations of the measurements, the nominal as-constructed thickness, the minimum as-measured thickness, the ASME Code required thickness and the corrosion margin available at the time. The Staff found the current program, based on the submitted information acceptable. The Staff also noted in the Safety Evaluation that since water leaking from the pools above the reactor cavity has been the cause of corrosion, the licensee should make a commitment to the effect that an additional inspection of the drywell will be performed about 3 months after discovery of significant water leakage onto the outside of the drywell shell. Oyster Creek is committed to inspect the drains for leakage during refueling outages and during plant operation. The source of water leakage will be investigated and appropriate corrective actions taken, including an evaluation of the drywell shell to ensure drywell integrity. A review of plant documentation did not provide objective evidence that the commitment has been implemented since 1998. Issue Report #348545 was issued in accordance with Oyster Creek corrective action process to document the lapse in implementing the commitment and to reinforce strict compliance with commitment implementation in the future.

During a recent walkdown of the torus by the system engineer, water was found in three 5-gallon containers that are installed to collect water leakage from the sand bed drains. Two of the 3 containers were found nearly full. The third container was approximately half full. Inspection of the drain lines shows that the lines are currently dry and that water in the containers is not due to a current water leakage.

The containers are closed such that their overflow is unlikely as confirmed by no water ponding on the floor. Thus it is concluded with reasonable assurance that the volume of

water is limited to what is contained in the containers. This small amount of water is not expected to have significant impact on the drywell shell and on the coating of the shell since the coating is designed for submerged environment. Furthermore, inspection of sand bed region coating conducted in 2004 did not indicate coating degradation or indications of drywell shell corrosion. Similarly, UT examinations on the upper region of the drywell showed a decrease in the corrosion rate since the previous inspection in 2000. Thus, the small volume of water found in the bottles should not have created an environment that would result in significant corrosion to the drywell shell. Issue Report #00470325 was issued, in accordance with Oyster Creek corrective action process, to investigate the source of water and evaluate its impact on the drywell shell.

Based on the discussion above and as indicated in the tables supplied in response to item d) below, Oyster Creek concluded that drywell corrosion is effectively managed both during the current and proposed renewed terms of plant operation. The monitored locations under the current term were subject to extensive UT measurements conducted over several years. NRC Staff found the sampling methodology to identify these locations, and the results of inspections, acceptable for the current term. The same locations will be inspected during the extended period of operation.

In summary Oyster Creek has conducted extensive examinations to identify the cause of drywell corrosion, employed a robust sampling process, quantified with reasonable assurance the extent of drywell shell thinning due to corrosion, and assessed its impact on the drywell structural integrity.

Water intrusion into the gap between the drywell shell and the drywell shield wall was identified as the cause for corrosion. Corrective actions have been taken to mitigate corrosion in the sand bed region and in the upper region of the drywell. Corrosion of the drywell shell in the sand bed region has been arrested. These actions also have effectively reduced the rate of corrosion to a negligible amount in the upper region as demonstrated by UT thickness measurements (see Table-1, and Table-2). Oyster Creek and its consultants performed stress and buckling analyses considering all design basis loads and load combinations. The results of these analyses indicate that buckling controls the minimum drywell shell thicknesses in the sand bed region while areas above the sand bed region are controlled by accident pressure membrane stresses. In both cases, the minimum measured drywell shell thickness satisfies ASME Section III requirements.

- (b) The factors considered in establishing the minimum required drywell thickness at various elevations of the drywell are described in detail in engineering analyses documented in two GE Reports, Index No. 9-1, 9-2, and 9-3, 9-4. Report Index No. 9-1, 9-2 was generated for the drywell condition with sand in the sand bed region and Report Index No. 9-3, 9-4 is for the drywell condition without sand in the sand bed region (see Attachment 2 & 3) The two reports were transmitted to the NRC Staff in December 1990 and in 1991 respectively. Report Index No. 9-3, 9-4 was revised later to correct errors identified during an internal audit and was resubmitted to the Staff in January 1992. Analysis described in Report Index No. 9-3, 9-4 (i.e., without sand) is the current applicable analysis to the drywell.

The analysis is based on the original Code of record, ASME Code, Section VIII, and Code Cases 1270N-5, 1271, and 1272N-5. The Code and the Code Cases do not provide specific guidance in two areas. The first relates to the size of a region of increased membrane stress due to thickness reductions from local or general corrosion effects, and the second pertains to the allowable stresses for Service Level C or post-accident conditions. In the first case, guidance was sought from ASME Section III, NE-3213.10. For Service Level C or post-accident conditions, the Standard Review Plan was used as guidance to develop the allowable stresses.

The analysis is based on a 36-degree section model that takes advantage of symmetry of the drywell with 10 vents. The model includes the drywell shell from the base of the sand bed region to the top of elliptical head and the vent and vent header. The torus is not included in this model because the vent bellows provide a very flexible connection, which does not allow significant structural interaction between the drywell and the torus. The analysis considered drywell geometry and materials, thickness reduction from corrosion, test loads, normal operating loads, design basis accident loads, seismic loads, refueling loads, and design basis load combinations. Pressure and temperature were in accordance with approved Technical Specification Amendment No. 165, which established a revised design basis accident pressure of 44 psig and accident temperature of 292°F. The results of the analysis show that the minimum required ASME Code thickness of the drywell shell above the sand bed region is controlled by membrane stresses and the minimum drywell shell thickness in the sand bed region is controlled by buckling. The minimum required ASME Code thicknesses above the sand bed region are shown in Table-1.

For the sand bed region, the analysis conservatively assumed that the shell thickness in the entire sand bed region has been reduced uniformly to a thickness of 0.736 inches. This thickness satisfies ASME Code requirements and considered the minimum required thickness.

As described above, the buckling analysis was performed assuming a uniform general thickness of the sand bed region of 0.736 inches. However the UT measurements identified isolated, localized areas where the drywell shell thickness is less than 0.736 inches. Acceptance for these areas was based on engineering calculation C-1302-187-5320-024.

The calculation uses a Local Wall Acceptance Criteria. This criterion can be applied to small areas (less than 12" by 12"), which are less than 0.736" thick so long as the small 12" by 12" area is at least 0.536" thick. However the calculation does not provide additional criteria as to the acceptable distance between multiple small areas. For example, the minimum required linear distances between a 12" by 12" area thinner than 0.736" but thicker than 0.536" and another 12" by 12" area thinner than 0.736" but thicker than 0.536" were not provided.

The actual data for two bays (13 and 1) shows that there are more than one 12" by 12" areas thinner than 0.736" but thicker than 0.536". Also the actual data for two bays shows that there are more than one 2 1/2" diameter areas thinner than 0.736" but thicker

than 0.490". Acceptance is based on the following evaluation.

The effect of these very local wall thickness areas on the buckling of the shell requires some discussion of the buckling mechanism in a shell of revolution under an applied axial and lateral pressure load.

To begin the discussion we will describe the buckling of a simply supported cylindrical shell under the influence of lateral pressure and axial load. As described in chapter 11 of the Theory of Elastic Stability, Second Edition, by Timoshenko and Gere, thin cylindrical shells buckle in lobes in both the axial and circumferential directions. These lobes are defined as half wave lengths of sinusoidal functions. The functions are governed by the radius, thickness and length of the cylinder. If we look at a specific thin walled cylindrical shell both the length and radius would be essentially constants and if the thickness was changed locally the change would have to be significant and continuous over a majority of the lobe so that the compressive stress in the lobe would exceed the critical buckling stress under the applied loads, thereby causing the shell to buckle locally. This approach can be easily extrapolated to any shell of revolution that would experience both an axial load and lateral pressure as in the case of the drywell. This local lobe buckling is demonstrated in The GE Letter Report "Sandbed Local Thinning and Raising the Fixity Height Analysis" where a 12 x 12 square inch section of the drywell sand bed region is reduced by 200 mils and a local buckle occurred in the finite element eigenvalue extraction analysis of the drywell. Therefore, to influence the buckling of a shell the very local areas of reduced thickness would have to be contiguous and of the same thickness. This is also consistent with Code Case 284 in Section -1700 which indicates that the average stress values in the shell should be used for calculating the buckling stress. Therefore, an acceptable distance between areas of reduced thickness is not required for an acceptable buckling analysis except that the area of reduced thickness is small enough not to influence a buckling lobe of the shell. The very local areas of thickness are dispersed over a wide area with varying thickness and as such will have a negligible effect on the buckling response of the drywell. In addition, these very local wall areas are centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the shell sand bed region which is located at the midpoint between two vents.

The acceptance criteria for the thickness of 0.49 inches confined to an area less than 2½ inches in diameter experiencing primary membrane + bending stresses is based on ASME B&PV Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular NE-3213.10 limits the meridional distance between openings without reinforcement to  $2.5 \times (\text{square root of } Rt)$ . Also Paragraph NE-3335.1 only applies to openings in shells that are closer than two times their average diameter.

The implications of these paragraphs are that shell failures at these locations from primary stresses produced by pressure cannot occur provided openings in shells have sufficient reinforcement. The current design pressure of 44 psig for drywell requires a

**From:** <George.Beck@exeloncorp.com>  
**To:** <dja1@nrc.gov>, <rkm@nrc.gov>  
**Date:** 04/05/2006 5:02:53 PM  
**Subject:** FW: Audit Q & A (Question Numbers AMP-141, 210, 356)

Note: As originally transmitted this email was undeliverable to the NRC; it exceeded the size limit. It is being retransmitted without the AMP-210.pdf. This file will be reconstituted and sent in smaller ".pdf"s; the first 11 pages are attached.

George

> -----Original Message-----

> **From:** Beck, George  
 > **Sent:** Wednesday, April 05, 2006 4:39 PM  
 > **To:** Donnie Ashley (E-mail); 'Roy Mathew (E-mail)' (E-mail)  
 > **Cc:** Ouaou, Ahmed; Hufnagel Jr, John G; Warfel Sr, Donald B; Polaski, Frederick W  
 > **Subject:** Audit Q & A (Question Numbers AMP-141, 210, 356)

> Donnie/Roy,

> Attached are the responses to AMP-210 and AMP-356 in an updated version of the reports from the AMP/AMR Audit database. Also included is a revised version of AMP-141. These answers have been reviewed and approved by Technical Lead, Don Warfel.

> Regarding AMP-210, please note:

> As pointed out in our response to NRC Question AMP-210, (8a)(1), "The 0.806" minimum average thickness verbally discussed with the Staff during the AMP audit was recorded in location 19A in 1994. Additional reviews after the audit noted that lower minimum average thickness values were recorded at the same location in 1991 (0.803") and in September 1992 (0.800"). However, the three values are within the tolerance of +/- 0.010" discussed with the Staff."

> Regarding AMP-141, please note:

> Our response to AMP-141 has been revised to reflect additional information developed during the ongoing preparation of RAI responses.

> Please let John Hufnagel or me know if you have any questions.

> George

>> <<Pages from AMP-210.pdf>>  
 >> <<AMP-141.pdf>>  
 >> <<AMP-356.pdf>>

.....  
 This e-mail and any of its attachments may contain Exelon Corporation proprietary information, which is privileged, confidential, or subject to copyright belonging to the Exelon Corporation family of Companies. This e-mail is intended solely for the use of the individual or entity to which it is addressed. If you are not the intended recipient of this e-mail, you are hereby notified that any dissemination, distribution,

copying, or action taken in relation to the contents of and attachments to this e-mail is strictly prohibited and may be unlawful. If you have received this e-mail in error, please notify the sender immediately and permanently delete the original and any copy of this e-mail and any printout. Thank You.  
\*\*\*\*\*

CC: <ahmed.ouaou@exeloncorp.com>, <john.hufnagel@exeloncorp.com>, <donacl.warfel@exeloncorp.com>, <fred.polaski@exeloncorp.com>

**Mail Envelope Properties** (44343066.C5F : 19 : 7263)

**Subject:** FW: Audit Q & A (Question Numbers AMP-141, 210, 356)  
**Creation Date:** 04/05/2006 5:01:46 PM  
**From:** <George.Beck@exeloncorp.com>

**Created By:** George.Beck@exeloncorp.com

**Recipients**

nrc.gov  
OWGWPO01.HQGWDO01  
DJA.1 (D. Ashley)

nrc.gov  
TWGWPO01.HQGWDO01  
RKM (Roy Mathew)

exeloncorp.com  
fred.polaski CC  
donald.warfel CC  
john.hufnagel CC  
ahmed.ouaou CC

**Post Office**  
OWGWPO01.HQGWDO01  
TWGWPO01.HQGWDO01

**Route**  
nrc.gov  
nrc.gov  
exeloncorp.com

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	2679	05 April, 2006 5:01:46 PM
TEXT.htm	5457	
Pages from AMP-210.pdf	64593	
AMP-141.pdf	47353	
AMP-356.pdf	71556	
Mime.822	262768	

**Options**  
**Expiration Date:** None  
**Priority:** Standard  
**Reply Requested:** No  
**Return Notification:** None

**Concealed Subject:** No  
**Security:** Standard



## ***NRC Information Request Form***

**Item No**  
AMP-210

**Date Received:**      **Source**  
1/24/2006      AMP Audit

**Topic:**  
IWE

**Status:**      Open

**Document References:**  
B.1.27

**NRC Representative**      Morante, Rich

**AmerGen (Took Issue):**      Hufnagel, Joh

**Question**

Pages 25 through 31 of the PBD present a discussion of the OCGS operating experience.

(8a)The following statements related to drywell corrosion in the sand bed region need further explanation and clarification:

As a result of the presence of water in the sand bed region, extensive UT thickness measurements (about 1000) of the drywell shell were taken to determine if degradation was occurring. These measurements corresponded to known water leaks and indicated that wall thinning had occurred in this region.

Please explain the underlined statement. Were water leaks limited to only a portion of the circumference? Was wall thinning found only in these areas?

After sand removal, the concrete surface below the sand was found to be unfinished with improper provisions for water drainage. Corrective actions taken in this region during 1992 included; (1) cleaning of loose rust from the drywell shell, followed by application of epoxy coating and (2) removing the loose debris from the concrete floor followed by rebuilding and reshaping the floor with epoxy to allow drainage of any water that may leak into the region. UT measurements taken from the outside after cleaning verified loss of material projections that had been made based on measurements taken from the inside of the drywell. There were, however, some areas thinner than projected; but in all cases engineering analysis determined that the drywell shell thickness satisfied ASME code requirements.

Please describe the concrete surface below the sand that is discussed in paragraph above.

Please provide the following information:

- (1) Identify the minimum recorded thickness in the sand bed region from the outside inspection, and the minimum recorded thickness in the sand bed region from the inside inspections. Is this consistent with previous information provided verbally? (.806 minimum)
- (2) What was the projected thickness based on measurements taken from the inside?
- (3) Describe the engineering analysis that determined satisfaction of ASME code requirements and identify the minimum required thickness value. Is this consistent with previous information provided verbally? (.733 minimum)
- (4) Is the minimum required thickness based on stress or buckling criteria?
- (5) Reconcile and compare the thickness measurements provided in (1) and (3) above with the .736 minimum corroded thickness that was used in the NUREG-1540 analysis of the degraded Oyster

## ***NRC Information Request Form***

- (1) Identify the minimum recorded thickness in the sand bed region from the outside inspection, and the minimum recorded thickness in the sand bed region from the inside inspections. Is this consistent with previous information provided verbally? (.806 minimum)
- (2) What was the projected thickness based on measurements taken from the inside?
- (3) Describe the engineering analysis that determined satisfaction of ASME code requirements and identify the minimum required thickness value. Is this consistent with previous information provided verbally? (.733 minimum)
- (4) Is the minimum required thickness based on stress or buckling criteria?
- (5) Reconcile and compare the thickness measurements provided in (1) and (3) above with the .736 minimum corroded thickness that was used in the NUREG-1540 analysis of the degraded Oyster Creek sand bed region.

**Response:**

1. The minimum recorded thickness in the sand bed region from outside inspection is 0.618 inches. The minimum recorded thickness in the sand bed region from inside inspections is 0.603. These minimum recorded thicknesses are isolated local measurement and represent a single point UT measurement. The 0.806 inches thickness provided to the Staff verbally is an average minimum general thickness calculated based on 49 UT measurements taken in an area that is approximately 6"x 6". Thus the two local isolated minimum recorded thicknesses cannot be compared directly to the general thickness of 0.806".

The 0.806" minimum average thickness verbally discussed with the Staff during the AMP audit was recorded in location 19A in 1994. Additional reviews after the audit noted that lower minimum average thickness values were recorded at the same location in 1991 (0.803") and in September 1992 (0.800"). However, the three values are within the tolerance of +/- 0.010" discussed with the Staff.

2. The minimum projected thickness depends on whether the trended data is before or after 1992 as demonstrated by corrosion trends provided in response to NRC Question #AMP-356. For license renewal, using corrosion rate trends after 1992 is appropriate because of corrosion mitigating measures such as removal of the sand and coating of the shell. Then, using corrosion rate trends based on 1992, 1994, and 1996 UT data; and the minimum average thickness measured in 1992 (0.800"), the minimum projected average thickness through 2009 and beyond remains approximately 0.800 inches. The projected minimum thickness during and through the period of extended operation will be reevaluated after UT inspections that will be conducted prior to entering the period of extended operation, and after the periodic UT inspection every 10 years thereafter.

3. The engineering analysis that demonstrated compliance to ASME code requirements was performed in two parts, Stress and Stability Analysis with Sand, and Stress and Stability Analyses without Sand. The analyses are documented in GE Reports Index No. 9-1, 9-2, 9-3, and 9-4, were transmitted to the NRC Staff in December 1990 and in 1991 respectively. Index No. 9-3 and 9-4, were revised later to correct errors identified during an internal audit and were resubmitted to the Staff in January 1992 (see attachment 1 & 2). The analyses are briefly described below.

The drywell shell thickness in the sand bed region is based on Stability Analysis without Sand. As

## ***NRC Information Request Form***

described in detail in attachment 1 & 2, the analysis is based on a 36-degree section model that takes advantage of symmetry of the drywell with 10 vents. The model includes the drywell shell from the base of the sand bed region to the top of elliptical head and the vent and vent header. The torus is not included in this model because the bellows provide a very flexible connection, which does not allow significant structural interaction between the drywell and the torus. The analysis conservatively assumed that the shell thickness in the entire sand bed region has been reduced uniformly to a thickness of 0.736 inches.

As discussed with the Staff during the AMP audit, the basic approach used in the buckling evaluation follows the methodology outlined in ASME Code Case N-284 revision 0 that was reconciled later with revision 1 of the Code Case. Following the procedure of this Code Case, the allowable compressive stress is evaluated in three steps. In the first step, a theoretical buckling stress is determined, and secondly modified using appropriate capacity and plasticity reduction factors. In the final step, the allowable compressive stress is obtained by dividing the buckling stress calculated in the second step by a safety factor of 2.0 for Design and Level A & B service conditions and 1.67 Level C service conditions.

Using the approach described above, the analysis shows that for the most severe design basis load combinations, the limits of ASME Section III, Subsection NE 3213.10 are fully met. For additional details refer to Attachment 1 & 2.

As described above, the buckling analysis was performed assuming a uniform general thickness of the sand bed region of 0.736 inches. However the UT measurements identified isolated, localized areas where the drywell shell thickness is less than 0.736 inches. Acceptance for these areas was based on engineering calculation C-1302-187-5320-024.

The calculation uses a "Local Wall Acceptance Criteria". This criterion can be applied to small areas (less than 12" by 12"), which are less than 0.736" thick so long as the small 12" by 12" area is at least 0.536" thick. However the calculation does not provide additional criteria as to the acceptable distance between multiple small areas. For example, the minimum required linear distances between a 12" by 12" area thinner than 0.736" but thicker than 0.536" and another 12" by 12" area thinner than 0.736" but thicker than 0.536" were not provided.

The actual data for two bays (13 and 1) shows that there are more than one 12" by 12" areas thinner than 0.736" but thicker than 0.536". Also the actual data for two bays shows that there are more than one 2 1/2" diameter areas thinner than 0.736" but thicker than 0.490". Acceptance is based on the following evaluation.

The effect of these very local wall thickness areas on the buckling of the shell requires some discussion of the buckling mechanism in a shell of revolution under an applied axial and lateral pressure load.

To begin the discussion we will describe the buckling of a simply supported cylindrical shell under the influence of lateral pressure and axial load. As described in chapter 11 of the Theory of Elastic Stability, Second Edition, by Timoshenko and Gere, thin cylindrical shells buckle in lobes in both the

## ***NRC Information Request Form***

axial and circumferential directions. These lobes are defined as half wave lengths of sinusoidal functions. The functions are governed by the radius, thickness and length of the cylinder. If we look at a specific thin walled cylindrical shell both the length and radius would be essentially constants and if the thickness was changed locally the change would have to be significant and continuous over a majority of the lobe so that the compressive stress in the lobe would exceed the critical buckling stress under the applied loads, thereby causing the shell to buckle locally. This approach can be easily extrapolated to any shell of revolution that would experience both an axial load and lateral pressure as in the case of the drywell. This local lobe buckling is demonstrated in The GE Letter Report "Sandbed Local Thinning and Raising the Fixity Height Analysis" where a 12 x 12 square inch section of the drywell sand bed region is reduced by 200 mils and a local buckle occurred in the finite element eigenvalue extraction analysis of the drywell. Therefore, to influence the buckling of a shell the very local areas of reduced thickness would have to be contiguous and of the same thickness. This is also consistent with Code Case 284 in Section -1700 which indicates that the average stress values in the shell should be used for calculating the buckling stress. Therefore, an acceptable distance between areas of reduced thickness is not required for an acceptable buckling analysis except that the area of reduced thickness is small enough not to influence a buckling lobe of the shell. The very local areas of thickness are dispersed over a wide area with varying thickness and as such will have a negligible effect on the buckling response of the drywell. In addition, these very local wall areas are centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the shell sand bed region which is located at the midpoint between two vents.

The acceptance criteria for the thickness of 0.49 inches confined to an area less than 2½ inches in diameter experiencing primary membrane + bending stresses is based on ASME B&PV Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular NE-3213.10 limits the meridional distance between openings without reinforcement to  $2.5 \times (\text{square root of } Rt)$ . Also Paragraph NE-3335.1 only applies to openings in shells that are closer than two times their average diameter.

The implications of these paragraphs are that shell failures at these locations from primary stresses produced by pressure cannot occur provided openings in shells have sufficient reinforcement. The current design pressure of 44 psig for drywell requires a thickness of 0.479 inches in the sand bed region of the drywell. A review of all the UT data presented in Appendix D of the calculation indicates that all thicknesses in the drywell sand bed region exceed the required pressure thickness by a substantial margin. Therefore, the requirements for pressure reinforcement specified in the previous paragraph are not required for the very local wall thickness evaluation presented in Revision 0 of Calculation C-1302-187-5320-024.

Reviewing the stability analyses provided in both the GE Report 9-4 and the GE Letter Report Sand bed Local Thinning and Raising the Fixity Height Analysis and recognizing that the plate elements in the sand bed region of the model are 3" x 3" it is clear that the circumferential buckling lobes for the

## ***NRC Information Request Form***

drywell are substantially larger than the 2 ½ inch diameter very local wall areas. This combined with the local reinforcement surrounding these local areas indicates that these areas will have no impact on the buckling margins in the shell. It is also clear from the GE Letter Report that a uniform reduction in thickness of 27% to 0.536" over a one square foot area would only create a 9.5% reduction in the load factor and theoretical buckling stress for the whole drywell resulting in the largest reduction possible. In addition, to the reported result for the 27% reduction in wall thickness, a second buckling analysis was performed for a wall thickness reduction of 13.5% over a one square foot area which only reduced the load factor and theoretical buckling stress by 3.5% for the whole drywell resulting in the largest reduction possible. To bring these results into perspective a review of the NDE reports indicate there are 20 UT measured areas in the whole sand bed region that have thicknesses less than the 0.736 inch thickness used in GE Report 9-4 which cover a conservative total area of 0.68 square feet of the drywell surface with an average thickness of 0.703" or a 4.5% reduction in wall thickness. Therefore, to effectively change the buckling margins on the drywell shell in the sand bed region a reduced thickness would have to cover approximately one square foot of shell area at a location in the shell that is most susceptible to buckling with a reduction in thickness greater than 25%. This leads to the conclusion that the buckling of the shell is unaffected by the distance between the very local wall thicknesses, in fact these local areas could be contiguous provided their total area did not exceed one square foot and their average thickness was greater than the thickness analyzed in the GE Letter Report and provided the methodology of Code Case N284 was employed to determine the allowable buckling load for the drywell. Furthermore, all of these very local wall areas are centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the shell sand bed region, which is located at the midpoint between two vents.

The minimum thickness of 0.733" is not correct. The correct minimum thickness is 0.736".

4. The minimum required thickness for the sand bed region is controlled by buckling.

5. We cannot reconcile the difference between the current (lowest measured) of 0.736" in NUREG-1540 and the minimum measured thickness of 0.806 inches we discussed with the Staff. Perhaps the value in NUREG-1540 should be labeled minimum required by the Code, as documented in several correspondences with the Staff, instead of lowest measured. In a letter dated September 15, 1995, GPU provided the Staff a table that lists sand bed region thicknesses. The table indicates that nominal thickness is 1.154", the minimum measured thickness in 1994 is 0.806", and the minimum thickness required by Code is 0.736". These thicknesses are consistent with those discussed with the Staff during the AMP/AMR audit.

Question: NUREG-1540, published in April 1996, includes the following statements related to corrosion of the Oyster Creek sand bed region: (page vii) However, to assure that these measures are effective, the licensee is required to perform periodic UT measurements, and (page 2) As assurance that the corrosion rate is slower than the rate obtained from previous measurements, GPU is committed to make UT measurements periodically. Please reconcile the aging management commitment (one-time UT inspection and monitoring of the condition of the coating) with the apparent requirement/commitment documented in NUREG-1540. Please reconcile the aging management commitment (one-time UT inspection and monitoring of the condition of the coating) with the apparent requirement/commitment documented in NUREG-1540.

---

---

# Safety Evaluation Report

Related to the License Renewal of Oyster Creek  
Generating Station

Docket No. 50-219

AmerGen Energy Company, LLC

---

---

U.S. Nuclear Regulatory Commission

Office of Nuclear Reactor Regulation

March 2007



the drywell shell in the inspection trenches in drywell bays #5 and #17. AmerGen will monitor the two trenches for the presence of water during each refueling outage. The staff identified this commitment item as a license condition.

#### Ultrasonic Testing Measurement Issues

In the sand pocket region of the drywell shell, the most susceptible bays are incorporated in the sampling. However, the staff believes that readings should be taken at vulnerable locations and that UT techniques are reliable. The first issue is addressed as part of Open Item 4.7.2-1.2 and the second issue is addressed below.

The second item is that a review of UT data indicates that the UT measurements taken from inside the drywell after 1992 show a general increase in the metal thickness. In some cases, the average increase is as much as 40 mils in a 2-year timeframe. In general, it appears that the UT measurements taken after 1992 require proper calibration, considering the coatings on both sides of the drywell shell. The staff requested that the applicant address this issue during a public meeting held June 1, 2006.

In its response dated June 20, 2006, the applicant provided the following discussion of sensitivities involved with the UT measurement process and how they will be minimized in the future:

UT Instrumentation Uncertainties. The UT instrumentation, which includes the transducer, cable and ultrasonic unit, will be calibrated to within approximately +/- 0.010 inches. Exelon Procedure (ER-AA-335-004) step 4.1.3 requires that the UT instruments must be checked within 2% of the calibration standard (block) prior to use. For the sand bed region, which is nominally 1" thick, a 1-inch thick calibration standard block is used. This results in checking the UT instrument to within 0.020" inches or +/- 0.010". UT instrumentation accuracy is verified under controlled conditions where UT thickness readings are performed on calibration blocks. The calibration blocks have been precisely machined to prescribed thicknesses, which are then verified by micrometer readings.

Actual Drywell Surface Roughness and UT Probe Location Repeatability. Due to the corrosion, the outside surface of the Drywell Vessel is not smooth and uniform. The surface condition is indicative of general corrosion, which is rough with high and low points spaced very closely together. This profile was verified when the sand was removed in 1992. The UT Instrumentation probes are 7/16" in diameter and are dual element transducers (i.e. half transmits sound and the other half receives). The probes emit a focused beam that measures an area significantly smaller than 7/16" diameter and will record the thinnest reading within that area.

Because the surface roughness of the drywell within this 7/16" diameter can vary, the probe must be placed at precisely the same location to precisely repeat a thickness reading. A slight shift of the probe will result in a reading which is correct, but different from a previous reading.

The variability associated with this factor is reduced by the use of the stainless steel template. The template has been manufactured with holes in a 7 by 7 pattern on 1 inch centers. Each of the 49 holes has been machined with a diameter so that the UT probe fits within each hole snugly. The templates are machined with 1/16" wide slits on each

edge of the template at 0, 90, 180, and 270 degrees. During inspections the slits in the template are lined up with permanent marks that were placed on the drywell shell when the location was originally inspected. The UT readings are then taken by placing the probe inside each hole in the template.

Inspection procedures require that NDE personnel performing the inspection place the template precisely on the permanent markings.

---

**Actual Drywell Surface Roughness and UT Probe Rotation.** The UT probe sends the signal from one side of the probe and receives the signal on the other side. The probe must be oriented in the same plane in order to measure exactly the same point. Test data taken on a mock up with similar roughness showed that a variance up to 0.016 inch was noted when rotating the probe 360 degrees over the same spot. Therefore, a slight rotation of the probe will result in a reading, which is correct, but different from a previous reading.

Inspection procedures require that NDE personnel performing the inspection place the probe in the same orientation.

---

**Temperature Effects.** Significant temperature differences between inspections may result in a shift in the material thickness. Therefore, the inspection specification will require that NDE personnel performing the inspection record the surface temperature of the area that is inspected.

---

**Batteries.** Inspection specifications require the installation of new batteries prior to each series of inspections.

---

**NDE Technician.** Inspection specifications require that personnel conducting UT examinations be qualified in accordance with Exelon Procedure ER-AA-335-004.

---

**Calibration Block.** Exelon Procedure ER-AA-335-004 requires that calibration blocks used during the inspection be inspected to verify that the ultrasonic response equals the physical measurement.

---

**Internal Surface Cleanliness.** The inspection areas are covered with a qualified grease to protect the examination surface from rusting between inspection periods. The grease must be removed prior to the inspection and reapplied after the inspection. Tests performed in April and May of 2006 show that the presence of the grease will increase the readings as much as 12 mils. In 1996, the governing specification did not clearly specify the requirement to remove the grease prior to the inspection. Therefore it is possible that the requirement to remove the grease was not communicated to the contractor, and that the contractor who performed the 1996 inspection may have not removed the grease.

The inspection procedures will clearly require that personnel conducting UT examinations remove the grease prior to performing the examination.

---

**UT Unit Settings.** It is possible that the ultrasonic unit can be set in a "high gain" setting which may bias the machine into including the external coating as part of the thickness. Future inspections will use modern "state of the art" UT units that do not have gain



settings.

Identification of the Physical Inspection Location. There is a potential that inspection locations may be mislabeled on the data sheets. The inspection procedures uniquely and clearly identify each inspection location and provide the specific instruction as to the area's location.

Data Analysis. The above potential variables will be considered in the analysis of the data. The analysis not only determines a mean for each grid or sub-grid, but also the variance of the means. These variances will be compared to past inspections to ensure consistency. The mean and the variance are compared to the acceptance criteria.

In addition, the mean UT thickness values for a current inspection will be computed and compared to the previous inspection prior to restarting from an outage. If data anomalies similar to 1996 are identified corrective actions will be taken, including new UT measurements, as necessary, to ensure accuracy of measurements.

Based on the applicant's discussion of the variables involved in the UT results, the staff finds it reasonable to conclude that the anomalous readings of 1994 and 1996 could be attributed to one or more of the factors enumerated in the discussion. The staff was concerned about systematic corrections to the UT measurements and could not determine the basis for the applicant's use of the anomalous readings nor systematic corrections. The applicant could not isolate the factors that contributed to these anomalous results; therefore, it plans to utilize the lessons learned from the experience for the future UT examinations. On the basis of the applicant's written response, the staff determined that its concerns have been resolved.

#### 4.7.2.2.2 Minimum Drywell Thickness

In RAI 4.7.2-1 dated March 10, 2006, the staff requested that the applicant provide a summary of the factors considered in establishing the minimum required drywell thickness.

In its response dated April 7, 2006, the applicant explained that the factors considered in establishing the minimum required drywell thickness at various elevations of the drywell are described in detail in engineering analyses documented in two GE reports, Index Nos. 9-1, 9-2, and 9-3, 9-4. Report Index No. 9-1, 9-2 was generated for the drywell condition with sand in the sand bed region and Report Index No. 9-3, 9-4 addressed the drywell condition without sand in the sand bed region. The two reports were transmitted to the staff in December 1990 and 1991, respectively. Report Index No. 9-3, 9-4 was revised later to correct errors identified during an internal audit and was resubmitted to the staff in January 1992. The analysis described in Report Index No. 9-3, 9-4 (i.e., without sand) is the current applicable analysis for the drywell.

In its response the applicant also noted that it based the analysis on the original code of record, ASME Code, Section VIII, and Code Cases 1270N-5, 1271-N, and 1272N-5. The ASME Code and its Code Cases do not provide specific guidance in two areas. The first relates to the size of a region of increased membrane stress due to thickness reductions from local or general corrosion effects, and the second pertains to the allowable stresses for Service Level C or post-accident conditions. In the first case, guidance was sought from ASME Code Section III, NE-3213.10. For Service Level C or post-accident conditions, the SRP-LR was used as guidance to develop the allowable stresses. Additionally, the applicant summarized the analysis efforts in the following paragraphs:

The analysis is based on a 36-degree section model that takes advantage of symmetry of the drywell with 10 vents. The model includes the drywell shell from the base of the sand bed region to the top of elliptical head and the vent and vent header. The torus is not included in this model because the vent bellows provide a very flexible connection, which does not allow significant structural interaction between the drywell and the torus. The analysis considered drywell geometry and materials, thickness reduction from corrosion, test loads, normal operating loads, design basis accident loads, seismic loads, refueling loads, and design basis load combinations. Pressure and temperature were in accordance with approved Technical Specification Amendment No. 165, which established a revised design bases accident pressure of 44 psig and accident temperature of 292°F. The results of the analysis show that the minimum required ASME Code thickness of the drywell shell above the sand bed region is controlled by membrane stresses and the minimum drywell shell thickness in the sand bed region is controlled by buckling. The minimum required ASME Code thicknesses above the sand bed region are shown in Table 1 (attached to the response). For the sand bed region, the analysis conservatively assumed that the shell thickness in the entire sand

required thickness.

As described above, the buckling analysis was performed, assuming a uniform general thickness of the sand bed region of 0.736 inches. However, the UT measurements identified isolated, localized areas where the drywell shell thickness is less than 0.736 inches. Acceptance for these areas was based on engineering calculation C-1 302-1 87-5320-024. The calculation uses a "Local Wall Acceptance Criteria." This criterion can be applied to small areas (less than 10" by 10") which are less than 0.736 inches thick. The calculation is based on

length and radius would be essentially constants and if the thickness was changed locally, the change would have to be significant and continuous over a majority of the lobe so that the compressive stress in the lobe would exceed the critical buckling stress under the applied loads, thereby causing the shell to buckle locally. This approach can be easily extrapolated to any shell of revolution that would experience both an axial load and lateral pressure as in the case of the drywell. This local lobe buckling is demonstrated in the GE Letter Report "Sandbed Local Thinning and Raising the Fixity Height Analysis" where a 12 x 12 square inch section of the drywell sand bed region is reduced by 200 mils and a local buckle occurred in the finite element eigenvalue extraction analysis of the drywell. Therefore, to influence the buckling of a shell, the very local areas of reduced thickness would have to be contiguous and of the same thickness. This is also consistent with Code Case 284 in Section-1700 which indicates that the average stress values in the shell should be used for calculating the buckling stress. Therefore, an acceptable distance between areas of reduced thickness is not required for an acceptable buckling analysis except that the area of reduced thickness is small enough not to influence a buckling lobe of the shell. The very local areas of thickness are dispersed over a wide area with varying thickness and as such will have a negligible effect on the buckling response of the drywell. In addition, these very local wall areas are centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the shell sand bed region which is located at the midpoint between two vents.

The acceptance criteria for the thickness of 0.49 inches confined to an area less than 2½ inches in diameter experiencing primary membrane + bending stresses is based on ASME Boiler and Pressure Vessel (B&PV) Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement-of-Multiple Openings. The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular, NE-3213.10 limits the meridional distance between openings without reinforcement to 2.5 x (square root of Rt). Also, Paragraph NE-3335.1 only applies to openings in shells that are closer than two times their average diameter. The implications of these paragraphs are that shell failures at these locations from primary stresses produced by pressure cannot occur provided openings in shells have sufficient reinforcement. The current design pressure of 44 psig for the drywell requires a thickness of 0.479 inches in the sand bed region of the drywell. A review of all the UT data presented in Appendix D of the calculation indicates that all thicknesses in the drywell sand bed region exceed the required pressure thickness by a substantial margin. Therefore, the requirements for pressure reinforcement specified in the previous paragraph are not required for the very local wall thickness evaluation presented in Revision 0 of Calculation C-1302-187-5320-024.

Reviewing the stability analyses provided in both the GE Report 9-4 and the GE Letter Report, "Sand bed Local Thinning and Raising the Fixity Height Analysis," and recognizing that the plate elements in the sand bed region of the model are 3" x 3", it is clear that the circumferential buckling lobes for the drywell are

substantially larger than the 2½ inch diameter very local wall areas. This, combined with the local reinforcement surrounding these local areas, indicates that these areas will have no impact on the buckling margins in the shell. It is also clear from the GE Letter Report that a uniform reduction in thickness of 27 percent to 0.536" over a one square foot area would only create a 9.5 percent reduction in the load factor and theoretical buckling stress for the whole drywell resulting in the largest reduction possible. In addition to the reported result for the 27 percent reduction in wall thickness, a second buckling analysis was performed for a wall thickness reduction of 13.5 percent over a one square foot area which only reduced the load factor and theoretical buckling stress by 3.5 percent for the whole drywell, resulting in the largest reduction possible. To bring these results into perspective, a review of the nondestructive examination (NDE) reports indicates that there are 20 UT measured areas in the whole sand bed region that have thicknesses less than the 0.736 inch used in GE Report 9-4, which cover a conservative total area of 0.68 square feet of the drywell surface with an average thickness of 0.703" or a 4.5 percent reduction in wall thickness.

Therefore, to effectively change the buckling margins on the drywell shell in the sand bed region a reduced thickness would have to cover approximately one square foot of shell area at a location in the shell that is most susceptible to buckling with a reduction in thickness greater than 25 percent. This leads to the conclusion that the buckling of the shell is unaffected by the distance between the very local wall thicknesses, in fact these local areas could be contiguous provided their total area did not exceed one square foot and their average thickness was greater than the thickness analyzed in the GE Letter Report, and provided the methodology of Code Case N284 was employed to determine the allowable buckling load for the drywell. Furthermore, all of these very local wall areas are centered about the vents, which significantly stiffen the shell. This stiffening effect limits the shell buckling to a point in the shell sand bed region, which is located at the midpoint between two vents.

In summary, the applicant noted that the minimum required drywell shell thickness is based on an analysis conducted in accordance with ASME Code. Factors considered include drywell geometry, material of construction, reduced wall thickness due to corrosion, and applicable design-basis loads and load combinations. Accident pressure and temperature are 44 psig and 292 °F, respectively, in accordance with the approved technical specification amendment No. 165.

In a letter dated April 7, 2006, the applicant responded to RAI 4.7.2-1. In its response the applicant stated that the minimum required thicknesses of the drywell shell above the sand bed region shown in Table-1 of the response are controlled by membrane stresses. The minimum required general drywell shell thickness in the sand bed region of 0.736 inch is controlled by buckling. Localized areas in the sand bed region where the thickness is less than 0.736 inch are evaluated against a local thickness acceptance criteria (0.49 inch) developed based on ASME Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2, "Gross Structural Discontinuity," NE-3213.10, "Local Primary Membrane Stress," NE-3332.1, "Openings Not Requiring Reinforcement," NE-3332.2, "Required Area of Reinforcement," and NE-3335.1, "Reinforcement of Multiple Openings." Application of these ASME Code sections is justified as discussed above, and specific buckling sensitivity analysis results support the conclusion that, on an average wall thickness basis, buckling of the shell is unaffected by local wall thickness areas

as these are distributed over the sand bed region.

The staff reviewed the cited analysis reports to ensure that the parameters used and the assumptions made in the analysis are valid for the period of extended operation. However, based on the review conducted, the staff requested that the applicant provide additional information to address certain gross assumptions.

Attachment 1A of the GPU letter dated November 26, 1990, makes a statistical evaluation of the UT measurement data taken up to 1990. On the cover page of the report, GPU Nuclear Corporation states a disclaimer, "the work is conducted by an individual(s) for use by GPU. Neither GPU nor the authors of the report warrant that the report is complete or accurate ...." In view of this disclaimer, the staff at a public meeting on June 1, 2006, asked the applicant to provide a detailed description of the way the UT measurement data, whether taken as part of the 6-inch by 6-inch grid, or isolated readings, were evaluated and used in performing the analysis.

In its response dated June 20, 2006, the applicant clarified the use of the statistical evaluation as follows:

The disclaimer noted by the NRC staff is on the cover page of Technical Data Report (TDR) No. 948 Revision 1, "Statistical Analysis of the Drywell Thickness Data." The disclaimer statement is a standard clause that was placed on TDRs developed in accordance with the applicable GPUN procedure at the time. AmerGen points out that TDR No. 1027, which is also a part of Attachment 1A includes the same disclaimer. The disclaimer was intended to reinforce that TDRs are not design basis documents and were not design verified in accordance with the GPUN QA Program. In this case TDR 948 was developed to summarize the initiative that surveyed the drywell and that assessed initial corrosion rates based on data collected from 1986 through December 1988. However this TDR did not serve as the design basis document, which demonstrated the drywell shell met design basis requirements. The TDR in Section 1 (Introduction/Background) explains that the TDR documents the assumptions, methods and results of the statistical analysis used to evaluate the corrosion rates. The section then states that the complete analysis is documented in calculation C-1302-187-5300-005.

Calculation C-1302-187-5300-005, "Statistical Analysis of Drywell Thickness Data Thru 12-31-88" did serve as the design basis document, which demonstrated the drywell shell met design basis requirements. This calculation was developed and design verified in accordance with the GPUN QA Program and is approximately 200 pages long. A review of the information contained in the TDR Section 4.6 (Summary of Conclusion) shows that it is consistent with the information in Section 2 (Summary of Results) in calculation C-1302-0187-5300-005. Thus, the information in the TDR No. 948 represents design quality information.

In response to the NRC's question on how the UT measurement data were evaluated and used in the drywell analysis, AmerGen provided a description of how the 49-point array statistical analysis was performed in response to NRC Q&A #AMP-356, item (4). In that response, AmerGen stated that the methodology and acceptance criteria that are applied to each grid of point thickness readings, including both global (entire array) evaluation and local (subregion of array) are

described in engineering specification IS-328227-004 and in calculation No. C-1302-187-5300-011, "Statistical Analysis of Drywell Thickness Data Thru 4-24-90". This calculation is the more recent version of calculation C-1302-187-5300 and has been submitted by AmerGen to the NRC.

These two documents were submitted to the NRC in a letter dated November 26, 1990 and provided to the Staff during the AMP/AMR audit. A brief summary of the methodology and acceptance criteria is described below.

The initial locations identified in 1986 and 1987 where corrosion loss was most severe were selected for repeat inspection over time to measure corrosion rates. For locations where the initial investigations found significant wall thinning, UT inspection consisted of 49 individual UT data points equally spaced over a 6"x 6" area. Each new set of 49 values was then tested for normal distribution. If the data was normally distributed, then the mean value of the 49 points was calculated and used to represent the general drywell shell thickness in the tested area. If the 49 points were not normally distributed, then the grid was subdivided into datasets (usually 2, top and bottom) that were normally distributed. The mean value for each dataset was then calculated. The minimum mean value was compared to the minimum required thickness as described below.

The mean values of each grid were then compared to the required minimum uniform thickness criteria of 0.736 inches. In addition each individual reading was compared to the local minimum required criteria of 0.490 inches. The basis for the required minimum uniform thickness criteria and the local minimum required criteria is provided in response to NRC Question #AMP-210. A decrease in the mean value over time is representative of corrosion. If corrosion does not exist, the mean value will not vary with time, although random variations in the UT measurements as a result of such factors as variables in the inspection process and in environmental conditions may occur. If corrosion is continuing, the mean thickness will decrease linearly with time. Therefore the curve fit of the data is tested to determine if linear regression is appropriate, in which case the corrosion rate is equal to the slope of the line. If a slope exists, then upper and lower 95% confidence intervals of the curve fit are calculated. The lower 95% confidence interval is then projected into the future and compared to the required minimum uniform thickness criteria of 0.736 inches.

A process similar to that described above is applied to the thinnest individual reading in each grid. The lowest reading taken is also verified against the local minimum thickness requirement. Then the curve fit of the data is tested to determine if linear regression is appropriate. If a slope exists, then the lower 95% confidence interval is then projected into the future and compared to the required minimum local thickness criteria of 0.490 inches.

The staff finds that the applicant has provided an explanation of the documents used for the design basis calculations. Furthermore, the applicant provided the process used in establishing the minimum thickness of the drywell used in the 1991 GE analysis. Based on the discussion provided above, the staff finds the applicant's historical method of determining the minimum required wall thickness acceptable because these processes use recognized industry standards for performance and evaluation of results. On the basis of the applicant's written response, the

# Exelon

Nuclear

CC-AA-309-1001  
Revision 2

Design Analysis (Major Revision)		Last Page No. * 1 of 184 <b>183</b>	
Analysis No.:	G-1302-187-5320-024	Revision: *	2 <b>OT 3/20/07</b>
Title:	O.C. Drywell Ext. UT Evaluation in Sandbed		
EC/EOR No.:	06-01078	Revision: *	0
Station(s): *	Oyster Creek	Component(s): *	
Unit No.:	1		
Discipline: *	Mechanical		
Descrip. Code/Keyword: *			
Safety/QA Class: *	Q		
System Code: *	187		
Structure: *	Drywell		
<b>CONTROLLED DOCUMENT REFERENCES *</b>			
Document No.:	From/To	Document No.:	From/To
GE Report Index 9-3	From		
GE Report Index 9-4	From		
GE Letter Report PC-0391407	From		
Is this Design Analysis Safeguards Information? * Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, see SY-AA-101-106 Does this Design Analysis contain Unverified Assumptions? * Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, AT/AR#: _____ This Design Analysis SUPERCEDES: * N/A In its entirety.			
Description of Revision (list affected pages for partials): * See the Summary of Change Sheet, which is attached.			
Preparer: *	Peter Tamburo	<i>P. Tamburo</i>	3/26/07
Method of Review: *	Detailed Review <input checked="" type="checkbox"/>	Alternate Calculations (attached) <input type="checkbox"/>	Testing <input type="checkbox"/>
Reviewer: *	<i>JULIE A. BARNWELL</i>	<i>John Chalk</i>	2-27-07
Review Notes: *	Independent review <input checked="" type="checkbox"/>	Peer review <input type="checkbox"/>	5/18/07
Calculation was reviewed for adequacy of methodology, new data entry accuracy, and spot checking of mathematical computations. A comparison with previous revision was made. Based on my review and successful resolution of technical comments, I find the calculation acceptable.			
(For External Analyses Only)	External Approver: * <i>NA</i>		
Exelon Reviewer: *	<i>NA</i>		
Is a Supplemental Review Required? * Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, complete Attachment 3			
Exelon Approver: *	<i>F.H. Ray</i>	<i>F. H. Ray</i>	5/18/07

TITLE O.C. Drywell Ext. UT Evaluation in Sandbed

REV	SUMMARY OF CHANGE	APPROVAL	DATE
2	<p>A complete revision to incorporate 2006 data of the same inspection locations. In addition the calculation section for each bay now includes a spatial evaluation of the data. Also the calculation section for each bay now includes an additional evaluation with respect to the amount of material that is less than 0.736" and its location with respect to the original calculated stress locations.</p> <p>Revision bars are not shown since revision 2 affects most pieces of Revision 1.</p>	<p><i>P. T. L.</i> Pete Tamburro</p> <p><i>J. Abramovic</i> J. Abramovic</p> <p><i>Howie Ray</i> Howie Ray</p>	<p>2/28/07</p> <p>3-29-07</p> <p>5/18/07</p>



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1902-187-5320-024	Rev. No. 2	Sheet No. 3 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

### Table of Contents

Section	Page
1.0 PROBLEM STATEMENT:	4
2.0 SUMMARY OF RESULTS:	4
3.0 REFERENCE:	6
4.0 ASSUMPTIONS AND BASIC DATA:	6
5.0 DESIGN INPUTS:	8
6.0 METHODS OF ANALYSIS:	10
7.1 UT EVALUATION BAY #1:	20
7.3 UT EVALUATION BAY #3:	35
7.5 UT EVALUATION BAY #5:	40
7.7 UT EVALUATION BAY #7:	44
7.9 UT EVALUATION BAY #9:	48
7.11 UT EVALUATION BAY #11:	52
7.13 UT EVALUATION BAY #13:	56
7.15 UT EVALUATION BAY #15:	70
7.17 UT EVALUATION BAY #17:	80
7.19 UT EVALUATION BAY #19:	90

Appendix A: Summary Of Measurements Of Impressions Taken From Bay #13 (3 pages)

Appendix B: Buckling Capacity Evaluation For Varying Uniform Thickness Through The Whole Sandbed Region Of The Drywell (5 pages)

Appendix C: Pictures Showing Condition Of The Drywell In The Sandbed Region (9 pages)

Appendix D: 1992 NDE Inspection Sheets for the Drywell Sandbed Region (51 pages)

Appendix E: 2006 NDE Inspection Sheets for the Drywell Sandbed Region (10 pages)

Appendix F - 1992 Letter Describing the Drywell Surfaces, Reference 3.6 (3 pages)

Appendix G - Figure 3-11 through 3-13 of GE Index Report 9.5 refer 3.4 (2 pages)

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 4 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

## 1.0 PROBLEM STATEMENT

The purpose of this calculation is to evaluate the Ultrasonic Test (UT) thickness measurements taken in the sandbed region during the 14R outage (1992) in support of the O.C. drywell corrosion mitigation project. These measurements were taken from the outside of the shell. Access to the sandbed region was achieved by cutting ten holes completely through the shield wall from the torus room. These 1992 inspections began with visual inspections to identify the thinnest areas in each bay. UT measurements were then performed on the thinnest points within each area.

In October 2006 the majority of these areas were UT inspected a second time. The locations were found using the data sheets from the 1992 inspection.

In addition, revision 2 of this calculation develops representative areas and thicknesses for each bay.

This calculation is not intended to develop corrosion rates based on comparison of the 1992 and 2006 UT data. This is due to uncertainties and inconsistencies between the 1992 and 2006 external UT readings. Reference 3.8 provides an assessment of corrosion rates in the sandbed from 1992 to 2006 utilizing regularly monitored locations from inside the drywell. Reference 3.8 concludes that there were no observable corrosion rates in the sandbed between 1992 and 2006. Reference 3.8 also performs a "worst case" analysis of the external data reviewed in this calculation and concludes that even when assuming the worst apparent material loss (which is not credible), none of these locations would corrode to less the minimum required thickness prior to 2008, which is the next schedule inspection of these areas.

## 2.0 SUMMARY OF RESULTS

This calculation demonstrates that the UT thickness measurements for all bays meet the required minimum uniform and local thicknesses.

This was performed by evaluating the UT measurements for each bay against acceptance criteria for general buckling, local buckling, and primary membrane plus bending stresses.

All UT measurements for bays 3, 5, 7, and 9 are all greater than the uniform acceptance criteria and therefore acceptable (see table 2-1).

All UT measurements for bays 11, 15, and 17 are all greater than the uniform acceptance criteria, except for one measurement in each bay. Further evaluation of these three areas show that they meet the local criteria and are therefore acceptable (see table 2-1).

All UT measurements for bays 1, 13 and 19 are evaluated using uniform and local criteria and found to be acceptable. The results are acceptable (see table 2-1).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1202-187-5920-024	Rev. No. 2	Sheet No. 5 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

**TABLE (2-1) SUMMARY OF 1992 AND 2006 UT EVALUATIONS**

Drywell No.	Local Uniform Sandbed Thickness	Local Sandbed Thickness	Local Sandbed Thickness	Local Sandbed Thickness	Local Sandbed Thickness	Local Sandbed Thickness	Acceptable
1	0.736"	0.802"	0.636" Per Sec. 6.2	0.696" over a 36" by 36" Area	0.490"	0.665" (Area 3)	Yes
3	0.736"	0.865"	0.636" Per Sec. 6.2	NA - All readings were greater than 0.736"	0.490"	0.764" (Area 8)	Yes
5	0.736"	0.960"	0.636" Per Sec. 6.2	NA - All readings were greater than 0.736"	0.490"	0.880" (Area 5)	Yes
7	0.736"	0.995"	0.636" Per Sec. 6.2	NA - All readings were greater than 0.736"	0.490"	0.920" (Area 1)	Yes
9	0.736"	0.905"	0.636" Per Sec. 6.2	NA - All readings were greater than 0.736"	0.490"	0.783" (Area 9)	Yes
11	0.736"	0.783"	0.636" Per Sec. 6.2	0.747" over a 2 1/4" diameter area	0.490"	0.700" (Area 1)	Yes
13	0.736"	0.786"	0.636" Per Sec. 6.2	0.658" over a 12" by 12" Area	0.490"	0.802" (Area 2)	Yes
15	0.736"	0.788"	0.636" Per Sec. 6.2	0.711" over a 12" by 12" Area	0.490"	0.711" (Area 1)	Yes
17	0.736"	0.892"	0.636" Per Sec. 6.2	0.663" over a 12" by 12" Area	0.490"	0.663" (Area 2)	Yes
19	0.736"	0.804"	0.636" Per Sec. 6.2	0.720" over a 36" by 36" Area	0.490"	0.717" (Area 11)	Yes

- Notes: 1) This value is the average of all individual UT readings. -  
 2) This value is the average of recorded thicknesses in a local area not greater than 36" by 36".  
 3) This value is the thinnest of all individual UT readings in that Bay.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 6 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julián Abramović		Date

### 3.0 REFERENCE:

- 3.1 Drywell sandbed region pictures (Appendix C).
- 3.2 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE - Part 1 Stress Analysis, Revision 0 dated February, 1991 Report 9-3.
- 3.3 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE - Part 2 Stability Analysis, Revision 2 dated November, 1992 Report 9-4.
- 3.4 ASME Section III Subsection NB Class MC Components 1989.
- 3.5 GE letter report "Sandbed Local Thinning and Raising the Fixity Height Analysis (Line Items 1 and 2 In Contract PC-0391407)" dated December 11, 1992.
- 3.6 GPON Memo 5320-93-020 From K. Whitmore to J. C. Flynn "Inspection of Drywell Sand Bed Region and Access Hole", Dated January 28, 1993.
- 3.7 Theory of Elastic Stability, by Stephen P. Timoshenko and James M. Gere, Second Edition, Engineering Societies Monographs, McGraw Hill Book Company, New York, 1961.
- 3.8 Calculation C-1302-187-E310-041, Rev. 0 Statistical Analysis of Drywell Vessel Sandbed Thickness Data 1992, 1994, 1996, and 2006.
- 3.9 TDR 1108 "Summary Report of Corrective Action Taken From Operating Cycle 12 through 14R.
- 3.10 ASME Section VIII, 1962 Edition.

### 4.0 ASSUMPTIONS AND BASIC DATA:


- 4.1 Raw UT measurements for each bay are presented in Appendix D and summarized in the body of calculation.
- 4.2 References 3.2, 3.3, and 3.5 have been design verified and are assumed correct.
- 4.3 The average of a series of thinnest UT readings within an area results in a conservative estimate of the average thickness of the area. This concept is illustrated in figure 4.3-1

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Case No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 7 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Figure 4.3 -1

Outside The Drywell

Rough Surface  
of the Drywell



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5120-024	Rev. No. 2	Sheet No. 8 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

## 5.0 DESIGN INPUTS:

- 5.1 Observations of the outside surface of the drywell shell indicate a rough surface with varying peaks and valleys. In order to characterize an average roughness representing the depth difference of peaks and valleys, two impressions were made 1992 at the two thinnest UT measurements for bay 13 using Epoxy putty.

Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated. A value of 0.200 inch was used in this calculation as a conservative depth of uniform roughness for the entire outside surface of the drywell in the sandbed region. This is defined as  $T_{rough}$ .

- 5.2 Drywell Design Pressure = 44.0 psig, Oyster Creek, UFSAR Revision 13, Section 3.8.2.8, Page 3.8-61. Drywell Design Temperature = 292°F, Oyster Creek, UFSAR Revision 13, Table 3.11-1

- 5.3 The required sandbed shell thickness for the Design Pressure and Temperature is defined in paragraph ASME B&PV Code, Subsection NE, paragraph NE-3324.4, Spherical Shells, as:

$$t = \frac{PR}{2S - 0.2P} \quad \text{Where: } P = \text{Design Pressure}$$

R = Inside Radius of the Shell = 420 inches

S = Maximum Allowable Stress, SA 212 Grade B  
= 19,300 psi (From ASME B&PV Code Section VIII  
1962 Edition and Reference 3.2, Section 2.2)

- 5.4 Drywell Sandbed buckling design thickness is 0.736 inches. Taken from References 3.3, and 3.5.
- 5.5 Analytical design inputs are taken from References 3.3, 3.4, and 3.5.
- 5.6 The 1992 UT data is provided in appendix D.
- 5.7 The 2006 UT data is provided in Appendix E.
- 5.8 In 2006 Inspectors located the majority of the same areas by using the 1992 NDE Inspection Data Sheets. Since many of the inspected locations were ground down in 1992 to develop a smooth surface, the bulk of the locations could be found by observing small flat convex areas in contrast to surrounding the surfaces that were rough. The data is provided in Appendix E.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 9 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

These readings were not intended for corrosion rate trending due to uncertainties and inconsistencies between the 1992 and 2006 UT readings. These uncertainties include:

- a) The roughness of the inspected surfaces due to the previously corroded surface of the shell in the sandbed regions
- b) The different UT technologies between 1992 and 2006
- c) UT equipment instrument uncertainties and
- d) The poor repeatability in attempting to inspect the exact same unmarked locations over time

Never the less a conservative evaluation was performed in which the worst case difference between 2006 and 1992 values were evaluated to ensure that the next scheduled inspection is appropriate (reference 3.8).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1362-187-5320-024	Rev. No. 2	Sheet No. 10 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

## 6.0 METHODS OF ANALYSIS:

### Acceptance Criteria

The requirements of section 6.1 and 6.3 shall be met or the requirements of section 6.2 and 6.3 shall be met.

### 6.1 Sandbed General Uniform Wall Criteria:

*Criteria: The Drywell Vessel in the Sandbed (between elevations 8' 11½" and 12' 3") shall have an average thickness greater than the uniform general thickness of 0.736" or meet the requirements of section 6.2.*

This acceptance criteria is based upon GE Reports 9-3 and 9-4 (Ref. 3.2 & 3.3) as well as other GE studies (Ref. 3.5). The GE reports used a projected uniform thickness of 0.736 inches in the sandbed area. This area is defined to be from the bottom to top of the sandbed, i.e., El. 8'-11½" to El. 12'-3" and extending circumferentially one full bay.

Individual readings less than 0.736" may be acceptable as long as the average thicknesses for surrounding area is greater than 0.736" and there are no individual UT readings less than 0.490 inches. Areas up to 36" by 36" may be evaluated to the uniform criteria by averaging thinnest readings within the area.

Therefore, if all the UT measurements for thickness in one bay are greater than 0.736 inches the bay is evaluated to be acceptable. Also if the average thickness of adjoining readings (within an area as large as 36" by 36") is greater than 0.736" then that area is acceptable.

Also "Evaluation Thicknesses" calculated per section 6.4 may compared to the uniform acceptance criteria of 0.736".

Where the above evaluation methods cannot meet this acceptance criteria, a more detailed evaluation for local buckling shall be performed per section 6.2.

### 6.2 Local Wall Criteria For Buckling:


*Criteria: An evaluated area for local buckling shall not be larger than 36" by 36" wide. The center of the area shall be no larger than 12" by 12" and shall be on average 0.636" thick or greater. The surrounding 36" by 36" area centered on 12" by 12" area shall be on average thicker than the transition from 0.636" to 0.736".*



Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 11 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici	Date

This criteria is schematically shown below.

Figure 6.2-1



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2.	Sheet No. 12 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

The studies in Reference 3.5 do not reflect actual drywell shell conditions but are used as assessment tools for areas of the sandbed region that have reduced thickness. The methodology used in these studies is provided in reference 3.5 with excerpts provided here. The studies contain a two-step eigenvalue formulation procedure to perform linear elastic buckling analysis of the drywell shell with local areas of reduced thickness. The first step is a static analysis of the structure with all the anticipated loads applied. The structural stiffness matrix,  $[K]$ , the stress stiffness matrix,  $[S]$ , and the applied stresses,  $[\sigma_{ap}]$ , developed and saved from this static analysis. A buckling pass is then run to solve for the lowest eigenvalue or load factor,  $\lambda$ , for the whole structure at which elastic buckling can occur. This load factor, or eigenvalue is a multiplier for the applied stress state or applied load at which the onset of elastic buckling will theoretically occur. All the applied stresses in the structure are scaled equally by the load factor.

This analysis technique is applied to the drywell pie slice finite element model, with a reduction in thickness of 0.200 inches (below the design buckling thickness of 0.736") in a local area of 12 x 12 inches in the sandbed region, tapering to the original thickness over an additional 12 inches, located to result in the largest reduction in load factor possible. This location is selected at the point of maximum deflection of the eigenvector shape associated with the lowest buckling load. The theoretical load factor / eigenvalue for this case was reduced by 9.5% from 6.14 to 5.56.

It should be noted that this reduction of 0.200 inches is over a 144 square inch area of the shell while the actual surface area including the tapering of the thickness is 36 by 36 inches or 1,296 square inch area with thicknesses that are below the 0.736 inch buckling design thickness. This additional tapered area and its reduced thicknesses also contributed to the 9.5% reduction in load factor.

In addition, a second buckling analysis was performed for a wall thickness reduction of 0.636 inches over the one square foot area. The results of this case reduced the load factor and theoretical buckling stress by 3.9% in Reference 3.5. The center of the thinned area was located close to the maximum displacement point in the buckling analysis with uniform thickness 0.736" as per Reference 3.5. The actual surface area including the tapering of the thickness is a 36 by 36 inch or 1,296 square inch area with thicknesses that are below the buckling design thickness. This additional tapered area and its reduced thicknesses also contribute to the 3.9% reduction in load factor stated previously. The total loss in volume, compared to the same area with a thickness of 0.736", is 72 cubic inches.

For this calculation only the second case, which is more conservative, is to be used as acceptance criteria.

Actual individual thicknesses readings within the 12" by 12" area may be less than 0.636" as long as the individual readings are greater than 0.490" (section 6.3) and the average thickness over the entire 12" by 12" area is greater than 0.636". The same rationale is applicable to the transition region outside the 12" by 12" area.


Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 13 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici	Date

The actual UT readings and their spatial relationship will be compared to the acceptance criteria by plotting the profile of the areas and the recorded thicknesses overlaid on the criteria. This concept is shown on figure 6.2-2. Profiles will be developed in two directions, one in the vertical direction and the second in the horizontal direction.

Figure 6.2-2

1) Dotted lines are thickness which have not been measured but are greater than measured areas. The solid lines are actual recorded thickness for each area. Therefore plotting the recorded UT Readings which are the thinnest at each location provides a conservative estimate of the thickness of the region.

2) The distance between areas and their spatial relationship was obtained from the original data sheets.



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 14 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramowicz		Date

### 6.2.1 Correction for the Location of the Locally Thin Area.

The above criteria based on a 36" by 36" area was developed from sensitivity studies (reference 3.5) using the original ANSYS model which modeled the Drywell Vessel. The sensitivity studies placed the 36" by 36" grid on the area of the model that had the highest buckling stresses. This area is located between the centerlines of the vent lines. Areas below the vent lines had less compressive stresses. Therefore locally thin areas located under a vent lines will have more margin than the same locally thin areas located between the centerline of the vent lines.

This is shown in figure 3-11 and 3-13 of the original GE study (reference 3.4). These figures show the calculated compressive stresses from the original finite element modeling of the Drywell Vessel for the bounding case. In particular, figure 3-13 shows that the circumferential stresses in the bounding case vary from approximately 4300 to 5400 psi under the vent line to approximately 6500 psi at the centerline between the vent lines). Therefore it is concluded that there is at least 20% additional margin in areas that are below the centerlines of the vent line. These figures are attached in Appendix G.

### 6.2.2 Cumulative Effect of Locally Thin Area To Buckling

All inspected locations with UT measurements below 0.736 inches have been determined to be in isolated locations less than 2 1/4 inches in diameter.

The effect of these very local wall thickness areas on the buckling of the shell requires some discussion of the buckling mechanism in a shell of revolution under an applied axial and lateral pressure load.

To begin the discussion we will describe the buckling of a simply supported cylindrical shell under the influence of lateral external pressure and axial load. As described in Chapter 11 of Reference 3.7, thin cylindrical shells buckle in lobes in both the axial and circumferential directions. These lobes are defined as half wavelengths of sinusoidal functions. The functions are governed by the radius, thickness and length of the cylinder. If we look at a specific thin walled cylindrical shell both the length and radius would be essentially constants and if the thickness was reduced locally then this reduction would have to be significant and over a majority of the lobe so that the compressive stress in the lobe would exceed the critical buckling stress under the applied loads, thereby causing the shell to buckle locally. This is demonstrated in Reference 3.5 where a 12 x 12 square inch section of the drywell sandbed region is reduced by 100 mils and a local buckle occurred in the finite element eigenvalue extraction analysis of the drywell.

Now reviewing the stability analyses provided in both References 3.3 and 3.5 and recognizing that the finite elements in the sandbed region of the model are 3" x 3", it is clear that the circumferential buckling lobes for the drywell are substantially larger than the 2 1/4 inch diameter very local wall areas. This combined with the local reinforcement surrounding these local areas

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 15 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovic	Date	

and the spherical shell being close to the constraint provided by the concrete supporting structure indicates that these areas will have no impact on the buckling margins in the shell.

It is also clear from Reference 3.5 that for the first case a uniform reduction in thickness of 27% over a one square foot area followed by a transition zone would only create a 9.5% reduction in the load factor and theoretical buckling load of the drywell. Although this reduction of 27% is only over a 144 square inch area of the shell, the actual surface area including the transition zone to the 0.736 inch buckling design thickness is a 36 inch by 36 inch or 1,296 square inch area. This area of reduced thickness was located in the portion of the sandbed considered most susceptible to buckling, the midpoint of a bay between two vents.

In addition, a second case was performed (Reference 3.5) for a wall thickness reduction of 13.5% or a thickness of 0.636 inches over a one square foot area followed by a transition zone from 0.636 inches to 0.736 inches. Again, although this reduction from 0.736 inches to 0.636 inches is over a 144 square inch area of the shell, while the actual surface area including the transition zone to the buckling design thickness is a 36 inch by 36 inch or a 1,296 square inch area. This second buckling analysis resulted in a 3.9% reduction in the load factor. The total loss in volume, compared to the same area with a thickness of 0.736", is 72 cubic inches.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Case No. C-1102-187-5320-024	Rev. No. 2	Sheet No. 16 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 6.3 Very Local Wall Criteria - Primary Membrane Plus Bending

Criteria: An individual UT reading shall be greater than 0.490".

The required sandbed shell thickness for the Design Pressure and Temperature is defined in paragraph ASME B&PV Code, Subsection NE, paragraph NE-3324.4, Spherical Shells, as:

$$t = \frac{PR}{2S - 0.2P} \quad \text{Where: } P = \text{Design Pressure}$$

R = Inside Radius of the Shell = 420 inches

S = Maximum Allowable Stress, SA 212 Grade B  
= 19,300 psi (From ASME B&PV Code Section VIII  
1962 Edition and Reference 3.2, Section 2.2)

Substituting values in the equation we have:

$$t = \frac{(44.0 \text{ psig})(420.0")}{2(19,300 \text{ psi}) - 0.2(44.0 \text{ psig})} = 0.4789 \text{ inches}$$

This acceptance criteria for primary membrane plus bending stresses is based on ASME B&PV Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings.

The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular NE-3213.10 limits the meridional distance between openings without reinforcement to  $2.5\sqrt{Rt}$ . Also Paragraph NE-3335.1 only applies to openings in shells that are closer than 2 times their average diameter.

The implication of these paragraphs is that shell failures from primary stresses produced by design pressure cannot occur provided openings in shells have sufficient reinforcement. The current design pressure of 44 psig for the drywell requires a thickness of 0.479 inches in the sandbed region of the drywell. Therefore, the requirements for primary membrane plus bending stresses, specified by the above code sections are not required for very local wall thickness as long as all measured thickness are greater than 0.479 inches evaluation presented in the calculation. In summary 0.479 inches can be considered the uniform general criteria for primary membrane plus bending stresses and there are no proximity requirements as long as all UT readings are greater than 0.479".

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 17 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Therefore the Drywell Vessel in the sandbed vessel could be uniformly 0.479" thick and still withstand the design pressure of 44 psig and meet code stress allowable.

Revision 0 of the calculation associated this acceptance criteria with a value of 0.490" and not 0.479". Also this acceptance criteria was mistakenly attributed to primary membrane plus bending stresses (pressure) and local buckling criteria, and was limited to a 2 1/4" diameter area. However review of the basis for the criteria (as described above) shows that this criteria only applies to primary membrane plus bending stresses and not buckling. In addition as documented above, the 0.479" value is a uniform thickness requirement value for primary membrane plus bending stresses. Therefore the 2 1/4" diameter area restriction and proximity restrictions to other locally thin areas (greater than 0.479") is not applicable to this criteria.

However for purposes of maintaining historical consistency and to ensure additional conservatism 0.490" will remain as the value for this as acceptance criteria in this calculation.

#### 6.4 Development of "Evaluation Thickness"

This detailed evaluation is based, in part, on visual observations of the shell surface plus a knowledge of the inspection process. This evaluation arrives a meaningful value for the general sandbed shell thickness for use in the assessment to the uniform and local buckling acceptance criteria. This meaningful value is referred to as the "Evaluation Thickness". It is computed by accounting for the depth measurements taken around the areas with the thinnest centers in 1992 and considering the roughness of the shell surface. The pit depth measurements were performed over a 1 inch band around points that were less than 0.736 inch. Therefore that resulting Evaluation Thickness is an estimate of the average thickness of the 2 inch diameter area around the individual thinnest reading.

##### 6.4.1 Estimates the Surface Roughness

The factor that estimates the surface roughness is first discussed. The surface of the shell has been characterized as being "dimpled" as in the surface of a golf ball where the dimples are about one half inch in diameter (Appendix C). Also, the surface contains some depressions 12 to 18 inches in diameter not closer than 12 inches apart, edge to edge (Ref 3.6). Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated to be at 0.185 inches. A value of 0.200 inch was used in this calculation as a conservative depth of uniform dimples for the entire outside surface of the drywell in the sandbed region.

##### 6.4.2 Estimate of Area Surrounding the Thinnest UT Reading

The inspection focused on the thinnest portion of the drywell, even if it was very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. Observations indicate that some inspected spots are very deep. They are much deeper than the normal dimples found, and very local, not more than 1 to 2 inches in diameter. Typically these observations were made after the spot was surface prepped

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 18 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

for UT measurement. This results in a wide dimple to accommodate the UT probe and is slightly deeper than originally found. The depth of these areas was measured within a 1" band with a depth gauge and straight edge at 0°, 45°, 90° and 135° around these inspected dimples. The depths obtained were averaged with respect to the tops of the locally rough areas. These depths are referred to herein as the AVG micrometer measurements.

As these AVG micrometer measurements are very local in nature their effect on the structural response of the drywell to applied loads is very limited. A more meaningful shell thickness for the drywell structural response to applied loads is the general shell thickness near the UT measured indications. This can be obtained on a smooth shell exterior surface by adding the UT measured thickness at the bottom of the indication and the AVG micrometer measurements of the indication depth. But because the exterior of the drywell shell in the sandbed region is very rough and dimpled the measurement described above would result in general shell thicknesses near the indications over a 2 1/2" diameter area (See Figure 6.1). To determine a conservative general shell thickness at the locations of interest Design Input 5.1 of this calculation is subtracted from the combination of the UT measurement and the depth micrometer readings. This thickness is then used to determine the drywell shell susceptibility to buckling by comparing it to the uniform and local buckling acceptance criteria. This thickness is referred to as the "Evaluation Thickness" and can be attributed to an approximate 2" diameter area around the UT reading and is computed as follows:

$$T (\text{evaluation}) = UT (\text{measurement}) + AVG (\text{micrometer}) - Trough$$

where:

$$T (\text{evaluation}) = \text{General shell thickness used for the evaluation}$$

$$UT (\text{measurement}) = \text{thickness measurement at the area (location)}$$

$$AVG (\text{micrometer}) = \text{average depth of the area relative to its immediate surroundings}$$

Trough = 0.200 inches = a conservative value of depth of typical dimple on the shell surface. See Design Input 5.1.


After this calculation, if the thickness for analysis is greater than 0.736 inches, the area is evaluated as acceptable. If not, the area must meet the criteria in section 6.2.

The procedure was originally performed on the 1992 UT inspection data and repeated on the 2006 data. Both sets of results are documented.



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 19 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

FIGURE 6.4-I



Subject O.C. Drywell Ext. UT Evaluation in Sandhed		Calc No. C-1302-187-5520-024	Rev. No. 2	Sheet No. 20 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici	Date	

## 7.0 CALCULATIONS:

### 7.1 EVALUATION OF BAY #1 SUMMARY

The outside surface of this bay is rough and full of dimples similar to the outside surface of a golf ball. This observation is made by the inspector who located the thinnest areas in 1992. The 2006 inspections confirmed this observation (references 3.6). This inspection focused on the thinnest areas of the drywell, even if it was very local. The shell appears to be relatively uniform in thickness except for a band of corrosion which looks like a "bathtub" ring, located 15 to 20 inches below the vent pipe reinforcement plate, i.e., weld line as shown in Figure 1-1. (Figure 1-1 is not to scale). The graphical presentation in Figure 1-1 of measured indications is extracted from Appendix D, Calculation Pages 71 to 76. Based on the inspectors observations the bathtub ring is 12 to 18 inches wide and about 75 inches long located in the center of the bay. Beyond the bathtub ring on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800 inches. Above the bathtub ring the shell exhibits no corrosion since the original lead primer on the vent pipe reinforcement plate is intact. Measurements 14 and 15 confirm that the thickness above the bathtub ring is at 1.154 inches starting at elevation 11'-00". Below the bathtub ring the shell is uniform in thickness where no abrupt changes in thicknesses are present. Figure 1-2 plots areas that are thinner than 0.736" in 2006. Figure 1-2 is to scale with respect to the distances between the readings.

#### 7.1.1 Local Readings Less Than The Uniform Criteria

Table I-1 below provides individual UT readings for 1992 and 2006. These readings are the thinnest single readings within each locally thin area. All readings are confined to areas less than 2 1/4" inches in diameter. Shaded readings are less than the uniform criteria of 0.736 inches and must be further evaluated. These areas and their location are shown on figure 1-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

Areas 14 and 15 were selected to confirm that no corrosion had taken place in the area above the bathtub ring. Table I-1 also provides the results of the 2006 inspection.

Table I-1 Bay # 1 thinnest UT Data

Location	1992 UT Measurements	2006 UT Measurements
	(inches)	(inches)
1	0.720	0.740
2	0.716	0.690
3	0.705	0.665
4	0.760	0.738
5	0.710	0.686
6	0.760	0.731
7	0.700	0.689

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 21 of 183
<b>Originator</b> Peter Tamburro		<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici	<b>Date</b>

Location	1992 UT Measurements	2006 UT Measurements
	(inches)	(inches)
8	0.805	0.783
9	0.805	0.754
10	0.839	0.824
11	0.714	0.711
12	0.723	0.722
13	0.792	0.719
14	1.147	1.157
15	1.156	1.160
16	0.796	0.795
17	0.860	0.846
18	0.917	0.899
19	0.890	0.865
20	0.965	0.912
21	0.726	0.712
22	0.852	0.854
23	0.850	0.828
Average	0.822	0.801

**7.1.2 Bay #1 Very Local Wall Thickness Evaluation (Pressure Only)**

The table shows that all readings are greater than the criteria of 0.490". The thinnest reading was in area 3, was 0.565 inches in 2006.

**7.1.3 Bay 1 Local Wall Thickness Evaluation (Local Buckling)**

The values in Table 1-1 are the thinnest individual readings found in the areas. For purposes of this calculation all these areas will be considered to be 2 1/2" in diameter. Eight areas (1, 2, 3, 5, 7, 11, 12, and 21) shown in Table 1-1 have individual measurements below 0.736 inches in 1992. Therefore the depth measurements were performed on these areas in 1992 (Table 1-2). At each location, micrometer readings were taken at the 0, 45, 90, and 135 degree orientation. The following table provides a summary of the depths in each azimuth.

**Table 1-2 Bay 1 AVG Micrometer Calculations**

Location	0°	45°	90°	135°	Average
1	0.272"	0.204"	0.206"	0.185"	0.217"
2	0.143"	0.133"	0.143"	0.154"	0.143"

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 22 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Jofien Abramovici		Date

3	0.397"	0.316"	0.329"	0.347"
5	0.330"	0.290"	0.304"	0.315"
7	0.208	0.281"	0.246"	0.330"
11	0.200"	0.211"	0.225"	0.211"
12	0.299"	0.316"	0.261"	0.328"
21	0.272"	0.202"	0.238"	0.183"

**Example Of Calculation in Table 1-2**

$$(\text{AVG Micrometer})_1 = \frac{D_{1-0^\circ} + D_{1-45^\circ} + D_{1-90^\circ} + D_{1-135^\circ}}{4}$$

$$(\text{AVG Micrometer})_1 = \frac{0.272'' + 0.204'' + 0.206'' + 0.185''}{4} = 0.217''$$

Where:  $D_{1-0^\circ}$  = Micrometer Depth Reading for location 1 at 0 degrees taken from Appendix D, Calculation Page 74, etc.

The following table provides (per section 6.4) the "Evaluation Thickness" at the locally thin areas. Shaded areas are less than the uniform acceptance criteria of 0.736" and must be evaluated further.

**Table 1-3 Summary Of Measurements Below 0.736"**

Location	0°	45°	90°	135°	Acceptance Criteria	Remarks	
1	0.720"	0.710"	0.217"	0.200"	0.737"	71.3.3	
2	0.716"	0.690"	0.143"	0.200"	0.629"	71.3.5	
3	0.705"	0.665"	0.347"	0.200"	0.852"	0.812	71.3.1
5	0.710"	0.680"	0.313"	0.200"	0.823"	0.793"	71.3.1
6	0.760"	0.731"					71.3.3
7	0.700"	0.665"	0.266"	0.200"	0.766"	0.736"	71.3.3
11	0.714"	0.711"	0.212"	0.200"	0.726"	0.721"	71.3.1
12	0.724"	0.722	0.301"	0.200"	0.625"	0.823	71.3.1
15	0.792"	0.719"					71.3.3
21	0.726"	0.712	0.211"	0.200"	0.737"	0.711"	71.3.3

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 23 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### Example of Calculation in Table 1-3

$$T_{(Evaluation)I} = UT_{(Measurement)I} + (AVG \text{ Micrometer})_I - T_{rough}$$

Where:  $UT_{(Measurement)I} = 0.720"$  Taken from Appendix D, Calculation Page 71, Location 1

$T_{rough} = 0.200"$  See Design Input 5.1 and Section 6, Acceptance Criteria, General Wall.

$$T_{(Evaluation)I} = 0.720" + 0.217" - 0.200" = 0.737"$$

Areas 6 and 13 were not characterized in 1992 since the individual thinnest readings within the areas were greater than 0.736". However in 2006 these reading were less than 0.736". Therefore the thinnest individual readings are evaluated per section 6.2. This is conservative since no credit is taken for the surrounding thicker material around the thinnest reading (see assumption 4.3).

#### 7.1.3.1 Areas 3, 5, and 12

Table 1-3 show that the resulting "Evaluation Thickness" of areas 3, 5 and 12 are greater than 0.736 inches and are therefore acceptable.

#### 7.1.3.2 Evaluation of Area 13

Refer to figure 1-6. Area 13 has a single reading of 0.719". This location is next to areas 4 (0.738"), 5 (0.680"), 9 (0.754"), and 19 (0.856"). The "Evaluation Thickness" of area 5 is 0.793" and therefore this location is acceptable. These five areas are bounded by a 23" by 16" area. Since five single points were determined by the inspectors to be the thinnest within this area, the average of these individual readings is a conservative estimate of the average thickness of the 16" by 23" area (see assumption 4.3). The average of these five readings is 0.751", which is greater than 0.736".

#### 7.1.3.3 Evaluation of Areas 1, 2, 6, 7, 11, and 21

Area 2, which has an individual reading of 0.690", was combined with neighboring areas 7 (0.669"), 11 (0.711") and 21 (0.712") (see figure 1-3). These four areas can be captured in a 14" by 18" area that has an average thickness of 0.696". The average thickness value for areas 2, 7, 11, and 21 were then located in relationship to areas 1, and 6 (see figure 1-3). Figure 1-4 and 1-5 show the profile of the 36" by 36" area with the thickness of areas 1, and 6 and the average thickness of areas 2, 7, 11 and 21 overlaid with a curve depicting the acceptance criteria.

Figure 1-4 shows the profile along the horizontal axis and figure 1-5 show the profile along the vertical axis. The figures show that the average thicknesses are greater than the criteria.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc. No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 24 of 183
<b>Originator</b> Peter Tamburo	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

Please note that Figure 1-4 does show that the two locally thin areas come close to the edges of the 36" by 36" acceptance criteria envelope. However since these areas are significantly smaller than the analyzed area and since the two areas are actually located at an azimuth of the drywell that sees less stress (7.1.3.4) the approach to the envelope is judged to be inconsequential.

#### 7.1.3.4 Combined Effect of The 10 Areas on Buckling

There are several conservative factors associated with the size and the location of the locally thin areas which cannot be quantified but are judged to be substantial in demonstrating that the measured thickness are adequate. These are described below.

**7.1.3.4.1** Refer to figure 1-7. The locally thin area for this bay that is less than 0.736 inches is located directly under the vent line.

The local buckling criteria (section 6.2) is based on sensitivity studies that placed a 36" by 36" locally thin grid on the area of the finite element model that had the highest buckling stresses. This area is located between the centerlines of the vent lines (+66" to -66" as shown in figure 1-2). Areas below the vents lines had less compressive stresses (-36" to +36"). Therefore locally thin areas located under a vent lines will have more margin than the same locally thin areas located between the centerline of the vent lines. Review of the original GE study (see appendix F) shows that stresses under the vent line are at least 20% less than the stresses between the centerline of the vent lines. Therefore the necessary wall thickness to maintain the required safety factor for portions of the vessel under the vent lines is substantially less (by at least 20%) than the calculated required uniform thickness of 0.736".

**7.1.3.4.2** A second factor is the cumulative size of the ten locally thin areas, which is significantly much smaller than the analyzed 36" by 36" area (see the figure in section 6.2). The total volume of this 36" by 36" area when compared to the volume of a similar 36" by 36" area with a uniform thickness of 0.736" correspond to a reduced volume of 72.0 cubic inches.

The cumulative volume of all ten locally thin areas is about 1.7 cubic inches (see the table below).

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/2 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $(0.736 - \text{Column 2}) * 3.142 * (2.5/2)^2 * 2$
1	0.710	0.128
2	0.690	0.226
3	0.665	0.349
5	0.680	0.275
6	0.731	0.025
7	0.669	0.329

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 25 of 183.
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovic		Date

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/2 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $(0.736 - \text{Column 2}) * 3.142 * (2.5/2) ** 2$
11	0.711	0.123
12	0.722	0.069
13	0.719	0.083
21	0.712	0.118
	Total	1.723

Therefore the comparison of the "as found" volume reduction, which is about 1.723 cubic inches, to the "analyzed" volume reduction of 72 cubic inches leads to the conclusion that the effect on the buckling load factor is negligible.

In addition since the majority of the vessel in this bay is thicker than 0.736", the thicker areas will reinforce the locally thin areas. For example approximately 7210 square inches of surface area in this bay (of a total of 9072 square inches) is 800 mils or thicker (refer to figure 13-7). When compared to same surface area with a thickness of 0.736" there is a total increase in volume of at least 460 cubic inches. (e.g.  $460 = (0.8 - 0.736) * 7210$ ). This additional volume will reinforce the locally thin areas.

#### 7.1.4 Bay #1 General Wall Thickness Criteria (Buckling)

##### Outside the "Bathtub Ring"

Refer to figure 1-1

Taking the average of the UT measured thicknesses of areas 6, 7, 8, 9, 16, 17, 18, 19, 22 and 23 gives a average thickness of 0.824 inches in 1992 and 0.802 inches 2006 for the shell below the bathtub ring. Based on this a conservative mean thickness of 0.802 inches, is estimated to represent the evaluation thickness for this bay outside the bounds of the bathtub ring. Therefore it is concluded that these areas are acceptable based on the thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Above the bathtub ring the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurements 14 and 15 confirm that the thickness above the bathtub ring is at 1.154 inches starting at elevation 11'-00".

##### In the "Bathtub Ring"

Areas 1, 2, 3, 4, 5, 10, 11, 12, 13, 20, and 21 are confined to the bathtub ring as shown in Figure 1-1 and 1-2. To determine the general shell thickness in the bathtub ring area of this bay the evaluation thicknesses for each of the areas defined above are averaged together. An example of a typical calculation of the general wall thickness defined as the evaluation thickness is presented below for clarity:

An average value of the evaluation thicknesses presented in Table 1-3 for this band is as follows:

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 26 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Area	Evaluation Thickness (1992)	Evaluation Thickness (2006)
1	0.737"	0.727"
2	0.659"	0.633"
3	0.852"	0.812"
4*	NA	0.738**
5	0.823"	0.793"
10*	NA	0.824**
11	0.726"	0.723"
12	0.825"	0.823"
13*	NA	0.719**
20*	NA	0.912**
21	0.737"	0.714"
	Average = 0.766"	Average = 0.765"

\* Note for area 4, 10, 13 and 20 the actual 2006 UT measurement were used since these areas were not characterized in 1992.

Again given that the average evaluation thickness of the shell in the bathtub ring area exceeds the buckling design thickness of 0.736 inches the shell area within the bathtub ring is also acceptable using the results of Reference 3.3.

### 7.1.5 Conclusion

Figure 1-7 illustrates representative areas and thicknesses in this bay as follows:

- Area B - This is a 23" wide and 16" high area, which is at least 0.751" thick. This thickness is based on the thickness of the Bathtub Ring (refer to section 7.1.3.2).
- Area C - This is a 36" by 36" area which is at least 0.696 inches thick. This thickness is based on the evaluation in section 7.1.3.3.
- Area D - The remaining areas of the Bay are 0.800 inches thick or greater. This thickness is based on the evaluation in section 7.1.4.
- Area E - This is a 11" wide by 18" high area which and is at least 0.765 inches thick. This thickness is based on the thickness of the Bathtub ring (refer to section 7.1.4).



<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 27 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

Therefore this bay meets the acceptance criteria based on the following:

- 1) All individual readings are greater than 0.490 inches.
- 2) Except for Area C, the entire bay has thickness greater than 0.736 inches.
- 3) Area C (which is limited to an area of 36" by 36") meets the acceptance criteria in section 6.2.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 28 of 183
Originator Peter Tamburo	Date 5/21/07	Reviewed by Julien Abramovici		Date

Figure 1-1.

# BAY #1 DATA

## NOTES:

- All "Location" measurements from intersection of the DW shell and vent collar fillet welds.
- Pit depths are average of four readings taken at 0/45/90/135° within 1" band surrounding ground spots. Only measured where remaining wall thk. was below 0.236".





Figure 1-2

# Bay 1 2006

C-1302-187-5320-024  
Rev 2, Page 29

## Spatial Relationship Of Locally Thin Areas



OCLR00030704

Figure 1-3

# Bay 1 Locations 1, 2, 6, 7, 11 and 21 Evaluation Thickness





Figure 1-4


### Bay 1 Horizontal Profile (Evaluation Thickness versus Local Buckling Criteria)



C-1302-187-5320-024  
Rev 2, Page 31

Figure 1-5

### Bay 1 Vertical Profile (Evaluation Thickness versus Local Buckling Criteria)




— 636 Criteria — 1 — Average 2, 7, 11, and 21 — 6

OCLR00030707

Figure 1-6

### Bay 1 locations 5 and 13 Evaluation Thickness




C-1302-187-6320-024  
Rev 2, Page 83

OCLR00030708

Figure 1-7

C-1302-167-5320-024  
Rev 2, Page 34

# Bay 1 2006 Representative Thicknesses



All X and Y dimensions are referenced from 13 inches to the right of centerline of the vent line (X direction) and the bottom of the Penetration Reinforcement Pad (Y dimension).  
Reference NDE Data sheets 92-072-12 page 1 of 2 and 1R21LR-022 page 2 of 2.



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 35 of 183
Originator Peter Tamburni	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.3 UT EVALUATION BAY #3 SUMMARY

The outside surface of this bay is rough, similar to bay one, full of dimples comparable to the outside surface of golf ball (references 3-6). This observation was made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness except for a bathtub ring 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact.

#### 7.3.1 Local Readings Less Than The Uniform Criteria

Eight areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Table 3-1 and Fig. 3-1). These areas are a deliberate attempt to produce a minimum measurement. Table 3-1 shows measurements taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches. Therefore, the uniform criteria is met throughout the bay and it is concluded that the bay is acceptable.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 36 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 1/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

These areas and their location are shown on figure 3-2.

**Table 3-1 Bay # 3 Thinnest UT Data**

Location	1992 UT Measurements (inches)	2006 UT Measurements (inches)
1	0.795	0.795
2	1.000	0.999
3	0.857	0.850
4	0.898	0.903
5	0.823	0.819
6	0.968	0.972
7	0.826	0.816
8	0.780	0.764
Average	0.8685	0.865

**7.3.2 Bay #3 Very Local Wall Thickness Evaluation (Pressure Only)**

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was 0.764" in area 8 recorded in 2006.

**7.3.3 Bay 3 Local Wall Thickness Evaluation (Local Buckling)**

The results indicate that all of the areas have thickness greater than the 0.736 inches. Therefore the uniform criteria is met throughout the bay and the use of the local wall thickness criteria for buckling is not required.

**7.3.4 Bay 3 General Wall Thickness Criteria (Buckling)**

The UT measurements presented in Table 3-1 equal an average of 0.868 inches in 1992 and 0.865" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of reference 3.3.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1502-187-5320-024	Rev. No. 2	Sheet No. 37 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.3.5 Conclusion

It is concluded that Bay 3 is acceptable since all individual UT readings in 1992 and 2006 were greater than the uniform acceptance criteria.

Figure 3-2 illustrates the representative thicknesses in this bay, which is 0.865 inches or greater (refer to section 7.3.4).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1309-187-5320-024	Rev. No. 2	Sheet No. 38 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici	Date	

# BAY #3 DATA

Figure 3-1

## NOTES:

1. All "Location" measurements from intersection of the DW shell and vent collar fillet welds.





FIGURE (3)

Figure 3-2

# Bay 3 2006 Spatial Relationship Of Locally Thin Areas



Squares are less than 0.736\*  
Triangles are greater than 0.736\*

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 40 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.5 UT EVALUATION BAY 5 SUMMARY

The outside surface of this bay is rough and very similar to bay 3 except that the local areas are clustered at the junction of bays 3 and 5, at about 30 inches above the floor. The shell surface is full of dimples comparable to the outside surface of a golf ball (references 3.6). This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Eight areas were selected to represent the thinnest areas based on the visual observations of the shell surface (see Fig. 5-1). These areas are a deliberate attempt to produce a minimum measurement. Table 5-1 shows these thickness values. The results indicate that all of the areas have thickness greater than the 0.736 inches.

#### 7.5.1 Local Readings Less Than The Uniform Criteria

The individual thinnest UT measurements for locally thin areas are presented in Table 5-1. All 1992 and 2006 reading were greater than 0.736 inches. Therefore, the uniform criteria is met throughout the bay and it is concluded that the bay is acceptable.

These areas and their location are shown on figure 5-2.

Table 5-1 Bay # 5 Thinnest UT Data

Location	1992 UT	2006 UT
	Measurements (inches)	Measurements (inches)
1	0.970	0.948
2	1.040	0.955
3	1.020	0.989
4	0.910	0.948
5	0.890	0.880
6	1.060	0.981
7	0.990	0.974
8	1.010	1.007
Average	0.986	0.960

#### 7.5.2 Bay #5 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was 0.880" in area 5 recorded 2006.

#### 7.5.3 Bay 5 Local Wall Thickness Evaluation (Local Buckling)

<b>Subject</b> O.C. Drywall Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 41 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

The results indicate that all of the areas have thickness greater than the 0.736 inches. Therefore the uniform criteria is met throughout the bay and the use of the local wall thickness criteria for buckling is not required.

#### 7.5.4 Bay #5 General Wall Thickness Criteria (Buckling)

The UT measurements presented in Table 5-1 equal an average of 0.986 inches in 1992 and 0.960" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

#### 7.5.5 Conclusion

It is concluded that Bay 5 is acceptable since all individual UT readings in 1992 and 2006 were greater than the uniform acceptance criteria.

Figure 5-2 illustrates the representative thicknesses in this bay, which is 0.960 inches or greater (refer to section 7.5.4).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 42 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date





FIGURE (5)



Figure 5-2

# Bay 5 2006 Spatial Relationship Of Locally Thin Areas



Squares are less than 0.736"  
Triangles are greater than 0.736"

C-1302-187-5320-024  
Rev. 2 Page 43

OCLR00030718

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 44 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.7 UT EVALUATION BAY 7 SUMMARY

The observation of the drywell surface for this bay showed uniform dimples in the corroded area, but they are shallow compared to those in bay 1. The bathtub ring seen in the other bays was not very prominent in this bay (references 3.6). This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Seven areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 7-1). These areas are a deliberate attempt to produce a minimum measurement. Table 7-1 presents these values.

#### 7.7.1 Bay #7 Local Readings Less Than The Uniform Criteria

The individual thinnest UT measurements for locally thin areas are presented in Table 7-1. All 1992 and 2006 readings are greater than 0.736 inches. Therefore, the uniform criteria is met throughout the bay and it is concluded that the bay is acceptable.

These areas and their location are shown on figure 7-2.

Table 7-1 Bay # 7 Thinnest UT Data

Location	1992 UT Measurements (inches)	2006 UT Measurements (inches)
1	0.920	NA
2	1.016	NA
3	0.954	0.956*
4	1.040	NA
5	1.030	1*
6	1.045	1.02*
7	1.000	1.002*
Average	1.000	0.995

\* - These were the thinnest documented readings on the 2006 data sheet.

#### 7.7.2 Bay #7 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 1, was 0.920 inches in 1992.

#### 7.7.3 Bay 7 Local Wall Thickness Evaluation (Local Buckling)

The results indicate that all of the areas have thickness greater than the 0.736 inches. Therefore the uniform criteria is met throughout the bay and the use of the local wall thickness criteria for buckling is not required.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 45 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

#### 7.7.4 Bay #7 General Wall Thickness Criteria (Buckling)

The UT measurements presented in Table 5-1 equal an average of 1.000 inches in 1992 and 0.995" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

#### 7.7.5 Conclusion

It is concluded that Bay 7 is acceptable since all individual UT readings in 1992 and 2006 were greater than the uniform acceptance criteria.

Figure 7-2 illustrates the representative thicknesses in this bay, which is 0.995 inches or greater (refer to section 7.5.4).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 46 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date





FIGURE (7)

Figure 7-2

# Bay 7 2006 Spatial Relationship Of Locally Thin Areas



The average for the entire bay is 995 mfls or greater

Squares are less than 0.736"  
Triangles are greater than 0.736"

C-1802-187-5320-024  
Rev. 2, Page 47

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 43 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.9 UT EVALUATION BAY #9 SUMMARY

The observation of the drywell shell for this bay was very similar to bay 7 except that the bathtub ring was more evident in this bay (references 3.6). The shell appears to be relatively uniform in thickness except for a bathtub ring 6 to 9 inches wide approximately 6 to 8 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact. Ten areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 9-1). These areas are a deliberate attempt to produce a minimum measurement. Table 9-1 shows readings taken to measure the thinnest thicknesses of the drywell shell.

#### 7.9.1 Bay #9 Local Readings Less Than The Uniform Criteria

The individual thinnest UT measurements are presented in Table 9-1. All 1992 and 2006 readings are greater than 0.735 inches. Therefore, the uniform criteria is met throughout the bay and it is concluded that the bay is acceptable.

These areas and their location are shown on figure 9-2.

Table 9-1 Bay # 9 Thinnest UT Data

Location	1992 UT	2006 UT
	Measurements (inches)	Measurements (inches)
1	0.960	0.968
2	0.940	0.934
3	0.994	0.989
4	1.020	1.016
5	0.985	0.964
6	0.820	0.802
7	0.825	0.820
8	0.791	0.781
9	0.832	0.823
10	0.980	0.955
Average	0.915	0.895

#### 7.9.2 Bay #7 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 8, was 0.781 inches in 2006.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 49 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

**7.9.3 Bay 7 Local Wall Thickness Evaluation (Local Buckling)**

The results indicate that all of the areas have thickness greater than the 0.736 inches. Therefore the uniform criteria is met throughout the bay and the use of the local wall thickness criteria for buckling is not required.

**7.9.4 Bay #7 General Wall Thickness Criteria (Buckling)**

The UT measurements presented in Table 9-1 equal an average of 0.915 inches in 1992 and 0.905" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

**7.9.5 Conclusion**

It is concluded that Bay 9 is acceptable since all individual UT readings in 1992 and 2006 were greater than the uniform acceptance criteria.

Figure 9-2 illustrates the representative thicknesses in this bay, which is 0.905 inches or greater (refer to section 7.9.4).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5326-024	Rev. No. 2	Sheet No. 50 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Figure 9-1

# BAY #9 DATA

## NOTES:

1. All measurements from Intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE (9)




Figure 9-2

# Bay 9 2006 Spatial Relationship Of Locally Thin Areas

Center Line Of Vent Line

Inches



Squares are less than 0.736"  
Triangles are greater than 0.736"

C-1802-187-5320-024  
Rev. 2, Page 51

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 52 of 113
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici	Date	

### 7.11 UT EVALUATION BAY #11 SUMMARY

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of a golf ball. The shell appears to be relatively uniform in thickness except for local areas at the upper right corner of Figure 11-1, located at about 10 to 12 inches below the vent pipe reinforcement plate.

#### 7.11.1 Bay #11 Local Readings Less Than The Uniform Criteria

Eight areas were selected to represent the thinnest local areas based on the visual observations of the shell surface (Fig. 11-1). These areas are a deliberate attempt to produce a minimum measurement (references 3.6). Table 11-1 shows readings taken to measure the thicknesses of the drywell shell. Area 1 as shown in Table 11-1, has a reading less than 0.736 inches. Inspector observations indicate that this area was very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surrounds was measured at 4 locations round the spot and the average is shown in Table 11-2.

These areas and their location are shown on figure 11-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

Table 11-1 Bay # 11 Thinnest UT Data

Location	1992 UT	2006 UT
	Measurements	Measurements
	(inches)	(inches)
1	0.705	0.700
2	0.770	0.760
3	0.832	0.830
4	0.755	0.751
5	0.831	0.823
6	0.800	0.756
7	0.831	0.817
8	0.815	0.825
Average	0.792	0.783

#### 7.11.2 Bay #11 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 1, was 0.700 inches in 2006.

#### 7.11.3 Bay 11 Local Wall Thickness Evaluation (Local Buckling)

One area (area 1) shown in Table 11-1 had a individual measurement below 0.736 inches in 1992 and in 2006. Therefore the depth measurements were performed in 1992 (Table 11-2). The calculated "Evaluation Thickness" for both the 1992 and 2006 are greater than 0.736" and therefore meet the acceptance criteria.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 53 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

The calculation of the average depth for Bay 11, Area 1 is as follows:

**Table 11-2 Summary of Measurements Below 0.736 Inches**

Measurement	Measurement	Measurement	Measurement	Measurement	Measurement	Measurement
0.705"	0.770"	0.246"	0.200"	0.751"	0.746"	Acceptable

**7.11.4 Bay #11 General Wall Thickness Criteria (Buckling)**

The UT measurements presented in Table 11-1 equal an average of 0.792 inches in 1992 and 0.783" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

**7.11.5 Conclusion**

It is concluded that Bay 11 is acceptable since all but one individual UT readings in 1992 and 2006 were greater than the uniform acceptance criteria. The calculated "Evaluation thickness" of the one remaining area is greater than then 0.763" criteria

Figure 11-2 illustrates the representative thicknesses in this bay, which is 0.783 inches or greater (refer to section 7.11.4).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 54 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovic	Date

Figure 11-1

# BAY #11 DATA

## NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at  $0.45^\circ/90^\circ/135^\circ$  within 1" band surrounding the ground spots. This measurement was only taken when wall thickness was below 0.736".





FIGURE (11)

Figure 11-2

# Bay 11 2006 Spatial Relationship Of Locally Thin Areas



The average for the entire bay is 0.783 Inches or greater

Squares are less than 0.736"  
Triangles are greater than 0.736"

C-1302-187-5320-024  
Rev. 2, Page 55

OCLR00030730

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 56 of 183
<b>Originator</b> Peter Tamburra	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

### 7.13 EVALUATION OF BAY #13 SUMMARY

The outside surface of this bay is rough and full of dimples similar to bay L. This observation was made by the inspector who located the thinnest areas thereby biasing the remaining wall measurements to the conservative side (references 3,6). This inspection focused on the thinnest areas, even if very local. The variation in shell thickness is greater in this bay than in the other bays. The bathtub ring below the vent pipe reinforcement plate was less prominent than was seen in other bays. The corroded areas are about 12 to 18 inches in diameter and are at 12 inches apart, located in the middle of the sandbed. Beyond the corroded areas on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800". Near the vent pipe and reinforcement plate the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurement 20 confirms that the thickness above the bathtub ring is at 1.154 inches. Outside the bathtub ring the shell appears to be fairly uniform in thickness where no abrupt changes in thickness are present.

#### 7.13.1 Local Readings Less Than The Uniform Criteria

The table below provides individual UT readings for 1992 and 2006. These readings are the thinnest single reading within each locally thin area. All readings are confined to areas less than 2 1/2 inches in diameter. Shaded readings are less than the uniform criteria of 0.736 inches and must be evaluated. The 1992 individual UT readings for areas 6, 10, 11, 14, and 19 were less than the corresponding 2006 values. For all other area the 2006 value were less than the 1992 values. These areas and their location are shown on figure 13-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

Table 13-1 Bay # 13 Thinnest UT Data

Location	1992 UT Measurements (inches)	2006 UT Measurements (inches)
1/1A	0.672/0.890	NA
2/2A	0.722/0.943	NA
3	0.941	0.923
4	0.915	0.873
5/5A	0.718/0.861	0.708
6/6A	0.655/0.976	0.658
7/7A	0.618/0.752	0.602
8/8A	0.718/0.900	0.704
9	0.924	0.915
10/10A	0.928/0.810	0.741
11/11A	0.685/0.854	0.699
12	0.885	0.886
13	0.932	0.814
14	0.868	0.87

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 57 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Location	1992 UT Measurements	2006 UT Measurements
	(inches)	(inches)
15/15A	0.687/0.590	0.756
16	0.829	0.814
17	0.807	NA
18	0.825	NA
19	0.912	0.916
20	1.170	NA
Average	0.810	0.786

\* In 1992 two UT measurements were performed on these locations. The first was the thinnest reading within the location and the second was intended to provide a value for thickness of the immediate area surrounding the thinnest point.

#### 7.13.2 Bay #13 Very Local Wall Thickness Evaluation (Pressure Only)

The table shows that all readings are greater than the criteria of 0.490". The thinnest reading was in area 7, was 0.602 inches in 2006.

#### 7.13.3 Bay 13 Local Wall Thickness Evaluation (Local Buckling)

Nine areas shown in Table 13-1 have individual measurements below 0.736 inches in 1992. Six areas shown in Table 13-1 have individual measurements below 0.736 inches in 2006. Figure 13-2 shows the areas of these areas.

Inspector observations indicate that these areas were not more than 1 to 2 inches in diameter. The individual thickness values in Table 13-1 are the thinnest individual readings found in these areas. For purposes of this calculation all these areas will be considered to be 2 1/2" in diameter.

In 1992 for areas 1, 2, 5, 6, 7, 8, 10, 11, and 15 the measured thinnest UT reading was less than 0.736". Therefore micrometer depth measurements were performed on these areas to better characterize the thickness of surrounding area. At each location, micrometer readings were taken at the 0, 45, 90, and 135 degree orientation. The following table provides a summary of the depths in each azimuth.

Table 13-2 Bay 13 AVG Micrometer Calculations

Area	0°	45°	90°	135°	Avg
1	0.330"	0.382"	0.346"	0.346"	0.351"
2	0.312"	0.377"	0.360"	0.393"	0.360"
5	0.150"	0.193"	0.230"	0.298"	0.217"
6	0.327"	0.339"	0.290"	0.247"	0.301"

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. G-1302-187-5320-024	Rev. No. 2	Sheet No. 58 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Area	2006	1992	2006	1992	2006
7	0.241	0.279"	0.260"	0.239"	0.255"
8	0.324"	0.245"	0.262"	0.279"	0.278"
10	0.186"	0.173"	0.255"	0.229"	0.211"
11	0.240"	0.231"	0.271"	0.283"	0.256"
15	0.288"	0.277"	0.239"	0.288"	0.273"

Table 13-3 provides (per section 6.4) the "Evaluation Thickness" at the locally thin areas. Based on the 2006 data, areas 6, 8, 10 and 15 are greater than the uniform acceptance criteria of 0.736" and are therefore acceptable. Areas 1 and 2 were not found in 2006. However the 1992 "Evaluation Thicknesses" for these two areas are significantly larger than 0.736".

Shaded areas (5, 7, and 11) have resulting evaluation thicknesses less than the uniform acceptance criteria of 0.736" and must be evaluated in further detail. The 2006 "Evaluation Thicknesses" of all three areas are less than the 1992 values. Therefore only the 2006 "Evaluation Thicknesses" will be addressed in the remainder of this section.

Table 13-3 Summary of Measurements Below 0.736 Inches

Area	2006 Evaluation Thickness (in)	1992 Evaluation Thickness (in)	2006 Mean Thickness (in)	1992 Mean Thickness (in)	2006 Acceptance Criteria (in)	1992 Acceptance Criteria (in)	Remarks
1	0.672"	NA	0.351"	0.200"	0.823"	NA	7.13.5
2	0.722"	NA	0.360"	0.200"	0.882"	NA	7.13.5
5	0.718"	0.708	0.217"	0.200"	0.735"	0.725	7.13.5.1
6	0.655"	0.658	0.301"	0.200"	0.756"	0.759	7.13.5
7	0.618"	0.602	0.255"	0.200"	0.673"	0.657	7.13.3.2
8	0.718"	0.704	0.278"	0.200"	0.796"	0.782	7.13.3.2
10	0.728"	0.741	0.211"	0.200"	0.739"	0.752	7.13.5
11	0.685"	0.699	0.256"	0.200"	0.741"	0.725	7.13.3.2
15	0.683"	0.666	0.273"	0.200"	0.756"	0.739	7.13.5

### 7.13.3.1 Evaluation of Area 5

Refer to figure 13-6. Area 5 has a single reading of 0.708" in 2006. This area is next to areas 10 (0.741") and 14 (0.870"). These three areas are bounded by a 8" by 12" area. Since these single points were determined by the inspectors to be the thinnest within this area, the average of these three thicknesses is a conservative estimate of the average thickness of the area (see assumption 4.3).



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 59 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

The average of these three readings is 0.773", which is greater than 0.736". Therefore area 5 meets the 0.736" uniform criteria.

#### 7.13.3.2 Evaluation of Areas 7, 8, and 11

Areas 7, 8 and 11 were evaluated together in a single 12" by 12" area (see figure 13-2 and 13-3) and compared to the local buckling criteria established in section 6.2.

Area 7 has a single reading of 0.602" that is less than 0.636" (the thickness criteria for the 12" by 12" area). This area was combined with areas 8 (0.704") and 11 (0.669"). These three areas are bounded by a 12" by 12" area. Since these single points were determined by the inspectors to be the thinnest within this area, the average of these three thicknesses is a conservative estimate of the average thickness of the 12" by 12" area (see assumption 4.3). The average of these three readings is 0.658", which is greater than local buckling criteria of 0.636". Therefore areas 7, 8 and 11 meet the local buckling criteria. Figure 13-4 and 13-5 show the profile of the 36" by 36" area with average of 7, 8 and 11 minimum thickness overlaid on the curve depicting the acceptance criteria.

Figure 13-4 shows the profile along the horizontal axis and figure 13-5 shows the profile along the vertical axis.

#### 7.13.3.3 Combined Effect of Locally Thin Areas on Buckling

There are several conservative factors associated with the size and the location of the locally thin areas which cannot be quantified but are judged to be substantial in demonstrating that the measured thickness are adequate. These are described below.

**7.13.3.3.1** Refer to figure 13-7. The locally thin area for this bay that is less than 0.737 inches is located directly under the vent line.

The local buckling criteria (section 6.2) is based on sensitivity studies that placed a 36" by 36" locally thin grid on the area of the finite element model that had the highest buckling stresses. This area is located between the centerlines of the vent lines (+66" to -66" as shown in figure 13-2). Areas below the vent lines had less compressive stresses (-36" to +36"). Therefore locally thin areas located under a vent lines will have more margin than the same locally thin areas located between the centerline of the vent lines. Review of the original GE study (see appendix F) shows that stresses under the vent line are at least 20% less than the stresses between the centerline of the vent line. Therefore the necessary wall thickness to maintain the required safety factor for portions of the vessel under the vent lines is substantially less (by at least 20%) than the calculated required uniform thickness of 0.736".

**7.13.3.3.2** A second factor is the cumulative size of the nine locally thin areas, which is significantly much smaller than the analyzed 36" by 36" area (see the figure in section 6.2). The total volume of this 36" by 36" area when compared to the volume of a similar 36" by 36" area with a uniform thickness of 0.736" correspond to a reduced volume of 72.0 cubic inches.

The cumulative volume of all nine (in 1992) locally thin areas is less than 2.086 cubic inches (see the table below).

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 60 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Table 13-4

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/4 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $0.736 - \text{Column 2}) * 3.142 * (2.5/2)**2$
1	0.672	0.314
2	0.722	0.069
5	0.718	0.088
6	0.655	0.398
7	0.618	0.579
8	0.718	0.088
10	0.728	0.039
11	0.685	0.260
15	0.683	0.260
Total -		2.086

Therefore the comparison of the "as found" volume reduction which is less than 2.086 cubic inches to the "analyzed" volume reduction of 72 cubic inches leads to the conclusion that the effect on the buckling load factor is negligible.

In addition since the majority of the vessel in this bay is thicker than 0.736", the thicker areas will reinforce the locally thin areas. For example approximately 7730 square inches of surface area in this bay (of a total of 9072 square inches) is 800 mils or thicker (refer to figure 13-7). When compared to same surface area with a thickness of 0.736" there is a total increase in volume of at least 495 cubic inches. (e.g.  $495 = (0.8 - 0.736) * 7730$ ). This additional volume will reinforce the locally thin areas.

#### 7.13.4 Bay #13 General Wall Thickness Criteria (Buckling)

##### Outside the "Bathtub Ring"

Refer to figure 13-1 Measurement 20 confirms that the thickness above the bathtub ring is at 1.154 inches. Below the bathtub ring the shell appears to be fairly uniform in thickness where no abrupt changes in thickness are present.

Taking the average of the UT measured thicknesses of areas 3, 4, 9, 12, 13, 16, 17, 18, and 19 gives a average thickness of 0.824 inches in 1992 and 0.802 inches 2006 for the shell below the bathtub ring. Therefore it is concluded that these areas are acceptable based on the thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 61 of 183
Originator Peter Tamburro	Date 3/21/97	Reviewed by Julien Abramovic		Date

### In the "Bathtub Ring"

Areas 5, 6, 7, 8, 10, 11, 14, and 15 are confined to the bathtub ring as shown in Figure 13-1 and 13-2. To determine the general shell thickness in the bathtub ring area of this bay the evaluation thicknesses for each of the areas defined above are averaged together.

An average value of the evaluation thicknesses presented in this band is as follows.

Table 13-5

Area	1992 Evaluation Thickness	2006 Evaluation Thickness
5	0.735"	0.725"
6	0.756"	0.759"
7	0.673"	0.657"
8	0.796"	0.782"
10	0.739"	0.752"
11	0.741"	0.725"
14	0.868"	0.870"
15	0.756"	0.739"
	Average = 0.758"	Average = 0.751"

The table shows an average evaluation thickness of greater than 0.758 inches in 1992 and greater than 0.751 inches in 2006 for the bathtub ring. These results are based on UT readings and average micrometer readings for only the thinnest area. UT readings and micrometer readings were generally not taken for the remainder of the shell, which were greater than 0.736 inches. In reality, the remainder of the shell is much thicker than the above results.

Again given that the average evaluation thickness of the shell in the bathtub ring area exceeds the buckling design thickness of 0.736 inches the shell area within the bathtub ring is also acceptable using the results of Reference 3.3.

### 7.13.5 Conclusion

Figure 13-7 illustrates representative areas and thicknesses in this bay as follows:

Area B - This is a 18" high by 60 inches wide area, which is at least 0.751" thick. This thickness is based on the thickness of the Bathtub ring (refer to section 7.13.4).

Area C - This is a 12" by 12" area (within area B) is at least 0.658 inches thick. This thickness is based on the evaluation in section 7.13.3.2.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 62 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

Area D- The remaining areas of the Bay is 0.800 inches thick or greater. This thickness is based on the evaluation in section 7.13.4.

Therefore this bay meets the acceptance criteria based on the following:

- 1) All individual readings are greater than 0.490 inches.
- 2) Except for Area C, the entire bay has thickness greater than 0.736 inches.
- 3) Area C (which is limited to an area of 12" by 12") meets the acceptance criteria in section 6.2.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 63 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Figure 13-1

## BAY #13 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Spots with suffix (e.g. 1A or 2A) were located close to the spots in question and were ground carefully to remove minimum amount of metal but adequate enough for UT.
3. PII depths are average of four readings taken at 0/45/90/135° within 1" distance around ground spot. Taken only where remaining wall showed below 0.736".





Figure 13-2

# Bay 13 - 2006

## Spatial Relationship Of Locally Thin Areas




OCLR00030739

Figure 13-3

# Bay 13 Points 7, 8 and 11

C-1302-187-5920-024  
Rev. 2, Page 65



OCLR00030740

Figure 13-4

# Bay 13 Points 7, 8 and 11 Horizontal Profile






Figure 13-5

# Bay 13 Points 7, 8 and 11 Vertical Profile

C-1302-187-5320-024  
Rev. 2, Page 67





Figure 13-6

# Bay 13 2006 Representative Thicknesses




C-1302-187-5320-024  
Rev. 2, Page 68

OCLR00030743

Figure 13-7

### Bay 13 - 2006 Locally Thin Areas

C-1302-187-5320-024  
Rev. 2, Page 69



OCLR00030744

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Case No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 70 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.15 UT EVALUATION BAY 15 SUMMARY

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball. The bathtub ring seen in the other bays, was not very prominent in this bay (references 3.6). This observation is made by the inspector who located the thinnest areas for the UT examination. The upper portion of the shell beyond the ring exhibits no corrosion where the original red lead primer is still intact. The shell appears to be relatively uniform in thickness.

#### 7.15.1 Bay #15 Local Readings Less Than The Uniform Criteria

Eleven areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 15-1). These areas are a deliberate attempt to produce a minimum measurement. Table 15-1 shows readings taken to measure the thinnest thicknesses of the drywell shell. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one area in 1992 and another area in 2006. Inspector observations indicate that these areas were very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surrounding was measured at 4 azimuths around the spot and the average is shown in Table 15-1.

These areas and their location are shown on figure 15-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

**Table 15-1 Bay #15 Thinnest UT Data**

Location	1992 UT Measurements	2006 UT Measurements
	(inches)	(inches)
1	0.786	0.711
2	0.829	0.777
3	0.932	0.935
4	0.795	0.791
5	0.850	0.817
6	0.794	0.715
7	0.808	0.805
8	0.770	0.760
9	0.722	0.720
10	0.860	0.837
11	0.825	0.798
Average	0.816	0.788

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 71 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramoyici		Date

### 7.15.2 Bay #15 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 1, was 0.711 inches in 2006.

### 7.15.3 Bay 15 Local Wall Thickness Evaluation (Local Buckling)

**Table 15-2 Summary of Measurements Below 0.736 Inches**

Area	1992	2006	1992	2006	1992	2006	Section
9	0.722"	0.720"	0.337"	0.200"	0.859"	0.857"	7.15.3.1
1	0.736"						7.15.3.2

#### 7.15.3.1 Evaluation of Area 9

The calculated "Evaluation Thickness" of area 9 in 1992 and 2006 are greater than 0.736". Therefore this area meets the acceptance criteria.

#### 7.15.3.2 Evaluation of Area 1

The individual thinnest reading for area 1 in 1992 was greater than 0.736". Therefore this area was not characterized with a micrometer and depth measurements are not available. This area cannot be evaluated using the "Evaluation Thickness". However the 2006 reading was less than 0.736". Therefore area 1 was evaluated against the local buckling criteria per section 6.2.

Area 1 has a single reading of 0.711" in 2006. This single point was determined by the inspectors to be the thinnest within this area. Figure 15-3 plots area 1 and all other recorded areas close by. Figure 15-3 overlays a 36" by 36" area on these locally thin areas. The center 12" by 12" of the area is overlaid on top of area 1.

Figure 13-4 and 13-5 shows the profile of the 36" by 36" area with the area thickness overlaid on the curve depicting the acceptance criteria. Figure 13-4 shows the profile along the horizontal axis and figure 13-5 shows the profile along the vertical axis. These figures show that the local buckling criteria is met.

#### 7.15.3.3 Combined Effect of Locally Thin Areas on Buckling

There are several conservative factors associated with the size and the location of the locally thin areas which cannot be quantified but are judged to be substantial in demonstrating that the measured thickness are adequate. These are described below.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 72 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

7.15.3.3.1 Refer to figure 15-7. The locally thin area for this bay that is less than 0.736 inches is located under the vent line.

The local buckling criteria (section 6.2) is based on sensitivity studies that placed a 36" by 36" locally thin grid on the area of the finite element model that had the highest buckling stresses. This area is located between the centerlines of the vent lines (+66" to -66" as shown in figure 15-2). Areas below the vents lines had less compressive stresses. Therefore locally thin areas located under a vent lines will have more margin than the same locally thin areas located between the centerline of the vent lines. Review of the original GE study shows that stresses under the vent line are at least 20% less than the stresses between the centerline of the vent lines. Therefore the necessary wall thickness to maintain the required safety factor for portions of the vessel under the vent lines is substantially less (by at least 20%) than the calculated required uniform thickness of 0.736".

7.15.3.3.2 A second factor is the cumulative size of the locally thin areas, which are significantly much smaller than the analyzed 36" by 36" area (see the figure in section 6.2). The total volume of this 36" by 36" area when compared to the volume of a similar 36" by 36" area with a uniform thickness of 0.736" correspond to a reduced volume of 72.0 cubic inches.

The cumulative volume of two locally thin areas is 0.219 cubic inches (see the table below).

Table 15-3

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/2 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $(0.736 - \text{Column 2}) * 3.142 * (2.5/2) ** 2$
1	0.711	0.133
9	0.72	0.085
	Total	0.218

Therefore the comparison of the "as found" volume reduction which is less than 0.219 cubic inches to the "analyzed" volume reduction of 72 cubic inches leads to the conclusion that the effect on the buckling load factor is negligible.

In addition since the majority of the vessel in this bay is thicker than 0.736", the thicker areas will reinforce the locally thin areas. For example approximately 8925 square inches of surface area in this bay (of a total of 9072 square inches) is 788 mils or thicker (refer to figure 15-7). When compared to same surface area with a thickness of 0.736" there is a total increase in volume of at least 464 cubic inches. (e.g.  $464 = (0.788 - 0.736) * 8925$ ). This additional volume will reinforce the locally thin areas.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 73 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.15.4 Bay #15 General Wall Thickness Criteria (Buckling)

The UT measurements presented in Table 15-1 equal an average of 0.815 inches in 1992 and 0.788" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

### 7.15.5 Conclusion

Figure 15-7 illustrates representative areas and thicknesses in this bay as follows:

- Area A - This is a 12" high by 12 inches wide area, which is at least 0.711" thick. This thickness is based on section 7.15.3.2).
- Area D- The remaining area of the Bay is 0.788 inches thick or greater. This thickness is based on the evaluation in section 7.15.4.

Therefore this bay meets the acceptance criteria based on the following:

- 1) All individual readings are greater than 0.490 inches.
- 2) Except for Area A, the entire bay has thickness greater than 0.736 inches.
- 3) Area A (which is limited to an area of 12" by 12") meets the acceptance criteria in section 6.2.





Figure 15-2

# Bay 15 2006 Spatial Relationship Of Locally Thin Areas

C-1302-187-5320-024  
Rev. 2, Page 75

Evaluated area  
Area in 15-3





Figure 15-3

### Bay 15 Locations 1, 2, 6, 7, 11 and 21 Evaluation Thickness




C-1802-187-5920-024  
Rev. 2, Page 76

OCLR00030751

Figure 15-4

### Bay 1 Horizontal Profile (Evaluation Thickness versus Local Buckling Criteria)




— 636 Criteria ■ Point →

OCLR00030752

Figure 15-5

### Bay 1 Vertical Profile (Evaluation Thickness versus Local Buckling Criteria)




— 636 Criteria ■ Points —

C-1802-187-5320-024  
Rev. 2, Page 78

Figure 15-6

C-1302-187-5320-024  
Rev. 2, Page 79

# Bay 15 2006 Locally thin Areas



All X and Y dimensions are referenced from the centerline of the vent line (X direction) and the bottom of the Penetration Reinforcement Pad (Y dimension).  
Reference NDE Data sheet 92-072-21 page 1 of 1 and 1R2ALR-015 page 2 of 2.

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 80 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

### 7.17.1 UT EVALUATION BAY #17 SUMMARY

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball (references 3.6). The shell appears to be relatively uniform in thickness except for a band 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact.

#### 7.17.1 Bay #17 Local Readings Less Than The Uniform Criteria

Eleven areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 17-1). These areas are a deliberate attempt to produce a minimum measurement. Table 17-1 shows readings taken to measure the thinnest thicknesses of the drywell shell. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one area. Area 9 as shown in Table 17-1, has a reading below 0.736 inches. Inspectors' observations indicate that this area is very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surroundings was measured at 4 areas around the spot and the average is shown in Table 17-1.

Table 17-1 shows that one area was less than 0.736" in 1992 and another area in 2006. All other areas were greater than 0.736".

These areas and their location are shown on figure 17-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

Table 17-1 Bay # 17 Thinnest UT Data

Location	1992 UT	2006 UT
	Measurements	Measurements
	(inches)	(inches)
1	0.916	0.909
2	1.150	0.663
3	0.898	0.894
4	0.951	0.963
5	0.913	0.822
6	0.992	0.909
7	0.970	0.970
8	0.990	0.960
9	0.720	0.970
10	0.830	0.844
11	0.770	NA
Average	0.918	0.890

#### 7.17.2 Bay #17 Very Local Wall Thickness Evaluation (Pressure Only)

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 2, was 0.663 inches in 2006.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 81 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julia Abramowicz		Date

### 7.17.3 Bay 17 Local Wall Thickness Evaluation (Local Buckling)

**Table 17-2 Summary of Measurements Below 0.736 Inches**

Area	1992 Thinnest Reading	2006 Thinnest Reading	1992 Local Criteria	2006 Local Criteria	1992 Evaluation	2006 Evaluation	Reference
9	6.120"	0.970"	0.351"	0.200"	0.871"	1.121"	7.17.3.1
2	1.150"	0.663"					7.17.3.2

#### 7.17.3.1 Area 9

The calculated "Evaluation Thickness" of area 9 in 1992 is greater than 0.736". Therefore this area meets the acceptance criteria. Since the 2006 UT measurement was much greater than the 1992 value a corresponding "Evaluation Thickness" for 2006 was not considered and only the 1992 value used for the evaluation.

#### 7.17.3.2 Area 2

The 1992 value for area 1 is not considered credible. The basis for this statement is that the corresponding corrosion rate would have to be 35 mils per year for the 1992 value to be credible. This amount of corrosion would have been observed by the visual coating inspections. Especially since the corrosion byproducts, which are between 5 to 10 times less dense than the carbon steel, would create a blister in the area which would be about 2 1/4" in diameter. However the "worst case" evaluation was performed in reference 3.8 by applying a 35 mil per year rate on the thinnest reading found in 2006 (location 7 and in bay-13 which is 602 mils). The evaluation showed that that location would not corrode to the less than the very local criteria (490 mil) prior to the next committed inspection, which is 2008.

The individual thinnest reading for area 2 in 1992 was greater than 0.736". Therefore this area was not characterized with a micrometer and depth measurements are not available. This area cannot be evaluated using the "Evaluation Thickness". Therefore area 2 will be evaluated against the local buckling criteria per section 6.2.

Area 2 has a single reading of 0.663" in 2006. This single point was determined by the inspectors to be the thinnest within this area. Figure 17-3 plots area 2 and all other close by areas recorded in 1992 and 2006. Figure 15-3 overlays a 36" by 36" area on these areas. The center 12" by 12" of the area is overlaid on top of area 2.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 82 of 163
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

Figure 17-4 and 17-5 shows the profile of the 36" by 36" area with the single thickness overlaid on the curve depicting the acceptance criteria. Figure 17-4 shows the profile along the horizontal axis and figure 17-5 shows the profile along the vertical axis. These figures show that the local buckling criteria is met.

#### 7.17.3.3 Combined Effect of Locally Thin Areas on Buckling

There are several conservative factors associated with the size and the location of the locally thin areas which cannot be quantified but are judged to be substantial in demonstrating that the measured thickness are adequate. These are described below.

7.17.3.3.1 Refer to figure 17-7. The locally thin area for this bay that is less than 0.736 inches is not located between the centerline of the vent lines. The 12" by 12" locally thin area is located approximately at +20" to +56" of the vent line.

The local buckling criteria (section 6.2) is based on sensitivity studies that placed a 36" by 36" locally thin grid on the area of the finite element model that had the highest buckling stresses. This area is located between the centerlines of the vent lines (+66" to -66" as shown in figure 17-2). Areas between +20" to +56" from the vent lines had less compressive stresses. Review of the original GB study (see appendix F) shows that stresses in this region are at least 10% less than the stresses between the centerline of the vent lines. Therefore the necessary wall thickness to maintain the required safety factor for portions of the vessel under the vent lines is less (by at least 10%) than the calculated required uniform thickness of 0.736".

7.17.3.3.2 A second factor is the cumulative size of the two locally thin areas, which are significantly much smaller than the analyzed 36" by 36" area (see the figure in section 6.2). The total volume of this 36" by 36" area when compared to the volume of a similar 36" by 36" area with a uniform thickness of 0.736" correspond to a reduced volume of 72.0 cubic inches.

The cumulative volume of two locally thin areas is less than 0.634 cubic inches (see the table below).

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/2 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $0.736 - \text{Column 2}) * 3.142 * (2.5/2)^2 * 2$
2	0.633	0.549
9	0.720	0.085
	Total	0.634

Therefore the comparison of the "as found" volume reduction which is less than 0.634 cubic inches to the "analyzed" volume reduction of 72 cubic inches leads to the conclusion that the effect on the buckling load factor is negligible.



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 83 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

In addition since the majority of the vessel in this bay is thicker than 0.736", the thicker areas will reinforce the locally thin areas. For example approximately 7776 square inches of surface area in this bay (of a total of 9072 square inches) is 892 mils or thicker (refer to figure 15-7). When compared to same surface area with a thickness of 0.736", there is a total increase in volume of at least 1210 cubic inches. (e.g.  $1210 = (0.892 - 0.736) * 7776$ ). This additional volume will reinforce the locally thin areas.

#### 7.17A Bay #17 General Wall Thickness Criteria (Buckling)

The UT measurements presented in Table 17-1 equal an average of 0.918 inches in 1992 and 0.892" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

#### 7.17.5 Conclusion

Figure 17-7 illustrates representative areas and thicknesses in this bay as follows:

- Area A - This is a 12" high by 12 inches wide area, which is at least 0.663" thick. This thickness is based on section 7.17.3.2).
- Area B - This is a 36" high by 36 inches wide area surrounding area, which is at least 0.850" thick. This thickness is based on section 7.17.3.2.
- Area C - The remaining area of the Bay is 0.892 inches thick or greater. This thickness is based on the evaluation in section 7.17.4.

Therefore this bay meets the acceptance criteria based on the following:

- 1) All individual readings are greater than 0.490 inches.
- 2) Except for Area A, the entire bay has thickness greater than 0.736 inches.
- 3) Area A (which is limited to an area of 12" by 12") meets the acceptance criteria in section 6.2.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 84 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici	Date

Figure 17-1

# BAY #17 DATA

1. All measurements from intersection of the DW (out) shell and vent collar (inlet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spots. Taken only when remaining wall thickness was below 0.738".




FIGURE (17)

Figure 17-2

# Bay 17 2006

## Spatial Relationship Of Locally Thin Areas

Evaluated area  
Area 17-8




Figure 17-3

# Bay 17 Locations 1, 2, 6, 7, 11 and 21 Evaluation Thickness

C-1802-187-5320-024  
Rev. 2, Page 86





Figure 17-4

### Bay 17 Horizontal Profile (Evaluation Thickness versus Local Buckling Criteria)




— 636 Criteria ■ Point

C-1302-167-5320-024  
Rev. 2, Page 87

Figure 17-5

### Bay 17 Vertical Profile (Evaluation Thickness versus Local Buckling Criteria)

Figure 17-3




C-1302-187-5320-024  
Rev. 2, Page 88

Figure 17-6

C-1302-187-5320-024  
Rev. 2, Page 89

# Bay 17 2006 Locally Thin Area

Bottom of Penetration  
Reinforcement Pad



All X and Y dimensions are referenced from the centerline of the vent line (X direction) and the bottom of the Penetration Reinforcement Pad (Y dimension). Reference NDE Data sheet 92-072-04 page 1 of 1 and 1R21LR-021 page 2 of 2.

OCLR00030764

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 90 of 183
Originator Peter Tamburto	Date 3/21/07	Reviewed by Julien Abramovici		Date

### 7.19 UT EVALUATION BAY 19 SUMMARY

The outside surface of this bay is rough and very similar to bay 17. Areas 1 through 7 as shown in Table 19-1, were ground carefully to minimize loss of good metal. The shell surface is full of dimples comparable to the outside surface of a golf ball (references 3.6). This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Ten areas were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 19-1). These areas are a deliberate attempt to produce a minimum measurement. Table 19-1 shows readings taken to measure the thinnest thicknesses of the drywell shell. The results indicate that all of the areas have thickness greater than the 0.736 inches.

#### 7.19.1 Bay #19 General Wall (Sandbed Region) Thickness Evaluation

Table 19-1 shows that no areas were less than 0.736" in 1992 and three areas in 2006. All other areas were greater than 0.736". Since the area were greater than 0.736" in 1992 depth measurement were not performed in 1992. Therefore these area will be evaluated per section 6.2.

These areas and their location are shown on figure 19-2. The figure presents the areas with readings less than 0.736 inches as squares and areas with readings over 0.736 inches as triangles.

Table 19-1 Bay # 19 Thinnest UT Data

Location	1992 UT Measurements (inches)	2006 UT Measurements (inches)
1	0.932	0.867
2	0.924	0.850
3	0.955	0.894
4	0.940	NA
5	0.950	0.883
6	0.860	NA
7	0.969	0.820
8	0.753	0.721
9	0.776	0.728
10	0.790	0.736
11	NA	0.732
Average	0.885	0.801

#### 7.19.2 Bay #19 Very Local Wall Thickness Evaluation (Pressure Only)



Subject G.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 91 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

All individual readings were greater than the acceptance criteria of 0.490". The thinnest reading was in area 11, which was 0.712 inches in 2006.

### 7.19.3 Bay 19 Local Wall Thickness Evaluation (Local Buckling)

**Table 19-2 Summary of Measurements Below 0.736 Inches**

Location	2005 Measurement	2006 Measurement	2007 Measurement	2008 Measurement	2009 Measurement	2010 Measurement	Remarks
B	0.753	0.721	Not Available	NA	NA	NA	7.19.3.1
P	0.776	0.728	Not Available	NA	NA	NA	7.19.3.2
II	NA	0.712	Not Available	NA	NA	NA	7.19.3.3

#### 7.19.3.1 Evaluation of Area 8

Refer to figure 19-2. Area 8 has a single reading of 0.721". This area is next to areas 1 (0.867"). These two areas are bounded by a 16" by 6" area. Since these single points were determined by the inspectors to be the thinnest within this area, the average of these two thicknesses is a conservative estimate of the average thickness of the 16" by 6" area (see assumption 4.3). The average of these three readings is 0.794", which is greater than 0.736". Therefore area 8 meets the 0.736" uniform criteria.

#### 7.19.3.2 Evaluation of Areas 9 and 11

In 2006 area 9 had a single reading of 0.728 and area 11 had a single reading of 0.712". These single points were determined by the inspectors to be the thinnest within this area. Figure 19-3 plots area 9 and 11 along with area 10, which is 0.736". Figure 19-3 overlays a 36" by 36" area on these locations.

Figure 19-4 and 19-5 shows the profile of the 36" by 36" area with the single thickness overlaid on the curve depicting the acceptance criteria. Figure 19-4 shows the profile along the horizontal axis and figure 13-5 shows the profile along the vertical axis. These figures show that the local buckling criteria is met. Please note that Figure 19-4 does shows that the two locally thin area come close to the edges of the 36" by 36" acceptance criteria envelope. However since these areas are significantly smaller than the analyzed area and since the two areas are actually located at an azimuth of the drywell that sees less stress (7.19.3.3) the closeness to the envelop is judge to be inconsequential. Also these areas were found to be thinner than 0.736" at different times.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 92 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

Most likely the 2006 data is more representative, which means that there is only one area in this bay, which is less than 0.736 inches.

### 7.19.3.3 Combined Effect of Locally Thin Areas on Buckling

There are several conservative factors associated with the size and the location of the locally thin areas which cannot be quantified but are judged to be substantial in demonstrating that the measured thickness are adequate. These are described below.

7.19.3.3.1 Refer to figure 19-7. The locally thin area for this bay that is less than 0.736 inches is located directly under the vent line.

The local buckling criteria (section 6.2) is based on sensitivity studies that placed a 36" by 36" locally thin grid on the area of the finite element model that had the highest buckling stresses. This area is located between the centerlines of the vent lines (+66" to -66" as shown in figure 19-2). Areas below the vents lines had less compressive stresses. Therefore locally thin areas located under a vent lines will have more margin than the same locally thin areas located between the centerline of the vent lines. Review of the original GE study (see appendix F) shows that stresses under the vent line are at least 20% less than the stresses between the centerline of the vent lines. Therefore the necessary wall thickness to maintain the required safety factor for portions of the vessel under the vent lines is substantially less (by at least 20%) than the calculated required uniform thickness of 0.736".

7.19.3.3.2 A second factor is the cumulative size of the locally thin areas, which are significantly much smaller than the analyzed 36" by 36" area (see the figure in section 6.2). The total volume of this 36" by 36" area when compared to the volume of a similar 36" by 36" area with a uniform thickness of 0.736" correspond to a reduced volume of 72.0 cubic inches.

The cumulative volume of two locally thin areas is less than 0.251 cubic inches (see the table below).

Area	Thinnest reading inside the area (inches) (Column 2)	Equivalent volume loss of 2 1/2 inches diameter area with thickness equal to thinnest readings (Column 2) when compared to a uniform thickness of 0.736 inches $(0.736 - \text{Column 2}) * 3.142 * (2.5/2)^{**2}$
8	0.721	0.080
9	0.728	0.043
10	0.736	0.000
11	0.712	0.128
	Total	0.251

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 93 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

Therefore the comparison of the "as found" volume reduction which is less than 0.251 cubic inches to the "analyzed" volume reduction of 72 cubic inches leads to the conclusion that the effect on the buckling load factor is negligible.

In addition since the majority of the vessel in this bay is thicker than 0.736", the thicker areas will reinforce the locally thin areas. For example approximately 7680 square inches of surface area in this bay (of a total of 9072 square inches) is 800 mils or thicker (refer to figure 15-7). When compared to same surface area with a thickness of 0.736" there is a total increase in volume of at least 490 cubic inches. (e.g.  $490 = (0.800 - 0.736) * 7680$ ). This additional volume will reinforce the locally thin areas.

#### 7.19.4 Bay #19 General Wall Thickness Criteria (Buckling)

The UT measurements presented in Table 17-1 equal an average of 0.885 inches in 1992 and 0.801" in 2006. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

#### 7.19.5 Conclusion

Figure 19-7 illustrates representative areas and thicknesses in this bay as follows:

- Area A - This is a 16 inches high by 6 inches wide area, which is at least 0.794" thick. This thickness is based on section 7.19.3.2).
- Area B - This is a 36" high by 36 inches wide area is at least 0.720" thick. This thickness is based on section 7.19.3.1.
- Area C - The remaining area of the Bay is 0.800 inches thick. This thickness is based on the evaluation in section 7.19.4 or greater.

Therefore this bay meets the acceptance criteria based on the following:

- 1) All individual readings are greater than 0.490 inches.
- 2) Except for Area B, the entire bay has thickness greater than 0.736 inches.
- 3) Area C (which is limited to an area of 36" by 36") meets the acceptance criteria in section 6.2.

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 94 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici	Date

Figure 19-1

## BAY #19 DATA

### NOTES:

- All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE (19)

Figure 19-2

# Bay 19 2006

C-1302-187-5320-024  
Rev. 2, Page 95

## Spatial Relationship Of Locally Thin Areas




Figure 19-3

### Bay 19 Locations 1, 2, 6, 7, 11 and 21 Evaluation Thickness





Figure 19-4


### Bay 19 Horizontal Profile (Evaluation Thickness versus Local Buckling Criteria)



C-1302-187-5320-024  
Rev. 2, Page 97

Figure 19-5

### Bay 19 Vertical Profile (Evaluation Thickness versus Local Buckling Criteria)



— 636 Criteria ■ Points

G-1802-187-6320-024  
Rev. 2, Page 98


OCLR00030773



Figure 19-7

# Bay 19 2006 Locally Thin Areas

C-1302-187-5320-024  
Rev. 2, Page 89



OCLR00030774

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 100 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

Appendix A: Summary Of Measurements Of Impressions Taken From Bay #13 (3 pages total)

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 101 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

The purpose of this appendix is to characterize the depth of typical uniform dimples on the shell surface. This depth is used in acceptance criteria to quantify the evaluation thickness for an area where the micrometer readings are available.

Two locations in bay 13 were selected since bay 13 is the roughest bay. Impressions of drywell shell surface using DMR 503 Epoxy Replication Putty manufactured by Dyna Mold Inc were made. These impressions were about 10 inches in diameter and about 1 inch thick. The UT locations 7 and 10 in bay 13 were identified in each of these impressions as the reference points. This is a positive impression of the drywell shell surface. The depth of the typical dimples were measured as follows;

<u>READING</u> (Location)	<u>DEPTH #10</u> (inches)	<u>DEPTH #7</u> (inches)
1	0.150	0.075
2	0.000	0.110
3	0.200	0.135
4	0.140	0.200
5	0.150	0.000
6	0.040	0.000
7	0.150	0.170
8	0.010	0.205
9	0.134	—
10	0.145	0.145
11	0.118	0.064
12	0.105	0.200
13	0.125	0.045
14	0.200	0.180
15	0.135	0.105
16	0.100	—
17	0.175	0.035
18	0.175	0.015
19	0.155	0.190
20	0.175	0.055
21	0.175	0.305
22	—	0.135

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 102 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici	Date	

Location #10:

Mean Value = 0.131  
Standard Deviation = 0.055  
  
Mean Value + One S.D. = 0.186

Location #7:

Mean Value = 0.118  
Standard Deviation = 0.082  
  
Mean Value + One S.D. = 0.200

Therefore, a value of 0.200 inches was used as the depth of uniform dimples for the entire outside surface of the drywell in the sandbed region.

<b>Subject</b> G.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 103 of 163
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>

Appendix B: Buckling Capacity Evaluation For Varying Uniform Thickness Through The Whole Sandbed Region Of The Drywell (5 pages total)

Based Upon GE Buckling Analysis (Reference 3.3)

**Note: Tables on sheets 53 to 56 are not used in this calculation and are provided for historical purpose only from Rev. 0.**

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-167-5320-024	Rev. No. 2	Sheet No. 104 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramoyici	Date

**CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GE OYCRIS&T - UNIFORM THICKNESS  $t=0.736$  Inch**

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.736	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	46.590	6.140
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	7.588	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.510	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.806	
11	X Parameter, $X = (P_{eq}/8E) (d/t)^2$		0.087	
12	Delta C (From Figure -)		0.072	
13	Modified Capacity Reduction Factor, ALPHA <sub>1, mod</sub>		0.326	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.182	2.001
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, $\Delta = S_c/S_y$		0.400	
16	Plasticity Reduction Factor, NU1		1.000	
17	Inelastic Instability Stress, $S_i = NU1 \times S_e$	(ksi)	15.182	2.001
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.591	1.000
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$	(%)	0.0	

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 103 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

**CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GE OYCRFST01 - UNIFORM THICKNESS  $t=0.776$  Inch**

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420.	
2	Sphere Thickness, t	(in.)	0.776	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	49.357	6.857
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	7.198	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.248	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	X Parameter, $X = (P_{eq}/8E)(d/t)^2$		0.078	
12	Delta C (From Figure -)		0.066	
13	Modified Capacity Reduction Factor, ALPHA <sub>1, mod</sub>		0.316	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.583	2.165
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA = $S_e/S_y$		0.410	
16	Plasticity Reduction Factor, NUI		1.000	
17	Inelastic Instability Stress, $S_i = NUI \times S_e$	(ksi)	15.183	2.165
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.592	1.082
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$	(%)	82	

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 106 of 183
Originator Peter Tamburo	Date 3/21/07	Reviewed by Julien Abramovici		Date

**CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GPUN EVALUATION FOR UNIFORM THICKNESS  $t=0.800$  Inch USING THICKNESS RATIO**

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.800	
3	Material Yield Strength, Sy	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	50.884	7.288
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	6.982	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.120	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	K* Parameter, $K^* = (P_{eq}/SE)(d/t)^2$		0.073	
12	Delta C (From Figure - )		0.063	
13	Modified Capacity Reduction Factor, ALPHA <sub>1, mod</sub>		0.311	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.824	2.266
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA = $S_e/S_y$		0.416	
16	Plasticity Reduction Factor, NU1		1.000	
17	Inelastic Instability Stress, $S_i = NU1 \times S_e$	(ksi)	15.824	2.266
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.912	1.133
19	Compressive Stress Margin, M = $(S_{all}/S_m - 1) \times 100\%$	(%)	13.3	



Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 107 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by Julien Abramovici		Date

**CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GPUN EVALUATION FOR UNIFORM THICKNESS  $t = 0.850$  Inch USING THICKNESS RATIO**


ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.850	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	54.063	8.227
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	6.571	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	3.878	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	X' Parameter, $X' = (P_{eq}/SE) (d/t)^2$		0.065	
12	Delta C (From Figure - )		0.057	
13	Modified Capacity Reduction Factor, ALPHA <sub>1, mod</sub>		0.300	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	16.257	2.474
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA = $S_e/S_y$		0.428	
16	Plasticity Reduction Factor, NUI		1.000	
17	Inelastic Instability Stress, $S_I = NUI \times S_e$	(ksi)	16.257	2.474
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_I/FS$	(ksi)	8.128	1.237
19	Compressive Stress Margin, $M = (S_{all}/S_m \cdot I) \times 100\%$	(%)	23.7	

<b>Subject</b> O.C. Drywell Ext. UF Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 2	<b>Sheet No.</b> 108 of 183
<b>Originator</b> Peter Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b> Julien Abramovici		<b>Date</b>


This page was left blank intentionally

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandford		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 3	<b>Sheet No.</b> 109 of 183
<b>Originator</b> Fete Tamburo	<b>Date</b> 3/21/07	<b>Reviewed by</b>		<b>Date</b>



Sand Bad Region - Typical condition found on initial entry.




Corrosion product on drywell vessel

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. O-1302-187-5320-024	Rev. No. 3	Sheet No. 110 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date




Bay #12 - DW shell showing plug . The plug is located in the middle of the worst corroded area of the shell. The plug showed no sign of corrosion.




Bay #13 - DW shell showed less prominent "Tub Ring" than what was seen in other

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Case No.</b> C-1302-181-5320-024	<b>Rev. No.</b> 3	<b>Sheet No.</b> 111 of 183
<b>Originator</b> Pete Tamburo	<b>Date</b> 3/21/07	<b>Reviewed by</b>		<b>Date</b>



Bay #1 - Looking at the worst corroded area on shell near vent tube collar. The ground spots seen here correspond to UT spot 20.2 - 2.3




Bay #13 - Lower Mid portion of the DW shell showing UT spot 5.6 and 10. This close up photo shows the roughness of the corroded surface and how each UT spot has been picked up in the deep valleys - thereby biasing the remaining wall readings to the conservative side




# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-S320-024	<b>Rev. No.</b> 3	<b>Sheet No.</b> 113 of 183
<b>Originator</b> Pete Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b>		<b>Date</b>




Bay #16 - Looking towards Bay #17 which has been closed with foam for coating work in Bay #17. Note the typical surface of the DNV shell and localized corroded spot




Bay #13 - Looking toward Bay #15 - Lower left corner showing UT spot #7, 12 & 15. This close up has captured the peaks and valleys of the corroded shell in vivid detail. Later NDE inspection revealed notch between peaks and valleys in the  $\Delta 25" - 0.40"$

# GPU Nuclear

Subject O.C. Drywell Ext. IJT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 114 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date



Bay #18 Looking toward Bay #19 showing portions of OCV shell and concrete floor, after removal of loose debris of sand / rust. The concrete floor in this bay is one of the better ones. However - Note O no drainage channel and O cratered holes near shell corner




Bay #18 - Note the original lead primer on vent-tube OCV surface. The "Tub Ring" was less prominent on the shell in this bay except a portion in lower left corner. Also note presence of lead primer on vent collaring plate.



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> O-1302-187-5320-074	<b>Rev. No.</b> 3	<b>Sheet No.</b> 115 of 183
<b>Originator</b> Pete Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b>		<b>Date</b>




**Bay #13 - Looking toward Bay #11 - Lower right corner of D/W shell showing UT spots 9, 10, 18 & 19. Note the location of these spots - all are located in the valleys of the corroded surface. This photo also shows the condition of the concrete floor. It appears**



**Bay #13 - Looking toward Bay #15 - This photo captures the concrete floor condition and a portion of lower shell corroded surface in very great detail. The floor in this area**

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 5	Sheet No. 116 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date



Finished floor, vessel with two top coats - caulking material applied.



Drain after floor has been refurbished

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1362-187-5320-024	Rev. No. 5	Sheet No. 117 of 183
Originator Pete Tamburro	Date 5/21/07	Reviewed by	Date	

Appendix D: NDE Inspection Sheets for the Drywell Sandbed Region (52 pages total)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Case No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 118 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date



## NDE Request Oyster Creek

DC Charge No. 151A-57307

Request No. 92-578

To be filled in by Requestor			
Job Order No.	Sheet Form No.	BA No. <u>342295</u>	Date of Request
Job Description <u>UT THICKNESS OF D.W. INNER</u>		System	
Job Location <u>SAND BED AREA</u>		Applicable Code/Specification <u>ASME SEC. VIII</u>	
Type of NDE required:			
<input type="checkbox"/> Visual	<input type="checkbox"/> Hard Penetrant	<input type="checkbox"/> Eddy Current	<input type="checkbox"/> Ultrasonic
<input type="checkbox"/> Radiograph	<input type="checkbox"/> Magnetic Particle	<input type="checkbox"/> Alloy Separator	<input type="checkbox"/> Acoustic Emissions
<input type="checkbox"/> Video	<input type="checkbox"/> Radiographic	<input type="checkbox"/> Ferrite	
NDE Requested by <u>J. SLATER FOR</u>		Phone No.	Date <u>12-8-97</u>
Remarks <u>JOHN FLYNN</u>			

To be filled in by NDE Coordinator					
NDE Coordinator <u>J. SLATER</u>					Date
Instructions					
UT	PT	MT	ET	VT	ET
<input checked="" type="checkbox"/> <del>UT</del>	Type	DT	Multiple	<input type="checkbox"/> Direct	<input type="checkbox"/> Probe
<input type="checkbox"/> RT	<input type="checkbox"/> A1	<input type="checkbox"/> Red	<input type="checkbox"/> RT	<input type="checkbox"/> Yield Loss	<input type="checkbox"/> Double
<input type="checkbox"/> ET	<input type="checkbox"/> A2	<input type="checkbox"/> Black	<input type="checkbox"/> CT	<input checked="" type="checkbox"/> INDIRECT/VIDEO	<input type="checkbox"/> Single
<input type="checkbox"/> RT	<input type="checkbox"/> A3	<input type="checkbox"/> Dry	X-Ray	<input type="checkbox"/> Mirror	<input type="checkbox"/> Coll.
<input type="checkbox"/> Other	<input type="checkbox"/> B1	<input type="checkbox"/> Crown	<input type="checkbox"/> 150 KV	<input type="checkbox"/> Borescope	<input type="checkbox"/> Gauge
<input type="checkbox"/> Acoustic Emission	<input type="checkbox"/> B2	Wet	<input type="checkbox"/> 250 KV	<input type="checkbox"/> Fiberoptic	<input type="checkbox"/> Single
	<input type="checkbox"/> B3	<input type="checkbox"/> Back		<input type="checkbox"/> Binocular	<input type="checkbox"/> Alloy Dep.
		<input type="checkbox"/> Fluorescent		<input type="checkbox"/> Camera	<input type="checkbox"/> Ferrite
Remarks					



Results	MAJOR #s open/closed/cond. val.	Proc. No.
<input type="checkbox"/> Accept	<u>NA</u>	Proc. No.
<input type="checkbox"/> Retest		Proc. No.
<input type="checkbox"/> Hold		Job start date
<input type="checkbox"/> Other		Job stop date
NDE Coordinator	Date Closed	Date to DCC
<u>J. SLATER</u>	<u>12-25-97</u>	<u>12-25-97</u>

Notes - Original, Final Copy      Gold - Operator, Final Copy      1450182-03-07



# GPU Nuclear

Subject O.C. Drywell Ext. IT Evaluation in Sandbed		Calc. No. C-1302-187-5326-024	Rev. No. 3	Sheet No. 120 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by	Date	

GPU Nuclear			INDEX REPORT LOG			
Oyster Creek - OC			Page _____ of _____			
INDEX # 92-072			Test: <input type="checkbox"/> DT <input type="checkbox"/> NT <input type="checkbox"/> OT <input type="checkbox"/> ST <input type="checkbox"/> T <input type="checkbox"/> D			
System Location: D.W. LINER SANDBED			Date: _____			
Report #	Test Type	Date of Test	Passing			Remarks
			I	E	T	
92-072-01	UT	12-5-92				BAY 17
92-072-02	UT	12-5-92				BAY 18
92-072-03	UT	12-11-92				BAY 17
92-072-04	UT	12-11-92				BAY 17
92-072-05	UT	12-19-92				BAY 19
92-072-06	UT	12-11-92				BAY 17
92-072-07	UT	12-11-92				BAY 19
92-072-08	UT	12-11-92				BAY 17
92-072-09	UT	12-22-92				BAY 11
92-072-10	UT	12-22-92				BAY 11
92-072-11	UT	12-22-92				OVERLAY PLATE
92-072-12	UT	1-2-93				BAY 1
92-072-13	UT	1-2-93				BAY 1
92-072-14	UT	1-2-93				BAY 3
92-072-15	UT	1-2-93				BAY 3
92-072-16	UT	1-2-93				BAY 5
92-072-17	UT	1-2-93				BAY 5
92-072-18	UT	1-2-93				BAY 1
92-072-19	UT	1-5-93				BAY 1
92-072-20	UT	1-8-93				BAY 7

FORM NO. 4135 (REV. 7/25/01) 228, 624

AD001537

# GPU Nuclear

Subject O.C. Drywell Ext. IIT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 121 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date

Program	Size	Screen	Depth
1	5 mls 30" single #32500 cob	6"	2"
2	5 mls 30" single #20002	2"	2"
3	5 mls #32500 #32500	2"	2"
4	5 mls tubular water delay	2" delay	2" delay
5	5 mls tubular water delay	2" spec screen	none
6	5 mls tubular water delay	2" spec screen	2"
7	5 mls 30" single #32500 cob	1"	1"
8	5 mls #32500 #32500	1"	2"
9	5 mls 30" delay #32500 cob	2"	none
10	5 mls 30" dual #32500	1"	1"
11	5 mls 30" dual #32500	2"	2"

Specs for your info.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandwell		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 122 of 183
Originator Fete Tambarro	Date 3/21/07	Reviewed by		Date

GPU Nuclear				Ultrasonic Thickness Data Sheet			
<input checked="" type="checkbox"/> DS	<input type="checkbox"/> TM-1	<input type="checkbox"/> TIME	<input type="checkbox"/> CHART	Units	GA	NOTE REQUEST	7.0-0744
Task Description				RT	Thickness	013	Date
Comp. Dept.				System	189	Component	Ext. W. W. S.
Procedure/Spec				SA-320	SA-320	SA-320	SA-320
Test Surface				0.0	0.0	0.0	0.0
Examiner	Sight	PRINCE J. CHAVEZ	ID No.				
Examiner	Sight	PRINCE J. CHAVEZ	ID No.				
Thermometer/STN				22.0	22.0	22.0	22.0
CAL. BR. STN				2.27	2.27	2.27	2.27
CAL. BR. TEMP				2.27	2.27	2.27	2.27
Position #/Reading in inches							
Cal. Unit				5	5	5	5
Diameter				5	5	5	5
Gauging Reference (Inches)							
Techniques							
Drawing							
Drawing No.							
Drawing Title							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							
Drawing Reviewer							
Drawing Date							
Drawing Scale							
Drawing Author							





# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 124 of 183
Originator Pete Tambore	Date 3/21/07	Reviewed by		Date

2.5 inches under

### Ultrasonic Thickness Data Sheet

<input type="checkbox"/> 100 <input type="checkbox"/> 1000 <input type="checkbox"/> 10000 Thickness	Name: <i>N/A</i> NDE Request: <i>92 - UTA</i> Material: <i>N/A</i>	Drawing No./Rev: <i>3E-157-03-001</i> Thickness: <i>1/8"</i> Material: <i>SA-509</i>	Date Sheet No.: <i>1007-001</i> Date: <i>1-18-07</i>	Drawing No./Rev: <i>3E-157-03-001</i> Thickness: <i>1/8"</i> Material: <i>SA-509</i>	Drawing No./Rev: <i>3E-157-03-001</i> Thickness: <i>1/8"</i> Material: <i>SA-509</i>
Examined By: <i>[Signature]</i> ID No.: <i>[Redacted]</i> Technician: <i>[Redacted]</i>					
Examined Site: <i>Prim. Mod. F. Bayonet</i>					
Thermometer SN: <i>92-085</i> Part Temperature: <i>18.7</i> D-Value: <i>5700-030</i> Cal. SN: <i>92-085</i> Cal. Date: <i>11/11/05</i> Cal. By: <i>AM</i> Cal. Exp. Date: <i>11/11/07</i>					
Position #/Resting in Inches					
			Drawing: <i>3E-157-03-001</i>		
Inspected by: <i>[Signature]</i> Date: <i>1-18-07</i> Page: <i>1</i> of <i>1</i>					

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Case No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 125 of 183
<b>Originator</b> Pete Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b>		<b>Date</b>

**Sketch Form (with grid)**

**GPU Nuclear**     **YME**     **OTHER**

**Component:** Drywell Deck    **Sandbed Area**

**Location:** Bay # 1

**Drawing:**

**Drawn by:** [Signature]

**Checked by:** [Signature]

**Date:** 3/21/07

**Scale:** 1/4" = 1'-0"

**Notes:**  
 1. SANDBED AREA IS TO BE EVALUATED WITH THE UT EQUIPMENT.  
 2. THE UT EQUIPMENT IS TO BE USED TO EVALUATE THE SANDBED AREA.  
 3. THE UT EQUIPMENT IS TO BE USED TO EVALUATE THE SANDBED AREA.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 126 of 185
Originator Pete Tamborra	Date 3/21/87	Reviewed by		Date

**Ultrasonic Thickness Data Sheet**

Item # 92-572      Data Sheet No. 92-572

Task Description UT Thickness      Date 3-21-87

Comp. Order GPU Nuclear Unit Bay 7 System IG

Procedure/Spec ASME Sec. V, Art. 10, Para. 10.1, 10.2, 10.3, 10.4      Code/Spec. Eng. INFO

Test Station D-2      Thickness 1/8"      Material C.S.

Examiner [Signature]      ID No. [Redacted]      Level II

Examiner [Signature]      ID No. [Redacted]      Level II

Thermometer/Sensor Bay 7 Temperature 235°F      Technique Point to Point

Cal. Str. Eng. JBY ZIA      Cal. No. ASME Sec. V, Art. 10, Para. 10.1, 10.2, 10.3, 10.4

Cal. Rec. Temp. 77°F

Drawing: Bay #1


Position & Reading in Inches

Call No.	5	7.5	10	12.5	15	17.5	20	22.5	25	27.5	30	32.5	35	37.5	40	42.5	45	47.5	50	52.5	55	57.5	60	62.5	65	67.5	70	72.5	75	77.5	80	82.5	85	87.5	90
Thickness	5	7.5	10	12.5	15	17.5	20	22.5	25	27.5	30	32.5	35	37.5	40	42.5	45	47.5	50	52.5	55	57.5	60	62.5	65	67.5	70	72.5	75	77.5	80	82.5	85	87.5	90

Revised By: [Signature]      Level II      Date 3-21-87      Page 1 of 1

# GPU Nuclear

Subject G.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 127 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date



NOTE: See 92.0718  
Rev. 3 of 9

## INSPECTION SPOTS FOR UT Bay #1

### NOTE:

1. GRIND FLAT FOR UT WITH MINIMUM REMOVAL OF SUELL AT THE VALLEY

# GPU Nuclear

Subject <b>O.C. Drywell Ext. UT Evaluation in Sandbed</b>	Calc No. <b>C-1302-187-5320-024</b>	Rev. No. <b>1</b>	Sheet No. <b>128 of 183</b>
Originator <b>Pete Tamburo</b>	Date <b>3/21/07</b>	Reviewed by	Date


## Ultrasonic Thickness Data Sheet

06  07  08  09  10  11  12  13  14  15  16  17  18  19  20  21  22  23  24  25  26  27  28  29  30  31  32  33  34  35  36  37  38  39  40  41  42  43  44  45  46  47  48  49  50  51  52  53  54  55  56  57  58  59  60  61  62  63  64  65  66  67  68  69  70  71  72  73  74  75  76  77  78  79  80  81  82  83  84  85  86  87  88  89  90  91  92  93  94  95  96  97  98  99  100

Title Description: **UT**  
 Comp. Desc: **Drywell Ext.**  
 Flange/Reference: **22.02.03**  
 Test Surface: **00**  
 Examined: **Sight**  
 Examined Sign: **[Signature]**  
 Technician: **John J. Choate, Lynn**  
 Thermometer: **SIN 20.00** Part Temperature: **22.0** Exhale Temperature:  
 Cal. Air: **87F** Cal. In: **0.0** Cal. Air: **87F**  
 Cal. Air Temp: **72**

NDE Request: **50-0702**  
 Date: **1/28/07**  
 Drawing No.: **22.02.03**  
 Thickness: **0.5**  
 Calibration: **0.5**  
 Operator: **[Signature]**  
 Technician: **[Signature]**  
 Date: **3/21/07**  
 Drawing: **[Signature]**

Contractor Readings (Inches):  
 1. 0.5  
 2. 0.5  
 3. 0.5  
 4. 0.5  
 5. 0.5  
 6. 0.5  
 7. 0.5  
 8. 0.5  
 9. 0.5  
 10. 0.5  
 11. 0.5  
 12. 0.5  
 13. 0.5  
 14. 0.5  
 15. 0.5  
 16. 0.5  
 17. 0.5  
 18. 0.5  
 19. 0.5  
 20. 0.5  
 21. 0.5  
 22. 0.5  
 23. 0.5  
 24. 0.5  
 25. 0.5  
 26. 0.5  
 27. 0.5  
 28. 0.5  
 29. 0.5  
 30. 0.5  
 31. 0.5  
 32. 0.5  
 33. 0.5  
 34. 0.5  
 35. 0.5  
 36. 0.5  
 37. 0.5  
 38. 0.5  
 39. 0.5  
 40. 0.5  
 41. 0.5  
 42. 0.5  
 43. 0.5  
 44. 0.5  
 45. 0.5  
 46. 0.5  
 47. 0.5  
 48. 0.5  
 49. 0.5  
 50. 0.5  
 51. 0.5  
 52. 0.5  
 53. 0.5  
 54. 0.5  
 55. 0.5  
 56. 0.5  
 57. 0.5  
 58. 0.5  
 59. 0.5  
 60. 0.5  
 61. 0.5  
 62. 0.5  
 63. 0.5  
 64. 0.5  
 65. 0.5  
 66. 0.5  
 67. 0.5  
 68. 0.5  
 69. 0.5  
 70. 0.5  
 71. 0.5  
 72. 0.5  
 73. 0.5  
 74. 0.5  
 75. 0.5  
 76. 0.5  
 77. 0.5  
 78. 0.5  
 79. 0.5  
 80. 0.5  
 81. 0.5  
 82. 0.5  
 83. 0.5  
 84. 0.5  
 85. 0.5  
 86. 0.5  
 87. 0.5  
 88. 0.5  
 89. 0.5  
 90. 0.5  
 91. 0.5  
 92. 0.5  
 93. 0.5  
 94. 0.5  
 95. 0.5  
 96. 0.5  
 97. 0.5  
 98. 0.5  
 99. 0.5  
 100. 0.5

Position / Reading in inches  


Reviewed by: **[Signature]** Date: **3/21/07**  
 Layer: **00**  
 Date: **1/28/07** Page: **128 of 183**












# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 153 of 183
Originator Pete Tamburro	Date 3/21/67	Reviewed by		Date

Bay #5





# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 125 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

*aligned*

**Ultrasonic Thickness Data Sheet**

QCI  TQM  TMC  Clean  NA  
 Name *MA*  
 Date *3-21-07*  
 Transducer *40*  
 Couplant/Spray *Pen 3000*  
 System *187*  
 Drawing No./Rev. *34-187-21-504*  
 Title/Spec. *187*  
 Material *6*

Test Surface *20*  
 Examination Sight *3*  
 Examiners Sight *3*  
 Thickness *0.15*  
 ID No. *0.15*  
 ID No. *0.15*  
 Calibration *187-21-504*  
 Qualification *187-21-504*  
 Technician *187-21-504*

Temperature *50*  
 Cal. Btg. *5/10*  
 Cal. Cnt. *222222*  
 Cal. Cnt. *222222*  
 Cal. Btg. Temp. *72*  
 Position & Reading in Inches

Cal. Btg.	Cal. Cnt.	Cal. Btg.	Cal. Cnt.	Cal. Btg.	Cal. Cnt.	Cal. Btg.	Cal. Cnt.
<i>0.15</i>	<i>0.15</i>	<i>0.15</i>	<i>0.15</i>	<i>0.15</i>	<i>0.15</i>	<i>0.15</i>	<i>0.15</i>

*Bay #7*

*5 5 5 5 5 5 5 5*

*SAND*

Date *3-21-07*  
 Page *1*  
 Reviewer *187-21-504*  
 Level *II*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-157-5320-024	Rev. No. 3	Sheet No. 136 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date

*Alleged*

**Ultrasonic Thickness Data Sheet**

GPU Nuclear    
  TMI    
  TMI-2    
  TMI-3    
  TMI-4    
  TMI-5    
  TMI-6    
  TMI-7    
  TMI-8    
  TMI-9    
  TMI-10    
  TMI-11    
  TMI-12    
  TMI-13    
  TMI-14    
  TMI-15    
  TMI-16    
  TMI-17    
  TMI-18    
  TMI-19    
  TMI-20    
  TMI-21    
  TMI-22    
  TMI-23    
  TMI-24    
  TMI-25    
  TMI-26    
  TMI-27    
  TMI-28    
  TMI-29    
  TMI-30    
  TMI-31    
  TMI-32    
  TMI-33    
  TMI-34    
  TMI-35    
  TMI-36    
  TMI-37    
  TMI-38    
  TMI-39    
  TMI-40    
  TMI-41    
  TMI-42    
  TMI-43    
  TMI-44    
  TMI-45    
  TMI-46    
  TMI-47    
  TMI-48    
  TMI-49    
  TMI-50    
  TMI-51    
  TMI-52    
  TMI-53    
  TMI-54    
  TMI-55    
  TMI-56    
  TMI-57    
  TMI-58    
  TMI-59    
  TMI-60    
  TMI-61    
  TMI-62    
  TMI-63    
  TMI-64    
  TMI-65    
  TMI-66    
  TMI-67    
  TMI-68    
  TMI-69    
  TMI-70    
  TMI-71    
  TMI-72    
  TMI-73    
  TMI-74    
  TMI-75    
  TMI-76    
  TMI-77    
  TMI-78    
  TMI-79    
  TMI-80    
  TMI-81    
  TMI-82    
  TMI-83    
  TMI-84    
  TMI-85    
  TMI-86    
  TMI-87    
  TMI-88    
  TMI-89    
  TMI-90    
  TMI-91    
  TMI-92    
  TMI-93    
  TMI-94    
  TMI-95    
  TMI-96    
  TMI-97    
  TMI-98    
  TMI-99    
  TMI-100    

Title/Description: *UT Sandbed*  
 Comp. Name: *Orwell Unit*  
 Procedure/Specs: *ASNT SNT-TC-1B*  
 Test Surface: *0.0*  
 Examiner: *PT*  
 Sketches: *PT*  
 Temperature: *22.2 F*  
 Cal. Date: *03/21/07*  
 Cal. Exp. Temp: *22.2 F*  
 Position #/Reading in Inches: *001/1*  
 Material: *SA-509*  
 ID No.: *001*  
 ID No.: *001*  
 Calibration Standard (Inches): *0.001, 0.002, 0.003, 0.004, 0.005, 0.006, 0.007, 0.008, 0.009, 0.010*  
 Test Setup:  CPM  Other  
 Drawing: *001*  
 Scale: *1:1*  
 Date: *03/21/07*  
 Time: *10:00*  
 Location: *001*  
 Part No.: *001*  
 Page 1 of 1  
 Reviewed by: *PT*



# GPU Nuclear


Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 138 of 183
Originator Fete Tambano	Date 3/21/07	Reviewed by		Date

<b>GPU Nuclear</b>					<b>Ultrasonic Thickness Data Sheet</b>					
<input type="checkbox"/> OC	<input type="checkbox"/> TWT	<input type="checkbox"/> TWT	<input type="checkbox"/> TWT	<input type="checkbox"/> TWT	No. Requests	9/1/07	Drawn Sheet No.	111	Date	3/21/07
Task Description: <i>see drawing</i>					Inspector	<i>[Signature]</i>	Code/Spec	<i>[Blank]</i>	Scale	<i>[Blank]</i>
Comp. Descr: <i>Drywell Ext. Part 1</i>					Drawing No./Rev.	<i>36-187-5320-101-002</i>	Material	<i>[Blank]</i>	System	<i>[Blank]</i>
Procedure/Flw: <i>ASME Section V, Part 5, UT-1010</i>					Thickness	<i>1.5</i>	Thickness	<i>1.5</i>	System	<i>[Blank]</i>
Test Stations: <i>[Blank]</i>					ID No.	<i>[Blank]</i>	ID No.	<i>[Blank]</i>	Level	<i>[Blank]</i>
Examiner: <i>[Signature]</i>					Print: <i>Thickness &amp; Waveform</i>	Print: <i>MUTL &amp; Burst</i>	Calibration Readings (Inches)	<i>[Table]</i>	Technique	<i>[Blank]</i>
Sampling: <i>Sight / 100% / 100%</i>					Thermometer: <i>50°F</i>	Cal. Blk. SN: <i>[Blank]</i>	Cal. Blk. Temp: <i>65°F</i>			
Position / Reading in Inches					<i>[Hand-drawn diagram of a pipe with a scale and various markings]</i>					
Swept by: <i>[Signature]</i>					<i>[Large grid area for data recording]</i>					




# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 139 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by	Date	



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 140 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date



DAY-II — U.T. SPOTS FOR GRINDING

NOTE: GRIND ONE SPOT AT A TIME. REMARK THE SPOT # AFTER GRINDING.



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. G-1392-187-5320-024	Rev. No. 3	Sheet No. 142 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

Sketch Form (with grid)

Date Sheet No. 92-072-31

Disposition: *NA* Rev. *NA*


**GPU Nuclear**

CG  MA  OTHER

Component: *Drywell Head Sandbed Area*

Location: *Bay # 11*

Drawing




Prepared by <i>[Signature]</i>	Date: <i>11/1/07</i>
Reviewed by <i>[Signature]</i>	Date: <i>11/1/07</i>
Sheet No. <i>117</i> of <i>117</i>	Page <i>1</i> of <i>1</i>
Scale: <i>1/16" = 1'</i>	NDP Reference: <i>73-072</i>

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed	<b>Calc. No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 3	<b>Sheet No.</b> 143 of 183
<b>Originator</b> Pete Tamburro	<b>Date</b> 3/21/07	<b>Reviewed by</b>	<b>Date</b>

*See Photo under*

<b>GPU Nuclear</b>		<b>Ultrasonic Thickness Data Sheet</b>	
<input checked="" type="checkbox"/> <b>DC</b>	<input type="checkbox"/> <b>DA</b>	<input type="checkbox"/> <b>Class</b>	<input type="checkbox"/> <b>Class</b>
<b>Part Description</b> Drywell Ext. Sandbed		<b>Item #</b>	<b>Part No.</b>
<b>Comp. Descr.</b> Drywell Ext. Sandbed		<b>System</b> DRYWELL	<b>Category</b> Ext. Sandbed
<b>Spec. Ref.</b> ASME B31.1-2001		<b>Drawing No.</b> DW-100-24-001	<b>Revision</b> 1/1
<b>Part Thickness</b> 0.2	<b>Part ID</b> 100-24-001	<b>Part</b> 100-24-001	<b>Part</b> 100-24-001
<b>Examiner</b> SGT	<b>Sign</b> [Signature]	<b>Print</b> SGT	<b>Print</b> SGT
<b>Examiner</b> SGT	<b>Sign</b> [Signature]	<b>Print</b> SGT	<b>Print</b> SGT
<b>Thermometer</b> (N/A) 25.0, <b>Part Temperature</b> 25.0 F		<b>Cal. Ref.</b> (N/A) 2.1	
<b>Cal. Ref.</b> (N/A) 2.1		<b>Cal. Ref.</b> (N/A) 2.1	
<b>Cal. Ref.</b> (N/A) 2.1		<b>Cal. Ref.</b> (N/A) 2.1	
<b>Position #/Reading in Inches</b>			
<b>ACTG</b>	<b>RECORDED</b>	<b>TIME</b>	<b>DATE</b>
1	0.4	3:00	3/21/07
2	0.4	3:05	3/21/07
3	0.4	3:10	3/21/07
4	0.4	3:15	3/21/07
5	0.4	3:20	3/21/07
6	0.4	3:25	3/21/07
7	0.4	3:30	3/21/07
8	0.4	3:35	3/21/07



*[Handwritten signature]*





# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 146 of 183
Originator Pete Tamburo	Date 3/21/87	Reviewed by		Date

done 2/1/87

**Ultrasonic Thickness Data Sheet**

GPU Nuclear	Title Sheet	Item #	NDI Request #	Date Sheet Prepared	Date
Test Description: Drywell Ext. Sandbed	System: SA	Drawing Number: 37-157-27-207	Test No: SA	Location: Sand Bed	
Thermometer: SA-22-206 Part Temperature: 22.7	Cal. 214, S/N: 212	Cal. 214, Stamp: 22.7	Position - Reading in Inches		

Examiner: [Signature]	Sign: [Signature]	Print: [Signature]	ID No: [Redacted]	Level: SA
Executive: [Signature]	Sign: [Signature]	Print: [Signature]	ID No: [Redacted]	Level: SA

Cal. 214, S/N: 212	Cal. 214, Stamp: 22.7	Cal. 214, S/N: 212	Cal. 214, Stamp: 22.7
Cal. 214, S/N: 212	Cal. 214, Stamp: 22.7	Cal. 214, S/N: 212	Cal. 214, Stamp: 22.7

Drawing	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00
---------	------	------	------	------	------	------	------	------	------

Reviewed by: [Signature]	Date: 3/21/87	Page: 146
--------------------------	---------------	-----------



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1502-187-5320-024	Rev. No. 3	Sheet No. 147 of 183
Originator Pete Tamburro	Date 3/23/07	Reviewed by		Date

**Ultrasonic Thickness Data Sheet**

*From Tank*

GPU Nuclear	Item #	Material	Thickness	Location	Orientation	Notes
08 00 01	114	SA-516	0.375	Top of Tank	Vertical	
08 00 02	114	SA-516	0.375	Top of Tank	Vertical	
08 00 03	114	SA-516	0.375	Top of Tank	Vertical	
08 00 04	114	SA-516	0.375	Top of Tank	Vertical	
08 00 05	114	SA-516	0.375	Top of Tank	Vertical	
08 00 06	114	SA-516	0.375	Top of Tank	Vertical	
08 00 07	114	SA-516	0.375	Top of Tank	Vertical	
08 00 08	114	SA-516	0.375	Top of Tank	Vertical	
08 00 09	114	SA-516	0.375	Top of Tank	Vertical	
08 00 10	114	SA-516	0.375	Top of Tank	Vertical	
08 00 11	114	SA-516	0.375	Top of Tank	Vertical	
08 00 12	114	SA-516	0.375	Top of Tank	Vertical	
08 00 13	114	SA-516	0.375	Top of Tank	Vertical	
08 00 14	114	SA-516	0.375	Top of Tank	Vertical	
08 00 15	114	SA-516	0.375	Top of Tank	Vertical	
08 00 16	114	SA-516	0.375	Top of Tank	Vertical	
08 00 17	114	SA-516	0.375	Top of Tank	Vertical	
08 00 18	114	SA-516	0.375	Top of Tank	Vertical	
08 00 19	114	SA-516	0.375	Top of Tank	Vertical	
08 00 20	114	SA-516	0.375	Top of Tank	Vertical	
08 00 21	114	SA-516	0.375	Top of Tank	Vertical	
08 00 22	114	SA-516	0.375	Top of Tank	Vertical	
08 00 23	114	SA-516	0.375	Top of Tank	Vertical	
08 00 24	114	SA-516	0.375	Top of Tank	Vertical	
08 00 25	114	SA-516	0.375	Top of Tank	Vertical	
08 00 26	114	SA-516	0.375	Top of Tank	Vertical	
08 00 27	114	SA-516	0.375	Top of Tank	Vertical	
08 00 28	114	SA-516	0.375	Top of Tank	Vertical	
08 00 29	114	SA-516	0.375	Top of Tank	Vertical	
08 00 30	114	SA-516	0.375	Top of Tank	Vertical	
08 00 31	114	SA-516	0.375	Top of Tank	Vertical	
08 00 32	114	SA-516	0.375	Top of Tank	Vertical	
08 00 33	114	SA-516	0.375	Top of Tank	Vertical	
08 00 34	114	SA-516	0.375	Top of Tank	Vertical	
08 00 35	114	SA-516	0.375	Top of Tank	Vertical	
08 00 36	114	SA-516	0.375	Top of Tank	Vertical	
08 00 37	114	SA-516	0.375	Top of Tank	Vertical	
08 00 38	114	SA-516	0.375	Top of Tank	Vertical	
08 00 39	114	SA-516	0.375	Top of Tank	Vertical	
08 00 40	114	SA-516	0.375	Top of Tank	Vertical	
08 00 41	114	SA-516	0.375	Top of Tank	Vertical	
08 00 42	114	SA-516	0.375	Top of Tank	Vertical	
08 00 43	114	SA-516	0.375	Top of Tank	Vertical	
08 00 44	114	SA-516	0.375	Top of Tank	Vertical	
08 00 45	114	SA-516	0.375	Top of Tank	Vertical	
08 00 46	114	SA-516	0.375	Top of Tank	Vertical	
08 00 47	114	SA-516	0.375	Top of Tank	Vertical	
08 00 48	114	SA-516	0.375	Top of Tank	Vertical	
08 00 49	114	SA-516	0.375	Top of Tank	Vertical	
08 00 50	114	SA-516	0.375	Top of Tank	Vertical	

Temperature: 225°F, Humidity: 25%, Wind: 0 mph, Rain: 0 in/hr, Bar: 30.1 in Hg, Cal. Br. Temp.: 22.5°F

Position: Randomly in Tank

Reviewed by: *[Signature]*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 148 of 183
Originator Pete Tambura	Date 3/21/87	Reviewed by		Date

GPU Nuclear

Calibration Sheet

Cal Sheet 228-01

System A872	Component SPT-10	Procedure SPT-10	Product SPT-10	Material SPT-10	Date 3/21/87	Sheet No. 148 of 183
Manufacturer SPT-10	Part No. SPT-10	Serial No. SPT-10	Lot No. SPT-10	Cal Date 3/21/87	Cal Due 3/21/87	Cal No. SPT-10
Cal Standard SPT-10	Cal Direction SPT-10	Cal Type SPT-10	Cal Size SPT-10	Cal Magn SPT-10	Cal Date 3/21/87	Cal No. SPT-10
System Check SPT-10	System Check SPT-10	System Check SPT-10	System Check SPT-10	System Check SPT-10	System Check SPT-10	System Check SPT-10
Gain SPT-10	Offset SPT-10	Linearity SPT-10	Resolution SPT-10	Repeatability SPT-10	Stability SPT-10	Accuracy SPT-10
Frequency SPT-10	Amplitude SPT-10	Phase SPT-10	Waveform SPT-10	Impedance SPT-10	Temperature SPT-10	Humidity SPT-10
Reflection SPT-10	Attenuation SPT-10	Isolation SPT-10	Shielding SPT-10	Calibration SPT-10	Verification SPT-10	Acceptance SPT-10
Remarks SPT-10	Remarks SPT-10	Remarks SPT-10	Remarks SPT-10	Remarks SPT-10	Remarks SPT-10	Remarks SPT-10

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 149 of 183
Originator Pete Tambure	Date 3/21/87	Reviewed by		Date

Sketch Form (with grid)

Drawn by: *NA*


Checked by: *NA*

CO  TR  OTHER

Component: **DRY WELL LINERS**

Location: **BAY 13**

Drawn by:



TECHNIQUES USED TO DETERMINE DIST. OF GROUND HIGHS

UT READING LOCATION	0°	45°	90°	135°
1	330	382	346	270
2	312	377	360	275
3	300	373	358	288
4	287	367	350	277
5	281	377	350	239
6	275	385	342	277
7	264	373	335	279
8	250	361	331	262
9	239	377	324	255
10	227	367	324	255
11	215	355	317	255
12	207	341	304	255
13	194	327	297	255
14	180	311	284	255
15	167	297	274	255

DEPTH MICROMETER USED C-1302-187-5320-024  
 VERIFIED BY: BLACK 274 & 287

Prepared by: *[Signature]*  
 Date: *3/21/87*  
 Checked by: *[Signature]*  
 Date: *3/21/87*  
 Drawn by: *NA*  
 Date: *3/21/87*



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 5	Sheet No. 151 of 183
Originator Ecto Tamburo	Date 3/21/07	Reviewed by		Date

**GPU Nuclear**

cc  TM  Other

Component: DAYWELL Head - Fuel/Mod Area

Location: Bay # 1B

Sketch Form (with grid)

Date: 3/21/07

Drawing No: N/A

Part: N/A

Prepared by: [Signature]

Checked by: [Signature]

Date: 3/21/07

Page: 1 of 1

WDE/Report No: 72-272

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. G-1502-187-5320-024	Rev. No. 3	Sheet No. 152 of 183
Originator Pete Tamburas	Date 3/21/87	Reviewed by		Date

all signs 276

**Ultrasonic Thickness Data Sheet**

**UT Nuclear**

NDI Request: *2-2-87*

Trans No: *401*

Component Name: *Sect 122*

Part No: *122*

System: *122*

Examiner: *[Signature]*

Examinee: *[Signature]*

Thermometer: *SIN 2222* Perf Temperature: *22.8* D-Meter: *SIN 2222*

Cal Blk: *S/N 212* Cal for: *212*

Set this Temp: *21*

Drawn: *[Signature]*

Level 1: *[Signature]*

Level 2: *[Signature]*

Level 3: *[Signature]*

Calibration Range: *0.50 - 1.50*

Cal Blk	0.50	0.75	1.00	1.25	1.50
Range	0.50	0.75	1.00	1.25	1.50

Position (Heating in inches)

Area: *Area A*

Temp: *21*

UT Data Table:

Point	Reading	Temp	Notes
1	0.50	21	
2	0.75	21	
3	1.00	21	
4	1.25	21	
5	1.50	21	

# GPU Nuclear

Subject <b>O.C. Drywell Ext. UT Evaluation in Sandbed</b>		Calc No. <b>C-1302-187-5320-024</b>	Rev. No. <b>3</b>	Sheet No. <b>153 of 183</b>
Originator <b>Pete Tamburro</b>	Date <b>3/21/07</b>	Reviewed by		Date

<input checked="" type="checkbox"/> GPU Nuclear		<b>Ultrasonic Thickness Data Sheet</b>	
<input checked="" type="checkbox"/> 00 <input type="checkbox"/> 10 <input type="checkbox"/> 100 <input type="checkbox"/> 1000 Test Description: <b>UT Thickness</b>	NDE Process: <b>UT</b> Test No: <b>100</b>	Date Started: <b>3/21/07</b> Date Completed: <b>3/21/07</b>	Code/Spec: <b>ASME Sec III</b>
Equip. Desc: <b>CP-1000</b> Procedure/Spec: <b>ASME Sec III</b>	System: <b>UT</b> Transducer: <b>5MHz</b>	Dr. Name: <b>J. Tamburro</b> Material: <b>SA-508</b>	ID No: <b>100</b> ID No: <b>100</b>
Test Surface: <b>00</b> Examiner: <b>J. Tamburro</b> Examiner: <b>J. Tamburro</b>	Print: <b>UT</b> Print: <b>UT</b>	Calibration: <b>ASME Sec III</b> Calibration: <b>ASME Sec III</b>	Thickness: <b>0.5</b> Thickness: <b>0.5</b>
Thermometer: <b>SN 22-232</b> Cal. Exp. SN: <b>00</b> Cal. Exp. Temp: <b>00</b>	Fluid Temperature: <b>00</b> Cal. Exp. SN: <b>00</b> Cal. Exp. Temp: <b>00</b>	Position / Reading in Inches <b>0.5</b>	Drawing: <b>ASME Sec III</b>





# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 155 of 183
Originator Pete Tamboro	Date 3/21/07	Reviewed by	Date

**Ultrasonic Thickness Data Sheet**

**ASME**  **API**  **ASNT**  **Other**  
 Task Description: UT Thickness Measurement  
 Comp. Draw: Drywell Ext. for 187 Spec: ASME  
 Procedure/Spec: ASNT SNT-TC-1B Drawing No: 25-287-23 Rev: 001  
 Test Surface: 00 Thickness: 0.8 Material: Carbon Steel  
 Examiner: [Signature] Date: 3/21/07  
 Examiner: [Signature] Date: 3/21/07  
 Thermometer: 68 Part Temperature: 21.5 Datum: 3/21/07  
 Cal. Exp. No.: 28 Cal. Exp. Date: 03/21/07  
 Cal. Exp. Temp.: 21.5 Cal. Exp. Loc.: ASNT

Drawing: 25-287-23  
 Position / Reading in Inches: ASNT

Location	Dist	Cor	Cor	Dist	Cor	Cor	Dist	Cor	Cor	Dist	Cor	Cor	Dist	Cor	Cor	Dist	Cor	Cor	
1																			
2																			
3																			
4																			
5																			
6																			
7																			
8																			
9																			
10																			
11																			
12																			
13																			
14																			
15																			
16																			
17																			
18																			
19																			
20																			
21																			
22																			
23																			
24																			
25																			
26																			
27																			
28																			
29																			
30																			

Reviewed by: [Signature] Date: 3/21/07  
 Inspector: [Signature] Date: 3/21/07

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 156 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

Sketch Form (with grid)

GO   
  TM   
  OTHER

Components: DRYWELL INTER SANDBED AREA  
 Location: BAY # 17  
 Drawing:

Data Sheet No: 92-072-23  
 Drawing No: 17A  
 Rev: 1A

AREA: 0.45' x 0.135'  
9.385' x 0.135' = 1.267'

Checked and submitted  
 Technician utilized for the pit depth measurements

Prepared by: [Signature]  
 Reviewed by: [Signature]

Date: 3/21/07  
 Page: 1 of 1  
 W&E Form No: 92-072

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-6320-024	Rev. No. 5	Sheet No. 157 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

402.41mtr 6.2874

### Ultrasonic Thickness Data Sheet

<b>GPU Nuclear</b>	Date Sheet Run <i>03/21/07</i>	NDE Request <i>27-0722</i>	Date <i>03/21/07</i>	Company <i>Plant &amp; 2000</i>
ESI ID <input type="checkbox"/> TMI <input type="checkbox"/> Class <i>A</i>	Test No. <i>101</i>	Drawings/Refs <i>31-107-28.000 Rev. 0</i>	Material <i>CS</i>	Corrosion <i>None</i>
Test Description <i>RT Thickness</i>	Comp. Descr. <i>Drywell Ext. 2000</i>	System <i>2000</i>	Procedure/Ref. <i>ASNT SNT-TC-1A</i>	Thickness <i>1.8</i>
Test Substrate <i>CD</i>	Examiner <i>Slatt</i>	From <i>Procedure 03/21/07</i>	ID No. <i>[Redacted]</i>	Level <i>CS</i>
Examiner <i>Slatt</i>	Print Mark <i>F</i>	Examination Pressure (psi)	Cal. No. <i>ASNT SNT-TC-1A</i>	Other <i>None</i>
Temperature <i>65°F</i>	Print Temperature <i>65°F</i>	Cal. Bk. S/N <i>1000</i>	Cal. Bk. Temp. <i>65°F</i>	

**Position #/Reading in Inches**

Position #	Reading 1	Reading 2	Reading 3	Reading 4	Reading 5
1	1.80	1.80	1.80	1.80	1.80
2	1.80	1.80	1.80	1.80	1.80
3	1.80	1.80	1.80	1.80	1.80
4	1.80	1.80	1.80	1.80	1.80
5	1.80	1.80	1.80	1.80	1.80
6	1.80	1.80	1.80	1.80	1.80
7	1.80	1.80	1.80	1.80	1.80
8	1.80	1.80	1.80	1.80	1.80
9	1.80	1.80	1.80	1.80	1.80
10	1.80	1.80	1.80	1.80	1.80
11	1.80	1.80	1.80	1.80	1.80
12	1.80	1.80	1.80	1.80	1.80
13	1.80	1.80	1.80	1.80	1.80
14	1.80	1.80	1.80	1.80	1.80
15	1.80	1.80	1.80	1.80	1.80
16	1.80	1.80	1.80	1.80	1.80
17	1.80	1.80	1.80	1.80	1.80
18	1.80	1.80	1.80	1.80	1.80
19	1.80	1.80	1.80	1.80	1.80
20	1.80	1.80	1.80	1.80	1.80

**Drawing**

Reviewed by *[Signature]*



# GPU Nuclear

Subject O.C. Drywell Ext. HT Evaluation in Sandbed		Calc. No. C-1502-187-5320-024	Rev. No. 3	Sheet No. 159 of 183
Originator Pete Tamborino	Date 3/21/97	Reviewed by	Date	

**Ultrasonic Thickness Data Sheet**

Plate Sheet No. 2722-05 Date 3/21/97

Test No. 16 NDT Requester PP-028 Inspector ASIM Part HT

Component Down Well Dry W System HT

Procedure/Spec. ASME Sec II Drawing Number J-187-12-104 Material SA-509

Test Surface SA Thickness 0.10

Examiner Sign: [Signature] Date: 3/21/97

Examiner Sign: [Signature] Date: 3/21/97

Thermometer SN: 22-212 Part Temperature: 627 O-Meter SN: 22-212  
 Cal. due SN: 5/97 Cal. due: 5/97 Cal. due: 5/97  
 Cal. by: [Signature] Cal. by: [Signature]

Position w/Reading in Inches

Position	1"	2"	3"	4"	5"	6"	7"	8"	9"	10"	Other
Reading	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10

Inspected by: [Signature] Date: 3/21/97

Reviewed by: [Signature] Date: 3/21/97

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 160 of 183
Originator Pete Tambopp	Date 1/21/07	Reviewed by	Date	

## Ultrasonic Thickness Data Sheet

Miscellaneous      Test      Thickness      N/A      None      N/A  
 Test Description: AT 114-549251     Code/Spec: ASME Sec. VIII     Date: 1/21/07

Comp. Descs: DIS/MAL-LINER, PWT #1     System: #81     Drawing Number: EB-18-1-1191     Rev: 8  
 Procedure/Rev: BSA-5522     Test of: Ser. 0     Thickness: 1 1/4"     Material: C-103

Test Surface: O.P.     Part: Jacketed Zircaloy-4     ID No: [REDACTED]     Level: 1  
 Examiner: Sign: [REDACTED]     PWT: MAX F. BALDWIN     ID No: [REDACTED]     Level: 1

Equipment: S/N E-1-022 Part Temperature 72.2° F     Emitter S/N 22-212  
 Cal. Bk. S/N 315     Cal. No. 22-212     AM EL-SERPA     Cl. 103     AM EL-SERPA  
 Cal. Bk. Temp. 72° F     Part No. 114-549251     AM EL-SERPA

Location	Orientation (degrees)					Thickness
	0°	45°	90°	135°	180°	
1	N/A	N/A	N/A	N/A	N/A	0.197
2	N/A	N/A	N/A	N/A	N/A	0.197
3	N/A	N/A	N/A	N/A	N/A	0.197
4	N/A	N/A	N/A	N/A	N/A	0.197
5	N/A	N/A	N/A	N/A	N/A	0.197
6	N/A	N/A	N/A	N/A	N/A	0.197
7	N/A	N/A	N/A	N/A	N/A	0.197
8	N/A	N/A	N/A	N/A	N/A	0.197
9	N/A	N/A	N/A	N/A	N/A	0.197
10	N/A	N/A	N/A	N/A	N/A	0.197
11	N/A	N/A	N/A	N/A	N/A	0.197
12	N/A	N/A	N/A	N/A	N/A	0.197
13	N/A	N/A	N/A	N/A	N/A	0.197
14	N/A	N/A	N/A	N/A	N/A	0.197
15	N/A	N/A	N/A	N/A	N/A	0.197
16	N/A	N/A	N/A	N/A	N/A	0.197
17	N/A	N/A	N/A	N/A	N/A	0.197
18	N/A	N/A	N/A	N/A	N/A	0.197
19	N/A	N/A	N/A	N/A	N/A	0.197
20	N/A	N/A	N/A	N/A	N/A	0.197
21	N/A	N/A	N/A	N/A	N/A	0.197
22	N/A	N/A	N/A	N/A	N/A	0.197
23	N/A	N/A	N/A	N/A	N/A	0.197
24	N/A	N/A	N/A	N/A	N/A	0.197
25	N/A	N/A	N/A	N/A	N/A	0.197
26	N/A	N/A	N/A	N/A	N/A	0.197
27	N/A	N/A	N/A	N/A	N/A	0.197
28	N/A	N/A	N/A	N/A	N/A	0.197
29	N/A	N/A	N/A	N/A	N/A	0.197
30	N/A	N/A	N/A	N/A	N/A	0.197
31	N/A	N/A	N/A	N/A	N/A	0.197
32	N/A	N/A	N/A	N/A	N/A	0.197
33	N/A	N/A	N/A	N/A	N/A	0.197
34	N/A	N/A	N/A	N/A	N/A	0.197
35	N/A	N/A	N/A	N/A	N/A	0.197
36	N/A	N/A	N/A	N/A	N/A	0.197
37	N/A	N/A	N/A	N/A	N/A	0.197
38	N/A	N/A	N/A	N/A	N/A	0.197
39	N/A	N/A	N/A	N/A	N/A	0.197
40	N/A	N/A	N/A	N/A	N/A	0.197

Position & Reading (inches)

Position & Reading (inches): WEST     Position & Reading (inches): EAST

Drawn by: [REDACTED]     Date: 1/21/07     Page: 1 of 1

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 2	Sheet No. 161 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date

GPU Nuclear

Calibration Sheet

1001 1001

System 187	Component Drywell Ext	Procedure Sensors 2000 2000 2007	Frequency 2000	Height 2000	File # 2000
Examined 3/21/07	Signature <i>[Signature]</i>	Inspector <i>[Signature]</i>	Initial <i>[Initials]</i>	Job <i>[Job ID]</i>	Drawn By <i>[Name]</i>
Examiner <i>[Name]</i>	Supervisor <i>[Name]</i>	Plant MORRIS S. BRADLEY	Unit 2000	System 2000	Drawn By <i>[Name]</i>
Instrument Settings:					
ID#	2000	Serial	2000	Transducer	2000
Model/Manufacturer	2000	Type	2000	Frequency	2000
Gain	2000	Start	2000	Stop	2000
Excited	2000	High	2000	Low	2000
Filter	2000	Out Direction	2000	Out Direction	2000
Unit	2000	Gain	2000	Gain	2000
Shunt Circuit	2000	Calib	2000	Calib	2000
Coarse	2000	Gain	2000	Gain	2000
Probe	2000	Time	2000	Time	2000
Depth	2000	Amplitude	2000	Amplitude	2000
Screen Depth	2000	Frequency	2000	Frequency	2000
Orientation	2000	Gain	2000	Gain	2000
CLR	2000	Gain	2000	Gain	2000
Frequency	2000	Gain	2000	Gain	2000
Reflect	2000	Gain	2000	Gain	2000
Filter	2000	Gain	2000	Gain	2000
Damping	2000	Gain	2000	Gain	2000
Reg Name	2000	Gain	2000	Gain	2000

Time/Date	Probe	Amplitude	Frequency	Gain	Gain	Gain
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000
2000	2000	2000	2000	2000	2000	2000

Initials: *[Initials]*

Signature: *[Signature]*

Date: 3/21/07

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 162 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by	Date

MOO PJTMI

<b>GPU Nuclear</b> System 1837 Component <i>Direct Line</i> Location <i>Plant 1, Unit 1, Sandbed</i> Date <i>3/21/07</i>		Calibration Sheet Frequency <i>500-2000 Hz</i> Initial <i>[Signature]</i> Final <i>[Signature]</i> Inspector <i>[Signature]</i> Date <i>3/21/07</i>	
Equipment Manufacturer <i>Moule</i> Model/Serial <i>1837</i> Gain <i>100</i> Filter <i>100</i> Delay <i>100</i> Sweep Circuit <i>None</i> Operator <i>[Signature]</i>	Calibration ID# <i>1837</i> Size and Ref. <i>1837</i> Thickness <i>1837</i> SPS <i>1837</i> Temp <i>1837</i> System Check Checklist Date <i>3/21/07</i>	Calibration ID# <i>1837</i> Type <i>1837</i> Size <i>1837</i> Angle <i>1837</i> CS/Direction DMM Error Confirmed Time <i>1837</i>	Amplitude % of FSH Frequency Sweep Direction Remarks Components Examined Date <i>3/21/07</i>
Frequency Filter Damping Filter Damping Filter Damping	Normal MHz MHz MHz MHz MHz MHz	Filter Damping Filter Damping Filter Damping Filter Damping	Filter Damping Filter Damping Filter Damping Filter Damping





# GPU Nuclear

Subject <b>O.C. Drywell Ext. UT Evaluation in Sandbed</b>		Calc. No. <b>C-1102-167-5320-024</b>	Rev. No. <b>3</b>	Sheet No. <b>164 of 183</b>
Originator <b>Pete Tamburo</b>	Date <b>3/21/07</b>	Reviewed by		Date

**GPU Nuclear**      Calibration Sheet      ON SHEET 163-1178

System: **187**      Component: **drywell**      Program: **growth**      Rev. **2**

Examiner: **[Signature]**      Inspector: **[Signature]**      Date: **3/21/07**

Examiner Signature: **[Signature]**      Inspector Signature: **[Signature]**

Inspection Settings:  
 TO: **2000**      FROM: **2000**  
 MHz/MHz: **2000/2000**  
 Gain: **20dB**  
 Comp: **20dB**  
 Filter: **20dB**  
 Sweep: **20dB**  
 Duty: **20%**  
 Beam Depth: **20%**

Operator: **[Signature]**  
 Frequency: **2000**      Normal  
 Reflected: **20%**      MPE  
 Filter: **20%**  
 Filter: **20%**  
 Frequency: **20%**

Frequency: **2000**

Transducer	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000	2000
Particulate	% FBW	inches	% FBW	inches	% FBW	inches	% FBW	inches	% FBW	inches	% FBW	inches	% FBW
	20	20	20	20	20	20	20	20	20	20	20	20	20
	20	20	20	20	20	20	20	20	20	20	20	20	20
	20	20	20	20	20	20	20	20	20	20	20	20	20

Remarks: **no structural abnormalities at 2000 Hz**

Company: **GPU Nuclear**

Inspected By: **[Signature]**      Date: **3/21/07**

Inspector: **[Signature]**      Date: **3/21/07**

NOTE: Frequency **2000**

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 165 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by	Date	

**Ultrasonic Thickness Data Sheet**

00  TMS  TMS  TMS  TMS  
 Test Description: DKT M-24 AL-242A, 4-242A, 4-242B, 4-242C  
 Comp. Desc.: MWD DRYWELL EXT. PLATE, SYSTEM 267  
 Procedure/Spec: ASME Sec. VIII, Div. 1, Part 5, Subpart 1, 1.0  
 Test/Bar/Spec: 0.0  
 Examined: [Signature]  
 Examined: [Signature]  
 Thermometer: 57N-2502A, Part Temperature: 58.1 F, 58.1 F, 58.1 F, 58.1 F  
 Cal. Mfr.: [Signature]  
 Cal. Date: 11/14/06  
 Cal. Exp.: 11/14/08

ID No.: [Redacted]  
 ID No.: [Redacted]  
 Material: SA-516  
 Thickness: 3/8"

Corr. Blk.	50%	75%	100%	125%	150%	175%	200%
Position	50%	75%	100%	125%	150%	175%	200%
Reading							

Position #/Reading in Inches  
 Drawing: [Redacted]  
 Level: [Redacted]  
 Reviewed by: [Signature]  
 Date: 03/21/07

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 166 of 183
Originator Pete Tambary	Date 3/21/07	Reviewed by		Date

<input checked="" type="checkbox"/> <b>DRUT</b> Nondestructive <input type="checkbox"/> <b>OD</b> <input type="checkbox"/> <b>TMR</b> <input type="checkbox"/> <b>CLASS</b> <input type="checkbox"/> <b>TR</b>		Data Sheet No. 2072-2 Date 12-18-02	
Task Description: DRY WELLS, ELECTRIC REEF-UP Scoping Description: PH.D. DRYWELL TEST PAPER SYSTEM #27		Description: ASSESS. TEST. VIII Location:	
Procedure(s): 8100 - BAP - 7201.07 / D Test Surface(s):		Orientation: C/S Inspector:	
Examiner Sign: <i>[Signature]</i>	Inspector Sign: <i>[Signature]</i>	ID No. [Redacted] Level: I Technician:	Calibration (Range/Type) (Required) Character: Size 75% / Level 7550 Diameter: 5700 / 7550 / 7200 / 6150 Date:
Thermometer (IN) 52.0, Bath Temperature 53.0, Dimensions (TZ-DIG) Cal. In. 1/8, AM 2:20 PM Dial Blk. Temp. 25.0, Cal. Exp. 1/1, AM 12:00 PM		Position # Results in inches	
Reviewed by: <i>[Signature]</i>		Date: 03/27/07	

Position #	Results in inches
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-167-5320-024	Rev. No. 3	Sheet No. 168 of 163
Originator Pete Tambora	Date 3/21/07	Reviewed by		Date

Equipment Signature: <i>[Signature]</i> Instrument Settings ID# 07-210 Model/Make DL-36 PARATEMETRICS Gain 20dB Coarse 20dB Fine 20dB Unrefl 20dB Sweep Circuit 20dB Coarse 20dB Fine 20dB Delay 20dB Start Depth 20dB Compensation 20dB T&R Frequency 20dB Reflect: 100% GON Filter: 100% ELDs Dampings: 100% FIBs	Ion Standard ID# 204 Size 204 Thickness 204 Name 204 System Check: 204 ELEM Error: A Change: 204	Station List ID# 204 Type 204 Plan 204 Size 204 Angle 204 Cal Operator Date 204 Time 204 Frequency 204 Amplitude 204 Reflect 204 Filter 204 Dampings 204 Gain 204	Search Unit Data Type 204 Contour 204 Min 204 Max 204 Harmonic 204 BR 204 Cap 204 Gain 204 ID# 204	ANI Review Reviewed By: <i>[Signature]</i> Date: 204 NDE Frequency: 204
Dimensions Thickness 204 Width 204 Height 204 Area 204 Volume 204 Weight 204 Density 204 Modulus 204 Poisson's 204 Thermal 204 Expansion 204 Contraction 204 T&R Frequency 204 Reflect: 204 Filter: 204 Dampings: 204 Gain 204	System Check ELEM Error: A Change: 204 Date 204 Time 204 Frequency 204 Amplitude 204 Reflect 204 Filter 204 Dampings 204 Gain 204	Station List ID# 204 Type 204 Plan 204 Size 204 Angle 204 Cal Operator Date 204 Time 204 Frequency 204 Amplitude 204 Reflect 204 Filter 204 Dampings 204 Gain 204	Search Unit Data Type 204 Contour 204 Min 204 Max 204 Harmonic 204 BR 204 Cap 204 Gain 204 ID# 204	ANI Review Reviewed By: <i>[Signature]</i> Date: 204 NDE Frequency: 204

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 169 of 183
Originator Pete Tamburo	Date 3/21/07	Reviewed by		Date

IR 211R-032  
 15-2-2  
 2006-12-10-22-06

**Appendix E**  
**Bay I 2006 UT data**

**BAY 1**

Point	Vertical	Horizontal	1982 value	2006 Value	Comments
1	D16	R27	0.720	0.710	
2	D22	R17	0.716	0.690	
3	D23	L3	0.705	0.665	
4	D24	L33	0.750	0.738	
5	D24	L45	0.710	0.680	
6	D46	R19	0.760	0.731	
7	D39	R7	0.700	0.668	
8	D48	R0	0.805	0.783	
9	D36	L38	0.805	0.754	
10	D16	R23	0.838	0.824	
11	D23	R12	0.714	0.711	
12	D24	L5	0.724	0.722	
13	D24	L40	0.792	0.719	
14	D2	R35	1.147	1.157	
15	D8	L51	1.155	1.160	
16	D50	R40	0.795	0.785	
17	D40	R16	0.860	0.845	
18	D38	L2	0.817	0.889	
19	D38	L24	0.890	0.865	
20	D16	R13	0.955	0.912	
21	D24	R15	0.725	0.712	
22	D32	R13	0.852	0.854	
23	D48	R15	0.850	0.828	

Very Rough Surfaces

Data obtained from

- NDE Data Sheets 92-072-12 page 1 of 1
- NDE Data Sheets 92-072-18 page 1 of 1
- NDE Data Sheets 92-072-19 page 1 of 1

All horizontal measurements taken 12" to the right of the centerline of the reinforcement ring (Boss).  
 All vertical measurements taken from bottom of vent nozzles at the 13" reference line.  
 Surface roughness prohibited characterization of all readings.

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

*[Signature]* 15-22-06

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 170 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

11212K-0012 A. 2 of 2

WSP CMT 10-22-06

BAY 3

Point	Vertical	Horizontal	UTZ value	2006 Value	Comments
1 D16		R63	0.785	0.785	PA
2 D18		R48	1	0.899	
3 D17		R33	0.857	0.850	
4 D13		L5	0.898	0.903	
5 D25		L6	0.823	0.818	
6 D15		L58	0.868	0.972	
7 D28		R4	0.828	0.818	
8 D34		L4	0.79	0.784	

Data obtained from  
NDE Data Sheets B2-073-74 page 1474  
Note: Per discussion with Engineering, single point readings were taken in Bay 3, based  
on surface readings.

Appendix E  
Bay 3 2006 UT data



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 171 of 183
Originator Pete Tamburo	Date 3/21/97	Reviewed by	Date	

1K21LR-019 Pg 2 of 2  
4/24/97 10-22-06

## BAY 5

Point	Vertical	Horizontal	1997 value	2006 Value	Comments
*	1 D38	R42	0.97	0.948	up .97 dn .97
*	2 D38	R7	1.04	0.965	Rough surface - up .99 dn .99
*	3 D42	R10	1.02	0.989	up 1.0 dn 1.04
*	4 D41	L7	0.97	0.948	Rough surface, also diahed
*	6 D42	L14	0.89	0.88	Rough surface
**	6 D47	R5	1.06	0.961	up 1.018 dn 1.014
**	7 D48	L18	0.99	0.974	Rough surface left .99 right N/A
**	8 D46	L31	1.01	1.007	Rough surface

Note: up, dn, left & right readings were taken 1/8" from recorded 2006 value reading.  
 Rough surface limited taking additional readings. Reference above.

\* = Vertical and horizontal measurements taken from top of coating on long seam 82" to right  
 \*\* = Vertical and horizontal measurements taken from bottom of nozzle at 8 o'clock position  
 Reference NDE Data Sheets 92-072-16 page 1 of 1

- 1 - Reference of the weld 82" to the right of the centerline of the bay.
  - 2 The original data sheet is not clear as to whether this point is to the right or left of the weld. Therefore NDE shall verify this dimension.
- Note: per discussion with Engineering, single point readings were taken in lieu of 8, based on surface curvature.

10-2a-06

Appendix E  
 Bay 5 2006 UT data

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 172 of 183
Originator Pete Tambore	Date 3/21/07	Reviewed by		Date

*R2112-005 2 2-1  
3-21-07  
10-22-06*

**BAY 7**

Point	Vertical	Horizontal	UT Probe	2006 Weld	Comments
1	D21	R38	0.92	N/A	Could not locate area
2	D21	R32	1.018	N/A	Could not locate area
3	D10	R20	0.984	0.984	updrn ranged from 0.868 to 0.980
4	D10	R10	1.04	1.04	N/A
5	D21	L6	1.03	1.003	updrn ranged from 1.000 to 1.049
6	D10	L23	1.045	1.023	updrn ranged from 1.020 to 1.052
7	D21	L12	1	1.003	updrn ranged from 1.002 to 1.026

Data obtained from:  
NDE Data Sheets 92-072-20 pages 1-4 of 4  
Note: up. dr readings were taken after both recorded 2006 welds finished.

**Appendix E**  
**Bay 7 2006 UT data**

*1500-2006*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 173 of 183
Originator Pete Tambiuro	Date 3/21/07	Reviewed by		Date

Appendix E  
Bay 9 2006 UT data

IR212R-006 Pg 2 of 2

2012.11  
10-22-06

## BAY 9

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1 D28		R32	0.96	0.968	
2 D18		R17	0.94	0.934	
3 D20		R8	0.984	0.989	
4 D27		R15	1.02	1.016	
5 D35		L5	0.985	0.984	
6 D13		L30	0.82	0.802	
7 D16		L35	0.825	0.82	
8 D21		L38	0.791	0.781	
9 D20		L53	0.832	0.823	
10 D30		L8	0.98	0.955	

Data obtained from  
NDE Data Sheets 92-072-22 page 1 of 1

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 174 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

1K31LR-00B P. 2 of 2

Appendix E  
Bay 11 2006 UT data

BAY 11

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D20	R29	0.705	0.700	N/A
2	D25	R32	0.77	0.760	
3	D21	L4	0.832	0.830	
4	D24	L6	0.755	0.751	
5	D32	L14	0.831	0.823	
6	D27	L22	0.8	0.766	
7	D31	R20	0.831	0.817	
8	D40	R13	0.85	0.825	

Data obtained from:  
NDE Data Sheets 92-072-10 page 1 of 1  
Note: per discussion with Engineering, single point readings were taken in lieu of 8, based on surface curvature.

NOT C III 10-23-06

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 175 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by	Date	

103112-00-73 3 of 2

## Appendix E Bay 13 2006 UT data

BAY 13

Probe	Vertical	Horizontal	1997/2006	2003	Comments
1 U1	R45		0.872	N/A	Could not locate wave
2 U1	R43		0.728	N/A	Could not locate wave
3 D21	R48		0.841	0.923	
4 D12	E38		0.915	0.873	
5 D21	E6		0.718	0.708	
6 D24	E6		0.855	0.858	
7 D17	E23		0.818	0.803	
8 D24	E20		0.718	0.704	
9 D28	R41		0.924	0.915	
10 D28	R12		0.728	0.741	
11 D28	E15		0.885	0.889	
12 D28	E23		0.886	0.886	
13 D18	D40		0.932	0.874	
14 D18	R8		0.888	0.870	
15 D20	U9		0.883	0.886	
16 D20	E29		0.829	0.874	
17 D9	R33		0.907	N/A	Could not locate wave
18 D22	R38		0.826	N/A	Could not locate wave
19 D37	R33		0.778	0.778	

Data obtained from  
NDE Data Sheets 02-072-04 page 1 of 2  
Notes per discussion with Engineering, all data points (results) are based on visual history of field of 3, based  
on surface corrosion.

added 4.25.07

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 176 of 183
Originator Pete Tamburro	Date 5/21/07	Reviewed by		Date

TABLE-015 IS 2006

## Appendix E Bay 15 2006 UT data

BAY 15

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1 D18		R25	0.768	0.779	0.711 to 0.778
2 D22		R21	0.828	0.798	0.771 to 0.768
3 D33		R17	0.932	0.835	
4 D30		R7	0.785	0.791	
5 D28		L3	0.85	0.855	0.817 to 0.855
6 D6		L8	0.794	0.797	0.715 to 0.762
7 D28		L4B	0.808	0.805	
8 D20		L35	0.77	0.760	
9 D36		L44	0.722	0.749	0.720 to 0.749
10 D24		L4B	0.86	0.852	0.837 to 0.862
11 D24		L85	0.825	0.843	0.768 to 0.843

Data obtained from  
 NDE Data Sheets 02-072-21 page 4 of 4  
 Note: scanned 0.20" area around recorded 2006 values unless otherwise specified for changes.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 177 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by	Date	

Report 12212-024  
 Report 021  
 Dr. Hill 11/22/06

*M.A. Smith*  
 10-19-2006

## BAY 17

Appendix E  
 Bay 3 2006 UT data

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1 D12		R50	0.916	0.909	
2 D9		R40	1.150	0.681	up 705 dn 683
3 D18		R26	0.898	0.894	
4 D34		R24	0.991	0.983	
5 D8		R20	0.913	0.822	
6 D17		R7	0.992	0.909	
7 D18		L4	0.970	0.970	
8 D34		L6	0.990	0.960	
9 D21		L9	0.720	0.970	
10 D3		L2	0.830	0.844	
11 N/A		N/A	N/A	N/A	

Note: measurement from vent pipe CL to floor 60"

Note: Down measurements taken from bottom of boss which is 18" below vent line.  
 Locations 9, 9, 8-3 look to be un-prepped flat areas of the original surface.  
 All left, right measurements taken from 8" left of liner (long seam)  
 Data obtained from  
 NDE Data Sheets 92-072-08 page 1 of 1

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 178 of 183
Originator	Date	Reviewed by	Date	

Appendix E  
Bay 19 2006 UT data

Report - 182112-018  
020  
By: [Signature]  
10-2-06

## BAY 19

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1D30		R60	0.932	0.904	UP .897 dn .867
2D52		R58	0.924	0.921	UP .850 dn .907
3D38		R40	0.955	0.932	UP .894 dn .905
4D32		R11	0.94	N/A	Could not locate area
6D31		R3	0.95	0.932	UP .883 dn .897
6D52		L65	0.86	N/A	Could not locate area
7D54		L10	0.969	0.891	UP .821 dn .912
8D16		R64	0.793/0.953	0.745	UP .721 dn .747
9D18		R12	0.716	0.780	UP .728 dn .745
10D19		R0	0.79	0.791	UP .735 dn .846
1120D		L18	N/A	0.736	UP .738 dn .712

Data obtained from  
NDE Data Sheets 92-072-05 page 1 of 1  
NDE Data Sheets 92-072-07 page 1 of 1  
Notes: Per discussion with Engineering, single point readings were taken in lieu of  $\sigma$ , based on surface curvature.  
\* This value is not clear from the original datasheet - NDE to verify this value.  
Notes: per discussion with Engineering, single point readings were taken in lieu of  $\sigma$ , based on surface curvature.

*Markus E. [Signature]*  
10/2/06



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation to Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 179 of 183
Originator Peter Tamburro	Date 3/21/07	Reviewed by		Date

## Appendix F

**GPU Nuclear**

## Memorandum

Subject: INSPECTION OF DRYWELL SAND BED REGION AND ACCESS HOLES

Date: January 28, 1993

From: K. L. Whitlock - Civil/Structural Mgr.

Location: Morris Corp. Center  
5520-93-020

To: J. C. Flynn - Manager, Special Projects, Engineering Projects

As requested by you, I conducted two visual inspections of the drywell sand bed region and several of the access holes. On December 22, 1992, I entered Bays 1, 3 and 17. From inside these bays, I could see all or portions of 1, 3, 5, 7, 15, 17 and 19. On January 21, 1993, I entered Bays 11, 13 and 19. From inside these bays, I could see all or portions of Bays 11, 13, 15, 17 and 19. At the time of the first inspection, bays 1, 3, 5, 17 and 19 had been cleaned of sand and corrosion material. No concrete repair or drywell coating had begun. At the time of the second inspection, Bays 11, 13 and 15 had been cleaned of sand and corrosion material. Epoxy had been placed on the floor in preparation of epoxy placement. However, no concrete repairs or drywell coating had begun in those bays. Bays 17 and 19 had been completed. The epoxy floor had been installed and the drywell had been coated. Following is a summary of my observations during these two inspections:

### 1. Drywell Shell

The drywell shell is sound metal with no loose material, rust or laminations. There are no apparent cracks or discontinuities. The shell is characterized by a rough surface full of dimples similar to the outside surface of a golf ball. The dimples are of varying sizes, but most are less than 1/2" in diameter. The shell appears to be relatively uniform in thickness except as noted below:

- (a) Above the elevation of the bottom of the holes through the concrete shield wall for the vent pipe (approximately 6" below the vent pipe reinforcement ring to drywell shell weld), corrosion is much less than below that elevation. Therefore, there is an obvious change in thickness at this elevation.
- (b) There are two strips around the vessel just below the vent pipe holes described in (a) above which are slightly thinner than the general area of the shell. These strips have been described as "bathtub rings."

KLW/WP/MEMO/2093-020/1

F

OCLR00030854

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 180 of 183
Originator Pete Tamburro	Date 3/21/87	Reviewed by	Date

## Appendix F

J. E. Flynn - Manager, Special Projects, Engineering Projects  
January 28, 1993  
5320-93-020  
Page 2

(c) In addition to the dimples, there are spots that appear to be thinner than the general area. The dimples in the surface occur in these thin spots to the same degree as in the rest of the corroded portion of the shell. The "thin" spots are typically a foot to 18" in diameter and probably comprise about 20% of the corroded area. In general, except in Bay 11, the thin spots are not readily apparent. Therefore, a more detailed characterization is difficult for the other Bays (see (d) below). I could not determine visually which of the thin spots are the thinnest. However, due to the small differences between the "thick" areas and the "thin" areas, and the amount of metal removed in preparation for the UT measurements, it is highly likely that the thickness readings reported in the UT measurements encompass the thinnest spots in the shell.

(d) Due to the results of the thickness measurements, a more detailed visual inspection was conducted of the drywell shell in Bay 13. The conditions observed during the inspection of Bay 13 are summarized below:

- The variation in thickness is greater in Bay 13 than in the other bays.
- The "thin" spots are about a foot to 18" in diameter and are at least 1 ft. apart (edge to edge, or 2 to 2-1/2 ft. center to center). Some spots are thinner than others. Again, I could not determine precisely which spots are the thinnest. However, due to the amount of metal removed to perform the UT measurements, the reported thicknesses in all likelihood envelop the smallest thicknesses in the shell.
- The thin spots comprise about 20% of the total area of the corroded portion of the shell. They are spread throughout the bay but are closer together (about 1 ft. apart) in the vicinity of the vent pipe and further apart toward the frames.

All of the observations discussed above apply in general to all portions of the drywell shell in the sandbed area. However, Bay 13 has a greater variation between the "thick" and "thin" areas than any of the other observed bays. In addition, the abrupt change in thickness at the elevation described in (a) above is more pronounced in Bay 13 than in other bays which were inspected. In fact, in the other bays the thin spots are not apparent unless a concerted effort is made to locate them. Due to this, a more detailed characterization is not drawn for the other bays.

After cleaning and coating, the drywell shell is sound metal with no apparent cracks, laminations, scale or rust. The surface is dimpled, but does not have severe changes in thickness which would result in significant stress risers.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 3	Sheet No. 181 of 183
Originator Pete Tamburro	Date 3/21/07	Reviewed by		Date

J. C. Flynn - Manager, Special Projects, Engineering Projects  
 January 28, 1993  
 5320-93-020  
 Page 3

Appendix F

2. Concrete Floor in the Sand Bed

The floor of the sand bed was found to be uneven and unfinished. A number of small and some large voids were found in the floor of the sand bed. In many places, the reinforcing bars placed to form the drainage channel in the floor are exposed. The deepest void observed in the floor is about 20" deep and about 3'-4' long. This void is located adjacent to the drywell shell. A number of smaller voids were also observed. A more complete and accurate recording of voids and exposed reinforcing is contained in ENCRs 92-188 and 92-062. The exposed reinforcing is generally sound with very little evident corrosion. The concrete in the floor is sound and no cracks are apparent.

After repair, the floor is sound, smooth and resilient. The configuration will lead to rapid draining of the sand bed should water enter the area. In addition, the slope provided will prevent water from standing adjacent to the drywell shell.

3. Concrete in Shield Wall, Frames and Access Holes

A number of small fissures, cracks and voids were observed in the drywell sand bed access holes. In addition, a number of voids and areas of exposed reinforcement were observed in the shield wall in the sand bed region. The voids in the sand bed area and access holes are documented in ENCR 93-062. The voids observed in the concrete comprise an insignificant percentage of the area of the shield walls. All voids are localized and isolated, and do not appear to be associated with any concrete cracking or spalling. All exposed concrete is sound and free of signs of degradation. Exposed bars appear to be sound and generally free of corrosion. In the areas where reinforcing is exposed, the reinforcing appears to be consistent with the reinforced concrete design drawings. No areas were observed which caused any concern with regard to structural adequacy of the shield wall, concrete frames or the Reactor Building.

This completes the record of observations from my inspection of the drywell sand bed region. If you have any questions or need additional information, please let me know.

  
 J. C. Flynn  
 Extension 7546


/fw

- cc: A. R. Saig - Engineer, Engineering Projects  
 J. J. Golitz - Director, Engineering Projects  
 J. H. Horton - Mechanical Analysis Manager  
 S. K. Saha - Engineer, Engineering & Design  
 D. G. Slear - Director, Engineering & Design  
 S. C. Tuminelli - Manager, Engineering Mechanics  
 H. Yekta - Engineer, Engineering & Design

KLR/WP/ENEM/2093-020/3

# GPU Nuclear

Subject O.C. Drywell Ext. DT Evaluation in Satchel	Calc No. C-13102-187-5320-024	Rev. No. 3	Sheet No. 182 of 189
Originator Pete Tamburro	Date 3/21/07	Reviewed by	Date



ANSYS 5.4A  
 OCT 20 1992  
 14:42:30  
 POST1 STRSS  
 STEP=1  
 ITER=1  
 SY (AVG)  
 MIDDLE  
 ELEM C8  
 UNX = 22222  
 UNY = 8245  
 UNZ = 689.72  
 NV -1  
 ZV -1  
 \*DIST -21.539  
 \*XF -46.39  
 \*YF -1.382  
 \*ZF -352.657  
 ANGLE=90  
 CENTROID HIDDEN  
 -6249  
 -7252  
 -6280  
 -5267  
 -4274  
 -3282  
 -2269  
 -1256  
 -683.431  
 689.72

Appendix G  
 Figure 3-11 from reference 3.4

Figure 3-11 Lower Drywell Horizontal Stress - Refueling Case  
 OYSTER CREEK DRYWELL ANALYSIS - SYN-SYS, SCORRD, REFUELD

# GPU Nuclear

Subject	Sheet No.
O.C. Drywell Est. UT Evaluation in Sandbed	183 of 183
Originator	Date
Pete Tamburro	
Calc. No.	Rev. No.
C-1977-197-5320-024	3
Reviewed by	
Date	
3/21/07	

ANSYS 4.4A  
 OCT 20 1982  
 14:48:49  
 POSITV STRESS  
 STEP=1  
 ITER=1  
 SN (AVG)  
 MIDDLE  
 ELEM C8  
 DMX =8.22232  
 SMN =-3548  
 SMX =6583  
 RV =1  
 ZY =1  
 CPDST=121.538  
 EXP =46.39  
 CTE =1.352  
 PZF =382.657  
 ANG2=-88  
 CENTROID HIDDEN  
 -3548  
 -2422  
 -1237  
 -179.061  
 894.778  
 2988  
 3206  
 4332  
 5457  
 6583




Figure 5-13 Lower Drywell Circumferential Stresses - Refueling Case

OYSIER CREEK DRYWELL ANALYSIS - SYN-SYN, HOSAND, REFUELING



Calculation Sheet

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 1 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**1.0 PROBLEM STATEMENT:**

The purpose of this calculation is to evaluate the UT thickness measurements taken in the sandbed region during the 14R outage in support of O.C drywell corrosion mitigation project. These measurements were taken from the outside of the shell. Access to the sandbed region was achieved by cutting ten holes completely through the shield wall from the torus room.

**2.0 SUMMARY OF RESULTS:**

This calculation demonstrates that the UT thickness measurements for all bays meet the minimum uniform and local required thicknesses.

The evaluation was performed by evaluating the UT measurements for each bay and dispositioning them relative to the uniform thickness of 0.736 inch used in GE structural analysis reports. Additional acceptance criteria was developed to address measurements below 0.736 inch. The results are summarized in Table 1.

UT measurements for bays 3, 5, 7, 9, and 19 were all above the 0.736 inches and therefore acceptable.

UT measurements for bays 11, 15, and 17 were all above 0.736 inches except for one measurement for each bay. After further evaluation of these three measurements including an examination of adjacent areas, it was determined that they were acceptable as shown on Table 1.

UT measurements for bays 1 and 13 were evaluated using detailed criteria described in this calculation and the results are summarized in Table 1 below:

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 2 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**2.0 SUMMARY OF RESULTS ( Continued ):**

Summary of UT Evaluations

Table (1)

BAY/UT Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4) * (1) + (2) - (3)	Remarks
Bay 11/ Loc. 1	0.705"	0.246"	0.200"	0.751"	Acceptable
Bay 15/ Loc. 9	0.722"	0.337"	0.200"	0.859"	Acceptable
Bay 17/ Loc. 9	0.720"	0.351"	0.200"	0.871"	Acceptable
Bay 1/ Loc. 1	0.720"	0.218"	0.200"	0.738"	Acceptable
Bay 1/ Loc. 2	0.716"	0.143"	0.200"	0.659"	Acceptable
Bay 1/ Loc. 3	0.705"	0.347"	0.200"	0.852"	Acceptable
Bay 1/ Loc. 5	0.710"	0.313"	0.200"	0.823"	Acceptable
Bay 1/ Loc. 7	0.700"	0.266"	0.200"	0.766"	Acceptable
Bay 1/ Loc. 11	0.714"	0.212"	0.200"	0.726"	Acceptable
Bay 1/ Loc. 12	0.724"	0.301"	0.200"	0.825"	Acceptable
Bay 1/ Loc. 21	0.726"	0.211"	0.200"	0.737"	Acceptable
Bay 13/ Loc. 1	0.672"	0.351"	0.200"	0.823"	Acceptable
Bay 13/ Loc. 2	0.729"	0.360"	0.200"	0.882"	Acceptable
Bay 13/ Loc. 5	0.718"	0.217"	0.200"	0.735"	Acceptable
Bay 13/ Loc. 6	0.655"	0.301"	0.200"	0.756"	Acceptable
Bay 13/ Loc. 7	0.618"	0.257"	0.200"	0.675"	Acceptable
Bay 13/ Loc. 8	0.718"	0.278"	0.200"	0.796"	Acceptable
Bay 13/ Loc. 10	0.728"	0.211"	0.200"	0.739"	Acceptable
Bay 13/ Loc. 11	0.685"	0.256"	0.200"	0.741"	Acceptable
Bay 13/ Loc. 15	0.683"	0.273"	0.200"	0.756"	Acceptable

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	3 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**3.0 REFERENCES:**

- 3.1 Drywell sandbed region pictures (see Appendix C).
- 3.2 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE - Part 1 Stress Analysis, Revision 0 dated February, 1991 Report 9-3.
- 3.3 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE - Part 2 Stability Analysis, Revision 2 dated November, 1992 Report 9-4.
- 3.4 ASME Section III Subsection NE Class MC Components 1989.
- 3.5 GE letter report " Sandbed Local Thinning and Raising the Fixity Height Analysis ( Line Items 1 and 2 In Contract PC-0391407 )" dated December 11, 1992.
- 3.6 GPUN Memo 5320-93-020 From K. Whitmore to J. C. Flynn "Inspection of Drywell Sand Bed Region and Access Hole", Dated January 28, 1993.

**4.0 ASSUMPTIONS AND BASIC DATA:**

- 4.1 Raw UT measurements are summarized for each bay in the body of calculation.
- 4.2 Observations of the outside surface of the drywell shell indicate a rough surface with varying peaks and valleys. In order to characterize an average roughness representing the depth difference of peaks and valleys, two impressions were made at the two lowest UT measurements for bay 13 using Epoxy putty . Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated. A value of 0.200 inch was used in this calculation as a conservative depth of uniform dimples for the entire outside surface of the drywell in the sandbed region .



Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 4 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**

**ACCEPTANCE CRITERIA - GENERAL WALL:**

The acceptance criteria used to evaluate the measured drywell thickness is based upon GE reports 9-3 and 9-4 (Ref. 3.2 & 3.3) as well as other GE studies (Ref. 3.5) plus visual observations of the drywell surface ( Ref. 3.6 and Appendix C ). The GE reports used an assumed uniform thickness of 0.736 inches in the sandbed area. This area is defined to be from the bottom to top of the sandbed, i.e., El. 8'-11½" to El. 12'-3" and extending circumferentially one full bay. Therefore, if all the UT measurements for thickness in one bay are greater than 0.736 inches the bay is evaluated to be acceptable. In bays where measurements are below 0.736 inches, more detailed evaluation is performed.

This detailed evaluation is based, in part, on visual observations of the shell surface plus a knowledge of the inspection process. The first part of this evaluation is to arrive at a meaningful value for shell thickness for use in the structural assessment. This meaningful value is referred to as the thickness for evaluation. It is computed by accounting for the depth of the spot where the thickness measurement is taken considering the roughness of the shell surface. The surface of the shell has been characterized as being "dimpled" as in the surface of a golf ball where the dimples are about one half inch in diameter ( Appendix C ). Also, the surface contains some depressions 12 to 18 inches in diameter not closer than 12 inches apart, edge to edge (Ref. 3.6). Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated to be at 0.186 inches. A value of 0.200 inch was used in this calculation as a conservative depth of uniform dimples for the entire outside surface of the drywell in the sandbed region .

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 5 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**
**ACCEPTANCE CRITERIA - GENERAL WALL: (Continued)**

The inspection focused on the thinnest portion of the drywell, even if it was very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. Observations indicate that some inspected spots are very deep. They are much deeper than the normal dimples found, and very local, not more than 1 to 2 inches in diameter. (Typically these observations were made after the spot was surface prepped for UT measurement. This results in a wide dimple to accommodate the meter and slightly deeper than originally found by 0.030 to 0.100 inches). The depth of these areas was measured and averaged with respect to the top of local areas as shown in Appendix A. These depths are referred to herein as the AVG micrometer measurements. The thickness for evaluation is then computed from the above information as:

$$T \text{ (evaluation)} = \text{UT (measurement)} + \text{AVG (micrometer)} - 0.200 \text{ inches}$$

where:

$$T \text{ (evaluation)} = \text{thickness for evaluation}$$

$$\text{UT (measurement)} = \text{thickness measurement at the area (location)}$$

$$\text{AVG (micrometer)} = \text{average depth of the area relative to its immediate surroundings}$$

$$0.200 \text{ inch} = \text{a conservative value of depth of typical dimple on the shell surface.}$$

After this calculation, if the thickness for analysis is greater than 0.736 inches; the area is evaluated to be acceptable.

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	6 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**5.0 CALCULATION:****ACCEPTANCE CRITERIA - LOCAL WALL:**

If the thickness for evaluation is less than 0.736 inches, then the use of specific GE studies is employed (Ref. 3.5). These studies contain analyses of the drywell using the pie slice finite element model, reducing the thickness by 0.200 inches in an area 12 x 12 inches in the sandbed region, tapering to original thickness over an additional 12 inches, located to result in the largest reduction possible. This location is selected at the point of maximum deflection of the eigenvector shape associated with the lowest buckling load. The theoretical buckling load was reduced by 9.5% from 6.41 to 5.56. Also, the surrounding areas of thickness greater than 0.736 inches is also used to adjust the actual buckling values appropriately. Details are provided in the body of the calculation.

**ACCEPTANCE CRITERIA - VERY LOCAL WALL (2½ Inches In DIAMETER):**

All UT measurements below 0.736 inches have been determined to be in isolated locations less than 2½ inches in diameter.

The acceptance criteria for these measurements confined to an area less than 2½ inches in diameter is based on the ASME Section III Subsection NE Class MC Components paragraph NE 3332.1 and NE 3335.1 titled "OPENING NOT REQUIRING REINFORCEMENT AND REINFORCEMENT OF MULTIPLE OPENINGS".

These Code provisions allow holes up to 2½ inches in diameter in Class MC vessels without requiring reinforcement. Therefore, thinned areas less than 2½ inches in diameter need not be provided with reinforcement and are considered local. Per NE 3213.10 the stresses in these regions are classified as local primary membrane stresses which are limited to an allowable value of 1.5 Sm. Local areas not exceeding 2½ inches in diameter have no impact on the buckling margins. Using the 1.5 Sm criteria given above, the required minimum thickness in these areas is:

$$T \text{ ( required )} = ( 2/3 ) * ( 0.736 ) = 0.490 \text{ inches}$$

Where 2/3 is  $S_m/1.5S_m$  and is the ratio of the allowable stresses.

UT thickness measurements for all ten bays are above 0.490 inches.

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	7 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 1:**

The outside surface of this bay is rough and full of dimples similar to the outside surface of golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. This inspection focused on the thinnest areas of the drywell, even if it was very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. The shell appears to be relatively uniform in thickness except for a band of corrosion which looks like a "bathtub" ring, located 15 to 20 inches below the vent pipe reinforcement plate, i.e, weld line as shown in Figure 1. ( Figure 1 and others like figures presented in this calculation are NOT TO SCALE). The bathtub ring is 12 to 18 inches wide and about 30 inches long located in the center of the bay. Beyond the bathtub ring on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800 inches. Above the bathtub ring the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurements 14 and 15 confirm that the thickness above the bathtub ring is at 1.154 inches starting at elevation 11'-00". Below the bathtub ring the shell is uniform in thickness where no abrupt changes in thicknesses are present. Thickness measurements below the bathtub ring are all above 0.800 inches except location 7 which is very local area.

Therefore, a conservative mean thickness of 0.800 inches is estimated to represent the evaluation thickness for this bay. Given a uniform thickness of 0.800 inches, the buckling margin for the refueling load condition can be recalculated based on the GE report 9-4 (Ref. 3.3). The theoretical buckling strength from report 9-4 (ANSYS Load Factor) is a square function of plate thicknesses. Therefore, a new buckling capacity for the controlling refueling load combination is calculated to be at 13% above the ASME factor of safety of 2 as shown in Appendix B.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 8 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**
**UT EVALUATION:**
**BAY # 1 ( Continued):**

Locations 1, 2, 3, 4, 5, 10, 11, 12, 13, 20, and 21 are confined to the bathtub ring as shown in Figure 1. An average value of these measurements is an evaluation thickness for this band as follows;

**Location      Evaluation Thickness**

1	0.738"
2	0.659"
3	0.852"
4	0.760"
5	0.823"
10	0.839"
11	0.726"
12	0.825"
13	0.792"
20	0.965"
21	0.737"

Average = 0.792"

An average evaluation thickness of 0.792 inches for the bathtub ring may raise concern given that the bathtub ring is noticeable and that the difference between its average evaluation thickness (0.792 inches) and the average thickness taken for the entire region (0.800 inches) is only 0.008 inches. This results from the fact that average micrometer readings were generally not taken for the remainder of the shell since each reading was greater than 0.736 inches. In reality, the remainder of the shell is much thicker than 0.800 inches. The appropriate evaluation thickness can not be quantified since no micrometer readings were taken.

The individual measured thicknesses must also be evaluated for structural compliance. Table 1-a identifies 23 locations of UT measurements that were selected to represent the thinnest areas, except locations 14 and 15, based on visual examination. These locations are a deliberate attempt to produce a minimum measurement. Locations 14 and 15 were selected to confirm that no corrosion had taken place in the area above the bathtub ring.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 9 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 1 ( Continued):**

Eight locations shown in Table 1-a (1, 2, 3, 5, 7, 11, 12, and 21) have measurements below 0.736 inches. Observations indicate that these locations were very deep and not more than 1 to 2 inches in diameter. The depth of each of these areas relative to its immediate surroundings was measured at 8 locations around the spot and the average is shown in Table 1-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for all measurements below 0.736 inches were found to be above 0.736 inches except for two locations, 2 and 11, as shown in Table 1-b. Locations 2 and 11 are in the bathtub ring and are about 4 inches apart. This area is characterized as a local area 4 x 4 inches located at about 15 to 20 inches below the vent pipe reinforcement plate with an average thickness of 0.692 inches. This thickness of 0.692 inches is 0.108 inches reduction from the conservative estimate of 0.800 inches evaluation thickness for the entire bay. In order to quantify the effect of this local region and to address structural compliance, the GE study on local effects is used (Ref. 3.5).

This study contains an analysis of the drywell shell using the pie slice finite element model, reducing the thickness by 0.200 inches (from 0.736 to 0.536 inches) in an area 12 x 12 inches in the sandbed region located to result in the largest reduction possible. This location is selected at the point of maximum deflection of the eigenvector shape associated with the lowest buckling load. The theoretical buckling load was reduced by 9.5%. The 4 x 4 inches local region is not at the point of maximum deflection. The area of 4 x 4 inches is only 11% of the 12 x 12 inches area used in the analysis. Therefore, this small 4 x 4 inches area has a negligible effect on the buckling capacity of the structure.

In summary, using a conservative estimate of 0.800 inches for evaluation thickness for the entire bay and the presence of a bathtub ring with an evaluation thickness of 0.792 inches plus the acceptance of a local area of 4 x 4 inches based on the GE study, it is concluded that the bay is acceptable.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 10 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 1 (Continued):****Bay # 1 UT Data****Table 1-a**

Location	UT Measurement (Inches)	Average Micrometer (Inches)
1	0.720	0.218
2	0.716	0.143
3	0.705	0.347
4	0.760	---
5	0.710	0.313
6	0.760	---
7	0.700	0.266
8	0.805	---
9	0.805	---
10	0.839	---
11	0.714	0.212
12	0.724	0.301
13	0.792	---
14	1.147	---
15	1.156	---
16	0.796	---
17	0.860	---
18	0.917	---
19	0.890	---
20	0.965	---
21	0.726	0.211
22	0.852	---
23	0.850	---

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	11 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**5.0 CALCULATION:**

**UT EVALUATION:**

**BAY # 1: (Continued)**

**SUMMARY OF Measurements BELOW 0.7**

**Table 1-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4) = (1) + (2) - (3)	Remarks
1	0.720"	0.218"	0.200"	0.738"	Acceptable
2	0.716"	0.143"	0.200"	0.659"	Acceptable
3	0.705"	0.347"	0.200"	0.852"	Acceptable
5	0.710"	0.313"	0.200"	0.823"	Acceptable
7	0.700"	0.266"	0.200"	0.766"	Acceptable
11	0.714"	0.212"	0.200"	0.726"	Acceptable
12	0.724"	0.301"	0.200"	0.825"	Acceptable
21	0.726"	0.211"	0.200"	0.737"	Acceptable



Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 12 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #1 DATA

### NOTES:

1. All "Location" measurements from Intersection of the DW shell and vent collar fillet welds.
2. Pit depts are average of four readings taken at 0/45°/90°/135° within 1" band surrounding ground spots. Only measured where remaining wall thk. was below 0.736".




FIGURE (1)

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 13 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:**

**UT EVALUATION:**

**BAY # 3:**

The outside surface of this bay is rough, similar to bay one, full of dimples comparable to the outside surface of golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness except for a bathtub ring 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact. Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 3). These locations are a deliberate attempt to produce a minimum measurement. Table 3 shows measurements taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

Given the UT measurements, a conservative mean evaluation thickness of 0.850 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

**Bay # 3 UT Data**

**Table 3**

Location	UT Measurement (inches)	Average Micrometer (inches)
1	0.795	---
2	1.000	---
3	0.857	---
4	0.898	---
5	0.823	---
6	0.968	---
7	0.826	---
8	0.780	---

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 14 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #3 DATA

### NOTES:

1. All "Location" measurements from Intersection of the DW shell and vent collar fillet welds.




FIGURE (3)

Subject <b>O.C Drywell Ext. Ut Evaluation in Sandbed</b>		Calc No. <b>C-1302-187-5320-024</b>	Rev. No. <b>0</b>	Sheet No. <b>15 of 54</b>
Originator <b>MARK YEKTA</b>	Date <b>01/12/93</b>	Reviewed by <b>S. C. Tumminelli</b>		Date <b>04/16/93</b>

**5.0 CALCULATION:**

**UT EVALUATION:**

**BAY # 5:**

The outside surface of this bay is rough and very similar to bay 3 except that the local areas are clustered at the junction of bays 3 and 5, at about 30 inches above the floor. The shell surface is full of dimples comparable to the outside surface of golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (see Fig. 5). These locations are a deliberate attempt to produce a minimum measurement. Table 5 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

Given the UT measurements, a conservative mean evaluation thickness of 0.950 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

**Bay # 5 UT Data**

**Table 5**

Location	UT Measurement (Inches)	Average Micrometer (Inches)
1	0.970	---
2	1.040	---
3	1.020	---
4	0.910	---
5	0.890	---
6	1.060	---
7	0.990	---
8	1.010	---

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 16 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

# BAY #5 DATA

## NOTES:

1. In this bay DW shell (butt) weld is about 8" to the right of C/L of vent tube. Therefore - all measurements were taken from a line drawn on shell which approx. coincide with vent tube C/L.




FIGURE (5)

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	17 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 7:**

The observation of the drywell surface for this bay showed uniform dimples in the corroded area, but they are shallow compared to those in bay 1. The bathtub ring seen in the other bays, was not very prominent in this bay. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Seven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 7). These locations are a deliberate attempt to produce a minimum measurement. Table 7 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

Given the UT measurements, a conservative mean evaluation thickness of 1.00 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

**Bay # 7 UT Data****Table 7**

Location	UT Measurement (inches)	Average Micrometer (inches)
1	0.920	---
2	1.016	---
3	0.954	---
4	1.040	---
5	1.030	---
6	1.045	---
7	1.000	---

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 18 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #7 DATA

### NOTES:

1. All measurements from the intersection of DW shell (butt) and vent collar (fillet) welds.




FIGURE (7)

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 19 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 9:**

The observation of the drywell shell for this bay was very similar to bay 7 except that the bathtub ring was more evident in this bay. The shell appears to be relatively uniform in thickness except for a bathtub ring 6 to 9 inches wide approximately 6 to 8 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact. Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 9). These locations are a deliberate attempt to produce a minimum measurement. Table 9 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

Given the UT measurements, a conservative mean evaluation thickness of 0.900 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

**Bay # 9 UT Data****Table 9**

Location	UT Measurement (inches)	Average Micrometer (inches)
1	0.960	---
2	0.940	---
3	0.994	---
4	1.020	---
5	0.985	---
6	0.820	---
7	0.825	---
8	0.791	---
9	0.832	---
10	0.980	---



Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 20 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #9 DATA

### NOTES:

1. All measurements from Intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE (9)

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	21 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 11:**

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of a golf ball. The shell appears to be relatively uniform in thickness except for local areas at the upper right corner of Figure 11, located at about 10 to 12 inches below the vent pipe reinforcement plate.

Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 11). These locations are a deliberate attempt to produce a minimum measurement. Table 11-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 1 as shown in Table 11-a, has a reading below 0.736 inches. Observations indicate that this location was very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surroundings was measured at 8 locations around the spot and the average is shown in Table 11-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for location 1 was found to be above 0.736 inches as shown in Table 11-b.

Given the UT measurements, a conservative mean evaluation thickness of 0.790 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 22 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**
**UT EVALUATION:**
**BAY # 11 (Continued):**
**Bay # 11 UT Data**
**Table 11-a**

Location	UT Measurement (Inches)	Average Micrometer (Inches)
1	0.705	0.246
2	0.770	---
3	0.832	---
4	0.755	---
5	0.831	---
6	0.800	---
7	0.831	---
8	0.815	---

**Summary of Measurements Below 0.736 Inches**
**Table 11-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4) = (1) + (2) - (3)	Remarks
1	0.705"	0.246"	0.200"	0.751"	Acceptable

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 23 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

## BAY #11 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" band surrounding the ground spots. This measurement was only taken when wall thickness was below 0.736".




FIGURE ( 11 )

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	24 of 54
Originator	Date	Reviewed by	Date
MARK YEKTA	01/12/93	S. C. Tumminelli	04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 13:**

The outside surface of this bay is rough and full of dimples similar to bay 1 as shown in Appendix C. This observation is made by the inspector who located the thinnest areas in deep valleys thereby biasing the remaining wall measurements to the conservative side. This inspection focused on the thinnest areas, even if very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. The variation in shell thickness is greater in this bay than in the other bays. The bathtub ring below the vent pipe reinforcement plate was less prominent than was seen in other bays. The corroded areas are about 12 to 18 inches in diameter and are at 12 inches apart, located in the middle of the sandbed. Beyond the corroded areas on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800 inches. Near the vent pipe and reinforcement plate the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurement 20 confirms that the thickness above the bathtub ring is at 1.154 inches. Below the bathtub ring the shell appears to be fairly uniform in thickness where no abrupt changes in thickness are present. Thickness measurements below the bathtub ring are all 0.800 inches or better.

Therefore, a conservative mean thickness of 0.800 inches is estimated to represent the evaluation thickness for this bay. Given a uniform thickness of 0.800 inches, the buckling margin for the refueling load condition is recalculated based on the GE report 9-4 (Ref. 3.3). The theoretical buckling strength from report 9-4 (ANSYS Load Factor) is a square function of plate thicknesses. Therefore, a new buckling capacity for the controlling refueling load combination is calculated to be at 13% above the ASME factor of safety of 2 as shown in Appendix B.

Subject		Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed		C-1302-187-5320-024	0	25 of 54
Originator	Date	Reviewed by		Date
MARK YEKTA	01/12/93	S. C. Tumminelli		04/16/93

**5.0 CALCULATION:**
**UT EVALUATION:**
**BAY # 13 ( Continued ):**

Locations 5, 6, 7, 8, 10, 11, 14, and 15 are confined to the bathtub ring as shown in Figure 13. An average value of these measurements is an evaluation thickness for this band as follows;

<u>Location</u>	<u>Evaluation Thickness</u>
-----------------	-----------------------------

5	0.735"
6	0.756"
7	0.675"
8	0.796"
10	0.739"
11	0.741"
12	0.885"
14	0.868"
15	0.756"
16	0.829"

Average = 0.778"

The inspector suspected that some of the above locations in the bathtub ring were over ground. Subsequent locations with suffix A, e.g. 5A, 6A, were located close to the spots in question and were ground carefully to remove the minimum amount of metal but adequate enough for UT examination as shown in Table 13-a. The results indicate that all subsequent measurements were above 0.736 inches. The average micrometer measurements taken for these locations confirm the depth measurements at these locations. In spite of the fact that the original measurements were taken at heavily ground locations they are the ones used in the evaluation.

The individual measurements must also be evaluated for structural compliance. Table 13-a identifies 20 locations of UT measurements that were selected to represent the thinnest areas, except location 20, based on visual examination. These locations are a deliberate attempt to produce a minimum measurement. Location 20 was selected to confirm that no corrosion had taken place in the area above the bathtub ring.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 26 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 13 ( Continued ):**

Nine locations shown in Table 13-a (1, 2, 5, 6, 7, 8, 10, 11, and 15) have measurements below 0.736 inches. Observations indicate that these locations were very deep, overly ground, and not more than 1 to 2 inches in diameter. The depth of each of these areas relative to its immediate surroundings was measured at 8 locations around the spot and the average is shown in Table 13-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for all measurements below 0.736 inches were found to be above 0.736 inches except for two locations, 5 and 7, as shown in Table 13-b. In addition, subsequent measurements close to the locations identified above, were taken and they were all above 0.736 inches. Locations 5 and 7 are in the bathtub ring and are about 30 inches apart. These locations are characterized as local areas located at about 15 to 20 inches below the vent pipe reinforcement plate with an evaluation thicknesses of 0.735 inches and 0.677 inches. The location 5 is near to location 14 for an average value of 0.801 inches and therefore acceptable. Location 7 could conservatively exist over an area of 6 x 6 inches for a thickness of 0.677 inches. This thickness of 0.677 inches is a full 0.123 inches reduction from the conservative estimate of 0.800 inches evaluation thickness for the entire bay. In order to quantify the effect of this local region and to address structural compliance, the GE study on local effects is used (Ref. 3.5).

This study contains an analysis of the drywell shell using the pie slice finite element model, reducing the thickness by 0.200 inches (from 0.736 to 0.536 inches) in an area 12 x 12 inches in the sandbed region located to result in the largest reduction possible. This location is selected at the point of maximum deflection of the eigenvector shape associated with the lowest buckling load. The theoretical buckling load was reduced by 9.5%. The 6 x 6 inch local region is not at the point of maximum deflection. The area of 6 x 6 inches is only 25% of the 12 x 12 inches area used in the analysis. Therefore, this small 6 x 6 inch area has a negligible effect on the buckling capacity of the structure.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 27 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**

**UT EVALUATION:**

**BAY # 13 ( Continued ):**

In summary, using a conservative estimate of 0.800 inches for evaluation thickness for the entire bay and the presence of a bathtub ring with a evaluation thickness of 0.778 inches plus the acceptance of a local area of 6 x 6 inches based on the GE study, it is concluded that the bay is acceptable.

**Bay # 13 UT Data**

**Table 13-a**

Location	UT Measurement (inches)	Average Micrometer (inches)
1/1A	0.672/0.890	0.351
2/2A	0.722/0.943	0.360
3	0.941	---
4	0.915	---
5/5A	0.718/0.851	0.217
6/6A	0.655/0.976	0.301
7/7A	0.618/0.752	0.257
8/8A	0.718/0.900	0.278
9	0.924	---
10/10A	0.728/0.810	0.211
11/11A	0.685/0.854	0.256
12	0.885	---
13	0.932	---
14	0.868	---
15/15A	0.683/0.859	0.273
16	0.829	---
17	0.807	---
18	0.825	---
19	0.912	---
20	1.170	---



Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 28 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 13 ( Continued ):****Summary of Measurements Below 0.736 Inches****Table 13-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4) = (1) + (2) - (3)	Remarks
1	0.672"	0.351"	0.200"	0.823"	Acceptable
2	0.722"	0.360"	0.200"	0.882"	Acceptable
5	0.718"	0.217"	0.200"	0.735"	Acceptable
6	0.655"	0.301"	0.200"	0.756"	Acceptable
7	0.618"	0.257"	0.200"	0.675"	Acceptable
8	0.718"	0.278"	0.200"	0.796"	Acceptable
10	0.728"	0.211"	0.200"	0.739"	Acceptable
11	0.685"	0.256"	0.200"	0.741"	Acceptable
15	0.683"	0.273"	0.200"	0.756"	Acceptable

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 29 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

## BAY #13 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Spots with suffix (e.g. 1A or 2A) were located close to the spots in question and were ground carefully to remove minimum amount of metal but adequate enough for UT.
3. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spot. Taken only where remaining wall showed below 0.736".




FIGURE ( 13 )

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	30 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 15:**

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball (Appendix C ). The bathtub ring seen in the other bays, was not very prominent in this bay. This observation is made by the inspector who located the thinnest areas for the UT examination. The upper portion of the shell beyond the ring exhibits no corrosion where the original red lead primer is still intact. The shell appears to be relatively uniform in thickness.

Eleven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 15). These locations are a deliberate attempt to produce a minimum measurement. Table 15-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 9 as shown in Table 15-a, has a reading below 0.736 inches. Observations indicate that this location was very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surrounding was measured at 8 locations around the spot and the average is shown in Table 15-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for location 9 was found to be above 0.736 inches as shown in Table 15-b.

Given the UT measurements, a conservative mean evaluation thickness of 0.800 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

Subject <b>O.C Drywell Ext. Ut Evaluation in Sandbed</b>		Calc No. <b>C-1302-187-5320-024</b>	Rev. No. <b>0</b>	Sheet No. <b>31 of 54</b>
Originator <b>MARK YEKTA</b>	Date <b>01/12/93</b>	Reviewed by <b>S. C. Tumminelli</b>		Date <b>04/16/93</b>

**5.0 CALCULATION:**
**UT EVALUATION:**
**BAY # 15:**
**Bay #15 UT Data**
**Table 15-a**

Location	UT Measurement (inches)	Average Micrometer (Inches)
1	0.786	---
2	0.829	---
3	0.932	---
4	0.795	---
5	0.850	---
6	0.794	---
7	0.808	---
8	0.770	---
9	0.722	0.337
10	0.860	---
11	0.825	---

**Summary of Measurements Below 0.736 Inches**
**Table 15-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4)=(1)+(2)-(3)	Remarks
9	0.722"	0.337"	0.200"	0.859"	Acceptable

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 32 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #15 DATA

### NOTES:

1. All measurements from intersection of the DW shell and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spots. Taken only when remaining wall thickness shown below 0.736".




FIGURE ( 15 )

Subject		Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed		C-1302-187-5320-024	0	33 of 54
Originator	Date	Reviewed by		Date
MARK YEKTA	01/12/93	S. C. Tumminelli		04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 17:**

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball. The shell appears to be relatively uniform in thickness except for a band 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact.

Eleven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 17). These locations are a deliberate attempt to produce a minimum measurement. Table 17-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 9 as shown in Table 17-a, has a reading below 0.736 inches. Observations indicate that this location is very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surroundings was measured at 8 locations around the spot and the average is shown in Table 17-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for location 9 was found to be above 0.736 inches as shown in Table 17-b.

Given the UT measurements, a conservative mean evaluation thickness of 0.900 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 34 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:**
**UT EVALUATION:**
**BAY # 17 (Continued):**
**Bay #17 UT Data**
**Table 17-a**

Location	UT Measurement (inches)	Average Micrometer (inches)
1	0.916	---
2	1.150	---
3	0.898	---
4	0.951	---
5	0.913	---
6	0.992	---
7	0.970	---
8	0.990	---
9	0.720	0.351
10	0.830	---
11	0.770	---

**Summary of Measurements Below 0.736 Inches**
**Table 17-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4)=(1)+(2)-(3)	Remarks
9	0.720"	0.351"	0.200"	0.871"	Acceptable

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 35 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #17 DATA

### NOTES:

1. All measurements from intersection of the DW (butt) shell and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spots. Taken only when remaining wall thickness was below 0.735".




FIGURE ( 17 )



Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 36 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**5.0 CALCULATION:****UT EVALUATION:****BAY # 19:**

The outside surface of this bay is rough and very similar to bay 17. Locations 1 through 7 as shown in Table 19, were ground carefully to minimize loss of good metal. The shell surface is full of dimples comparable to the outside surface of a golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Ten locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 19). These locations are a deliberate attempt to produce a minimum measurement. Table 19 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

Given the UT measurements, a conservative mean evaluation thickness of 0.850 inches is estimated for this bay and therefore, it is concluded that the bay is acceptable.

**Bay #19 UT Data****Table 19**

Location	UT Measurement (inches)	Average Micrometer (inches)
1	0.932	---
2	0.924	---
3	0.955	---
4	0.940	---
5	0.950	---
6	0.860	---
7	0.969	---
8	0.753	---
9	0.776	---
10	0.790	---

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 37 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

## BAY #19 DATA

### NOTES:

- All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE ( 19 )

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 38 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**APPENDIX A****SUMMARY OF MEASUREMENTS****OF****IMPRESSIONS TAKEN FROM BAY #13**

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 39 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

The purpose of this appendix is to characterize the depth of typical uniform dimples on the shell surface. This depth is used in acceptance criteria to quantify the evaluation thickness for an area where the micrometer readings are available.

Two locations in bay 13 were selected since bay 13 is the roughest bay. Impressions of drywell shell surface using DMR\_503 Epoxy Replication Putty manufactured by Dyna Mold Inc were made. These impressions were about 10 inches in diameter and about 1 inch thick. The UT locations 7 and 10 in bay 13 were identified in each of these impression as the reference points. This is a positive impression of the drywell shell surface. The depth of the typical dimples were measured as follows;

<u>READING</u> (Location)	<u>DEPTH # 10</u> (inches)	<u>DEPTH # 7</u> (inches)
1	0.150	0.075
2	0.000	0.110
3	0.200	0.135
4	0.140	0.200
5	0.150	0.000
6	0.040	0.000
7	0.150	0.170
8	0.010	0.205
9	0.134	-----
10	0.145	0.145
11	0.118	0.064
12	0.105	0.200
13	0.125	0.045
14	0.200	0.180
15	0.135	0.105
16	0.100	-----
17	0.175	0.035
18	0.175	0.015
19	0.155	0.190
20	0.175	0.055
21	0.175	0.305
22	-----	0.135

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 40 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

## Location # 10:

Mean Value = 0.131  
Standard Deviation = 0.055

Mean Value + One S.D = 0.186

## Location # 7:

Mean Value = 0.118

Standard Deviation = 0.082

Mean Value + One S.D = 0.200

Therefore, a value of 0.200 inches was used as the depth of uniform dimples for the entire outside surface of the drywell in the sandbed region.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 41 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

**APPENDIX B****BUCKLING CAPACITY EVALUATION****FOR VARYING****UNIFORM THICKNESS**

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 42 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93

CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GE OYCRIS&T - UNIFORM THICKNESS  $t= 0.736$  Inch

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
*** DRYWELL GEOMETRY AND MATERIALS				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.736	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modolus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
*** BUCKLING ANALYSIS RESULTS				
6	Theoretical Elastic Instability Stress, $St_e$	(ksi)	46.590	6.140
*** STRESS ANALYSIS RESULTS				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	7.588	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.510	3.300
*** CAPACITY REDUCTION FACTOR CALCULATION				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.806	
11	'X' Parameter, $X= (P_{eq}/8E) (d/t)^2$		0.087	
12	Delta C (From Figure - )	-	0.072	
13	Modified Capacity Reduction Factor, ALPHA <sub>i,mod</sub>		0.326	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.182	2.001
*** PLASTICITY REDUCTION FACTOR CALCULATION				
15	Yield Stress Ratio, $\Delta = S_e/S_y$		0.400	
16	Plasticity Reduction Factor, $NU_i$		1.000	
17	Inelastic Instability Stress, $S_i = NU_i \times S_e$	(ksi)	15.182	2.001
*** ALLOWABLE COMPRESSIVE STRESS CALCULATION				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.591	1.000
19	Compressive Stress Margin, $M=(S_{all}/S_m -1) \times 100\%$	(%)	0.0	

Subject O.C Drywell Ext. Ut. Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 43 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND  
GE OCRFST01 - UNIFORM THICKNESS  $t=0.776$  Inch

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.776	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $St_e$	(ksi)	49.357	6.857
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied meridional Compressive Stress, $S_m$	(ksi)	7.198	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.248	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	'X' Parameter, $X = (P_{eq}/8E) (d/t)^2$		0.078	
12	Delta C (From Figure - )	-	0.066	
13	Modified Capacity Reduction Factor, ALPHA <sub>i,mod</sub>		0.316	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.583	2.165
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, $\Delta = S_e/S_y$		0.410	
16	Plasticity Reduction Factor, $N_{U_i}$		1.000	
17	Inelastic Instability Stress, $S_i = N_{U_i} \times S_e$	(ksi)	15.583	2.165
<b>ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.792	1.082
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$		8.2	



Subject O.C Drywell Ext. Ut. Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 44 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND  
GPUN EVALUATION FOR UNIFORM THICKNESS t=0.800 Inch USING THICKNESS RATIO**

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.800	
3	Material Yield Strength, Sy	(ksi)	38	
4	Material Modolus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, Ste $6.857 * (0.800/0.776)^2 = 7.288$	(ksi)	50.884	7.288
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied meridional Compressive Stress, Sm	(ksi)	6.982	5.588
8	Applied Circumferential Tensile Stress, Sc	(ksi)	4.120	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHAI		0.207	
10	Circumferential Stress Equivalent Pressure, Peq	(psi)	15.697	
11	'X' Parameter, X= (Peq/8E) (d/t)^2		0.073	
12	Delta C (From Figure - )	-	0.063	
13	Modified Capacity Reduction Factor, ALPHA,i,mod		0.311	
14	Reduced Elastic Instability Stress, Se	(ksi)	15.824	2.266
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA=Se/Sy		0.416	
16	Plasticity Reduction Factor, NUI		1.000	
17	Inelastic Instability Stress, Si = NUI x Se	(ksi)	15.824	2.266
<b>ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, Sall = SI/FS	(ksi)	7.912	1.133
19	Compressive Stress Margin, M=(Sall/Sm -1) x 100%		13.3	

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 45 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93


CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND  
 GPUN EVALUATION FOR UNIFORM THICKNESS  $t=0.850$  Inch USING THICKNESS RATIO

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.850	
3	Material Yield Strength, Sy	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, Ste $6.857 * (0.800/0.776)^2 = 7.288$	(ksi)	54.063	8.227
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied meridional Compressive Stress, Sm	(ksi)	6.571	5.588
8	Applied Circumferential Tensile Stress, Sc	(ksi)	3.878	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA I		0.207	
10	Circumferential Stress Equivalent Pressure, Peq	(psi)	15.697	
11	'X' Parameter, $X = (Peq/8E) (d/t)^2$		0.065	
12	Delta C (From Figure - )	-	0.057	
13	Modified Capacity Reduction Factor, ALPHA, i, mod		0.300	
14	Reduced Elastic Instability Stress, Se	(ksi)	16.257	2.474
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA = Se/Sy		0.428	
16	Plasticity Reduction Factor, NU i		1.000	
17	Inelastic Instability Stress, Si = NU i x Se	(ksi)	16.257	2.474
<b>ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, Sa11 = SI/FS	(ksi)	8.128	1.237
19	Compressive Stress Margin, $M = (Sa11/Sm - 1) \times 100\%$		23.7	


Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 46 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93

**APPENDIX C****PICTURES SHOWING CONDITION****OF THE DRYWELL****IN THE SANDBED REGION**

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	47 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93




Sand Bed Region - Typical condition found on initial entry.



Corrosion product on drywell vessel

Subject		Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed		C-1302-187-5320-024	0	48 of 54
Originator	Date	Reviewed by		Date
MARK YIKTA	01/12/93	S. C. Tumminelli		04/16/93




Bay #13 - D/W shell showing plug . The plug is located in the middle of the worst corroded area of the shell The plug showed no sign of corrosion.




Bay #13 - D/W shell showed less prominent "Tub Ring" than what was seen in other

Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	49 of 54
Originator	Date	Reviewed by	Date
MARK YIKIA	01/12/93	S. C. Tumminelli	04/10/93




Bay #1 - Looking at the worst corroded area on shell near vent tube collar/ring. The ground spots seen here correspond to UT spot 20,21,2,3




Bay #13 - Lower Mid portion of the DW shell showing UT spot 5.6 and 10. This close up photo shows the roughness of the corroded surface and how each UT spot has been picked up in the deep valleys thereby biasing the remaining wall readings to the conservative side

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 50 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93




Bay #13 - Looking towards Bay#11 - Upper right corner of D/W shell. Note ① - Grinding depth on UT spot #1 & 2, ② - A part of "Bain Tub Flang" as delineated by marking and ③ locations of UT spots 3,4,13 & 17. The photo on right (although blurred by flash reflection) shows 1/8" projection of plug.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 51 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93




Bay #15 Looking towards Bay#17 which has been closed with foam for coating work in Bay #17. Note the typical surface of the D/W shell and localized corroded spot




Bay #13 - Looking toward Bay #15 - Lower left corner showing UT spot #7,12 & 16. This close up has captured the peaks and valleys of the corroded shell in vivid detail. Later NDE inspection revealed depth between peaks and valleys in the 0.25" - 0.40"



Subject	Calc No.	Rev. No.	Sheet No.
O.C Drywell Ext. Ut Evaluation in Sandbed	C-1302-187-5320-024	0	52 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93




Bay #15 Looking toward Bay #13 showing portions of DW shell and concrete floor, after removal of loose debris / sand / rust. The concrete floor in this bay is one of the better ones. However - Note ① no drainage channel and ② cratered holes near shell corner.




Bay #15 - Note the original lead primer on vent tube OD surface. The "Tub Ring" was less prominent on the shell in this bay except a portion in lower left corner. Also note presence of lead primer on vent collar/ring plate.

Subject O.C Drywell Ext. Ut Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 53 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli	Date 04/16/93




Bay #13 - Looking toward Bay #11 - Lower right corner of D/W shell showing UT spots 9, 10, 18 & 19 Note the location of these spots - all are located in the valleys of the corroded surface This photo also shows the condition of the concrete floor. It appears




Bay #13 - Looking toward Bay #15 - This photo captures the concrete floor condition and a portion of lower shell corroded surface in very great detail. The floor in this area

Subject O.C Drywell Ext. Ut Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 0	Sheet No. 54 of 54
Originator MARK YEKTA	Date 01/12/93	Reviewed by S. C. Tumminelli		Date 04/16/93



Finished floor, vessel with two top coats - caulking material applied.



Drain after floor has been refurbished

**ATTACHMENT 1**  
**Design Analysis Cover Sheet**  
Page 1 of 117

Design Analysis (Major Revision)		Last Page No. ' 117	
Analysis No.: ' C-1302-187-5320-024		Revision: ' 1	
Title: ' OC Drywell Ext. UT Evaluation in Sandbed			
EC/ECR No.: ' 06-00634		Revision: ' 0	
Station(s): ' Oyster Creek	Component(s): "		
Unit No.: ' 1	187		
Discipline: ' Mechanical/Structural Eng.			
Descrip. Code/Keyword: " UT Data Assessments			
Safety/QA Class: " Q			
System Code: " 187			
Structure: " Drywell Vessel			
<b>CONTROLLED DOCUMENT REFERENCES "</b>			
Document No.:	From/To	Document No.:	From/To
GE # Index 9-4	From		
GE # Index 9-3	From		
GE Letter Report: "Sandbed Local Thinning and Raising the Fixity Height Analysis"	From		
Is this Design Analysis Safeguards Information? " Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, see SY-AA-101-106			
Does this Design Analysis contain Unverified Assumptions? " Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, ATI/AR#: _____			
This Design Analysis SUPERCEDES: " N/A in its entirety.			
Description of Revision (list affected pages for partials): " Revised Calculation to clarify methods used to evaluate UT Measurements of the external Drywell Shell. Also, reformatted portions of the calculation to bring it inline with the existing calculation procedure at Oyster Creek Generating Station. Revised or added the following pages: 3, 4, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 21, 23, 25, 27, 30, 32, 33, 34, 35, 36, 37, 39, 40, 42, 43, and 45. Also added Appendix D, NDE Inspection Sheets			
Preparer: " Jeffrey H. Horton (Enercon)		07/24/06	
	<small>Print Name</small>	<small>Sign Name</small>	<small>Date</small>
Method of Review: " Detailed Review <input checked="" type="checkbox"/> Alternate Calculations (attached) <input type="checkbox"/> Testing <input type="checkbox"/>			
Reviewer: " Omesh Abhat (Enercon)		07/24/06	
	<small>Print Name</small>	<small>Sign Name</small>	<small>Date</small>
Review Notes: " Independent review <input checked="" type="checkbox"/> Peer review <input type="checkbox"/>	Review of the revised part of the calculation has been performed and is acceptable. The review (Rev. 1) addresses clarification of the original calculation only as described above under Description of Revision. Analytical buckling inputs are taken from References 3.3 (Table 4.1) and 3.5. They are assumed acceptable inputs for this calculation as provided by the client.		
(For External Analyses Only)			
External Approver: " Don Shivas (Enercon)		07/21/06	
	<small>Print Name</small>	<small>Sign Name</small>	<small>Date</small>
Exelon Reviewer: "		8/3/06	9/21/06
	<small>Print Name</small>	<small>Sign Name</small>	<small>Date</small>
Is a Supplemental Review Required? " Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> If yes, complete Attachment 3			
Exelon Approver: " T. NICKERSON *		9/21/06	
	<small>Print Name</small>	<small>Sign Name</small>	<small>Date</small>

ALL PAGES CHANGED  
CP1

\* ACTING MANAGER FOR F.H. RAY (WITH HIS CONCURRENCE).

**ATTACHMENT 2**  
**Owners Acceptance Review Checklist for External Design Analysis**  
Page 1 of 1

DESIGN ANALYSIS NO. C-1302-187-5320<sup>-024</sup> REV: 001

PAGE 1A OF 117

		Yes	No	N/A
1.	Do assumptions have sufficient rationale?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2.	Are assumptions compatible with the way the plant is operated and with the licensing basis?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3.	Do the design inputs have sufficient rationale?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.	Are design inputs correct and reasonable?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5.	Are design inputs compatible with the way the plant is operated and with the licensing basis?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6.	Are Engineering Judgments clearly documented and justified?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7.	Are Engineering Judgments compatible with the way the plant is operated and with the licensing basis?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8.	Do the results and conclusions satisfy the purpose and objective of the Design Analysis?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9.	Are the results and conclusions compatible with the way the plant is operated and with the licensing basis?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10.	Does the Design Analysis include the applicable design basis documentation?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11.	Have any limitations on the use of the results been identified and transmitted to the appropriate organizations?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12.	Are there any unverified assumptions?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13.	Do all unverified assumptions have a tracking and closure mechanism in place?	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
14.	Have all affected design analyses been documented on the Affected Documents List (ADL) for the associated Configuration Change?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15.	Do the sources of inputs and analysis methodology used meet current technical requirements and regulatory commitments? (If the input sources or analysis methodology are based on an out-of-date methodology or code, additional reconciliation may be required if the site has since committed to a more recent code)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.	Have vendor supporting technical documents and references (including GE DRFs) been reviewed when necessary?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

EXELON REVIEWER: Peter Tambura / P. A. T. H.  
Print / Sign

DATE: 8/2/06

# AmerGen

DOCUMENT NO.  
C-1302-187-5320-024

TITLE: OC Drywell Ext. UT Evaluation in Sandbed

REV	SUMMARY OF CHANGE	APPROVAL	DATE
0	Initial Issue	GPU Nuclear Signatures on File	04/16/93
1	<p>Revised Calculation to clarify methods used to evaluate UT Measurements of the external Drywell Shell. Also, reformatted portions of the calculation to bring it inline with the existing calculation procedure at Oyster Creek Generating Station. Revised or added the following pages: 3, 4, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 21, 23, 25, 27, 30, 32, 33, 34, 35, 36, 37, 39, 40, 42, 43, and 45. Also added Appendix D, NDE Inspection Sheets</p> <p><i>All Pgs changed. M</i></p> <p><i>A complete revision RT 7/21/06</i> <i>REVISION PERFORMED UNDER ECR#</i> <i>06-00034-M</i></p>	<p><i>Jeffrey H. Horton</i> Jeffrey H. Horton Enercon Services</p> <p><i>Omesh Abhat</i> Omesh Abhat Enercon Services</p> <p><i>Don Shivas</i> Don Shivas Enercon Services</p>	<p>07/24/06</p> <p>07/24/06</p> <p>07/24/06</p>
	<p><i>Please Note Originator and Reviewer at the Top of Pages 3 through 117 are associated with Revision 0.</i></p> <p><i>Revision 1 originator and Reviewer are documented on page I &amp; note.</i> <i>Pat T. 9/21/06</i></p>	<p><i>Pat T.</i> Peter Tamburro</p> <p><i>Chad A. Tipton</i> T. Nickerson (ACTING mgr. FOR F.H. RAY)</p>	<p><i>9/21/06</i></p> <p><i>9/21/06</i></p>

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 3 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## Table of Contents

Section	Page
1.0 PROBLEM STATEMENT:.....	4
2.0 SUMMARY OF RESULTS:.....	4
3.0 REFERENCE:.....	6
4.0 ASSUMPTIONS AND BASIC DATA:.....	6
5.0 DESIGN INPUTS:.....	6
6.0 METHODS OF ANALYSIS:.....	7
UT EVALUATION BAY #1:.....	14
UT EVALUATION BAY #3:.....	22
UT EVALUATION BAY #5:.....	24
UT EVALUATION BAY #7:.....	26
UT EVALUATION BAY #9:.....	28
UT EVALUATION BAY #11:.....	30
UT EVALUATION BAY #13:.....	33
UT EVALUATION BAY #15:.....	41
UT EVALUATION BAY #17:.....	44
UT EVALUATION BAY #19:.....	47
Appendix A: Summary Of Measurements Of Impressions Taken From Bay #13 (3 pages total).....	49
Appendix B: Buckling Capacity Evaluation For Varying Uniform Thickness Through The Whole Sandbed Region Of The Drywell (5 pages total).....	52
Appendix C: Pictures Showing Condition Of The Drywell In The Sandbed Region (9 pages total).....	57
Appendix D: NDE Inspection Sheets for the Drywell Sandbed Region (51 pages total).....	66

52 PT  
9/21/06

7.0 Calculations..... 14  
PT 9/21/06

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 4 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## 1.0 PROBLEM STATEMENT:

The purpose of this calculation is to evaluate the Ultrasonic Test (UT) thickness measurements taken in the sandbed region during the 14R outage in support of the O.C. drywell corrosion mitigation project. These measurements were taken from the outside of the shell. Access to the sandbed region was achieved by cutting ten holes completely through the shield wall from the torus room.

## 2.0 SUMMARY OF RESULTS:

This calculation demonstrates that the UT thickness measurements for all bays meet the minimum uniform and local required thicknesses.

The evaluation was performed by evaluating the UT measurements for each bay and positioning them relative to the uniform thickness of 0.736 inch used in the GE structural analysis reports References 3.2, 3.3 and 3.5. Additional acceptance criteria was developed to address measurements below 0.736 inch. The results are summarized in Table 2-1.

UT measurements for bays 3, 5, 7, 9, and 19 were all above the 0.736 inches and therefore acceptable.

UT measurements for bays 11, 15, and 17 were all above 0.736 inches except for one measurement for each bay. After further evaluation of these three measurements including an examination of adjacent areas, it was determined that they were acceptable as shown on Table 2-1.

UT measurements for bays 1 and 13 were evaluated using detailed criteria described in this calculation and the results are summarized in Table 2-1 below:



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 5 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

**SUMMARY OF UT EVALUATIONS**  
**TABLE (2-1)**

Drywell Bay	General Sandbed Shell Thickness <sup>(1)</sup>			Local Sandbed Thickness <sup>(2)</sup>			Comments
	Thickness Criteria Inches	Actual Thickness Inches	Acceptable Yes/No	Thickness Criteria Inches	Actual Thickness	Acceptable Yes/No	
1	0.736" whole Bay	UT <sub>Avg</sub> =0.822 T <sub>Eval</sub> =0.766	Yes Yes	0.636" over a 12"x12" area	T <sub>Eval</sub> = 0.692" Over a 4"x4" area	Yes	See Pages 14 through 21 for details of evaluation
3	0.736" whole Bay	UT <sub>Avg</sub> =0.868	Yes	0.636" over a 12"x12" area	N/A	N/A	No locations in bay are below 0.736". See Pages 22 & 23
5	0.736" whole Bay	UT <sub>Avg</sub> =0.986	Yes	0.636" over a 12"x12" area	N/A	N/A	No locations in bay are below 0.736". See Pages 24 & 25
7	0.736" whole Bay	UT <sub>Avg</sub> =1.001	Yes	0.636" over a 12"x12" area	N/A	N/A	No Locations in bay are below 0.736" see Pages 26 & 27
9	0.736" whole bay	UT <sub>Avg</sub> =0.915	Yes	0.636" over a 12"x12" area	N/A	N/A	No Locations in bay are below 0.736" see Pages 28 and 29
11	0.736" whole bay	UT <sub>Avg</sub> =0.792 T <sub>Eval</sub> =0.751	Yes	0.636" over a 12"x12" area	N/A	N/A	One location with a thickness less than 0.736" but not greater than 2" in Dia. See Pages 30 to 32
13	0.736" whole bay	UT <sub>Avg</sub> =0.810 T <sub>Eval</sub> =0.767	Yes	0.636" over a 12"x12" area	T <sub>Eval</sub> =0.693" over a 6"x6" area	yes	See pages 33 through 40 for details of evaluation
15	0.736" Whole Bay	UT <sub>Avg</sub> =0.816 T <sub>Eval</sub> =0.859	Yes	0.636" over a 12"x12" area	N/A	N/A	One location with a thickness less than 0.736" but not greater than 2" in Dia. See Pages 41 to 43
17	0.736" Whole Bay	UT <sub>Avg</sub> =0.918 T <sub>Eval</sub> =0.871	Yes	0.636" over a 12"x12" area	N/A	N/A	One location with a thickness less than 0.736" but not greater than 2" in Dia. See Pages 44 to 46
19	0.736" Whole Bay	UT <sub>Avg</sub> =0.885	Yes	0.636" over a 12"x12" area	N/A	N/A	No Locations in bay are below 0.736" see Pages 47 and 48

- Notes: 1. UT<sub>Avg</sub> are the average shell thickness readings using a D-Meter in local areas not less than the buckling design thickness of 0.736" these areas do not exceed 2" in diameter. T<sub>Eval</sub> is the average calculated Thickness of the shell surrounding areas not exceeding 2" in diameter that have UT D-Meter shell thickness readings less than 0.736". See Section 6, Methods of Analysis, Acceptance Criteria - General Wall (Sandbed Region) for details.
2. Small Areas of reduced thickness 2&1/2" or less in diameter have a negligible effect on shell buckling. See Section 6 Methods of Analysis, Acceptance Criteria - Very Local Wall (2&1/2 Inches in Diameter) for details.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 6 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

### 3.0 REFERENCE:

- 3.1 Drywell sandbed region pictures (Appendix C).
- 3.2 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE – Part 1 Stress Analysis, Revision 0 dated February, 1991 Report 9-3.
- 3.3 An ASME Section VIII Evaluation of the Oyster Creek Drywell for Without Sand Case Performed by GE – Part 2 Stability Analysis, Revision 2 dated November, 1992 Report 9-4.
- 3.4 ASME Section III Subsection NE Class MC Components 1989.
- 3.5 GE letter report "Sandbed Local Thinning and Raising the Fixity Height Analysis (Line Items 1 and 2 In Contract PC-0391407)" dated December 11, 1992.
- 3.6 GPUN Memo 5320-93-020 From K. Whitmore to J. C. Flynn "Inspection of Drywell Sand Bed Region and Access Hole", Dated January 28, 1993.
- 3.7 Theory of Elastic Stability, by Stephen P. Timoshenko and James M. Gere, Second Edition, Engineering Societies Monographs, McGraw Hill Book Company, New York, 1961

### 4.0 ASSUMPTIONS AND BASIC DATA:

- 4.1 Raw UT measurements for each bay are presented in Appendix D and summarized in the body of calculation.
- 4.2 References 3.2, 3.3 and 3.5 have been design verified and are assumed correct.

### 5.0 DESIGN INPUTS:

- 5.1 Observations of the outside surface of the drywell shell indicate a rough surface with varying peaks and valleys. In order to characterize an average roughness representing the depth difference of peaks and valleys, two impressions were made at the two lowest UT measurements for bay 13 using Epoxy putty.

Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated. A value of 0.200 inch was used in this calculation as a conservative depth of uniform roughness for the entire outside surface of the drywell in the sandbed region. This is defined as  $T_{rough}$ .

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 7 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

5.2 Drywell Design Pressure = 44.0 psig, Oyster Creek, UFSAR Revision 13, Section 3.8.2.8, Page 3.8-61

Drywell Design Temperature = 292°F, Oyster Creek, UFSAR Revision 13, Table 3.11-1

5.3 The required sandbed shell thickness for the Design Pressure and Temperature is defined in paragraph ASME B&PV Code, Subsection NE, paragraph NE-3324.4, Spherical Shells, as:

$$t = \frac{PR}{2S - 0.2P} \text{ Where: } P = \text{Design Pressure}$$

R = Inside Radius of the Shell = 420 inches

S = Maximum Allowable Stress, SA 212 Grade B  
= 19,300 psi (From ASME B&PV Code Section VIII  
1962 Edition and Reference 3.2, Section 2.2)

Substituting values in the equation we have:

$$t = \frac{(44.0 \text{ psig})(420.0")}{2(19,300 \text{ psi}) - 0.2(44.0 \text{ psig})} = 0.4789 \text{ inches}$$

5.3 Drywell Sandbed buckling design thickness is 0.736 inches. Taken from References 3.3, and 3.5

5.4 Analytical design inputs are taken from References 3.3, 3.4 and 3.5

## 6.0 METHODS OF ANALYSIS:

### Development of "Evaluation Thickness"

This detailed evaluation is based, in part, on visual observations of the shell surface plus a knowledge of the inspection process. The first part of this evaluation is to arrive at a meaningful value for the general sandbed shell thickness for use in the structural assessment. This meaningful value is referred to as the thickness for evaluation. It is computed by accounting for the depth of the spot where the thickness measurement is taken considering the roughness of the shell surface. The surface of the shell has been characterized as being "dimpled" as in the surface of a golf ball where the dimples are about one half inch in diameter (Appendix C). Also, the surface contains some depressions 12 to 18 inches in diameter not closer than 12 inches apart, edge to edge (Ref. 3.6). Appendix A presents the calculation of the depth of surface roughness using the drywell shell impressions taken in the roughest bay. Two locations in bay 13 were selected since it is the roughest bay. Approximately 40 locations within the two impressions were measured for depth and the average plus one standard deviation was calculated to be at 0.186 inches. A value of 0.200 inch was used in this calculation as a conservative depth of uniform dimples for the entire outside surface of the drywell in the sandbed region.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 8 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

The inspection focused on the thinnest portion of the drywell, even if it was very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. Observations indicate that some inspected spots are very deep. They are much deeper than the normal dimples found, and very local, not more than 1 to 2 inches in diameter. (Typically these observations were made after the spot was surface prepped for UT measurement. This results in a wide dimple to accommodate the meter and slightly deeper than originally found by 0.030 to 0.100 inches). The depth of these areas was measured with a depth gauge and straight edge at 0°, 45°, 90° and 135° around these inspected dimples. The depths obtained were averaged with respect to the tops of the locally rough areas. These depths are referred to herein as the AVG micrometer measurements. As these AVG micrometer measurements are very local in nature their effect on the structural response of the drywell to applied loads is very limited. A more meaningful shell thickness for the drywell structural response to applied loads is the general shell thickness near the UT measured indications. This can be obtained on a smooth shell exterior surface by adding the UT measured thickness at the bottom of the indication and the AVG micrometer measurements of the indication depth. But because the exterior of the drywell shell in the sandbed region is very rough and dimpled the measurement described above would give optimistic general shell thicknesses near the indications (See Figure 6.1). To determine a conservative general shell thickness at the locations of interest Design Input 5.1 of this calculation is subtracted from the combination of the UT measurement and the depth micrometer readings. This thickness is then used to determine the drywell shell susceptibility to buckling by comparing this thickness to the buckling design thickness of 0.736 inches. This thickness is referred to as the evaluation thickness which as described above is computed as:

$$T (\text{evaluation}) = UT (\text{measurement}) + AVG (\text{micrometer}) - T_{\text{rough}}$$

where:

T (evaluation) = General shell thickness used for the evaluation

UT (measurement) = thickness measurement at the area (location)

AVG (micrometer) = average depth of the area relative to its immediate surroundings

$T_{\text{rough}} = 0.200$  inches = a conservative value of depth of typical dimple on the shell surface. See Design Input 5.1.

After this calculation, if the thickness for analysis is greater than 0.736 inches; the area is evaluated as acceptable.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 9 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




FIGURE 6.1

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 10 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## Sandbed General Wall Criteria:

The acceptance criteria used to evaluate the measured drywell thickness is based upon GE reports 9-3 and 9-4 (Ref. 3.2 & 3.3) as well as other GE studies (Ref.3.5) plus visual observations of the drywell surface (Ref.3.6 and Appendix C). The GE reports used a projected uniform thickness of 0.736 inches in the sandbed area taken from References 3.3, and 3.5. This area is defined to be from the bottom to top of the sandbed, i.e., El. 8'-11½" to El. 12'-3" and extending circumferentially one full bay. Therefore, if all the UT measurements for thickness in one bay are greater than 0.736 inches the bay is evaluated to be acceptable. In bays where measurements are below 0.736 inches, more detailed evaluation is performed.

## Local Wall Criteria:

If the thickness for evaluation is less than 0.736 inches, then the use of specific GE studies is employed (Ref. 3.5). The studies in Reference 3.5 do not reflect actual drywell shell conditions but are used as assessment tools for areas of the sandbed region that have reduced thicknesses. The methodology used in these studies is provided in reference 3.3 with a excerpt provided here. The studies contain a two step eigenvalue formulation procedure to perform linear elastic buckling analysis of the drywell shell with local areas of reduced thickness. The first step is a static analysis of the structure with all the anticipated loads applied. The structural stiffness matrix,  $[K]$ , the stress stiffness matrix,  $[S]$ , and the applied stresses,  $[\sigma_{ap}]$ , are developed and saved from this static analysis. A buckling pass is then run to solve for the lowest eigenvalue or load factor,  $\lambda$ , for the whole structure at which elastic buckling can occur. This load factor, or eigenvalue is a multiplier for the applied stress state or applied load at which the onset of elastic buckling will theoretically occur. All the applied stresses in the structure are scaled equally by the load factor.

This analysis technique is applied to the drywell pie slice finite element model, with a reduction in thickness of 0.200 inches (below the design buckling thickness of 0.736") in a local area of 12 x 12 inches in the sandbed region, tapering to the original thickness over an additional 12 inches, located to result in the largest reduction in load factor possible. This location is selected at the point of maximum deflection of the eigenvector shape associated with the lowest buckling load. The theoretical load factor / eigenvalue for this case was reduced by 9.5% from 6.14 to 5.56.

It should be noted that this reduction of 0.200 inches is over a 144 square inch area of the shell while the actual surface area including the tapering of the thickness is 36 by 36 inches or 1,296 square inch area with thicknesses that are below the 0.736 inch buckling design thickness. This additional tapered area and its reduced thicknesses also contributed to the 9.5% reduction in load factor.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 11 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

In addition, to the reported result for the 0.536" or a 27% reduction in thickness buckling analysis, a second buckling analysis was performed for a wall thickness reduction of 13.5% or a thickness 0.636 inches over a one square foot area. The results of this case reduced the load factor and theoretical buckling stress by 3.9% in Reference 3.5. The center of the thinned area was located close to the maximum displacement point in the buckling analysis with uniform thickness 0.736" as per Reference 3.5. Again, although this reduction of 13.5% or 0.636 inches is over a 144 square inch area of the shell, the actual surface area including the tapering of the thickness is a 36 by 36 inch or 1,296 square inch area with thicknesses that are below the buckling design thickness. This additional tapered area and its reduced thicknesses also contribute to the 3.9% reduction in load factor stated previously.

### Very Local Wall Criteria (2½ Inches In Diameter or Less):

All inspected locations with UT measurements below 0.736 inches have been determined to be in isolated locations less than 2½ inches in diameter.

### **Primary Membrane Plus Bending**

The acceptance criteria for these measurements confined to an area less than 2 ½ inches in diameter experiencing primary membrane plus bending stresses is based on ASME B&PV Code, Section III, Subsection NE, Class MC Components, Paragraphs NE-3213.2 Gross Structural Discontinuity, NE-3213.10 Local Primary Membrane Stress, NE-3332.1 Openings not Requiring Reinforcement, NE-3332.2 Required Area of Reinforcement and NE-3335.1 Reinforcement of Multiple Openings. The use of Paragraph NE-3332.1 is limited by the requirements of Paragraphs NE-3213.2 and NE-3213.10. In particular NE-3213.10 limits the meridional distance between openings without reinforcement to  $2.5\sqrt{Rt}$ . Also Paragraph NE-3335.1 only applies to openings in shells that are closer than 2 times their average diameter.

The implication of these paragraphs are that shell failures at these locations from primary stresses produced by design pressure cannot occur provided openings in shells have sufficient reinforcement. The current design pressure of 44 psig for the drywell requires a thickness of 0.479 inches in the sandbed region of the drywell. A review of all the UT data presented in Appendix D of the calculation indicates that all thicknesses in the drywell sandbed region exceed the required pressure thickness by a substantial margin and there are no openings in the sandbed region of the drywell shell that do not contain the required design pressure reinforcement for the design code of record. Therefore, the requirements specified by the referenced code sections in the previous paragraph are not required for the very local wall thickness evaluation presented in the calculation.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 12 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Buckling

The effect of these very local wall thickness areas on the buckling of the shell requires some discussion of the buckling mechanism in a shell of revolution under an applied axial and lateral pressure load.

To begin the discussion we will describe the buckling of a simply supported cylindrical shell under the influence of lateral external pressure and axial load. As described in Chapter 11 of Reference 3.7, thin cylindrical shells buckle in lobes in both the axial and circumferential directions. These lobes are defined as half wave lengths of Sinusoidal functions. The functions are governed by the radius, thickness and length of the cylinder. If we look at a specific thin walled cylindrical shell both the length and radius would be essentially constants and if the thickness was reduced locally then this reduction would have to be significant and over a majority of the lobe so that the compressive stress in the lobe would exceed the critical buckling stress under the applied loads, thereby causing the shell to buckle locally. This is demonstrated in Reference 3.5 where a 12 x 12 square inch section of the drywell sandbed region is reduced by 200 mils and a local buckle occurred in the finite element eigenvalue extraction analysis of the drywell.

Now reviewing the stability analyses provided in both References 3.3 and 3.5 and recognizing that the finite elements in the sandbed region of the model are 3" x 3", it is clear that the circumferential buckling lobes for the drywell are substantially larger than the 2 1/2 inch diameter very local wall areas. This combined with the local reinforcement surrounding these local areas and the spherical shell being close to the constraint provided by the concrete supporting structure indicates that these areas will have no impact on the buckling margins in the shell.

It is also clear from Reference 3.5 that a uniform reduction in thickness of 27% over a one square foot area followed by a transition zone would only create a 9.5% reduction in the load factor and theoretical buckling load of the drywell. Although this reduction of 27% is only over a 144 square inch area of the shell, the actual surface area including the transition zone to the 0.736 inch buckling design thickness is a 36 inch by 36 inch or 1,296 square inch area. This area of reduced thickness was located in the portion of the sandbed considered most susceptible to buckling, the midpoint of a bay between two vents.

In addition, a second buckling analysis was performed (Reference 3.5) for a wall thickness reduction of 13.5% or a thickness of 0.636 inches over a one square foot area followed by a transition zone from 0.636 inches to 0.736 inches. Again, although this reduction from 0.736 inches to 0.636 inches is over a 144 square inch area of the shell, while the actual surface area including the transition zone to the buckling design thickness is a 36 inch by 36 inch or a 1,296 square inch area. This second buckling analysis resulted in a 3.9% reduction in the load factor.

To bring these analyses results into perspective with the inspected very local areas, a review of the NDE Reports (Appendix D) indicates there are twenty UT measured areas



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 13 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

all less than 2½" in diameter or less than 4.9 square inches each in area isolated throughout the entire sandbed region that have thicknesses less than 0.736". Compared to the analyses presented in Reference 3.5 the twenty areas would have to have a minimum area of reduced thickness of 144 square inches with a thickness of 0.636 which represents a 13.5% reduction in wall thickness that equates to a 72.0 cubic inch loss of material located in the portion of the drywell sandbed region most susceptible to buckling to produce a 3.9% reduction in the theoretical buckling load and load factor for the drywell. The review of the NDE Reports also indicated that the average wall thickness of the twenty areas is 0.703 inches which represents a 4.5% reduction in wall thickness that equates to a 3.2 cubic inch loss of material and a total maximum area of 98 square inches if the twenty measured areas were contiguous with each other. This indicates that the twenty isolated areas with thicknesses less than the buckling design thickness would not have a significant effect on the buckling of the OC Drywell Shell.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 14 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Turminelli		<b>Date</b>

## 7.0 CALCULATIONS:

### UT EVALUATION BAY #1:

The outside surface of this bay is rough and full of dimples similar to the outside surface of a golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. This inspection focused on the thinnest areas of the drywell, even if it was very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. The shell appears to be relatively uniform in thickness except for a band of corrosion which looks like a "bathtub" ring, located 15 to 20 inches below the vent pipe reinforcement plate, i.e., weld line as shown in Figure 1. (Figure 1 and other like figures presented in this calculation are NOT TO SCALE). The graphical presentation in Figure 1 of measured indications is extracted from Appendix D, Calculation Pages 71 to 76. Based on the inspectors observations the bathtub ring is 12 to 18 inches wide and about 75 inches long located in the center of the bay. Beyond the bathtub ring on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800 inches. Above the bathtub ring the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurements 14 and 15 confirm that the thickness above the bathtub ring is at 1.154 inches starting at elevation 11'-00". Below the bathtub ring the shell is uniform in thickness where no abrupt changes in thicknesses are present. Thickness measurements below the bathtub ring (Locations 6, 7, 8, 9, 16, 17, 18, 19, 22 and 23) are all above 0.750 inches (See Table 1-b) except location 7 which is very local area.

### Bay #1 General Wall (Sandbed Region) Thickness Evaluation

Therefore, taking the average of the UT measured thicknesses of locations 6, 7, 8, 9, 16, 18, 19 and 22 gives a average thickness of 0.816 inches for the shell below the bathtub ring. Based on this a conservative mean thickness of 0.800 inches, is estimated to represent the evaluation thickness for this bay outside the bounds of the bathtub ring. Given a uniform thickness of 0.800 inches for these areas of the bay, it is concluded that these areas are acceptable based on the thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Locations 1, 2, 3, 4, 5, 10, 11, 12, 13, 20, and 21 are confined to the bathtub ring as shown in Figure 1. To determine the general shell thickness in the bathtub ring area of this bay the evaluation thicknesses for each of the locations defined above are averaged together. An example of a typical calculation of the general wall thickness defined as the evaluation thickness is presented below for clarity:

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 15 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

$$(\text{AVG Micrometer})_1 = \frac{D_{1-0^\circ} + D_{1-45^\circ} + D_{1-90^\circ} + D_{1-135^\circ}}{4}$$

Where:  $D_{1-0^\circ}$  = Micrometer Depth Reading for location 1 at 0 degrees taken from Appendix D, Calculation Page 74, etc.

$$(\text{AVG Micrometer})_1 = \frac{0.272'' + 0.204'' + 0.206'' + 0.185''}{4} = 0.217''$$

$$T_{(\text{Evaluation})1} = UT_{(\text{Measurement})1} + (\text{AVG Micrometer})_1 - T_{\text{rough}}$$

Where:  $UT_{(\text{Measurement})1} = 0.720''$  Taken from Appendix D, Calculation Page 71, Location 1

$T_{\text{rough}} = 0.200''$  See Design Input 5.1 and Section 6, Acceptance Criteria, General Wall.

$$T_{(\text{Evaluation})1} = 0.720'' + 0.217'' - 0.200'' = 0.737''$$

## Bay 1 AVG Micrometer Calculations

Table 1-a

Location	Azimuth <sup>(1)</sup>				AVG
	0 <sup>0</sup>	45 <sup>0</sup>	90 <sup>0</sup>	135 <sup>0</sup>	
1	0.272''	0.204''	0.206''	0.185''	0.217''
2	0.143''	0.133''	0.143''	0.154''	0.143''
3	0.397''	0.316''	-----	0.329''	0.347''
5	0.330''	0.290''	0.304''	0.330''	0.313''
7	0.208	0.281''	0.246''	0.330''	0.266''
11	0.200''	0.211''	0.225''	0.211''	0.212''
12	0.299''	0.316''	0.261''	0.328''	0.301''
21	0.222''	0.202''	0.238''	0.183''	0.211''

**NOTES: 1. AZIMUTH DATA TAKEN FROM APPENDIX D, CALCULATION PAGE 74.**

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 16 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

An average value of the evaluation thicknesses presented in Table 1-c for this band is as follows;

<u>Location</u>	<u>Evaluation Thickness</u>
1	0.737"
2	0.659"
3	0.852"
4	0.760"
5	0.823"
10	0.839"
11	0.726"
12	0.825"
13	0.792"
20	0.965"
21	0.737"

Average = 0.792"

An average evaluation thickness of 0.792 inches for the bathtub ring may raise concern given that the bathtub ring is noticeable and that the difference between its average evaluation thickness (0.792 inches) and the average thickness taken for the entire region (0.800 inches) is only 0.008 inches. This results from the fact that average micrometer readings were generally not taken for the remainder of the shell since each reading was greater than 0.736 inches. In reality, the remainder of the shell is much thicker than 0.800 inches. The appropriate evaluation thickness cannot be quantified since no micrometer readings were taken.

Again given that the average evaluation thickness of the shell in the bathtub ring area exceeds the buckling design thickness of 0.736 inches the shell area within the bathtub ring is also acceptable using the results of Reference 3.3.

### Bay #1 Local Wall and Very Local Wall Thickness Evaluation

The individual measured thicknesses must also be evaluated for compliance with the local wall thickness criteria. Table 1-b identifies 23 locations of UT measurements that were selected to represent the thinnest areas, except locations 14 and 15, based on visual examination. These locations are a deliberate attempt to produce a minimum measurement. Locations 14 and 15 were selected to confirm that no corrosion had taken place in the area above the bathtub ring.

Eight locations shown in Table 1-b (1, 2, 3, 5, 7, 11, 12, and 21) have measurements below 0.736 inches. Inspectors observations indicate that these locations were very deep and not more than 1 to 2 inches in diameter. The depth of each of these areas relative to its immediate surroundings was measured at 4 locations around the spot and the average is shown in Table 1-a. Using the general wall thickness acceptance criteria described

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 17 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

earlier, the evaluation thickness for all measurements of very local areas below 0.736 inches were found to be above 0.736 inches except for two locations, 2 and 11, as shown in Table 1-c.

Locations 2 and 11 are in the bathtub ring and are about 4 inches apart. This area is characterized as a local area 4 x 4 inches located at about 15 to 20 inches below the vent pipe reinforcement plate with an average thickness of 0.692 inches.

In order to quantify the effect of this local region and to address structural compliance, the GE study on local effects was used (Ref. 3.5). This study contains an analysis of the drywell shell using the pie slice finite element model. The study reduced the thickness of a 12" by 12" area by 0.100 inches (0.636 inches) and included a transition zone of 12 inches all around from 0.636" to 0.736". When compared to a similar area with a buckling design thickness of 0.736" the total reduced area of 1,296 square inches represents a 13.5% reduction in local shell thickness and a material loss of 72.0 cubic inches. The center of the thinned area was located close to the calculated maximum displacement point in the buckling analysis with uniform thickness of 0.736 inch as per Reference 3.5. For this case the theoretical buckling load factor was reduced by 3.9%.

Based on the buckling design thickness of 0.736 inches the "as found" 4" by 4" area with a thickness of 0.692" represents a 6.3% reduction in local shell thickness and a material loss of 0.7 cubic inches. This volumetric consideration provides a quick visualization, while shell buckling depends on various parameters as discussed in Reference 3.3 and 3.7.

Comparison of the "as found" area of 4" x 4" with the "as analyzed" criteria of 0.636" over a 12" x 12" area, with an additional transition zone of 12", and its associated 13.5% reduction in shell wall thickness and a material loss of 72 cubic inches leads to the conclusion that the effect on the theoretical buckling load factor is negligible. Also based on the location of this 4" x 4" area, is almost directly below the vent and vent header assembly (between 12 to 17 inches to the right of the vent centerline and between 22 and 23 inches down from the vent weld line). This is in the area where buckling of the shell is limited due to the stiffening effect of the vent and vent header assembly. This effect can be clearly seen in the buckling analyses presented in References 3.3 and 3.5.

### Remaining Very Local Areas:

A review of Appendix D, Calculation pages 71, 73 and 75 indicates the remaining very local areas of reduced thickness are isolated from each other and therefore, have a negligible effect on the shell buckling. See Section 6, Very Local Wall Criteria (2 ½ inches in diameter or less) for details. Furthermore, the remaining local areas are centered about the vent which significantly stiffen the shell. This stiffening effect combined with the restraint provided by the concrete support structure limits the shell buckling to a point in the sandbed region which is located at the midpoint between the two vents.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 18 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Conclusion

In summary, using a conservative estimate of 0.800 inches for evaluation thickness for the entire bay (except the bathtub ring) and a 0.792 inch evaluation thickness for the bathtub ring, plus the acceptance of the local 4" by 4" area with an evaluation thickness of 0.692" based on the GE study, it is concluded that the bay is acceptable.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 19 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

**Bay # 1 UT Data**  
**Table 1-b**

<b>Location</b>	<b>D-Meter UT Measurement (inches)</b>	<b>Appendix D on Calculation Page</b>	<b>Average Micrometer (See Table 1-a) (inches)</b>
1	0.720	71	0.217
2	0.716	71	0.143
3	0.705	71	0.347
4	0.760	71	---
5	0.710	71	0.313
6	0.760	71	---
7	0.700	71	0.266
8	0.805	71	---
9	0.805	71	---
10	0.839	73	---
11	0.714	73	0.212
12	0.724	73	0.301
13	0.792	73	---
14	1.147	73	---
15	1.156	73	---
16	0.796	75	---
17	0.860	75	---
18	0.917	75	---
19	0.890	75	---
20	0.965	75	---
21	0.726	75	0.211
22	0.852	75	---
23	0.850	75	---

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 20 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Summary Of Measurements Below 0.736"

Table 1-c

<b>Location</b>	<b>UT Measurement (1)</b>	<b>AVG Micrometer (2)</b>	<b>Mean Depth/Valley (3)</b>	<b>T (Evaluation) (4)=(1)+(2)-(3)</b>	<b>Remarks</b>
1	0.720"	0.217"	0.200"	0.737"	Acceptable
2	0.716"	0.143"	0.200"	0.659"	Acceptable
3	0.705"	0.347"	0.200"	0.852"	Acceptable
5	0.710"	0.313"	0.200"	0.823"	Acceptable
7	0.700"	0.266"	0.200"	0.766"	Acceptable
11	0.714"	0.212"	0.200"	0.726"	Acceptable
12	0.724"	0.301"	0.200"	0.825"	Acceptable
21	0.726"	0.211"	0.200"	0.737"	Acceptable



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 21 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## BAY #1 DATA

### NOTES:

1. All "Location" measurements from intersection of the DW shell and vent collar fillet welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" band surrounding ground spots. Only measured where remaining wall thk. was below 0.736".




FIGURE (1)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 22 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Turminelli		<b>Date</b>

## UT EVALUATION BAY #3:

The outside surface of this bay is rough; similar to bay one, full of dimples comparable to the outside surface of golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness except for a bathtub ring 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact. Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 3). These locations are a deliberate attempt to produce a minimum measurement. Table 3 shows measurements taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

## Bay #3 General Wall (SandBed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 3 equal to 0.868 inches, a conservative mean evaluation thickness of 0.850 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using results of Reference 3.3.

Bay # 3 UT Data  
Table 3

<b>Location</b>	<b>D-Meter UT Measurement (inches)</b>	<b>Appendix D on Calculation Page</b>	<b>Average Micrometer (inches)</b>
1	0.795	77	---
2	1.000	77	---
3	0.857	77	---
4	0.898	77	---
5	0.823	77	---
6	0.968	77	---
7	0.826	77	---
8	0.780	77	---

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 23 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




FIGURE (3)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 24 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #5:

The outside surface of this bay is rough and very similar to bay 3 except that the local areas are clustered at the junction of bays 3 and 5, at about 30 inches above the floor. The shell surface is full of dimples comparable to the outside surface of a golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (see Fig. 5). These locations are a deliberate attempt to produce a minimum measurement. Table 5 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

## Bay #5 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 5 equal to 0.986 inches, a conservative mean evaluation thickness of 0.950 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Bay # 5 UT Data  
Table 5

Location	D-Meter UT Measurement (inches)	Appendix D on Calculation Page	Average Micrometer (inches)
1	0.970	80	---
2	1.040	80	---
3	1.020	80	---
4	0.910	80	---
5	0.890	80	---
6	1.060	80	---
7	0.990	80	---
8	1.010	80	---

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 25 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## BAY #5 DATA

### NOTES:

1. In this bay DW shell (butt) weld is about 6" to the right of C/L of vent tube. Therefore - all measurements were taken from a line drawn on shell which approx. coincide with vent tube C/L.




FIGURE (5)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 26 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #7:

The observation of the drywell surface for this bay showed uniform dimples in the corroded area, but they are shallow compared to those in bay 1. The bathtub ring seen in the other bays was not very prominent in this bay. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Seven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 7). These locations are a deliberate attempt to produce a minimum measurement. Table 7 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

## Bay #7 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 7 equal to 1.001, a mean evaluation thickness of 1.00 inch is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Bay # 7 UT Data  
Table 7

Location	D-Meter UT Measurement (inches)	Appendix D on Calculation Page	Average Micrometer (inches)
1	0.920	84	---
2	1.016	84	---
3	0.954	84	---
4	1.040	84	---
5	1.030	84	---
6	1.045	84	---
7	1.000	84	---

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 27 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## BAY #7 DATA

### NOTES:

1. All measurements from the intersection of DW shell (butt) and vent collar (fillet) welds.




FIGURE (7)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 28 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #9:

The observation of the drywell shell for this bay was very similar to bay 7 except that the bathtub ring was more evident in this bay. The shell appears to be relatively uniform in thickness except for a bathtub ring 6 to 9 inches wide approximately 6 to 8 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact. Ten locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 9). These locations are a deliberate attempt to produce a minimum measurement. Table 9 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

## Bay #9 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 9 equal to 0.915, a conservative mean evaluation thickness of 0.900 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Bay # 9 UT Data  
Table 9

<b>Location</b>	<b>D-Meter UT Measurement (inches)</b>	<b>Appendix D on Calculation Page</b>	<b>Average Micrometer (inches)</b>
1	0.960	85	---
2	0.940	85	---
3	0.994	85	---
4	1.020	85	---
5	0.985	85	---
6	0.820	85	---
7	0.825	85	---
8	0.791	85	---
9	0.832	85	---
10	0.980	85	---



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 29 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## BAY #9 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE (9)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 30 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #11:

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of a golf ball. The shell appears to be relatively uniform in thickness except for local areas at the upper right corner of Figure 11, located at about 10 to 12 inches below the vent pipe reinforcement plate.

Eight locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 11). These locations are a deliberate attempt to produce a minimum measurement. Table 11-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 1 as shown in Table 11-a, has a reading below 0.736 inches. Inspectors observations indicate that this location was very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surrounds was measured at 4 locations around the spot and the average is shown in Table 11-a. As described in Section 6, Methods of Analysis, Very Local Wall Acceptance Criteria, areas of reduced thickness equal to or less than 2 ½ inches are too small to reduce the shell critical buckling load. This combined with the location of the very local indication near the vent reinforcement (See Appendix D, Calculation Page 87) indicates that this area would have a negligible effect on the shell buckling response.

### Bay #11 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 11-a equal to 0.792 inches, a conservative mean evaluation thickness of 0.790 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

The calculation of the average depth for Bay 11, Location 1 is as follows:

$$(\text{AVG Micrometer})_1 = \frac{D_{1-0^\circ} + D_{1-45^\circ} + D_{1-90^\circ} + D_{1-135^\circ}}{4}$$

Where:  $D_{1-0^\circ}$  = Micrometer Depth Reading for location 1 at 0 degrees taken from Appendix D, Calculation Page 91, etc.

$$(\text{AVG Micrometer})_1 = \frac{0.289'' + 0.338'' + 0.157'' + 0.200''}{4} = 0.246''$$

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 31 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

**Bay # 11 UT Data**  
**Table 11-a**

<b>Location</b>	<b>UT Measurement (inches)</b>	<b>Appendix D Presented on Calculation Page</b>	<b>Average Micrometer (inches)</b>
1	0.705	87	0.246
2	0.770	87	---
3	0.832	87	---
4	0.755	87	---
5	0.831	87	---
6	0.800	87	---
7	0.831	87	---
8	0.815	87	---

**Summary of Measurements Below 0.736 Inches**  
**Table 11-b**

<b>Location</b>	<b>UT Measurement (1)</b>	<b>AVG Micrometer (2)</b>	<b>Mean Depth/Valley (3)</b>	<b>T (Evaluation) (4)=(1)+(2)-(3)</b>	<b>Remarks</b>
1	0.705"	0.246"	0.200"	0.751"	Acceptable

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 32 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## BAY #11 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0°/45°/90°/135° within 1" band surrounding the ground spots. This measurement was only taken when wall thickness was below 0.736".




FIGURE (11)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 33 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #13:

The outside surface of this bay is rough and full of dimples similar to bay 1 as shown in Appendix C. This observation is made by the inspector who located the thinnest areas in deep valleys thereby biasing the remaining wall measurements to the conservative side. This inspection focused on the thinnest areas, even if very local, i.e., the inspection did not attempt to define a shell thickness suitable for structural evaluation. The variation in shell thickness is greater in this bay than in the other bays. The bathtub ring below the vent pipe reinforcement plate was less prominent than was seen in other bays. The corroded areas are about 12 to 18 inches in diameter and are at 12 inches apart, located in the middle of the sandbed. Beyond the corroded areas on both sides, the shell appears to be uniform in thickness at a conservative value of 0.800". Near the vent pipe and reinforcement plate the shell exhibits no corrosion since the original lead primer on the vent pipe/reinforcement plate is intact. Measurement 20 confirms that the thickness above the bathtub ring is at 1.154 inches. Below the bathtub ring the shell appears to be fairly uniform in thickness where no abrupt changes in thickness are present. Thickness measurements below the bathtub ring (Locations 3, 4, 9, 12, 13, 16, 17, 18, and 19) are all 0.800 inches or better (See Table 13-b).

## Bay #13 General Wall (Sandbed Region) Thickness Evaluation

Therefore, given an average of the UT measurements of the locations below the bathtub ring is equal to 0.884 inches, a conservative mean thickness of 0.800 inches is estimated to represent the evaluation thickness for areas of shell in this bay outside the bathtub ring. Given a uniform thickness of 0.800 inches for these areas of the bay it is concluded that these areas are acceptable based on the thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Locations 5, 6, 7, 8, 10, 11, 14, and 15 are confined to the bathtub ring as shown in Figure 13. To determine the general shell thickness in the bathtub ring area of this bay the evaluation thicknesses (See Table 13-c) for each of the locations defined above are averaged together. An example of a typical calculation of the general wall thickness defined as the evaluation thickness is presented below for clarity:

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 34 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

$$(\text{AVG Micrometer})_5 = \frac{D_{5-0^\circ} + D_{5-45^\circ} + D_{5-90^\circ} + D_{5-135^\circ}}{4}$$

Where:  $D_{5-0^\circ}$  = Micrometer Depth Reading for Bay 13, location 5 at 0 degrees taken from Appendix D, Calculation Page 98, etc.

$$(\text{AVG Micrometer})_5 = \frac{0.150'' + 0.193'' + 0.230'' + 0.298''}{4} = 0.217''$$

$$T_{(\text{Evaluation})5} = UT_{(\text{Measurement})5} + (\text{AVG Micrometer})_5 - T_{\text{rough}}$$

Where:  $UT_{(\text{Measurement})5} = 0.718''$  Taken from Appendix D, Calc Page 93, Location 5

$T_{\text{rough}} = 0.200''$  See Design Input 5.1 and Section 6, Acceptance Criteria, General Wall.

$$T_{(\text{Evaluation})5} = 0.718'' + 0.217'' - 0.200'' = 0.735''$$

## Bay 13 AVG Micrometer Calculations

Table 13-a

Location	Azimuth <sup>(1)</sup>				AVG
	0 <sup>0</sup>	45 <sup>0</sup>	90 <sup>0</sup>	135 <sup>0</sup>	
1	0.330''	0.382''	0.346''	0.346''	0.351''
2	0.312''	0.377''	0.360''	0.393''	0.360''
5	0.150''	0.193''	0.230''	0.298''	0.217''
6	0.327''	0.339''	0.290''	0.247''	0.301''
7	0.241''	0.279''	0.260''	0.239''	0.255''
8	0.324''	0.245''	0.262''	0.279''	0.278''
10	0.186''	0.173''	0.255''	0.229''	0.211''
11	0.240''	0.231''	0.271''	0.283''	0.256''
15	0.288''	0.277''	0.239''	0.288''	0.273''

Notes: 1. Azimuth data taken from Appendix D, Calculation Page 98.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 35 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tunminelli		<b>Date</b>

An average value of the evaluation thicknesses presented in Table 13-c for this band is as follows;

<u>Location</u>	<u>Evaluation Thickness</u>
5	0.735"
6	0.756"
7	0.675"
8	0.796"
10	0.739"
11	0.741"
12	0.885"
14	0.868"
15	0.756"
16	0.829"

Average = 0.778"

The inspector suspected that some of the above locations in the bathtub ring were over ground. Subsequent locations with suffix A, e.g. 5A, 6A, were located close to the spots in question and were ground carefully to remove the minimum amount of metal but adequate enough for UT examination as shown in Table 13-b. The results indicate that all subsequent measurements were above 0.736 inches. The average micrometer measurements taken for these locations confirm the depth measurements at these locations. In spite of the fact that the original measurements were taken at heavily ground locations they are the ones used in the evaluation.

Again given that the average evaluation thickness of the shell in the bathtub ring area exceeds the buckling design thickness of 0.736 inches the shell area within the bathtub ring is also acceptable based on the results of Reference 3.3.

### Bay #13 Local Wall Thickness Evaluation

The individual measurements must also be evaluated for compliance with the local wall thickness criteria. Table 13-b identifies 20 locations of UT measurements that were selected to represent the thinnest areas, except location 20, based on visual examination. These locations are a deliberate attempt to produce a minimum measurement. Location 20 was selected to confirm that no corrosion had taken place in the area above the bathtub ring.

Nine locations shown in Table 13-b (1, 2, 5, 6, 7, 8, 10, 11, and 15) have measurements below 0.736 inches. Inspectors observations indicate that these locations were very deep, overly ground, and not more than 1 to 2 inches in diameters. The depth of each of these areas relative to its immediate surroundings was measured at 4 locations around the spot and the average is shown in Table 13-a. Using the general wall thickness acceptance criteria described earlier, the evaluation thickness for all measurements below 0.736 inches were found to be above 0.736 inches except for two locations, 5 and 7, as shown in Table 13-b. In addition, subsequent measurements close to the locations identified above, were taken and they were all above 0.736 inches.

## GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 36 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

Locations 5 and 7 are in the bathtub ring and are about 30 inches apart. These locations are characterized as local areas located at about 15 to 20 inches below the vent pipe reinforcement plate with an evaluation thicknesses of 0.735 inches and 0.673 inches. The location 5 is near to location 14 for an average value of 0.801 inches and therefore acceptable. Location 7 could conservatively exist over an area of 6 x 6 inches for a thickness of 0.673 inches.

In order to quantify the effect of this local region and to address structural compliance, the GE study on local effects is used (Ref. 3.5). This study contains an analysis of the drywell shell using the pie slice finite element model. The study reduced the thickness of a 12" by 12" area by 0.100 inches (0.636 inches) and included a transition zone of 12 inches all around from 0.636" to 0.736". When compared to a similar area with a buckling design thickness of 0.736" the modeled area represents a 13.5% reduction in local shell thickness and a material loss of 72.0 cubic inches. The center of the thinned area was located close to the calculated maximum displacement point in the buckling analysis with uniform thickness of 0.736 inch as per Reference 3.5. For this case the theoretical buckling load factor was reduced by 3.9%.

Based on the buckling design thickness of 0.736 inches the "as found" 6" by 6" area with a thickness of 0.673" represents a 8.6% reduction in local shell thickness and a material loss of 2.3 cubic inches. The volumetric consideration provides a quick visualization. While shell buckling depends on various parameters as discussed in References 3.3 and 3.7.

Comparison of the "as found" area of 6" x 6" with the "as analyzed" criteria of 0.636" over a 12" x 12" area, with an additional transition zone of 12", and its associated 13.5% reduction in shell wall thickness and a material loss of 72 cubic inches leads to the conclusion that the effect on the theoretical buckling load factor is negligible. Also based on the location of this 6" x 6" area, is almost directly below the vent and vent header assembly (between 20 to 26 inches to the left of the vent centerline and between 14 to 20 inches down from the vent weld line). This is in the area where buckling of the shell is limited due to the stiffening effect of the vent and vent header assembly. This effect can be clearly seen in the buckling analyses presented in References 3.3 and 3.5.

### Remaining Very Local Areas:

A review of Appendix D, calculation pages 93, 94, 95 and 96 indicates the remaining very local areas of reduced thickness are isolated from each other and therefore, have a negligible effect on the shell buckling. See Section 6, Very Local Wall Criteria (2&½ inches in diameter or less) for details. Furthermore, the remaining local areas are centered about the vent which significantly stiffen the shell. This stiffening effect combined with the restraint provided by the concrete support structure limits the shell buckling to a point in the sandbed region which is located at the midpoint between the two vents.



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 37 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Conclusion

In summary, using a conservative estimate of 0.800 inches for evaluation thickness for the entire bay (except the bathtub ring) and a 0.778 inch evaluation thickness for the bathtub ring , plus the acceptance of the local 6" by 6" area with an evaluation thickness of 0.673" based on the GE study; it is concluded that the bay is acceptable.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 38 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Bay # 13 UT Data

**Table 13-b**

Location	D-Meter UT Measurement (inches)	Appendix D presented on Calculation Page	Average Micrometer <sup>(1)</sup> (Table 13-a) (inches)
1/1A	0.672/0.890	93/95	0.351
2/2A	0.722/0.943	93/95	0.360
3	0.941	93	---
4	0.915	93	---
5/5A	0.718/0.851	93/95	0.217
6/6A	0.655/0.976	93/95	0.301
7/7A	0.618/0.752	93/95	0.255
8/8A	0.718/0.900	93/95	0.278
9	0.924	93	---
10/10A	0.728/0.810	93/95	0.211
11/11A	0.685/0.854	93/95	0.256
12	0.885	93	---
13	0.932	93	---
14	0.868	93	---
15/15A	0.683/0.859	93/95	0.273
16	0.829	93	---
17	0.807	93	---
18	0.825	93	---
19	0.912	93	---
20	1.170	93	---

(1) (1) Average values provided in this column are for locations 1, 2, 5, etc.

(1) (without suffix A) and not for 1A, 2A, 5A, etc. The values are compiled in Table 13-a

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 39 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

**Summary of Measurements Below 0.736 Inches**  
**Table 13-c**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4)=(1)+(2)-(3)	Remarks
1	0.672"	0.351"	0.200"	0.823"	Acceptable
2	0.722"	0.360"	0.200"	0.882"	Acceptable
5	0.718"	0.217"	0.200"	0.735"	Acceptable
6	0.655"	0.301"	0.200"	0.756"	Acceptable
7	0.618"	0.255"	0.200"	0.673"	Acceptable
8	0.718"	0.278"	0.200"	0.796"	Acceptable
10	0.728"	0.211"	0.200"	0.739"	Acceptable
11	0.685"	0.256"	0.200"	0.741"	Acceptable
15	0.683"	0.273"	0.200"	0.756"	Acceptable

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 40 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## BAY #13 DATA

### NOTES:

1. All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.
2. Spots with suffix (e.g. 1A or 2A) were located close to the spots in question and were ground carefully to remove minimum amount of metal but adequate enough for UT.
3. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spot. Taken only where remaining wall showed below 0.736".




Figure (13)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 41 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #15:

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball (Appendix C). The bathtub ring seen in the other bays, was not very prominent in this bay. This observation is made by the inspector who located the thinnest areas for the UT examination. The upper portion of the shell beyond the ring exhibits no corrosion where the original red lead primer is still intact. The shell appears to be relatively uniform in thickness.

Eleven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 15). These locations are a deliberate attempt to produce a minimum measurement. Table 15-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 9 as shown in Table 15-a, has a reading below 0.736 inches. Inspectors observations indicate that this location was very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surrounding was measured at 4 locations around the spot and the average is shown in Table 15-a. As described in Section 6, Methods of Analysis, Very Local Wall Acceptance Criteria, areas of reduced thickness equal to or less than 2 1/2 inches are too small to reduce the shell critical buckling load. This combined with the location of the very local indication near the vent reinforcement (See Appendix D, Calculation Page 99) indicates that this area would have a negligible effect on the shell buckling response.

## Bay #15 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 15-a is equal to 0.816 inches, a conservative mean evaluation thickness of 0.800 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

The calculation of the average depth for Bay 15, Location 9 is as follows:

$$(\text{AVG Micrometer})_9 = \frac{D_{9-0^\circ} + D_{9-45^\circ} + D_{9-90^\circ} + D_{9-135^\circ}}{4}$$

Where:  $D_{9-0^\circ}$  = Micrometer Depth Reading for location 9 at 0 degrees  
taken from Appendix D, Calculation Page 100, etc.

$$(\text{AVG Micrometer})_9 = \frac{0.356'' + 0.350'' + 0.359'' + 0.282''}{4} = 0.337''$$

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 42 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Bay # 15 UT Data

Table 15-a

Location	D-Meter UT Measurement (inches)	Appendix D on Calculation Page	Average Micrometer (inches)
1	0.786	99	---
2	0.829	99	---
3	0.932	99	---
4	0.795	99	---
5	0.850	99	---
6	0.794	99	---
7	0.808	99	---
8	0.770	99	---
9	0.722	99	0.337
10	0.860	99	---
11	0.825	99	---

## Summary of Measurements Below 0.736 Inches

Table 15-b

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4)=(1)+(2)-(3)	Remarks
9	0.722"	0.337"	0.200"	0.859"	Acceptable

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed	<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 43 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli	<b>Date</b>

## BAY #15 DATA

### NOTES:

1. All measurements from intersection of the DW shell and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spots. Taken only when remaining wall thickness shown below 0.736".




FIGURE (15)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 44 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #17:

The outside surface of this bay is rough, similar to bay 1, full of uniform dimples comparable to the outside surface of golf ball. The shell appears to be relatively uniform in thickness except for a band 8 to 10 inches wide approximately 6 inches below the vent header reinforcement plate. The upper portion of the shell beyond the band exhibits no corrosion where the original red lead primer is still intact.

Eleven locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 17). These locations are a deliberate attempt to produce a minimum measurement. Table 17-a shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches, except one location. Location 9 as shown in Table 17-a, has a reading below 0.736 inches. Inspectors observations indicate that this location is very deep and not more than 1 to 2 inches in diameter. The depth of area relative to its immediate surroundings was measured at 4 locations around the spot and the average is shown in Table 17-a. As described in Section 6, Methods of Analysis, Very Local Wall Acceptance Criteria, areas of reduced thickness equal to or less than 2 & 1/2 inches are too small to reduce the shell critical buckling load. This combined with the location of the very local indication near the vent reinforcement (See Appendix D, Calculation Page 103) indicates that this area would have a negligible effect on the shell buckling response.

### Bay #17 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 17-a is equal to 0.918 inches, a conservative mean evaluation thickness of 0.900 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

The calculation of the average depth for Bay 17, Location 9 is as follows:

$$(\text{AVG Micrometer})_9 = \frac{D_{9-0^\circ} + D_{9-45^\circ} + D_{9-90^\circ} + D_{9-135^\circ}}{4}$$

Where:  $D_{9-0^\circ}$  = Micrometer Depth Reading for location 9 at 0 degrees taken from Appendix D, Calculation Page 105, etc.

$$(\text{AVG Micrometer})_1 = \frac{0.368" + 0.407" + 0.289" + 0.342"}{4} = 0.351"$$



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 45 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

**Bay # 17 UT Data**  
**Table 17-a**

Location	D-Meter UT Measurement (inches)	Appendix D on Calculation Page	Average Micrometer (inches)
1	0.916	104	---
2	1.150	104	---
3	0.898	104	---
4	0.951	104	---
5	0.913	104	---
6	0.992	104	---
7	0.970	104	---
8	0.990	104	---
9	0.720	103	0.351
10	0.830	103	---
11	0.770	103	---

**Summary of Measurements Below 0.736 Inches**

**Table 17-b**

Location	UT Measurement (1)	AVG Micrometer (2)	Mean Depth/Valley (3)	T (Evaluation) (4)=(1)+(2)-(3)	Remarks
9	0.720"	0.351"	0.200"	0.871"	Acceptable

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 46 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## BAY #17 DATA

### NOTES:

1. All measurements from intersection of the DW (butt) shell and vent collar (fillet) welds.
2. Pit depths are average of four readings taken at 0/45°/90°/135° within 1" distance around ground spots. Taken only when remaining wall thickness was below 0.738".




FIGURE (17)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 47 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## UT EVALUATION BAY #19:

The outside surface of this bay is rough and very similar to bay 17. Locations 1 through 7 as shown in Table 19, were ground carefully to minimize loss of good metal. The shell surface is full of dimples comparable to the outside surface of a golf ball. This observation is made by the inspector who located the thinnest areas for the UT examination. The shell appears to be relatively uniform in thickness. Ten locations were selected to represent the thinnest areas based on the visual observations of the shell surface (Fig. 19). These locations are a deliberate attempt to produce a minimum measurement. Table 19 shows readings taken to measure the thicknesses of the drywell shell using a D-meter. The results indicate that all of the areas have thickness greater than the 0.736 inches.

## Bay #19 General Wall (Sandbed Region) Thickness Evaluation

Given an average of the UT measurements presented in Table 19 is equal to 0.885 inches, a conservative mean evaluation thickness of 0.850 inches is estimated for this bay. Therefore, it is concluded that the bay is acceptable based on the bay evaluation thickness exceeding the buckling design thickness for the sandbed region of 0.736 inches using the results of Reference 3.3.

Bay # 19 UT Data  
Table 19

<b>Location</b>	<b>D-Meter UT Measurement (inches)</b>	<b>Appendix D on Calculation Page</b>	<b>Average Micrometer (inches)</b>
1	0.932	109	---
2	0.924	109	---
3	0.955	109	---
4	0.940	109	---
5	0.950	109	---
6	0.860	109	---
7	0.969	109	---
8	0.753	108	---
9	0.776	108	---
10	0.790	108	---

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 48 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## BAY #19 DATA

### NOTES:

- All measurements from intersection of the DW shell (butt) and vent collar (fillet) welds.




FIGURE (19)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 49 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

Appendix A: Summary Of Measurements Of Impressions Taken From Bay #13 (3 pages total)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> .50 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

The purpose of this appendix is to characterize the depth of typical uniform dimples on the shell surface. This depth is used in acceptance criteria to quantify the evaluation thickness for an area where the micrometer readings are available.

Two locations in bay 13 were selected since bay 13 is the roughest bay. Impressions of drywell shell surface using DMR\_503 Epoxy Replication Putty manufactured by Dyna Mold Inc were made. These impressions were about 10 inches in diameter and about 1 inch thick. The UT locations 7 and 10 in bay 13 were identified in each of these impression as the reference points. This is a positive impression of the drywell shell surface. The depth of the typical dimples were measured as follows;

<u>READING</u> (Location)	(inches)	<u>DEPTH #10</u>	<u>DEPTH #7</u> (inches)
1	0.150	0.075	
2	0.000	0.110	
3	0.200	0.135	
4	0.140	0.200	
5	0.150	0.000	
6	0.040	0.000	
7	0.150	0.170	
8	0.010	0.205	
9	0.134	—	
10	0.145	0.145	
11	0.118	0.064	
12	0.105	0.200	
13	0.125	0.045	
14	0.200	0.180	
15	0.135	0.105	
16	0.100	—	
17	0.175	0.035	
18	0.175	0.015	
19	0.155	0.190	
20	0.175	0.055	
21	0.175	0.305	
22	—	0.135	

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 51 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

## Location #10:

Mean Value	=	0.131
Standard Deviation	=	0.055
Mean Value + One S.D.	=	0.186

## Location #7:

Mean Value	=	0.118
Standard Deviation	=	0.082
Mean Value + One S.D.	=	0.200

Therefore, a value of 0.200 inches was used as the depth of uniform dimples for the entire outside surface of the drywell in the sandbed region.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 52 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

Appendix B: Buckling Capacity Evaluation For Varying Uniform Thickness Through The Whole Sandbed Region Of The Drywell (5 pages total)

Based Upon GE Buckling Analysis (Reference 3.3)

**Note: Tables on sheets 53 to 56 are not used in this calculation and are provided for historical purpose only from Rev. 0.**



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 53 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GE OYCR1S&T - UNIFORM THICKNESS  $t=0.736$  Inch

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.736	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_e$	(ksi)	46.590	6.140
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	7.588	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.510	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.806	
11	'X' Parameter, $X = (P_{eq}/8E) (d/t)^2$		0.087	
12	Delta C (From Figure -)		0.072	
13	Modified Capacity Reduction Factor, ALPHA, 1, mod		0.326	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.182	2.001
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, $\Delta = S_e/S_y$		0.400	
16	Plasticity Reduction Factor, $N_{Uj}$		1.000	
17	Inelastic Instability Stress, $S_i = N_{Uj} \times S_e$	(ksi)	15.182	2.001
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.591	1.000
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$	(%)	0.0	

OCLR00014590

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 54 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli		Date

CALCULATION OF BUCKLING MARGIN.- REFUELING CASE, NO SAND -  
GE OYCRFST01 - UNIFORM THICKNESS  $t = 0.776$  Inch

<u>ITEM</u>	<u>PARAMETER</u>	<u>UNITS</u>	<u>VALUE</u>	<u>LOAD FACTOR</u>
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.776	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	49.357	6.857
<b>***STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	7.198	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	4.248	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	'X' Parameter, $X = (P_{eq}/8E) (d/t)^2$		0.078	
12	Delta C (From Figure - )		0.066	
13	Modified Capacity Reduction Factor, ALPHA,1, mod		0.316	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	15.583	2.165
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, $DELTA = S_e/S_y$		0.410	
16	Plasticity Reduction Factor, $NU_i$		1.000	
17	Inelastic Instability Stress, $S_i = NU_i \times S_e$	(ksi)	15.183	2.165
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	7.592	1.082
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$	(%)	8.2	

OCLR00014591

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 55 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
GPUN EVALUATION FOR UNIFORM THICKNESS  $t=0.800$  Inch USING THICKNESS RATIO

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.800	
3	Material Yield Strength, Sy	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, Ste	(ksi)	50.884	7.288
<b>***STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, Sm	(ksi)	6.982	5.588
8	Applied Circumferential Tensile Stress, Sc	(ksi)	4.120	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, Peq	(psi)	15.697	
11	'X' Parameter, $X = (Peq/8E) (d/t)^2$		0.073	
12	Delta C (From Figure -)		0.063	
13	Modified Capacity Reduction Factor, ALPHA,1, mod		0.311	
14	Reduced Elastic Instability Stress, Se	(ksi)	15.824	2.266
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, DELTA=Se/Sy		0.416	
16	Plasticity Reduction Factor, NU1		1.000	
17	Inelastic Instability Stress, Si = NU1 x Se	(ksi)	15.824	2.266
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, Sall = Si/FS	(ksi)	7.912	1.133
19	Compressive Stress Margin, $M = (Sall/Sm - 1) \times 100\%$	(%)	13.3	

OCLR00014592

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 56 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

CALCULATION OF BUCKLING MARGIN - REFUELING CASE, NO SAND -  
 GPUN EVALUATION FOR UNIFORM THICKNESS  $t = 0.850$  Inch USING THICKNESS RATIO

ITEM	PARAMETER	UNITS	VALUE	LOAD FACTOR
<b>*** DRYWELL GEOMETRY AND MATERIALS</b>				
1	Sphere Radius, R	(in.)	420	
2	Sphere Thickness, t	(in.)	0.850	
3	Material Yield Strength, $S_y$	(ksi)	38	
4	Material Modulus of Elasticity, E	(ksi)	29600	
5	Factor of Safety, FS		2	
<b>*** BUCKLING ANALYSIS RESULTS</b>				
6	Theoretical Elastic Instability Stress, $S_{te}$	(ksi)	54.063	8.227
<b>*** STRESS ANALYSIS RESULTS</b>				
7	Applied Meridional Compressive Stress, $S_m$	(ksi)	6.571	5.588
8	Applied Circumferential Tensile Stress, $S_c$	(ksi)	3.878	3.300
<b>*** CAPACITY REDUCTION FACTOR CALCULATION</b>				
9	Capacity Reduction Factor, ALPHA1		0.207	
10	Circumferential Stress Equivalent Pressure, $P_{eq}$	(psi)	15.697	
11	'X' Parameter, $X = (P_{eq}/8E) (d/t)^2$		0.065	
12	Delta C (From Figure - )		0.057	
13	Modified Capacity Reduction Factor, ALPHA,1, mod		0.300	
14	Reduced Elastic Instability Stress, $S_e$	(ksi)	16.257	2.474
<b>*** PLASTICITY REDUCTION FACTOR CALCULATION</b>				
15	Yield Stress Ratio, $DELTA = S_e/S_y$		0.428	
16	Plasticity Reduction Factor, $NU_i$		1.000	
17	Inelastic Instability Stress, $S_i = NU_i \times S_e$	(ksi)	16.257	2.474
<b>*** ALLOWABLE COMPRESSIVE STRESS CALCULATION</b>				
18	Allowable Compressive Stress, $S_{all} = S_i/FS$	(ksi)	8.128	1.237
19	Compressive Stress Margin, $M = (S_{all}/S_m - 1) \times 100\%$	(%)	23.7	

OCLR00014593

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 57 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

Appendix C: Pictures Showing Condition Of The Drywell In The Sandbed Region (9 pages total)

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 58 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>



Sand Bed Region - Typical condition found on initial entry.




Corrosion product on drywell vessel

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 59 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




Bay #13 - D/W shell showing plug . The plug is located in the middle of the worst corroded area of the shell. The plug showed no sign of corrosion.



Bay #13 - D/W shell showed less prominent "Tub Ring" than what was seen in other

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 60 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Turminelli		<b>Date</b>



Bay #1 - Looking at the worst corroded area on shell near vent tube collar/ring. The ground spots seen here correspond to UT spot 20.2: 2.3



Bay #13 - Lower Mid portion of the DAW shell showing UT spot 5.6 and 10. This close up photo shows the roughness of the corroded surface and how each UT spot has been picked up in the deep valleys thereby biasing the remaining wall readings to the conservative side



# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 61 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




Bay #13 - Looking towards Bay#11 - Upper right corner of DWV shell. Note (1) - Grinding depth on U1 spot #1 & 2, (2) - A part of "Calli Tub Ring" as delineated by marking and (3) locations of UT spots 3,4,13 & 17. The photo on right (although blurred by finish reflection) shows 1/8" projection of plug.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 62 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date




Bay #15 Looking towards Bay#17 which has been closed with foam for coating work in Bay #17. Note the typical surface of the D-W shell and localized corroded spot




Bay #13 - Looking toward Bay #15 - Lower left corner showing UT spot #7, 12 & 16. This close up has captured the peaks and valleys of the corroded shell in vivid detail. Later NDE inspection revealed a width between peaks and valleys in the 0.25" - 0.40"

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 63 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




Bay #15 Looking toward Bay #13 showing portions of DW shell and concrete floor, after removal of loose debris / sand / rust. The concrete floor in this bay is one of the better ones. However - Note (1) no drainage channel and (2) cratered holes near shell corner




Bay #15 - Note the original lead primer on vent tube OD surface. The "Tub Ring" was less prominent on the shell in this bay except a portion in lower left corner. Also note presence of lead primer on vent collar/ing plate.

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 64 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>




Bay #13 Looking toward Bay #11 - Lower right corner of D/W shell showing UT spots 9, 10, 18 & 19. Note the location of these spots - all are located in the valleys of the corroded surface. This photo also shows the condition of the concrete floor. It appears



Bay #13 - Looking toward Bay #15 - This photo captures the concrete floor condition and a portion of lower shell corroded surface in very great detail. The floor in this area

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 65 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>



Finished floor, vessel with two top coats - caulking material applied.



Drain after floor has been refurbished

# GPU Nuclear

<b>Subject</b> O.C. Drywell Ext. UT Evaluation in Sandbed		<b>Calc No.</b> C-1302-187-5320-024	<b>Rev. No.</b> 1	<b>Sheet No.</b> 66 of 117
<b>Originator</b> Mark Yekta	<b>Date</b> 01/12/93	<b>Reviewed by</b> S. C. Tumminelli		<b>Date</b>

Appendix D: NDE Inspection Sheets for the Drywell Sandbed Region (52 pages total)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 67 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date



## NDE Request Oyster Creek

QC Charge No. 3514-57307

Request No. 92-C75

1 To be filled in by Requestor																																																											
Job Order No.	Short Form No.	BA No. <u>322245</u>	Date of Request																																																								
Job Description <u>UT THICKNESS OF UML WELDS</u>																																																											
Job Location <u>SANDBED AREA</u>			System: <u>IND. P.I.C.</u>																																																								
Type of NDE requested:																																																											
<input type="checkbox"/> Visual	<input type="checkbox"/> Liquid Penetrant	<input type="checkbox"/> Eddy Current	<input checked="" type="checkbox"/> Ultrasonic																																																								
<input type="checkbox"/> Leakage	<input type="checkbox"/> Magnetic Particle	<input type="checkbox"/> Alloy Separator	<input type="checkbox"/> Acoustic Emissions																																																								
<input type="checkbox"/> Video	<input type="checkbox"/> Radiographic	<input type="checkbox"/> Ferrite																																																									
NDE Requested by: <u>J. SLITER FOR</u>		Phone No.:	Date <u>12-1-92</u>																																																								
Remarks <u>JOHN FLYNN</u>																																																											
2 To be filled in by NDE Coordinator																																																											
NDE Coordinator <u>J. SLITER</u>				Date																																																							
Instructions																																																											
<table border="0"> <thead> <tr> <th>UT</th> <th>PT</th> <th>MT</th> <th>RT</th> <th>VT</th> <th>ET</th> </tr> </thead> <tbody> <tr> <td><input checked="" type="checkbox"/> 0°</td> <td>Type</td> <td>Dry</td> <td>Isotope</td> <td><input type="checkbox"/> Direct</td> <td><input type="checkbox"/> Probe</td> </tr> <tr> <td><input type="checkbox"/> 45°</td> <td><input type="checkbox"/> A-1</td> <td><input type="checkbox"/> Red</td> <td><input type="checkbox"/> Ir<sup>192</sup></td> <td><input type="checkbox"/> Weld Insp</td> <td><input type="checkbox"/> Double</td> </tr> <tr> <td><input type="checkbox"/> 60°</td> <td><input type="checkbox"/> A-2</td> <td><input type="checkbox"/> Black</td> <td><input type="checkbox"/> Co<sup>60</sup></td> <td>INDIRECT/VIDEO</td> <td><input type="checkbox"/> Single</td> </tr> <tr> <td><input type="checkbox"/> 70°</td> <td><input type="checkbox"/> A-3</td> <td><input type="checkbox"/> Grey</td> <td>X-Ray</td> <td><input type="checkbox"/> Mirror</td> <td><input type="checkbox"/> Coil</td> </tr> <tr> <td><input type="checkbox"/> Other</td> <td><input type="checkbox"/> B-1</td> <td><input type="checkbox"/> Other</td> <td><input type="checkbox"/> 150 KV</td> <td><input type="checkbox"/> Boroscope</td> <td><input type="checkbox"/> Double</td> </tr> <tr> <td><input type="checkbox"/> Acoustic Emissions</td> <td><input type="checkbox"/> B-2</td> <td>Wet</td> <td><input type="checkbox"/> 250 KV</td> <td><input type="checkbox"/> Fiberoptic</td> <td><input type="checkbox"/> Single</td> </tr> <tr> <td></td> <td><input type="checkbox"/> B-3</td> <td><input type="checkbox"/> Black</td> <td></td> <td><input type="checkbox"/> Binocular</td> <td><input type="checkbox"/> Alloy Sep.</td> </tr> <tr> <td></td> <td></td> <td><input type="checkbox"/> Fluorescent</td> <td></td> <td><input type="checkbox"/> Camera</td> <td><input type="checkbox"/> Ferrite</td> </tr> </tbody> </table>						UT	PT	MT	RT	VT	ET	<input checked="" type="checkbox"/> 0°	Type	Dry	Isotope	<input type="checkbox"/> Direct	<input type="checkbox"/> Probe	<input type="checkbox"/> 45°	<input type="checkbox"/> A-1	<input type="checkbox"/> Red	<input type="checkbox"/> Ir <sup>192</sup>	<input type="checkbox"/> Weld Insp	<input type="checkbox"/> Double	<input type="checkbox"/> 60°	<input type="checkbox"/> A-2	<input type="checkbox"/> Black	<input type="checkbox"/> Co <sup>60</sup>	INDIRECT/VIDEO	<input type="checkbox"/> Single	<input type="checkbox"/> 70°	<input type="checkbox"/> A-3	<input type="checkbox"/> Grey	X-Ray	<input type="checkbox"/> Mirror	<input type="checkbox"/> Coil	<input type="checkbox"/> Other	<input type="checkbox"/> B-1	<input type="checkbox"/> Other	<input type="checkbox"/> 150 KV	<input type="checkbox"/> Boroscope	<input type="checkbox"/> Double	<input type="checkbox"/> Acoustic Emissions	<input type="checkbox"/> B-2	Wet	<input type="checkbox"/> 250 KV	<input type="checkbox"/> Fiberoptic	<input type="checkbox"/> Single		<input type="checkbox"/> B-3	<input type="checkbox"/> Black		<input type="checkbox"/> Binocular	<input type="checkbox"/> Alloy Sep.			<input type="checkbox"/> Fluorescent		<input type="checkbox"/> Camera	<input type="checkbox"/> Ferrite
UT	PT	MT	RT	VT	ET																																																						
<input checked="" type="checkbox"/> 0°	Type	Dry	Isotope	<input type="checkbox"/> Direct	<input type="checkbox"/> Probe																																																						
<input type="checkbox"/> 45°	<input type="checkbox"/> A-1	<input type="checkbox"/> Red	<input type="checkbox"/> Ir <sup>192</sup>	<input type="checkbox"/> Weld Insp	<input type="checkbox"/> Double																																																						
<input type="checkbox"/> 60°	<input type="checkbox"/> A-2	<input type="checkbox"/> Black	<input type="checkbox"/> Co <sup>60</sup>	INDIRECT/VIDEO	<input type="checkbox"/> Single																																																						
<input type="checkbox"/> 70°	<input type="checkbox"/> A-3	<input type="checkbox"/> Grey	X-Ray	<input type="checkbox"/> Mirror	<input type="checkbox"/> Coil																																																						
<input type="checkbox"/> Other	<input type="checkbox"/> B-1	<input type="checkbox"/> Other	<input type="checkbox"/> 150 KV	<input type="checkbox"/> Boroscope	<input type="checkbox"/> Double																																																						
<input type="checkbox"/> Acoustic Emissions	<input type="checkbox"/> B-2	Wet	<input type="checkbox"/> 250 KV	<input type="checkbox"/> Fiberoptic	<input type="checkbox"/> Single																																																						
	<input type="checkbox"/> B-3	<input type="checkbox"/> Black		<input type="checkbox"/> Binocular	<input type="checkbox"/> Alloy Sep.																																																						
		<input type="checkbox"/> Fluorescent		<input type="checkbox"/> Camera	<input type="checkbox"/> Ferrite																																																						
Remarks																																																											
Results	MNCR #'s open/closed/cond. rel.	Proc. No.																																																									
<input checked="" type="checkbox"/> Accept		Proc. No.																																																									
<input type="checkbox"/> Reject		Proc. No.																																																									
<input type="checkbox"/> Only		Job start date		Job stop date																																																							
NDE Coordinator		Date Closed		Date to DCC																																																							

Yellow - Originator Final Copy  
Pink - NDE Field Work Copy

Gold - Originators Initial Copy

N60692 (03-87)

OCLR00014604

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 68 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

<b>GPU Nuclear</b>		NDE/ISI Report Log		Page _____ of _____		
Oyster Creek - QC						
NDE Req. #: 92-072			Test: <input type="checkbox"/> PT <input type="checkbox"/> MT <input checked="" type="checkbox"/> VT <input type="checkbox"/> RT <input type="checkbox"/> UT <input type="checkbox"/>			
System/Location:			Item:			
Report #	Test Type	Date of Test	Results			Remarks
			Acc	Ret	Regradable	
92-072-21	UT	1-8-93				BAY 15
92-072-22	UT	1-7-93				BAY 9
92-072-23	UT	1/8/93				BAY 13
92-072-24	UT	1-11-93				BAY 13
92-072-25	UT	1-11-93				BAY 13
92-072-26	UT	1-11-93				BAY 13
92-072-27	VT	1-11-93				BAY 13 DEPTH GAUGE
92-072-28	VT	1-12-93				BAY 1 DEPTH GAUGE
92-072-29	VT	1-12-93				BAY 17 DEPTH GAUGE
92-072-30	VT	1-12-93				BAY 15 DEPTH GAUGE
92-072-31	VT	1-12-93				BAY 11 DEPTH GAUGE

Form ID 6153ADN 2230 01-2 18 821

40001537



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 69 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

GPU Nuclear		NDE/ISI Report Log		Page _____ of _____		
Oyster Creek - OC						
NDE Req. #: 92-072			Test: <input type="checkbox"/> PT <input type="checkbox"/> MT <input type="checkbox"/> VT <input type="checkbox"/> RT <input checked="" type="checkbox"/> UT <input type="checkbox"/>			
System/Location: D.U. LINER SANDBED			Item: _____			
Report #	Test Type	Date of Test	Results			Remarks:
			Acc	Met	Receivable	
92-072-01	UT	12-5-92				BAY 17
92-072-02	UT	12-5-92				BAY 19
92-072-03	UT	12-11-92				BAY 19
92-072-04	UT	12-11-92				BAY 17
92-072-05	UT	12-14-92				BAY 19
92-072-06	UT	12-14-92				BAY 17
92-072-07	UT	12-11-92				BAY 19
92-072-08	UT	12-11-92				BAY 17
92-072-09	UT	12-22-92				BAY 11
92-072-10	UT	12-22-92				BAY 11
92-072-11	UT	12-22-92				OVERLAY PLATE
92-072-12	UT	1-2-93				BAY 1
92-072-13	UT	1-2-93				BAY 1
92-072-14	UT	1-2-93				BAY 3
92-072-15	UT	1-2-93				BAY 3
92-072-16	UT	1-2-93				BAY 5
92-072-17	UT	1-2-93				BAY 5
92-072-18	UT	1-4-93				BAY 1
92-072-19	UT	1-5-93				BAY 1
92-072-20	UT	1-8-93				BAY 7

Form ID 6133ADM 7330 C1-2 IS 821

A0001537

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 70 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

PROGRAM	Xducer	SCREEN	Digital
1	5 mhz 74" Single H31900 (SP)	2"	2"
2	2.25 mhz 74" Single F28932	2"	2"
3	2 mhz M5EB M08524	2"	2"
4	5 mhz bubble water delay	2" delayed	2" delayed
5	5 mhz bubble water delay	2" SYNC SCREEN	NONE
6	5 mhz bubble water delay	2" SYNC SCREEN	2"
7	5 mhz 74" single H31900 (SP)	1"	1"
8	2 mhz M5EB M08524	1"	1"
9	5 mhz 74" delay G00504 single	2"	NONE
10	5 mhz 74" dual 014252	1"	1"
11	5 mhz 74" dual 014252	2"	2"

Some for your info. *per*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 71 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear	Item: N/A	NDE Request: 92-072	Data Sheet No.: 92-072-1
<input type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2	Class: N/A	Task No.: N/A	Date: 1/2/93
Task Description: UT Thickness		Code/Spec: F100 I.N.F.C.R.	
Comp. Desc.: Drywell Liner		System: 187	
Procedure/Rev.: 6100-010-2009-07 Rev 0		Drawing No./Rev.: 3E-187-29-001 Rev 0	
Test Surface: 0.0		Thickness: 1/16"	Material: C13
Examiner Sign: <i>[Signature]</i>	Print: J. Chiche Gude	ID No.: 574-28-0314	Level: II
Examiner Sign: <i>[Signature]</i>	Print: Mark F. Ragnell	ID No.: 653-6-1842	Level: I
Thermometer S/N 86-061 Pan Temperature 22.2 F		Techniques <input type="checkbox"/> CAT <input checked="" type="checkbox"/> D-Meter Other: N/A	
Cal. Blk. S/N 214	Cal. In: -1/4 AM 21:51 PM	Calibration Readings (Inches)	
Cal. Blk. Temp. 22 F	Cal. Out: -1/4 AM 22:15 PM	Cal. Blk. .5	.75 1.0 1.25 1.5
		D-Meter .5	.75 1.0 1.25 1.5

Position #/Reading in Inches

1	0.10	R 31	120
2	0.22	R 17	115
3	0.23	L 3	105
4	0.24	L 33	106
5	0.24	L 45	110
6	0.28	R 16	110
7	0.39	R 5	100
8	0.46	L 5	105
9	0.36	L 36	105

Drawing

Reviewed by: *[Signature]* Level: III Date: 1-3-93 Page 1 of 1

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 72 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

GPU Nuclear				Ultrasonic Thickness Data Sheet															
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TML-1	<input type="checkbox"/> TML-2	Class: N/A	Item: N/A	NDE Request: 92-092	Data Sheet No: 92-072-13	Date: 1/2/93												
Task Description: UT Thickness				Test No.: N/A															
Comp. Desc.: Drywell Cover				Code/Spec: ENL JNF02															
Procedure/Rev.: G100-0AP-7209.07 Rev. 0				Drawing No./Rev.: 32-187-29-001 Rev. 0															
Test Surface: 0.0				Thickness: 1/8"															
Examiner Sign: <i>[Signature]</i>				Print: J. Chawabe Sindo															
Examiner Sign: <i>[Signature]</i>				Print: Mark F. Bagnelli															
Thermometer SN 08-008 Pan Temperature 22.4 F				ID No.: 154-48-031A Level: II															
Cal. Bik. SN 214				ID No.: 553-21-1812 Level: I															
Cal. Bik. Temp. 77 F				Material: C/S															
Position #/Reading/Intrus				Techniques															
				<input checked="" type="checkbox"/> CRT <input type="checkbox"/> D-Meter Other: N/A															
Drawing 				Calibration Readings (Inches) <table border="1"> <tr> <td>Cal. Bik.</td> <td>.5</td> <td>.75</td> <td>1.0</td> <td>1.25</td> <td>1.5</td> </tr> <tr> <td>D-Meter</td> <td>.5</td> <td>.75</td> <td>1.0</td> <td>1.25</td> <td>1.5</td> </tr> </table>				Cal. Bik.	.5	.75	1.0	1.25	1.5	D-Meter	.5	.75	1.0	1.25	1.5
Cal. Bik.	.5	.75	1.0	1.25	1.5														
D-Meter	.5	.75	1.0	1.25	1.5														
Reviewed by: <i>[Signature]</i> P. 00 Level: All				Date: 1-3-93 Page: 2 of 2															

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 73 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

2 Points under

GPU Nuclear				Ultrasonic Thickness Data Sheet													
<input checked="" type="checkbox"/> DC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: N/A	Item: N/A	NDE Request: 92-072	Data Sheet No. 10-012-10											
Task Description: ULT THICKNESS				Task No.: N/A	Date: 1-4-93												
Comp. Desc.: DRYWELL LIMER Bay 1				System: 187	Code/Spec.: EN4 INFO												
Procedure/Rev.: GUCO - GAP - 7209 07				REV. 0	Drawing No./Rev.: 3E-187-29-DC1												
Test Surface: 0 D				Thickness: 1/8"	Material: C S												
Examiner Sign: <i>[Signature]</i>	Sign: <i>[Signature]</i>	Print: <i>Tom M. ...</i>	ID No.: 53-48-234	Level: I													
Examiner Sign: <i>[Signature]</i>	Sign: <i>[Signature]</i>	Print: <i>Mark F. Bagnell</i>	ID No.: 53-21-1002	Level: I													
Thermometer SN 92-0045 Part Temperature 16.5 F D-Meter SN 01-035				Techniques													
Cal. Bik. SN INV 219 Cal. In: N/A AM 13:11 PM				<input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter													
Cal. Bik. Temp. 76.5 F				Other: N/A													
Position #/Reading in Inches				Calibration Readings (inches)													
				Cal. Bik. .5	.75	1.0	1.25	1.5	N/A								
				D-Meter .5	.75	1.0	1.25	1.5	N/A								
<p>BAY #1</p> <p>10 11 12 13 14 15</p> <p>SAND</p>				Drawing													
				<table border="1"> <thead> <tr> <th>AREA</th> <th>MEASUREMENT</th> </tr> </thead> <tbody> <tr> <td>10 D 10 R 25</td> <td>1.439</td> </tr> <tr> <td>11 D 25 R 12</td> <td>1.114</td> </tr> <tr> <td>12 D 24 L 5</td> <td>1.224</td> </tr> <tr> <td>13 D 24 L 40</td> <td>1.092</td> </tr> <tr> <td>14 D 2 R 35</td> <td>1.107</td> </tr> <tr> <td>15 D 6 L 51</td> <td>1.156</td> </tr> </tbody> </table>				AREA	MEASUREMENT	10 D 10 R 25	1.439	11 D 25 R 12	1.114	12 D 24 L 5	1.224	13 D 24 L 40	1.092
AREA	MEASUREMENT																
10 D 10 R 25	1.439																
11 D 25 R 12	1.114																
12 D 24 L 5	1.224																
13 D 24 L 40	1.092																
14 D 2 R 35	1.107																
15 D 6 L 51	1.156																
Reviewed by: <i>[Signature]</i>				Level: 2		Date: 1-5-93		Page: 1 of 1									

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 74 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## Sketch Form (with grid)

OC     TM     OTHER

Component: DRYWELL liner Sandbed Area    Date Sheet No.: 92-072-28

Location: BAY # 1    Drawing No.: N/A    Rev.: N/A

Drawing

AREA	0°	45°	90°	135°
1	.272	.204	.206	.185
2	.143	.153	.143	.154
3	.377	.314	.329	.329
4	.330	.299	.304	.330
5	.281	.281	.246	.330
6	.209	.211	.225	.211
7	.200	.316	.241	.328
8	.279	.202	.238	.183
9	.316			
10	.225			
11	.238			
12				

\* VALLEY FROM AREA #12 INTERFERED WITH TAKE TAKING MEANINGLESS MEASUREMENT FEB 1993

Title: VT LV T    Date: 1-12-93

Page 1 of 1    NDE Request No.: 92-072

Date: 1/15-93    Level: JT

Prepared by: [Signature]    Reviewed by: [Signature]

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 75 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

one part under


GPU Nuclear				Ultrasonic Thickness Data Sheet																																																							
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: N/A	Item: N/A	NDE Request: 92-072	Data Sheet No.: 92-072-11																																																					
Task Description: ULT THICKNESS				Task No.: N/A	Date: 1-5-93																																																						
Comp. Desc.: DRYWELL LINER Bay 1				System: 167	Code/Spec.: ENG. INFO.																																																						
Procedure/Rev.: GICX CAP. 7209.07 REV.0				Drawing No./Rev.: SE 187-26-C01 REV.0	Material: C.S.																																																						
Test Surface: C.D.				Thickness: 1/8"																																																							
Examiner	Sign: <i>[Signature]</i>	Print: <i>John Tumminelli</i>	ID No.: 15440-239	Level: II																																																							
Examiner	Sign: <i>[Signature]</i>	Print: MARK TUMMINELLI	ID No.: 553-61-012	Level: I																																																							
Thermometer S/N 88-681 Part Temperature 72°F D-Meter S/N 93-0296				Techniques																																																							
Cal. Blk. S/N 14V 214 Cal. In: N/A AM 22:42 PM				<input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter																																																							
Cal. Blk. Temp. 72°F Cal. Out: N/A AM 12:55 PM				Other: N/A																																																							
Position #/Reading in Inches				Drawing																																																							
BAY #1				MEASUREMENT																																																							
SAND				AREA																																																							
				<table border="1" style="width:100%; border-collapse: collapse;"> <tr><td>16</td><td>D 50</td><td>R 40</td><td></td><td></td><td></td><td>796</td></tr> <tr><td>17</td><td>D 48</td><td>R 16</td><td></td><td></td><td></td><td>850</td></tr> <tr><td>18</td><td>D 38</td><td>L 2</td><td></td><td></td><td></td><td>917</td></tr> <tr><td>19</td><td>D 38</td><td>L 24</td><td></td><td></td><td></td><td>896</td></tr> <tr><td>20</td><td>D 18</td><td>R 13</td><td></td><td></td><td></td><td>965</td></tr> <tr><td>21</td><td>D 24</td><td>R 15</td><td></td><td></td><td></td><td>726</td></tr> <tr><td>22</td><td>D 32</td><td>R 15</td><td></td><td></td><td></td><td>852</td></tr> <tr><td>23</td><td>D 48</td><td>R 15</td><td></td><td></td><td></td><td>850</td></tr> </table>				16	D 50	R 40				796	17	D 48	R 16				850	18	D 38	L 2				917	19	D 38	L 24				896	20	D 18	R 13				965	21	D 24	R 15				726	22	D 32	R 15				852	23	D 48	R 15
16	D 50	R 40				796																																																					
17	D 48	R 16				850																																																					
18	D 38	L 2				917																																																					
19	D 38	L 24				896																																																					
20	D 18	R 13				965																																																					
21	D 24	R 15				726																																																					
22	D 32	R 15				852																																																					
23	D 48	R 15				850																																																					
Position #/Reading in Inches				Drawing																																																							
BAY #1				MEASUREMENT																																																							
SAND				AREA																																																							
				<table border="1" style="width:100%; border-collapse: collapse;"> <tr><td>20</td><td>O 31</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>18</td><td>O 16</td><td></td><td></td><td></td><td></td><td></td></tr> <tr><td>17</td><td>O 17</td><td></td><td></td><td></td><td></td><td></td></tr> </table>				20	O 31						18	O 16						17	O 17																																				
20	O 31																																																										
18	O 16																																																										
17	O 17																																																										
Reviewed by: <i>[Signature]</i>				Date: 1-6-93																																																							
Level: 17				Page: 1 of 1																																																							

MS402 (05-91)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 76 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

NDE REQ. 92.072  
Page 3 of 9



## INSPECTION SPOTS FOR UT Bay #1

- NOTE:
1. GRIND FLAT FOR UT WITH MINIMUM REMOVAL OF SHELL AT THE VALLEY.



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 77 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> GPU Nuclear	Item: N/A	NDE Request: 92-072	Data Sheet No.: 92-072-14																											
<input type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2	Class: N/A	Task No.: 010	Date: 1/12/93																											
Task Description: 187 Thick		Code/Spec: ENCL I NFER																												
Comp. Desc.: Drywell Case		Drawing No./Rev.: 31-187-29 Rev 0																												
System: 187		Material: C/S																												
Procedure/Rev.: G10 GNR 2E0802 Rev 0		ID No.: 15748 020																												
Test Surface: 0.0		Level: II																												
Examiner Sign: <i>[Signature]</i>	Print: J. Chalaba Land	ID No.: 557-21-162.2																												
Examiner Sign: <i>[Signature]</i>	Print: Mark F. Binelli	Level: I																												
Thermometer S/N 65-057 Part Temperature 22 F D-Meter S/N 00-0325		Techniques																												
Cal. Blk. S/N 214	Cal. Int: N/A AM 21:18 PM	<input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter																												
Cal. Blk. Temp. 22 F	Cal. Out: N/A AM 21:45 PM	Other: N/A																												
Position & Reading in Inches																														
Drawing		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>Cal. Blk.</th> <th>5</th> <th>7.5</th> <th>1.0</th> <th>1.5</th> <th>1.5</th> </tr> <tr> <th>D-Meter</th> <td>5</td> <td>7.5</td> <td>1.0</td> <td>1.5</td> <td>1.5</td> </tr> </table>		Cal. Blk.	5	7.5	1.0	1.5	1.5	D-Meter	5	7.5	1.0	1.5	1.5															
Cal. Blk.	5	7.5	1.0	1.5	1.5																									
D-Meter	5	7.5	1.0	1.5	1.5																									
		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th>AREA</th> <th>1</th> <th>2</th> <th>3</th> <th>4</th> <th>5</th> <th>6</th> <th>7</th> <th>8</th> </tr> <tr> <td>MIN. MEASUREMENT</td> <td>0.5" R 63</td> <td>0.9" R 50</td> <td>0.9" R 33</td> <td>0.13" L 5</td> <td>0.15" L 0</td> <td>0.15" L 56</td> <td>0.17" R</td> <td>0.21" L</td> </tr> <tr> <td></td> <td>79"</td> <td>140"</td> <td>217"</td> <td>234"</td> <td>223"</td> <td>266"</td> <td>236"</td> <td>280"</td> </tr> </table>		AREA	1	2	3	4	5	6	7	8	MIN. MEASUREMENT	0.5" R 63	0.9" R 50	0.9" R 33	0.13" L 5	0.15" L 0	0.15" L 56	0.17" R	0.21" L		79"	140"	217"	234"	223"	266"	236"	280"
AREA	1	2	3	4	5	6	7	8																						
MIN. MEASUREMENT	0.5" R 63	0.9" R 50	0.9" R 33	0.13" L 5	0.15" L 0	0.15" L 56	0.17" R	0.21" L																						
	79"	140"	217"	234"	223"	266"	236"	280"																						
Reviewed by: <i>[Signature]</i>		Level: III																												
Date: 1-3-93		Page 77 of 77																												

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 78 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

89 4025

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear		Data Sheet No. <u>92-072-15</u>	
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	<input type="checkbox"/> N/A
Task Description: <u>UT Thickness</u>		NDE Request: <u>72-072</u>	Date: <u>1/2/93</u>
Comp. Desc.: <u>Orywell Liner</u>		Code/Spec: <u>ENR 5.1.1.2</u>	Material: <u>C/S</u>
Procedure/Rev.: <u>G100-048-208-07 Rev. 0</u>		Drawing No./Rev.: <u>31-187-29-001 Rev. 0</u>	Material: <u>C/S</u>
Test Surface: <u>0.0</u>		Thickness: <u>1/8"</u>	ID No.: <u>514 Y8-0218</u> Level: <u>II</u>
Examiner Sign: <u>[Signature]</u>	Print: <u>J. Amodeo End</u>	ID No.: <u>553-1-118-2</u>	Level: <u>IL</u>
Examiner Sign: <u>[Signature]</u>	Print: <u>Mark J. Tumminelli</u>	Techniques <input checked="" type="checkbox"/> CRT <input type="checkbox"/> O Meter Other: <u>N/A</u>	
Thermometer SN <u>86-001</u> Part Temperature <u>22.6</u> F		D-Meter SN <u>157-113</u>	
Cal. Bk. SN <u>214</u>		Cal. Bk. <u>15</u>	
Cal. Bk. Temp. <u>77</u> F		Cal. Out: <u>N/A</u> AM <u>11:02</u> PM	
Position # Reading in Inches		Cal. Bk. <u>1.5</u> .75" <u>1.0</u> 1.25" <u>1.5</u>	
D-Meter <u>1.5</u> .75" <u>1.0</u> 1.25" <u>1.5</u>		Drawing	

Thermometer SN 86-001 Part Temperature 22.6 F

Cal. Bk. SN 214 Cal. Bk. 15

Cal. Bk. Temp. 77 F Cal. Out: N/A AM 11:02 PM

D-Meter SN 157-113 Cal. Bk. 1.5 .75" 1.0 1.25" 1.5

D-Meter 1.5 .75" 1.0 1.25" 1.5

Position # Reading in Inches

Position #	Reading in Inches
1	0.50
2	0.90
3	0.90
4	0.90
5	0.90
6	0.90
7	0.90
8	0.90

AREA  
1 0.50 R 63  
2 0.90 R 50  
3 0.90 R 33  
4 0.90 L 5  
5 0.90 L 8  
6 0.90 L 56  
7 0.90 R  
8 0.90 L

MAX. INCHES  
15.00  
10.00  
8.00  
6.00  
4.00  
2.00  
1.00

Drawing

DAY #3

SAND

Level: III

Date: 1-3-93

Page: 61 of 111

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 79 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli		Date

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear		Item: WIA	NDE Request: 72-072	Data Sheet No: 92-012-15
Task Description: 17 Thickens		System: 187	Task No.: N/A	Date: 1/2/93
Comp. Desc.: Drywell Cover		Drawing No./Rev.: 3E-187-2V-001 Rev. 0	Code/Spec.: CWI T-155.12	
Procedure/Rev.: G100-018 2E09.07 Rev. 0		Thickness: 1/8"	Material: C/P	
Test Surface: 0.0	Examiner Sign: <i>[Signature]</i>	ID No.: 154-18-0318	Level: II	
Examiner Sign: <i>[Signature]</i>	Print: Mark C. Turminelli	ID No.: 35-21-1A-2	Level: I	
Thermometer SN: 83 001 Part Temperature: 22 F	D-Meter SN: 137-113	Techniques <input checked="" type="checkbox"/> CRT <input type="checkbox"/> D Meter Other: N/A		
Cal. Bk. SN: 224	Cal. Wt: N/A AM 21:12 PM	Calibration Readings (Inches)		
Cal. Bk. Temp: 72 F	Cal. Out: N/A AM 21:35 PM	Cal. Bk. .5" .75" 1.0" 1.25" 1.5"	D-Meter .5" .75" 1.0" 1.25" 1.5"	
Position # Reading in Inches				

Position # 3

SAND

Position #	Reading in Inches
1	0.5"
2	0.8"
3	0.9"
4	0.13"
5	0.15"
6	0.15"
7	0.17"
8	0.21"

Techniques: Max. Imp. 150, 100, Rec. 90, Flat. 10, 6.40, 790

Level: III

Date: 1-3-93

Page: 81 of 117

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 80 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

**OC**  TMI-1  TMI-2  Class: W114

Task Description: 117 The 612's

Comp Desc: Drywell LWR

Procedure/Rev: 6100 CAP 700002 PK 2

Test Surface: 0.0

Examiner Sign: *[Signature]*

Examiner Sign: *[Signature]*

Thermometer S/N 23.126 Part Temperature 22.2 F D-Meter S/N 21.035

Cal. Blk. S/N 22.4 Cal. In: N/A AM 11:35 PM

Cal. Blk. Temp. 22 F Cal. Out: N/A AM 11:35 PM

Data Sheet No: 92-02-11

Date: 1/12/93

Code/Spec: ENI, INFCR

Drawing No./Rev: 31 187-20-071 Rev 0

Material: C-13

ID No: 157-43-0318 Level: II

ID No: 553-51-1202 Level: I

Techniques  
 CRT  D-Meter  
Other: N/A

Cal. Blk.	5	7.5	1.0	1.5	1.5
D-Meter	5	7.5	1.0	1.5	1.5

Thick: 1/8"

Print: J. Choche Lind

Print: Mark F. Buxnell

Position of Reading in Inches

Thermoniter S/N 23.126 Part Temperature 22.2 F D-Meter S/N 21.035

Cal. Blk. S/N 22.4 Cal. In: N/A AM 11:35 PM

Cal. Blk. Temp. 22 F Cal. Out: N/A AM 11:35 PM

Position of Reading in Inches

BAY #5

Drawing

Area	1	2	3	4	5	6
1	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"
2	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"
3	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"
4	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"
5	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"
6	0 - 10" X - 13	0 - 12" X - 8"	0 - 14" X - 10"	0 - 16" X - 7"	0 - 18" X - 6"	0 - 20" X - 4"

Min. wall point

Area

1 0 - 10" X - 13

2 0 - 12" X - 8"

3 0 - 14" X - 10"

4 0 - 16" X - 7"

5 0 - 18" X - 6"

6 0 - 20" X - 4"

Min. wall

Reviewed by: *[Signature]*

Level: III

Date: 1-3-93

Page 21 of 21

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 81 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli	Date	

*10 good*

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: N/A	Item: N/A	NDE Request: 72.072	Data Sheet No.: 92028-11
Task Description: 117 Thickens			Task No.: N/A		Date: 1/1/93	
Comp. Desc: Dupont Curve			System: 187		Code/Spec. Pw: T-3FCR	
Procedure Ref.: 500 GAP 7209.02			Drawing No./Rev.: 3E-187-29-001		Material: A105	
Test Surface: 0.0			Thickness: 1/16"		Material: C/S	
Examiner Sign: <i>[Signature]</i>	Print: J. Chascha Lind		ID No.: 154-45-0318	Level: II		
Examiner Sign: <i>[Signature]</i>	Print: Mark F. Burgnell		ID No.: 553-81-1822	Level: I		

Thermometer S/N 26-008, Part Temperature 22.2 F D-Meter S/N 37-113  
 Cal. Bk. S/N 22 F Cal. In: N/A AM 21:23 PM  
 Cal. Bk. Temp. 22 F Cal. Out: N/A AM 21:58 PM

Position = Reading in Inches

Cal. Bk.	.5"	.75"	1.0"	1.25"	1.5"
D-Meter	.5"	.75"	1.0"	1.25"	1.5"

Techniques:  CNT  D Meter Other: N/A

**Drawing**

RAY #5

S.A.M.

Reading	Area	Measurement
1	0-40"	2-13"
2	0-42"	2-8"
3	0-44"	2-10"
4	0-46"	2-7"
5	0-48"	2-11"
6	0-50"	2-4"
7	0-52"	2-24"
8	0-54"	2-28"

\* Area with


Indexed by: *[Signature]*

Date: 1-3-93 Page 81 of 91

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 82 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

BAY #5



CRATER - 12" DEEP MAX.  
NDE 98.072 - Page 9 of 9



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 84 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

*aligned*

<b>GPU Nuclear</b>																																																																	
<b>Ultrasonic Thickness Data Sheet</b>																																																																	
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: <i>N/A</i>	Item: <i>N/A</i>	NDE Request: <i>42-07E</i>	Data Sheet No.: <i>92-07E-3</i>																																																											
Task Description: <i>LIT THICKNESS</i>			Task No.: <i>N/A</i>			Date: <i>1-8-93</i>																																																											
Comp. Desc.: <i>Drywell Ext. S/W</i>			System: <i>187</i>			Code/Spec: <i>ENR T-6</i>																																																											
Procedure/Rev.: <i>ENR-CAP-2209-07 FIVE</i>			Drawing No./Rev.: <i>3E-187-29-001</i>			Material: <i>CS</i>																																																											
Test Surface: <i>CO</i>			Print: <i>Tom Yekta</i>			ID No.: <i>57-82-001</i>	Level: <i>I</i>																																																										
Examiner Sign: <i>[Signature]</i>			Print: <i>[Signature]</i>			ID No.: <i>11-44-2524</i>	Level: <i>II</i>																																																										
Examiner Sign: <i>[Signature]</i>			Print: <i>[Signature]</i>			Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter <input type="checkbox"/> Other																																																											
Thermometer SIN 22-026 Part Temperature 22F			D-Meter SIN 8182-015			Calibration Readings (Inches)																																																											
Cal. Blk. SN <i>218</i>			Cal. In: <i>02:20AM</i>			Cal. Blk. .5"    1.0"    1.5"    2.0"    2.5"    3.0"																																																											
Cal. Blk. Temp. <i>72</i> F			Cal. Out: <i>02:20AM</i>			D-Meter .5"    1.0"    1.5"    2.0"    2.5"    3.0"																																																											
Position w/ Reading in Inches			Drawing			Drawing																																																											
<p style="text-align: center;"><i>BAY #7</i></p>			<p style="text-align: center;"><i>AREA</i></p> <p style="text-align: center;"><i>MEASUREMENT</i></p>			<table border="1"> <tr><td>1</td><td>0.21"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>2</td><td>0.21"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>3</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>4</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>5</td><td>0.21"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>6</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> <tr><td>7</td><td>0.21"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td><td>0.19"</td></tr> </table>				1	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	2	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	3	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	4	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	5	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	6	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	7	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"
1	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
2	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
3	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
4	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
5	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
6	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
7	0.21"	0.19"	0.19"	0.19"	0.19"	0.19"	0.19"																																																										
<p style="text-align: center;"><i>SAND</i></p>			Level: <i>II</i>			Date: <i>1-8-93</i>																																																											
Reviewed by: <i>[Signature]</i>			Level: <i>II</i>			Page: <i>1</i> of <i>1</i>																																																											



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 85 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli	Date

All Good

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2 <input type="checkbox"/> Class: <i>NA</i>	Item: <i>NA</i>	NDE Request: <i>92-072</i>	Data Sheet No: <i>92-072-1</i>
Task Description: <i>UT Thickness</i>		Task No: <i>NA</i>	Date: <i>1-7-93</i>
Comp. Desc.: <i>COPPER LINED</i>		Code/Spec: <i>Exp. 1116</i>	
Procedure/Rev: <i>G100-2AC 220807</i>		Drawing No./Rev: <i>JE-167-29-001 RUC</i>	
Test Surface: <i>C.D. CAY #9</i>		Material: <i>CS</i>	
Examiner Sign: <i>[Signature]</i>	ID No.: <i>57-1023A</i>	Level: <i>II</i>	
Examiner Sign: <i>[Signature]</i>	ID No.: <i>11-44-2514</i>	Level: <i>II</i>	
Thermometer S/N <i>220808</i> Part Temperature <i>22 F</i> D-Meter S/N <i>220808</i> Cal. Blk. S/N <i>208</i> Cal. In: <i>2:02 AM 01/12/93</i> Cal. Blk. Temp. <i>22 F</i> Cal. Out: <i>0:05 AM 01/12/93</i>			

Cal. Blk.	.5	.10	.15						
D-Meter	.5	.10	.15						

Techniques  CRT  D-Meter  Other

**Position #/Reading in Inches**

**Drawing**

Point	Cal. Blk.	D-Meter	Reading	Remarks
1	0.21	R	.32	MEASURED
2	0.12	R	.17	.940
3	0.18	R	.18	.94
4	0.21	R	.12	.944
5	0.26	L	.14	1.020
6	0.30	L	.30	.905
7	0.18	L	.18	.82
8	0.22	L	.17	.825
9	0.15	L	.15	.771
10	0.32	L	.18	.832

Reviewed by: <i>[Signature]</i>	Date: <i>1-8-93</i>	Page: <i>1</i> of <i>1</i>
---------------------------------	---------------------	----------------------------

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 86 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli		Date

**Ultrasonic Thickness Data Sheet**

Nuclear

OC  TMI-1  TMI-2  Class: NA Item: NA NDE Request: 91-072 Data Sheet No.: 92-072-09

Task Description: UT of the Sandbed Test No.: NA Date: 12/12/92

Comp. Desc.: Examination of the Sandbed System: 107 Codes/Specs: ASME Sec. VIII

Procedure/Rev.: ASME Sec. VIII Drawing No./Rev.: 30-107-19-001 Rev. 0 Drawing No./Rev.: 30-107-19-001 Rev. 0

Test Surface: CS Thickness: 1/8" Material: CS

Examiner Sign: [Signature] Print: J. Turminelli ID No.: 137-001-501 Level: II

Examiner Sign: [Signature] Print: Mark F. Turminelli ID No.: 533-01-1622 Level: I

Thermometer S/N: 28-557 Part Temperature: 65 F D-Meter S/N: 113

Cal. Bk. S/N: 45 Cal. In: 1.0 AM 3:20 PM

Cal. Bk. Temp.: 65 F Cal. Out: 1.0 AM 3:15 PM

Position #/Facing In Inches

Cal. Bk.	.5	.75	1.0	1.25	1.5	1.75	2.0
D-Meter	.5	.75	1.0	1.25	1.5	1.75	2.0

Techniques  
 CRT  D-Meter  Other

**Drawing**

Position #/Facing In Inches

Position #/Facing In Inches	1	2	3	4	5	6	7	8
Reading	1.0	1.0	1.0	1.0	1.0	1.0	1.0	1.0

Reviewed by: [Signature] Level: III Date: 12-22-92 Page 1 of 1

95435 (03-90)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 87 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear		Item: <u>NA</u>		NDE Request: <u>92-013</u>		Data Sheet No.: <u>01110</u>											
Task Description: <u>OC Drywell Ext. UT</u>		Class: <u>NA</u>		Task No.: <u>NA</u>		Date: <u>12/12/92</u>											
Comp. Desc.: <u>Drywell Ext. UT</u>		System: <u>187</u>		Code/Spec: <u>ASME VIII</u>													
Procedure/Rev.: <u>ASME VIII</u>		Drawing No./Rev.: <u>3E-B1-25-001 REV</u>		Material: <u>1/8"</u>													
Test Surface: <u>1</u>		Print: <u>Institution: Unitek Lab</u>		ID No.: <u>1740-135</u>		Level: <u>I</u>											
Examiner Sign: <u>[Signature]</u>		Print: <u>Mark F. Bagnell</u>		ID No.: <u>SS-1-12-1</u>		Level: <u>II</u>											
Thermometer S/N <u>22-633</u> Part Temperature <u>65 F</u> D-Meter S/N <u>22-235</u>		Cal. In: <u>2:44 AM 2/12/93</u>		Cal. Out: <u>3:02 PM</u>		Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter Other											
Cal. Blk. S/N <u>72</u>		Position #/Reading in Inches		Calibration Readings (inches)													
Cal. Blk. Temp. <u>65 F</u>				<table border="1" style="width: 100%; text-align: center;"> <tr> <td>Cal. Blk.</td> <td>5"</td> <td>7"</td> <td>10"</td> <td>15"</td> </tr> <tr> <td>D-Meter</td> <td>5"</td> <td>7"</td> <td>10"</td> <td>15"</td> </tr> </table>		Cal. Blk.	5"	7"	10"	15"	D-Meter	5"	7"	10"	15"		
Cal. Blk.	5"	7"	10"	15"													
D-Meter	5"	7"	10"	15"													

**Drawing**


1	10.0	10.0	10.0	10.0	10.0	10.0
2	10.0	10.0	10.0	10.0	10.0	10.0
3	10.0	10.0	10.0	10.0	10.0	10.0
4	10.0	10.0	10.0	10.0	10.0	10.0
5	10.0	10.0	10.0	10.0	10.0	10.0
6	10.0	10.0	10.0	10.0	10.0	10.0
7	10.0	10.0	10.0	10.0	10.0	10.0
8	10.0	10.0	10.0	10.0	10.0	10.0

Reviewed by: [Signature] Level: I Date: 12-27-92 Page: 1 of 1

MS-103 (05-92)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 88 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date




BAY-11 — UT SPOTS FOR GRINDING

NOTE: GRIND ONE SPOT AT A TIME. REMARK THE SPOT # AFTER GRINDING.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed.		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 89 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date



## BAY-II - UT SPOTS FOR GRINDING

NOTE: GRIND ONE SPOT AT A TIME. REMARK THE SPOT # AFTER GRINDING.

# GPU Nuclear


Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 90 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

140C | ITMI

Cal Sheet # 14C-562

## Calibration Sheet

System 187	Component Drywell Ext. Dry II	Procedure SRO-58A-700-903	Rev 0
Examiner: Signature: <i>[Signature]</i>	Print: J. Walker	Initial: <i>[Signature]</i>	ID# 1318-019 Level II
Examiner: Signature: <i>[Signature]</i>	Print: Mark F. Bagnell	Initial: <i>[Signature]</i>	ID# 653-81-182 Level I
Instrument Settings ID# 237-113 Model/Manuf. SRO-58A-700-903	Search Unit Type <i>2.5</i> Freq <i>2.5</i> MHZ Size <i>1</i> Angle <i>0</i> Mode <i>4-2</i>	Search Unit Cable Type <i>2.5</i> Length <i>2.46</i>	
Gain Coarse <i>2.2</i> Fine <i>0.1</i> Uncal <i>0.1</i>	System Check <input type="checkbox"/> Exit Point <input checked="" type="checkbox"/> Angle <i>1-2</i> <i>1/4</i>	Couplant Make <i>2.5</i>	Thermometer SN: <i>2.5</i> Cal Due <i>3/2/93</i>
Sweep Circuit Coarse <i>1</i> Fine <i>1</i> Delay <i>1</i> Screen Depth <i>1</i>	Reflector Amplitude % of FSH Screen Reading in inches		
Operation (I&R) Frequency: <i>1.0</i> MHz Filter: <i>1.0</i> MHz Damping: <i>1.0</i> MHz	Date <i>12/12/92</i>		
Time/Date 15:30 1/12/93	Remarks:		
Reflector % FSH Inches	Reflector % FSH Inches	Reflector % FSH Inches	Reflector % FSH Inches
Initials <i>[Signature]</i>			



Technical Review  
Reviewed By *[Signature]*  
Level *III* Date *12-27-92*  
NDE Request #: *72-072*

Components Examined:  
*DRY II*

N0827 (05-90)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 91 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli		Date

Sketch Form (with grid)

OC  TM  OTHER


Component: DRYWELL LINER Sandbed Area

Location: BAY # 11

Drawing

Date Sheet No.: 92-072-31

Drawing No.: N/A Rev: N/A



AREA	0°	45°	90°	135°
1	.287	.378	.457	.200

Prepared by: [Signature] Date: 1/17/93

Reviewed by: [Signature] Date: 1/13/93

Title: VT LV II Page: 1 of 1 NDE Request No.: 92-072

Level: T

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 92 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

*Low Points under*

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2	Class: <u>NA</u>	Item: <u>NA</u>	NDE Request: <u>92-072</u>	Data Sheet No.: <u>92-072-23</u>
Task Description: <u>Drywell Extension (Lower thickness)</u>			Task No.: <u>NA</u>	Date: <u>1/13/93</u>
Comp. Desc.: <u>Drywell Extension Bay 13</u>		System: <u>DEWEL</u>	Code/Spec.: <u>ENR. 1.1.1.1</u>	
Procedure/Rev.: <u>6100-GAP-7107.01 Rev C</u>		Drawing No./Rev.: <u>35-197-29-001</u>		
Test Surface: <u>CD</u>		Thickness: <u>1/8</u>	Material: <u>C5</u>	
Examiner Sign: <u>YAS</u>	Print: <u>A. H. SHERBERT</u>	ID No.: <u>217-36-432</u>	Level: <u>II</u>	
Examiner Sign: <u>NA</u>	Print: <u>NA</u>	ID No.: <u>NA</u>	Level: <u>NA</u>	
Thermometer SN <u>92-022</u> Pan Temperature <u>74.2</u> F D-Meter SN <u>92-029</u>		Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter Other: <u>NA</u>		
Cal. Blk. SN: <u>219</u>	Cal. In: <u>NA</u> AM <u>1:20 PM</u>	Calibration Readings (Inches)		
Cal. Blk. Temp: <u>69</u> F	Cal. Out: <u>NA</u> AM <u>2:30 PM</u>	Cal. Blk. .502" <u>1.499</u>		
		D-Meter .502" <u>1.326</u>		

Area	Location	THICK
1	D6 R46	.814
2	D6 R39	.675
3	D16 R49	.931
4	D12 R35	.714
5	D16 R6	.135
6	D10 L1	.233
7	D17 L23	.632
8	D11 L10	.744

Position #/Reading in Inches

Reviewed by: <u>[Signature]</u>	Level: <u>NA</u>	Date: <u>1-8-93</u>	Page: <u>1</u> of <u>1</u>
---------------------------------	------------------	---------------------	----------------------------



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 93 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

7 Photo number

## Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2	Class: <i>N/A</i>	Item: <i>N/A</i>	NDE Request: <i>23-C-22</i>	Date Sheet No.: <i>23-C-22-20</i>
Task Description: <i>Cylinder Head Top Examination</i>		Task No.: <i>N/A</i>	Date: <i>1-11-93</i>	
Comp. Desc.: <i>Cylinder Head Bay 13</i>		System: <i>187</i>	Code/Spec: <i>ASME (ENG. INFO)</i>	
Procedure/Rev.: <i>ASME SA-590-7003-07</i>		Drawing No./Rev.: <i>35-187-24 001</i>	Material: <i>C.S.</i>	
Test Surface: <i>C.O.</i>		Thickness: <i>1/8"</i>	ID No.: <i>57-952-249</i> Level: <i>II</i>	
Examiner Sign: <i>[Signature]</i>	Sign: <i>[Signature]</i>	Print: <i>J. Van der Lijde</i>	ID No.: <i>10-44-2514</i> Level: <i>II</i>	Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter Other
Examiner Sign: <i>[Signature]</i>	Sign: <i>[Signature]</i>	Print: <i>LWS SACU 20EL7</i>	Calibration Readings (inches)	
Thermometer S/N: <i>52-1045</i> Part Temperature <i>63 F</i> D-Meter S/N: <i>233</i>		Cal. In: <i>11 AM 2:25 PM</i>		
Cal. Blk. S/N: <i>2-19</i>		Cal. Out: <i>12 AM 2:30 PM</i>		
Cal. Blk. Temp. <i>156 F</i>		Position #/Reading in inches		

AREA	ECCENTRICATION	THK.
1	UP-1" R-45"	0.672"
2	UP-1" R-36"	0.725"
3	O-21" R-48"	0.941"
4	O-12" R-36"	0.915"
5	O-21" R-6"	0.718"
6	O-24" L-8"	0.835"
7	O-17" L-22"	0.518"
8	O-24" L-26"	0.715"
9	O-28" R-41"	0.924"
10	O-28" R-12"	0.728"
11	O-28" L-15"	0.885"
12	O-28" L-23"	0.885"
13	O-18" R-40"	0.922"
14	O-18" R-8"	0.818"
15	O-20" L-9"	0.882"
16	O-20" L-29"	0.839"
17	O-9" R-28"	0.807"
18	O-22" R-28"	0.825"
19	O-37" R-28"	0.912"

Drawing: *BAY 13*

Date: *1-11-93*

Page: *1* of *2*

Reviewed by: *[Signature]* Level: *III*

40% reduced to 25% or less of test area if not marked red.

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 94 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

**NOTES:**



- SPOT #9 THRU #19 MARKED ON 4/10/93. SKD
- GRIND ABOVE SPOTS CAREFULLY AS NOT TO REDUCE SHELL THICKNESS EXCESSIVE
- UT ALL SPOTS (1 THRU 19) FOR REMAINING SHELL THICKNESS

Bay # 13

#12 672 24

Pg 2 of 2

*[Signature]*  
1-11-93



**NOTES**

- PLUG UNCORRODED - LOCATED IN A DEEP VALLEY.
- "TUB RING" LESS PROMINENT.
- SHELL & FLOOR NEEDS MORE CLEANING.

*[Signature]*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 95 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Data Sheet No.: 92-072-15  
 Date: 1/1/93

## Ultrasonic Thickness Data Sheet

Nuclear     OC     TMI-1     TMI-2    Class: N/A    Item: N/A    INDE Request: 92-072  
 Task Description: OCPWEL PUMP THE MEASUREMENT    Task No.: N/A  
 Comp. Desc.: Drywell liner Bay 13    System: 107    Code/Spec.: ENG I-86  
 Procedure/Rev.: 5100 OCP 720907 Rev 0    Drawing No./Rev.: 3E-187-29-001  
 Test Surface: O.D.    Thickness: .18"    Material: CB

Examiner Sign: *[Signature]*    ID No.: 57-48-03P    Level: ZE  
 Examiner Sign: *[Signature]*    ID No.:    Level: AB

Thermometer SN 2-022 Part Temperature 20 F    D-Meter SN 22-025  
 Cal. In: 2.19    Cal. In: 44 AM 12:32 PM     CRT     D-Meter  
 Cal. Bk. Temp. 70 F    Cal. Out: 19 AM 12:55 PM    Other:

Sign: *[Signature]*    Title: J. Chiche Luch    Material: CB  
 Sign: *[Signature]*    Title:    Material:

Drawing: *[Signature]*    Date: 1/1/93    Page: 1 of 1

Position #/Reading in Inches

Cal. Bk.	D-Meter	Cal. Bk.	D-Meter
.5	1.0	1.5	1.5
.5	1.0	1.5	1.5

Thickness

0.89"
0.94"
0.85"
0.81"
0.85"
0.91"
0.75"
0.80"
0.85"

A minimum of 3 readings were required to produce principal locations

BAY 13

SAND

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 96 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

*None Under*

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2	Class: <i>NA</i>	Item: <i>NA</i>	NDE Request: <i>92-072</i>	Data Sheet No.: <i>92-072-46</i>
Task Description: <i>Drywell Ext. Thick. 11/13/92</i>		Task No.: <i>NA</i>	Code/Spec.: <i>Eng. Inb.</i>	Date: <i>1/12/93</i>
Comp. Desc.: <i>Drywell Core Bay 13</i>		System: <i>107</i>	Drawing No./Rev.: <i>3E-107-29-001</i>	
Procedure/Rev.: <i>6100-02AP 7203.07 Rev. 0</i>		Thickness: <i>1/8"</i>	Material: <i>CS</i>	
Examiner Sign: <i>[Signature]</i>	Print: <i>J. Van Ocha Link</i>	ID No.: <i>NA</i>	Level: <i>II</i>	
Examiner Sign: <i>[Signature]</i>	Print: <i>[Signature]</i>	ID No.: <i>NA</i>	Level: <i>NA</i>	
Thermometer <i>SN 27.052</i> Part Temperature <i>20 F</i> D-Meter <i>SN 122.121</i>		Techniques <input checked="" type="checkbox"/> CRT <input type="checkbox"/> D-Meter		
Cal. Blk. SN <i>219</i>	Cal. In: <i>NA</i>	Calibration Readings (Inches)		
Cal. Blk. Temp. <i>20 F</i>	Cal. Out: <i>NA</i>	Cal. Blk. <i>.5</i>	<i>10</i>	<i>15</i>
		D-Meter <i>.5</i>	<i>10</i>	<i>15</i>

Position = Reading in Inches

Area	Thickness
1A	0.00
2A	0.00
3A	0.00
4A	0.00
5A	0.00
6A	0.00
7A	0.00
8A	0.00
9A	0.00
10A	0.00
11A	0.00
12A	0.00
13A	0.00
14A	0.00
15A	0.00

*11" minimum girth with adjustment to previous girth/UT locations.*

Review by: *[Signature]* Level: *II* Date: *11-93* Page *1* of *1*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 97 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

**Calibration Sheet**

System: 187    Component: BAY 13 LWR    Procedure: 5100-DAP-7209.07    Rev: 0

Cal Sheet # 144-113

Examiner: Signature: *[Signature]*    Initial: *JY*    Level: *II*

Examiner: Signature: *[Signature]*    Initial: *MB*    Level: *NA*

Instrument Settings  
 ID# 22-112    Model/Manual 5011-22    START  
 Gain Coarse 4.28    Fine 4.5    Uncrt 4.5

Search Unit  
 ID# 22-112    Type 5011 Camera    Length 22.6'  
 Freq 5 MHz    Size 22"    Angle 0 Mod/Leap

Search Unit Cable  
 Type 22-112    Initial: *JY*    Level: *II*  
 Initial: *MB*    Level: *NA*

Cal Standard  
 ID# 22-112    Size 22" Sch. 40  
 Thickness 5.5 1.5"    S/S 0.5"    Temp 72 °F

System Check  
 Exit Point    Date 1/11/93    Time 10:32 AM

Sweep Circuit  
 Coarse 2    Fine 4.5    Delay 0.362    Screen Depth 2"

Operational Settings  
 Frequency: 1011 100%    Normal 5 MHz  
 Reject: 1101 100%  
 Filter: 1101 100%  
 Damping: 1101 100%

Rep Rate: 280 Hz

Reflector	% FSH	Inches	% FSH	Inches	% FSH	Inches
1.0	82	1.0	82	1.0	82	1.0
1.5	82	1.5	82	1.5	82	1.5

Remarks:  
 Original calibration  
 Gate at 308 FSH  
 Refer to CAT Ribbon  
 onto sheet 92-070-26

Components Examined:  
 Drywell Line Bay 13

Thermometer  
 SN: 22-112    Cal Dia: 5.112

Graph: *[Graph showing amplitude vs distance]*

Initials: *[Signature]*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 98 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Sketch Form (with grid)

Component: DRY WELL LINEAR

Location: BAY 13

Drawing No: N/A Rev: N/A

Data Sheet No: 92-072-24-27

UT READING LOCATIONS	0°	45°	90°	135°
1	.330	.392	.346	.346
2	.312	.377	.360	.393
5	.150	.193	.230	.298
6	.327	.337	.290	.247
7	.241	.279	.260	.239
8	.324	.245	.267	.279
10	.186	.173	.255	.229
11	.240	.231	.271	.283
15	.289	.277	.239	.255

DEPTH MICROMETER USED GC-2-39  
VERIFIED ON BLOCK 219 & 207

TECHNIQUE USED TO DETERMINE DEPTH OF GROUND AREAS

Prepared by: [Signature]

Reviewed by: [Signature]

Title: VT LEVEL II Date: 1-11-93

Level: II Page 1 of 1 NDE Request No.: 92-072

Date: (-13-93)

GPU No

Subject

O.C. Drywel

Originator

Mark

*type in. etc. ?*

Ultrasonic Thickness Data Sheet

Subject

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 100 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

OC  TMI  OTHER

Component: DRYWELL liner Sandbed Area

Location: BAY # 15

Sketch Form (with grid)

Date Sheet No.: 92-072-30

Drawing No.: N/A Rev: NA

AREA	0°	45°	90°	135°
	.356	.350	.359	.282

*APPROX*

QC-2:39

0.335" (Checked by MIC. SHERMAN 1992)

Technique utilized for the PIT depth MEASUREMENTS

Prepared by: [Signature]

Reviewed by: [Signature]

Level: II

Date: 1-13-93

Page: 1 of 1

Date: 1/12/93

NDE Request No.: 92-072



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 101 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

**GPU Nuclear** Ultrasonic Thickness Data Sheet

OC  TMI-1  TMI-2 Class: *n/a* Item: *n/a* NDE Request: *92-072* Data Sheet No.: *92-072-01*

Test Description: *UT Thickness Measurements* Test No.: *n/a* Date: *12/31/92*

Comp. Desc.: *Drywell Area Bay 17* System: *187* Code/Spec: *ASME Sect. VIII*

Procedure/Rev.: *ASNT-501-7209.07* Drawing No./Rev.: *JE-197-29-101 Rev. 0*

Test Surface: *C.O.* Thickness: *1 1/8"* Material: *CS*

Examiner: *[Signature]* Print: *Jeanette Sanchez-Gudi* ID No.: *157-820210* Level: *II*

Examiner: *[Signature]* Print: *Mort F. Bagnell* ID No.: *553-81-1802* Level: *I*

Thermometer SN: *22-227* Part Temperature: *65 F* D-Meter SN: *152-113*

Cal. Bik. SN: *218* Cal. In: *2:10 AM* *n/a* PM

Cal. Bik. Temp: *60 F* Cal. Out: *2:15 AM* *n/a* PM

Techniques  
 CRT  D-Meter  
Other: *Sonic 1.2*

Cal. Bik.	0.5"	0.75"	1.0"	1.25"	1.5"	n/a
D-Meter	0.5"	0.75"	1.0"	1.25"	1.5"	n/a

Position #/Reading in Inches

Position #	Reading	Technique
1	0.30"	UT Measurement
2	0.12"	UT Measurement
3	0.22"	UT Measurement
4	0.52"	UT Measurement
5	0.25"	UT Measurement
6	0.52"	UT Measurement
7	0.28"	UT Measurement
8	0.52"	UT Measurement

Approximate position measurements  
D: Down, R: Right, C: Left

Number of readings indicated in brackets  
number at I.O. of Line.

Drawing

Reviewed by: *[Signature]* Date: *12-5-92* Page: *1* of *1*

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 102 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Ultrasonic Thickness Data Sheet																					
<input checked="" type="checkbox"/> GPU Nuclear	<input type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: <i>n/a</i>	Item: <i>n/a</i>	NDE Request: <i>92-072</i>	Data Sheet No: <i>92-072-04</i>	Test No.: <i>n/a</i>	Date: <i>12/14/92</i>												
Task Description: <i>UT Thickness</i>		Code/Spec.: <i>ASME Sect VIII</i>		Drawing No./Rev.: <i>32-187-29-C01 2/1/93</i>		Material: <i>C/S</i>															
Comp. Desc.: <i>Drywell Ext. Bay 17</i>		System: <i>187</i>		Drawing No./Rev.: <i>32-187-29-C01 2/1/93</i>		Material: <i>C/S</i>															
Procedure/Rev.: <i>K100 APP. 2109.07 Rev. 0</i>		Thickness: <i>1/8"</i>		ID No.: <i>132-63-518</i>		Level: <i>2</i>															
Test Surface: <i>C/O</i>		Printer: <i>Mark Yekta</i>		ID No.: <i>n/a</i>		Level: <i>n/a</i>															
Examiner Sign: <i>[Signature]</i>	Printer: <i>n/a</i>		Techniques		<input checked="" type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter <input type="checkbox"/> Other																
Examiner Sign: <i>[Signature]</i>	Printer: <i>n/a</i>		Thermometer S/N <i>92-032</i>		Calibration Readings (Inches)																
Part Temperature <i>52 F</i>		D-Meter S/N <i>22-122</i>		Cal. Blk. <i>.5</i>	<i>.25</i>	<i>.10</i>															
Cal. In: <i>n/a</i>		Cal. In: <i>n/a</i>		D-Meter <i>.5</i>	<i>.25</i>	<i>.10</i>															
Cal. Blk. Temp. <i>52 F</i>		Cal. Out: <i>n/a</i>		<table border="1"> <tr> <th>Cal. Blk.</th> <th>D-Meter</th> <th>Reading</th> </tr> <tr> <td><i>.5</i></td> <td><i>.5</i></td> <td><i>.10</i></td> </tr> <tr> <td><i>.25</i></td> <td><i>.25</i></td> <td><i>.10</i></td> </tr> </table>						Cal. Blk.	D-Meter	Reading	<i>.5</i>	<i>.5</i>	<i>.10</i>	<i>.25</i>	<i>.25</i>	<i>.10</i>			
Cal. Blk.	D-Meter	Reading																			
<i>.5</i>	<i>.5</i>	<i>.10</i>																			
<i>.25</i>	<i>.25</i>	<i>.10</i>																			
Position #/Reading in Inches		Drawing		<table border="1"> <tr> <th>Area</th> <th>Reading</th> <th>Thickness</th> </tr> <tr> <td><i>9</i></td> <td><i>0.25" K-30</i></td> <td><i>0.25"</i></td> </tr> <tr> <td><i>10</i></td> <td><i>0.25" K-11</i></td> <td><i>0.25"</i></td> </tr> <tr> <td><i>11</i></td> <td><i>0.25" K-12</i></td> <td><i>0.25"</i></td> </tr> </table>						Area	Reading	Thickness	<i>9</i>	<i>0.25" K-30</i>	<i>0.25"</i>	<i>10</i>	<i>0.25" K-11</i>	<i>0.25"</i>	<i>11</i>	<i>0.25" K-12</i>	<i>0.25"</i>
Area	Reading	Thickness																			
<i>9</i>	<i>0.25" K-30</i>	<i>0.25"</i>																			
<i>10</i>	<i>0.25" K-11</i>	<i>0.25"</i>																			
<i>11</i>	<i>0.25" K-12</i>	<i>0.25"</i>																			
Reviewed by: <i>[Signature]</i>		Level: <i>III</i>		Date: <i>12-14-92</i>		Page: <i>1</i> of <i>1</i>		MS-055 (Rev. 4/91)													

OCLR00014639

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 103 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

GPU Nuclear				Ultrasonic Thickness Data Sheet															
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: <i>NA</i>	Item: <i>NA</i>	NDE Request: <i>92-072</i>	Data Sheet No.: <i>92-072-04</i>													
Task Description: <i>WT Thickness</i>				Task No.: <i>NA</i>	Date: <i>12/10/92</i>														
Comp. Desc.: <i>Drywell Ext. Bay 17</i>				System: <i>187</i>	Code/Spec.: <i>ASME SA-7-111</i>														
Procedure/Rev.: <i>SA-7-111-1000-10</i>				Drawing No./Rev.: <i>JE-157-29-502-521-0</i>	Material: <i>SA-7-111</i>														
Test Surface: <i>C.O.</i>				Thickness: <i>1/8"</i>															
Examiner Sign: <i>[Signature]</i>	Print: <i>J. Chasch</i>	ID No.: <i>157-29-502</i>	Level: <i>II</i>																
Examiner Sign: <i>[Signature]</i>	Print: <i>NA</i>	ID No.: <i>NA</i>	Level: <i>NA</i>																
Thermometer S/N: <i>22-217</i> Part Temperature: <i>58.8</i> F				Techniques															
D-Meter S/N: <i>56</i> Cal. In: <i>NA</i> AM <i>1:01</i> PM				<input checked="" type="checkbox"/> CRT <input type="checkbox"/> D-Meter															
Cal. Blk. Temp.: <i>58</i> F				Other: _____															
Position of Reading in Inches				<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Cal. Blk.</th> <th>1.5"</th> <th>1.75"</th> <th>1.0"</th> <th>1.0"</th> <th>Other</th> </tr> <tr> <td>D-Meter</td> <td>5</td> <td>7.5</td> <td>10</td> <td>10</td> <td></td> </tr> </table>				Cal. Blk.	1.5"	1.75"	1.0"	1.0"	Other	D-Meter	5	7.5	10	10	
Cal. Blk.	1.5"	1.75"	1.0"	1.0"	Other														
D-Meter	5	7.5	10	10															
				<p style="text-align: center;">Drawing</p> <p><i>Thickness</i></p> <p><i>9 0.17" R 30"</i></p> <p><i>10 0.25" R 11"</i></p> <p><i>11 0.25" L 12"</i></p> <p><i>0.17"</i></p> <p><i>Performed after non-ferrous drilling</i></p> <p><i>Mean value used</i></p>															
								<p>Reviewed by: <i>[Signature]</i> Level: <i>III</i> Date: <i>12-14-92</i> Page: <i>1</i> of <i>1</i></p>											

N455 (05-87)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 104 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli		Date

Ultrasonic Thickness Data Sheet																																							
<input checked="" type="checkbox"/> Nuclear	Item: <i>N/A</i>	Item: <i>N/A</i>	Data Sheet No: <i>92-072-05</i>																																				
<input type="checkbox"/> OG <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2 Class: <i>N/A</i>	Task Description: <i>UT Thickness Measurements</i>	Task No: <i>N/A</i>	Date: <i>12/11/92</i>																																				
Comp. Desc.: <i>Drywell Ext. Ex 1197</i>	System: <i>187</i>	Code/Spec: <i>ASME Sect. I</i>																																					
Procedure/Rev: <i>6100 OAP 7209.07 P.1.0</i>	Drawing No./Rev: <i>3E-187-29-001 Rev. 0</i>	Material: <i>L/S</i>																																					
Test Surface: <i>0.0</i>	Thickness: <i>1.8"</i>																																						
Examiner Sign: <i>[Signature]</i>	Print: <i>Jonathan Vuchelinski</i>	ID No: <i>134-48-0318</i>	Level: <i>II</i>																																				
Examiner Sign: <i>[Signature]</i>	Print: <i>MARK F. RAGNELL</i>	ID No: <i>551-81-1512</i>	Level: <i>I</i>																																				
Thermometer <i>SN 22-012</i> Part Temperature <i>21.6</i> D-Meter <i>SN 24-012</i>	Cal. In: <i>10:45 AM</i>	Cal. Out: <i>1:21 PM</i>																																					
Cal. Blk. <i>SN 88</i>	Cal. In: <i>7.2</i>	Cal. Out: <i>F</i>																																					
Cal. Blk. Temp. <i>72</i>	Position #/Reading in inches																																						
Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter <input type="checkbox"/> Other																																							
Calibration Readings (Inches)																																							
Cal. Blk. <i>0.5"</i>	<i>0.75"</i>	<i>1.0"</i>	<i>1.0"</i>																																				
D-Meter <i>0.5"</i>	<i>0.71"</i>	<i>1.0"</i>	<i>1.0"</i>																																				
Drawing																																							
<table border="1"> <thead> <tr> <th>Area</th> <th>Position</th> <th>Thickness</th> </tr> </thead> <tbody> <tr><td>1</td><td>0.10</td><td>0.98</td></tr> <tr><td>2</td><td>0.12</td><td>1.15</td></tr> <tr><td>3</td><td>0.38</td><td>0.898</td></tr> <tr><td>4</td><td>0.52</td><td>0.951</td></tr> <tr><td>5</td><td>0.76</td><td>0.913</td></tr> <tr><td>6</td><td>0.52</td><td>0.992</td></tr> <tr><td>7</td><td>0.76</td><td>0.97</td></tr> <tr><td>8</td><td>0.52</td><td>0.98</td></tr> <tr><td>9</td><td>0.27</td><td>0.83</td></tr> <tr><td>10</td><td>0.24</td><td>0.845</td></tr> <tr><td>11</td><td>0.21</td><td>0.767</td></tr> </tbody> </table>				Area	Position	Thickness	1	0.10	0.98	2	0.12	1.15	3	0.38	0.898	4	0.52	0.951	5	0.76	0.913	6	0.52	0.992	7	0.76	0.97	8	0.52	0.98	9	0.27	0.83	10	0.24	0.845	11	0.21	0.767
Area	Position	Thickness																																					
1	0.10	0.98																																					
2	0.12	1.15																																					
3	0.38	0.898																																					
4	0.52	0.951																																					
5	0.76	0.913																																					
6	0.52	0.992																																					
7	0.76	0.97																																					
8	0.52	0.98																																					
9	0.27	0.83																																					
10	0.24	0.845																																					
11	0.21	0.767																																					
Reviewed by: <i>[Signature]</i> Date: <i>12-16-92</i> Page <i>1</i> of <i>1</i>																																							

HS435 (02-92)

# GPU Nuclear


Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc. No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 105 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

## Sketch Form (with grid)

OC  TMI  OTHER

Component: DRYWELL liner Sandbed Area  
 Location: BAY # 17  
 Date Sheet No.: 92-072-29  
 Drawing No.: N/A  
 Rev.: N/A

Drawing



Prepared by: [Signature]  
 Reviewed by: [Signature]  
 Title: VT LV II  
 Date: 1-13-93  
 Page: 1 of 1  
 Level: II  
 NDE Request No.: 92-072  
 Date: 1/12/93

FORM 1130-04P-7200-0817243

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 106 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

all done 01/22

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear	<input type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: <i>nd</i>	Item: <i>nd</i>	NDE Request: <i>92-172</i>	Data Sheet No.: <i>92-072-02</i>
Task Description: <i>UT Thickness</i>				Task No.: <i>nd</i>		Date: <i>12/15/92</i>	
Comp. Desc.: <i>OPERA LINE BAY 19</i>				System: <i>187</i>		Code/Spec: <i>ASME Sec. II</i>	
Procedure/Rev.: <i>6100-RNA-7209.07 Rev. 0</i>				Drawing No./Rev.: <i>36-187-29-001 Rev. 0</i>		Material: <i>CS</i>	
Test Surface: <i>O.C.</i>				Thickness: <i>1/8"</i>		ID No.: <i>154-10-011</i> Level: <i>I</i>	
Examiner Sign: <i>[Signature]</i>				Print: <i>JONATHAN JACOB LINDA</i>		ID No.: <i>551-81-1802</i> Level: <i>I</i>	
Examiner Sign: <i>[Signature]</i>				Print: <i>MICHEL F. BAGNEL</i>		Techniques	
Thermometer SN <i>21-272</i> Part Temperature <i>66.5</i> F				D-Meter SN <i>132-113</i>		Calibration Readings (Inches)	
Cat. Blk. SN <i>212</i>				Cat. In: <i>12:22 AM</i> <i>nd</i> PM		Cat. Blk. Temp. <i>68</i> F	
Cat. Blk. Temp. <i>68</i> F				Cat. Out: <i>12:36 AM</i> <i>nd</i> PM		<input checked="" type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter Other <i>Sonic 232</i>	

Position #/Reading in Inches

Cal. Blk.	0.5	0.75	1.0	1.25	1.5
D-Meter	0.5	0.75	1.0	1.25	1.5

Small 2.0 AREA  
 21 plug locations  
 12/15/92  
 NEW 12/16/92

BAY #19

Position measurements are approximately  
 uniform throughout the fraction indicated  
 a uniform surface at the T.O. of Liner

UT Measurement  
 0.71  
 0.96  
 0.78  
 0.99  
 0.85  
 0.86  
 0.83

Reviewed by: *[Signature]* Level: *III*

Date: *12-5-92* Page: *1* of *1*

MS453 05-90

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 107 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> OC <input type="checkbox"/> TMI-1 <input type="checkbox"/> TMI-2		Class: <i>N6</i>	Item: <i>N6</i>	NDE Request: <i>92-C-72</i>	Data Sheet No.: <i>92-072-03</i>
Task Description: <i>UT Thickness</i>		System: <i>187</i>		Code/Spec.: <i>ASME Sect III</i>	Date: <i>12/11/92</i>
Comp. Desc.: <i>Drywell Ext. 22.252</i>		Drawing No./Rev.: <i>35-187-29.001, 01.0</i>		Material: <i>CS</i>	
Procedure/Rev.: <i>ASME Sect III</i>		Thickness: <i>1/8"</i>		ID No.: <i>134-50-03.9</i>	Level: <i>II</i>
Test Surface: <i>010</i>	Examiner Sign: <i>[Signature]</i>	Print: <i>N6</i>	ID No.: <i>N6</i>	Level: <i>N6</i>	
Thermometer S/N: <i>22.252</i>	Part Temperature: <i>65.5 F</i>	D-Meter S/N: <i>232-23</i>	Techniques <input checked="" type="checkbox"/> CRT <input type="checkbox"/> D-Meter		
Cal. Bik. S/N: <i>53</i>	Cal. In: <i>1.31 AM</i>	Cal. Out: <i>2.02 PM</i>	Other: _____		
Cal. Bik. Temp.: <i>66 F</i>	Position #/Reading in Inches				

Cal. Bik. .5" .75" .10

D-Meter .5" .75" .10

Techniques  
 CRT  D-Meter

Other: \_\_\_\_\_

Thermometer S/N: *22.252* Part Temperature: *65.5 F* D-Meter S/N: *232-23*

Cal. Bik. S/N: *53* Cal. In: *1.31 AM* Cal. Out: *2.02 PM*

Cal. Bik. Temp.: *66 F*

Position #/Reading in Inches

Position #	Reading (inches)
1	0.125
2	0.125
3	0.125
4	0.125
5	0.125
6	0.125
7	0.125
8	0.125
9	0.125
10	0.125

Reviewed by: *[Signature]* Level: *III* Date: *12-16-92* Page *1* of *1*





# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 109 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

### Ultrasonic Thickness Data Sheet

<input checked="" type="checkbox"/> Nuclear	Item: N/A	NDE Request: Q12-072	Data Sheet No.: 93-072-07
<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: N/A	Task No.: N/A
Task Description: U.T. THICKNESS		Code/Spec.: ASME SEC VIII	Date: 12 11 92
Comp. Desc.: DRYWELL LINEA BAY 19		Drawing No./Rev.: 3E 181-27 (C) REV 0	
Procedure/Rev.: GILCO - GAP 7201 07 REV 0		Thickness: 1/8"	Material: C-15
Test Surface: O.D.		ID No.: 19-18-0219	Level: J
Examiner Sign: <i>[Signature]</i>	Print: Jonathan Undercube	ID No.: 553-51-1802	Level: J
Examiner Sign: <i>[Signature]</i>	Print: MARK F BAGWELL		
Thermometer S/N R 1-057 Part Temperature 72° F		Techniques <input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter Other: N/A	
Cal. Blk. S/N E.S.	Cal. Inc. N/A AM 12:45 PM	Cal. Blk. Temp. 72° F	Cal. Blk. O-Meter 0.5
Position #/Reading in Inches		Cal. Blk. D-Meter 0.75	Cal. Blk. O-Meter 1.0
		Cal. Blk. D-Meter 0.75	Cal. Blk. O-Meter 1.0

AREA	POSITION	MEASUREMENT
1	R 70	0.122
2	R 80	0.124
3	R 90	0.155
4	R 11	0.140
5	R 2	0.150
6	L 6	0.180
7	L 12	0.170
8	R 10	0.180
9	S 12	0.180
10	R 0	0.180
11	R 6	0.210
12	R 12	0.210
13	R 18	0.210
14	R 24	0.210
15	R 30	0.210

Drawing

Reviewed by: *[Signature]* Date: 12-16-92 Page 1 of 1



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 111 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

3-10C 117MI

**Calibration Sheet**

System: 187    Component: 187    Procedure: ASNT - SAFT - 500.1.1    Rev: 1.0

Examiner: Signature: [Signature]    Initial: MY    Level: 1

Examiner: Signature: [Signature]    Initial: MB    Level: 1

Instrument Settings  
 ID# 187  
 Model/Manuf DL 25 - PANAMETRICS  
 Gain Coarse 11A  
 Fine 11A  
 Uncal. 11A

Search Unit  
 ID# 22-020  
 Type 2.75" x 2.75"    MHz 5  
 Freq. 5  
 Size 5  
 Angle Mode 1

Search Unit Cable  
 Type 2.75" x 2.75"    Length 2.5'

Couplant  
 Make Sawdust    Batch# 52-82-1-1-1

Thermometer  
 SN: 27-2353    Cal Due 1-9-93

Cal Standard  
 ID# 8  
 Size 1/2" Sch. 40  
 Thickness 3.0 x 10  
 S/S CS  
 Temp 22 °F

System Check  
 Exit Point  
 Angle ±1 - 2

Date: 12/11/92    Time: 11:45

Reflector	Amplitude % of FSH	Screen Reading in inches
5	11A	1.15
10	11A	1.25
15	11A	1.35
20	11A	1.45
25	11A	1.55
30	11A	1.65
35	11A	1.75
40	11A	1.85
45	11A	1.95
50	11A	2.05
55	11A	2.15
60	11A	2.25
65	11A	2.35
70	11A	2.45
75	11A	2.55
80	11A	2.65
85	11A	2.75
90	11A	2.85
95	11A	2.95
100	11A	3.05

Remarks:  
 12.5" 12/11/92    1245' 12/11/92    1315' 12/11/92

Time/Date: 12.5" 12/11/92    % FSH: 11A    inches: 1.15

Reflector: 5    % FSH: 11A    inches: 1.15

Reflector: 10    % FSH: 11A    inches: 1.25

Reflector: 15    % FSH: 11A    inches: 1.35

Reflector: 20    % FSH: 11A    inches: 1.45

Reflector: 25    % FSH: 11A    inches: 1.55

Reflector: 30    % FSH: 11A    inches: 1.65

Reflector: 35    % FSH: 11A    inches: 1.75

Reflector: 40    % FSH: 11A    inches: 1.85

Reflector: 45    % FSH: 11A    inches: 1.95

Reflector: 50    % FSH: 11A    inches: 2.05

Reflector: 55    % FSH: 11A    inches: 2.15

Reflector: 60    % FSH: 11A    inches: 2.25

Reflector: 65    % FSH: 11A    inches: 2.35

Reflector: 70    % FSH: 11A    inches: 2.45

Reflector: 75    % FSH: 11A    inches: 2.55

Reflector: 80    % FSH: 11A    inches: 2.65

Reflector: 85    % FSH: 11A    inches: 2.75

Reflector: 90    % FSH: 11A    inches: 2.85

Reflector: 95    % FSH: 11A    inches: 2.95

Reflector: 100    % FSH: 11A    inches: 3.05

Rep Rate: 11A

Initials: [Signature]

Components Examined: 24 17-18

Technical Review  
 Reviewed By: [Signature]    Date: 12-14-92

NDE Request#: 92-072

N9927 (R13 90)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 112 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

11DC 11TMI

Cal Sheet 147512

## Calibration Sheet

System 187	Component Drywell liner	Procedure EUC-DAP 7209 07	Rev 0
Examiner: Signature: <i>[Signature]</i>	Print: <i>J. Yekta</i>	Search Unit ID# <i>92-010</i> Type <i>2.25 Sch 40</i> Freq <i>5</i> MHz Size <i>0.25</i> Angle <i>0</i> Mode <i>22</i>	Level Level <i>II</i> Level <i>II</i>
Examiner: Signature: <i>[Signature]</i>	Print: <i>[Signature]</i>	Cal Standard ID# <i>83</i> Size <i>1/8</i> Sch <i>40</i> Thickness <i>0.10</i> SS <i>CS</i> Temp <i>62</i> °F	Level Level <i>II</i> Level <i>II</i>
Instrument Settings ID# <i>92-010</i>	Model/Manuf <i>DL-26</i>	System Check <input type="checkbox"/> Exit Point <input type="checkbox"/> Angle <i>±1-2</i> °	Search Unit Cable Type <i>2.25 Sch 40</i> Length <i>2.5</i>
Gain Coarse <i>40</i> Fine <i>40</i> Uncal <i>40</i>	Sweep Circuit Coarse (Range) Fine <i>40</i> Delay <i>40</i> Screen Depth <i>40</i>	Date <i>12/14/92</i>	Couplant Make <i>Essex</i> Batch <i>52-11-12</i>
Operating (G&P) Frequency: <i>5</i> Normal MHz Reject: <i>10</i> <input type="checkbox"/> On % Filter: <i>10</i> <input type="checkbox"/> On % Damping: <i>10</i> <input type="checkbox"/> On %	Rep Rate: <i>40</i>	Time <i>1305</i>	Thermometer SN: <i>82-057</i> Cal Due <i>5-24-93</i>
Time/Date Reflector	% FSH	Inches	100%
5	40	0.5	90
7.5	40	0.75	80
10	40	1.0	70
13.25	40	1.25	60
13.99	40	1.4	50
14.05	40	1.4	40
14.1	40	1.4	30
14.15	40	1.4	20
14.2	40	1.4	10

Remarks:

Time/Date	% FSH	Inches
5	40	0.5
7.5	40	0.75
10	40	1.0
13.25	40	1.25
13.99	40	1.4
14.05	40	1.4
14.1	40	1.4
14.15	40	1.4
14.2	40	1.4

Components Examined:  
*04 17019*

ANN Review

Technical Review  
Reviewed By *[Signature]*  
Level  
Date *12-16-92*  
NDE Request# *92-077*

NP27 (6-90)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 113 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

MOC 111M

**Calibration Sheet**

System: 187      Component: Drywell Lines      Procedure: SMO - G.M. 720907      Rev: 0

Examiner: Signature: *[Signature]*      Initial: *MY*      Level: *II*

Examiner: Signature: *[Signature]*      Initial: *MY*      Level: *II*

Instrument Settings  
ID# *417-113*  
Model/Manuf. *SONIX 137 STRELL*

Gain  
Coarse *60.2*  
Fine *1.5*  
Uncal *1.5*

Sweep Circuit  
Coarse *2.0" (cal 0.23162) (Range)*  
Fine *1.0*  
Delay *1.0*  
Screen Depth *2*

Operation  
Frequency: *2.25* Normal MHz  
Reflect: *1:0H 1:0h* %  
Filter: *1:0H 1:0h* %  
Damping: *1:0H 1:0h* %

Rep Rate: *1000 Hz*

Cal Standard  
ID# *82*  
Size *1/2* Sch. *2*  
Thickness *5.5-1.0*  
S/S *CP*  
Temp *68* °F

System Check  
 Ext Point  
 Angle *1.2* *1.4*

Date: *12/14/92*

Search Unit  
ID# *000022*  
Type *PROBE*  
Freq *2* MHz  
Size *1/2*  
Angle *0* Mode *Comp*

Cal Direction  
 Axial  
 Circ.  
 Normal

Time: *1:00*

Search Unit Cable  
Type *Dist. Cnd*  
Length: *3.05'*

Couplant  
Make *Sonotek*      Batch# *100-82-102*

Thermometer  
S/N: *82-852*      Cal Due: *5-24-93*

100% DAC Plot

Amplitude % of FSH in Inches

Reflector	Amplitude % of FSH	Screen Reading in Inches
1	80	5
2	80	7.5
3	80	10

Remarks:  
*x calibration maintained at 80% AM*

Technical Review  
Reviewed By: *[Signature]*  
Level: *III*      Date: *12-16-92*

NDE Request#: *92-012*

Components Examined:  
*dry 17019*

Initials: *MY*

NY927 (05-90)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 114 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Ultrasonic Thickness Data Sheet											
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TM-1	<input type="checkbox"/> TM-2	Class: <i>nh</i>	Item: <i>nh</i>	NDE Request: <i>92-072</i>	Data Sheet No.: <i>92-072-11</i>					
Task Description: <i>DRY WALL LINER MOCK-UP</i>				Task No.: <i>nh</i>	Code/Spec: <i>ASME SECT VIII</i>		Date: <i>12-16-92</i>				
Comp. Desc.: <i>WELD OVERLAY TEST PLATE</i>				System: <i>187</i>	Drawing No./Rev: <i>-NA-</i>		Material: <i>C/S</i>				
Procedure/Rev.: <i>6100 - GAP - 7209.07 / 0</i>				Thickness: <i>3/4"</i>	ID No.: <i>154-480319</i>		Level: <i>I</i>				
Test Surface: <i>OD</i>				Printer: <i>J. Cavallaro Link</i>	ID No.: <i>462277035</i>		Level: <i>I</i>				
Examiner	Sign: <i>[Signature]</i>	Printer: <i>JAMES PHILIPPI</i>		Calibration Readings (Inches)		Techniques					
Examiner	Sign: <i>[Signature]</i>	Printer: <i>[Signature]</i>		Cal. Blk. .502	.752	1.001	1.251	<input type="checkbox"/> CRT	<input checked="" type="checkbox"/> D-Meter		
Thermometer S/N <i>52-063</i> Pan Temperature <i>68° F</i> D-Meter S/N <i>52-010</i>				Cal. Blk. S/N <i>214</i>	Cal. In: <i>NA</i>	AM <i>14:20</i>	PM	Other: <i>-NA-</i>			
Cal. Blk. Temp. <i>68° F</i>				Cal. Out: <i>NA</i>	AM <i>14:40</i>	PM	Position #/Reading in Inches				
Reviewed by: <i>[Signature]</i>				Level: <i>III</i>	Date: <i>12-27-92</i>		Page: <i>1</i>	of <i>1</i>			

Position #/Reading in Inches	Cal. Blk.	D-Meter	Technique
AISEAN	.73	.728	26 DL
BASE METAL	.94	.927	
1 PASS	1.12	1.114	
2 PASS			

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 115 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Ultrasonic Thickness Data Sheet																																	
<input checked="" type="checkbox"/> OC	<input type="checkbox"/> TMI-1	<input type="checkbox"/> TMI-2	Class: <i>NA</i>	Item: <i>NA</i>	MDE Request: <i>92-028</i>	Data Sheet No.: <i>92028-11</i>																											
Task Description: <i>DRY WALL LINER MOCK-UP</i>				Task No.: <i>NA</i>	Date: <i>12.16.92</i>																												
Comp. Desc.: <i>WELD OVERLAY TEST PLATE</i>				System: <i>187</i>	Code/Spec.: <i>ASME SECT VIII</i>																												
Procedure/Rev.: <i>6100 - GAP - 720F.07 / 0</i>				Drawing No./Rev.: <i>34</i>	Material: <i>C/S</i>																												
Test Surface: <i>OD</i>				Thickness: <i>3/4"</i>	ID No.: <i>54405031</i>	Level: <i>I</i>																											
Examiner Sign: <i>[Signature]</i>	Print: <i>J. Charles Lipp</i>				ID No.: <i>46237035</i>	Level: <i>I</i>																											
Examiner Sign: <i>[Signature]</i>	Print: <i>JAMES PHILLIPS</i>																																
Thermometer S/N: <i>67-063</i> Part Temperature: <i>66° F</i> D-Meter S/N: <i>92-010</i>				Techniques																													
Cal. Bik. S/N: <i>214</i> Cal. In: <i>NA</i> AM <i>12:30 PM</i>				<input type="checkbox"/> CRT <input checked="" type="checkbox"/> D-Meter																													
Cal. Bik. Temp: <i>68° F</i> Cal. Out: <i>NA</i> AM <i>12:40 PM</i>				Other: <i>NA</i>																													
Position #/Reading in Inches																																	
Drawing																																	
<table border="1"> <thead> <tr> <th>Cal. Bik.</th> <th>.502</th> <th>.752</th> <th>1.001</th> <th>1.251</th> <th></th> <th></th> <th></th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td>D-Meter</td> <td>.502</td> <td>.751</td> <td>1.000</td> <td>1.250</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>										Cal. Bik.	.502	.752	1.001	1.251						D-Meter	.502	.751	1.000	1.250									
Cal. Bik.	.502	.752	1.001	1.251																													
D-Meter	.502	.751	1.000	1.250																													
<table border="1"> <thead> <tr> <th>Position #</th> <th>Reading</th> <th>Notes</th> </tr> </thead> <tbody> <tr> <td>BASE METAL</td> <td>.73</td> <td></td> </tr> <tr> <td>1 PASS</td> <td>.94</td> <td></td> </tr> <tr> <td>2 PASS</td> <td>1.12</td> <td></td> </tr> <tr> <td>AISEAN</td> <td>26 DL</td> <td></td> </tr> <tr> <td></td> <td>.72</td> <td></td> </tr> <tr> <td></td> <td>.927</td> <td></td> </tr> <tr> <td></td> <td>1.114</td> <td></td> </tr> </tbody> </table>										Position #	Reading	Notes	BASE METAL	.73		1 PASS	.94		2 PASS	1.12		AISEAN	26 DL			.72			.927			1.114	
Position #	Reading	Notes																															
BASE METAL	.73																																
1 PASS	.94																																
2 PASS	1.12																																
AISEAN	26 DL																																
	.72																																
	.927																																
	1.114																																
Reviewed by: <i>[Signature]</i>	Level: <i>III</i>	Date: <i>12-27-92</i>	Page: <i>1</i> of <i>1</i>																														

HS555 (02-93)

# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed	Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 116 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Turminelli	Date

1700 117MM

Calibration Sheet

Cal Sheets 144-072

Procedure: 6100-GAP-7209.07 Rev. 0

Component: DRYWELL LIVER

Print: J. Canabek Linda

Print: JAMES PHILLIPPI

Search Unit: Search Unit Cable

Type: DASH Limp Length: 2 x 6'

Couplant: Make SANDERACE Batch: SYP-89-1-02

Thermometer: SIN: 92-063 Cal Due: 5-24-93

Cal Standard: ID# 214 Sch. 2A

Type: 2A

Thickness: 5-132

SIS: 6.8

Temp: 602 AB

System Check:  Exit Point A  Angle +1.2

Cal Direction:  Axial  Circ.  Normal

Time: 1410

Screen Reading: in inches

Reflector	Amplitude % of FSH	Screen Reading in inches
5	80	5
7.5	80	7.5
1.0	80	1.0
1.25	80	1.25

Date: 12-16-92

System Settings

ID# 187

Model/Manuf: SEMTE 137 / STAVELLEY

Gain: Coarse 602 AB Fine N/A

Sweep Circuit: 2.0" (VEL-2.31 2.41 Range)

Coarse N/A Fine N/A

Delay: 1.0

Screen Depth: 2

Operation: T&R Normal

Frequency: 2.25 MHz

Reflect: XOff 10On N/A

Filter: 10Off 10On FIAT 1

Damping: 10Off 10On 100.0

Rep Rate:

Time/Date	% FSH	Inches	% FSH	Inches	% FSH	Inches
1415 12-16-92	80	5	80	5	80	5
1425 12-16-92	80	7.5	80	7.5	80	7.5
	80	1.0	80	1.0	80	1.0
	80	1.25	80	1.25	80	1.25

Remarks:

Technical Review: [Signature] Date: 12-17-92

Reviewed By: [Signature] Level: [Signature]

NDE Request #: 92-072

Components Examined: Opposite Lines with overlay for table

Initials: [Signature]

140927 105-901



# GPU Nuclear

Subject O.C. Drywell Ext. UT Evaluation in Sandbed		Calc No. C-1302-187-5320-024	Rev. No. 1	Sheet No. 117 of 117
Originator Mark Yekta	Date 01/12/93	Reviewed by S. C. Tumminelli		Date

Examiner: *James Phillipi*      Signature: *James Phillipi*      Print: **JAMES PHILIPPI**      Initial: **JP**      ID# **462277033**      Level **I**

Instrument Settings: ID# **92-010**      Model/Manuf **DL-25**      PANAMETRICS

Gain: Coarse **N/A**      Fine **N/A**      Uncal **N/A**

Sweep Circuit: Coarse **N/A**      Fine **N/A**      (Range)

Delay: **N/A**

Screen Depth: **N/A**

Operation: T&R **Normal**      Frequency: **N/A**      MHz      Reject: **N/A**      %      Filter: **N/A**      %      Damping: **N/A**      %

Rep Rate: **N/A**

Cal Standard: ID# **214**      Size **N/A**      Sch. **N/A**      Thickness **5-7.5**      MHz      S/S **N/A**      Temp **68**      °F

Search Unit: ID# **92-032**      Type **D.792.60**      Freq **5**      MHz      Size **3/2**      Angle **0**      Mode **Low**

System Check:  Exit Point **A**       Angle **+1-2**

Cal Direction:  Axial       Circ.       Normal

Date: **12-16-92**      Time: **1412**

Reflector: **2.3**      Amplitude % of FSH **N/A**      Screen Reading in Inches **N/A**

Reflector: **1.0**      Amplitude % of FSH **N/A**      Screen Reading in Inches **N/A**

Reflector: **1.25**      Amplitude % of FSH **N/A**      Screen Reading in Inches **N/A**

Time/Date: **1420**      **12-16-92**      **1440**      **12-16-92**

Reflector	% FSH	Inches	% FSH	Inches	% FSH	Inches
<b>5</b>	<b>N/A</b>	<b>1.5</b>	<b>N/A</b>	<b>1.5</b>	<b>N/A</b>	<b>1.5</b>
<b>7.5</b>	<b>N/A</b>	<b>1.75</b>	<b>N/A</b>	<b>1.75</b>	<b>N/A</b>	<b>1.75</b>
<b>1.0</b>	<b>N/A</b>	<b>1.0</b>	<b>N/A</b>	<b>1.0</b>	<b>N/A</b>	<b>1.0</b>
<b>1.25</b>	<b>N/A</b>	<b>1.25</b>	<b>N/A</b>	<b>1.25</b>	<b>N/A</b>	<b>1.25</b>

Remarks: **Components Examined: Drywell Ext. weld overlay Test plate**

Search Unit Cable: Type **SCALE CONSTANT**      Length **2 x 6'**

Couplant: Melt **SANDSAFE**      Batch **SSP-89-1-02**

Thermometer: SN **92-063**      Cal Due **5-24-93**

100% DAC Plot

Reviewed By: *[Signature]*      Level: **Level I      Date: **12-22-92****

Technical Review: *[Signature]*

NDE Request: **92-072**

NO927 (05-90)

Passport 00546049 07

(AR A2152754 E09)

Page 1 of 10

**Reason For Evaluation: Water Found in Drywell Trench 5 - UT Data Evaluation**

During the 1R21 Refueling Outage, standing water was found in the trench at elevation 10' 3" in Bay 5 of the Drywell. The purpose of this technical evaluation is to develop a conservative approach to address the worst case concerns associated with the as-found water in the drywell concrete. This evaluation will assess the condition through comparisons of the original UT data taken in 1986, and the UT data taken during the 1R21 outage. Note that the sand and water corrosive environment was removed from the sandbed region in 1992. This evaluation will evaluate these UT results as they relate to potential corrosion concerns based on the current plant configuration with water existing in the drywell concrete area. This evaluation will address immediate concerns in the as-found wetted area of the drywell shell to demonstrate adequate design margins exist (in a worst-case scenario) to support startup of the plant and operation of the plant through the next cycle of operation. The complete assessment of all UT data taken in 1R21 and establishing the associated margins to support operating through the period of extended operation of the plant will be addressed separately.

This Tech Eval was developed in accordance with CC-AA-309-101 Revision 7.

The development of this Tech Eval was reviewed with Howie Ray in accordance with HU-AA-1212. The risk rank was assessed as a "2". Therefore a third party review will be performed.

**Background:**

In 1986 concrete was removed in two locations (one each in Bays 5 and 17) from the interior Drywell floor at elevation 10' 3". Approximately a 1 foot wide by 2 foot long section was removed at each location. These areas have been commonly referenced to as the "trenches". The purpose of the "trenches" was to expose the Drywell Vessel below the concrete inside the Drywell at elevation 10' 3" so that UT readings could be performed on the vessel.

The bottom of trenches in Bay 5 and 17 are located at approximately elevation 8' 9" and 9' 3" respectively, which generally correspond to the elevation of the sandbed floor located outside the Drywell. Therefore the UT readings from the original trench areas correspond to sections of the vessel that are not embedded in outside concrete. The results of these UT inspections were documented in TDR 851 and drawing 3E-SK-S-85. UT readings were taken on 1 inch centers. The results of the 1986 UT inspections show drywell thicknesses which are indicative of the vessel embedded on the inside of the Drywell and exposed to the sand environment on the outside, which was eventually eliminated in 1992 when the sand was removed from the sandbed region.

In 1992, following the removal of the sand from the sandbed region and the removal of corrosion byproducts, the Drywell Vessel was visually inspected from inside the sandbed, which is outside the Drywell Vessel. This inspection identified the thinnest locations in each of the 10 sandbed bays. These thinnest locations were then UT inspected. In some

cases the area had to be slightly grinded so that the UT probe could rest flat against the surface of the vessel. The thickness values and the locations of each reading, referenced from existing welds, were recorded on a series of NDE data sheets. At each location one UT reading was performed.

In 2006, UT readings of the interior Drywell shell were again recorded on 1 inch centers in the two trenches. These readings were intended for a comparison with the 1986 readings.

Also in 2006, 106 readings were taken of the external portion of the Drywell Vessel from within the former sandbed region. These locations were located using the 1992 NDE Inspection Data Sheet maps. These readings were intended for a comparison with the 1992 readings.

Additionally, during the 1R21 outage in 2006 more concrete was removed from the bottom of the trench in Bay 5 to expose an additional 6" by 12" section of the drywell vessel. This newly exposed section of the vessel lies below the sandbed floor on the outside of the drywell. Therefore the results of this inspection show drywell thicknesses that are indicative of the vessel that is embedded on both sides by concrete.

#### Detailed Evaluation:

#### Assumptions and Clarifications

1) TDR 851 documents that values initially recorded using "D" meter UT instrumentation in the Bay 5 trench in 1986 were much less than nominal.

In order to rule out that these readings did not indicate small or pin-point corrosion cells additional NDE investigations were performed in 1986 by GPUN and EPRI NDE personnel. The investigations revealed that the low readings were due to small inclusions in the steel plate rather than thin steel. This was later confirmed by the removal of a 2" diameter section of the Drywell Vessel, which contained an inclusion. Lab analysis of the inclusion characterized it as an "aluminide stringer" at the mid-wall plane of the plate parallel to the rolling direction (reference TDR 854). The conclusions of this investigation were also reviewed by the NRC in an SER (dated December 29, 1986, Docket No.50-219) and found to be acceptable.

However the actual readings were captured in Drawing 3E-SK-S-85.

Inclusions of this nature and size are acceptable in the manufacturing process of carbon steel plates and do not effect the ultimate strength of the plates,

If Oyster Creek were to perform an inspection of this plate for unacceptable indications then ASME Section III sub-section NB 2532 (2004) would provide acceptance criteria for indications as identified by UT inspection.

Subsection NB 2532 provides acceptance criteria as follows:

- 1) Any area where one or more imperfections produce continuous total loss of back reflection accompanied by continuous indications on the same plane that cannot be encompassed with a circle whose diameter is 3 inches or one half the plate thicknesses, whichever is greater is unacceptable.
- 2) In addition two or more imperfections smaller than described in 1 above shall be unacceptable unless separated by a minimum distance equal to the greatest diameter of the largest imperfection, or unless they may be collectively encompassed by the circle described in (1) above

The ultrasonic equipment (Panametrics 37DL) used during 1R21 displays both a "digital thickness readout" and an "A" scan presentation. Small inclusions whether gas or non-metallic that are flattened during the rolling process create perfect sound reflectors in plate. The "A" scan presentation gives the operator the ability to distinguish between non-relevant signals and true thickness readings. It also gives the operator the ability to adjust the appropriate signal (the one representing the full thickness) either by increasing or decreasing the gain to change the signal amplitude or by using a feature called "extended blank" which basically tells the machine not to record readings in a certain area. These adjustments are made so the correct reading can be obtained from the controlled storage module of the instrumentation database.

A review of the 1R21 data taken in the Bay 5 trench shows that the operator made several adjustments to both the gain and the extended blank.

In addition, had any of the inclusions been large enough to block the ultrasonic signal a reading would not have been recorded. No such readings were observed in 1R21. The inspection performed on the Bay 5 Trench during 1R21 was for thickness only, however the fact that we were able to get sound to penetrate through the entire thickness demonstrates that no area contained inclusions larger than the diameter of the transducer (0.438"). This would not have been the case due to the different technology used in 1986. Therefore using the ASME Section III guidance for the 1986 and 2006 inspection led to the following conclusions.

In 2006 all readings located on 1 inch centers were successfully obtained and back reflection were achieved on all readings. Therefore based on the size of the UT transducer no imperfections were detected, which approach 0.438 inches in diameter.

UT readings were collected on 1 inch centers with a UT transducer with a head size of 0.438 inches in diameter. Therefore the largest linear distance in the inspection area that would not have been scanned is approximately 0.976 inches, which is diagonal distance between two adjoining inspection points. Therefore any potential laminations approaching 1" in diameter would have been identified by the inspection and were not.

However oblong indications of up to 0.562 inches wide and that exceed 3" in length and are parallel to the grid pattern may not have been observed.

The existence of unacceptable indications is not considered credible for the following reasons:

- 1) The 1986 data shows that no three continuous 1 inch grid locations had indications of inclusions.
- 2) The indication would have to be oblong and parallel to the grid pattern.
- 3) Any inclusions or indications would have occurred in the manufacturing process randomly with respect to the location on the plate. Therefore, since 1986 and 2006 thickness readings are normally distributed (see attachment 2), it can be concluded with 95% confidence that the true condition of the plate is known in 2006.

Therefore for the purpose of this evaluation, all readings found to be lower than 0.780 inches were discounted from the 1986 readings for the trench in Bay 17. Also the 2006 data showed no similar readings (less than 0.780) in the lower 5 grids. The discounted readings are circled in attachment 1. Note that this treatment of the 1986 data is actually conservative for computing corrosion rate if they were compared to the 2006 data, because the 1986 values (if included) would have reduced the 1986 average thickness.

2) The uncertainties of the 1986, 1992, and 2006 UT readings can be as great as +/- .020 inches based on:

- a) The roughness of the inspected surfaces due to the previously corroded surface of the shell in the sandbed regions
- b) The different UT technologies between the 1986, 1992 and 2006
- c) UT Equipment Instrument Uncertainties and
- d) The uncertainties in attempting to inspect the exact same location over time

3) Row 7 points 6 and 7 in the Bay 17 trench data for 2006 were discounted because they were much thicker than the previous readings. These points are located on a much thicker weld. These readings were re-verified by NDE to be correct, however these values were discounted to maintain conservative results.

4) The sections of drywell vessel that were exposed by the removal of the concrete in trenches in 1986 continued to corrode from the exterior at elevated rates between 1986 and 1992 prior to the removal of the sand and epoxy coating application. For example inspection in 1992 showed that corrosion rates in Bay 17 could have been as great as 0.0211 inches per year, with 95% confidence (ref. C-1302-187-5300-021). The corrosion rates in the Bay 5 were estimated to be as great as 0.0113 inches per year, at 95% confidence (C1302-187-5300-028). Therefore the material loss measured by the 2006 UT inspection would include the corrosion rates that were known to exist from the sandbed side (exterior) between 1986 and 1992.

5) Direct point to point comparison of the 1986 and 2006 trench UT data cannot be performed since the precise location of the 1986 readings and grids were not marked.

#### Acceptance Criteria

Drywell Vessel Thickness criteria has been previously established (reference C-1302-187-5320-024) as follows:

- 1) General Uniform Thickness - 0.736 inches or greater.
- 2) If an area is less than 0.736" thick then that area shall be greater than 0.693" thick and shall be no larger than 6" by 6" wide. C-1302-187-5320-024 has previously dispositioned an area of this magnitude in Bay 13.
- 3) If an area is less than 0.693" thick then that area shall be greater than 0.490" thick and shall be no larger than 2" in diameter. C-1302-187-5320-024 calculated an acceptance criterion of .479 inches however; this evaluation is conservatively using .490 inches, which is the original GE acceptance criterion. Since the UT readings were taken on 1 inch centers and the transducer size is less than 0.5 inch these readings can be characterized as less than 2 inches in diameter.

#### Comparison of the Bay 5 Trench

The 1986 and 2006 data for the Bay 5 trench is located in attachment 1. A Mathcad spreadsheet that computes the average of each data set is provided in attachment 2. Please note that zero values are automatically discounted from the average and standard deviation computation. These are the values that were concluded to be inclusions in the 1986 data (see assumption 1).

The computation shows that a total of 302 readings were considered for 1986 and that the mean was 1.112 inches with a standard deviation of 0.045 inches and a standard error of .00259 inches. This meets the general acceptance criteria of 0.736 inches with a 95% confidence.

The computation shows that a total of 294 readings were considered for 2006 and that the mean is 1.074 inches with a standard deviation of 0.0456 inches and a standard error of .00266 inches. This meets the general acceptance criteria of 0.736 inches with a 95% confidence.

Assuming the material loss occurred continuously from 1986 to 2006 results in an apparent corrosion rate of 0.0019 inches per year. However when considering the aggressive corrosive environment that existed from 1986 to 1992 on the outside of the vessel, a corrosion rate of 0.0063 inches per year would be expected during this time frame (1986 to 1992). This rate is well within the range (up to 0.0113 inches per year)

measured in bay 5 during this period (see assumption/clarification 4). Therefore, it can be concluded that most of the material loss occurred between 1986 and 1992.

The minimum 2006 reading in this trench was 0.957 inches. This meets the local acceptance criteria of 0.49 inches.

#### **Comparison of the Bay 17 Trench**

The 1986 and 2006 data for the Bay 17 trench is located in Attachment 1. A Mathcad spreadsheet that computes the average of each data set is provided in Attachment 3. Note that zero values are automatically discounted from the average and standard deviation computation. These are the 2006 points, which were much thicker than the previous readings (see assumption 3).

The 1986 data consist of five, 7 row by 7 column grids and one additional row. The computation shows that a total of 250 readings were considered for 1986 and that the mean is 1.024 inches, with 95% confidence, a standard deviation of .045 inches, and a standard error of .002847 inches. This meets the general acceptance criteria of 0.736 inches with a 95% confidence.

The 2006 data consist of six 7 row by 7 column grids. The initial 2006 computation of the considered 290 readings resulted in a 0.963 inch mean with a standard deviation of .0713 inches and a standard error of .004184 inches. This meets the general acceptance criteria of 0.736 inches. Statistical review of the data shows that the distribution is skewed and cannot be considered completely normalized. Therefore the calculated mean for these six grids does not have a 95% confidence level. However closer review of the 2006 data shows that the top grid has a mean (0.845 inches) which was significantly less than the mean or the lower 5 grids (0.9852 inches). Statistical review of the 5 lower grids without the top grid shows that the distribution is completely normalized.

The mean of the lower 5 grids (with a total of 243 readings) is 0.9856 inches, a standard deviation of .0412 inches, and a standard error of 0.00266 inches. This meets the general acceptance criteria of 0.736 inches and is consistent with the standard deviation and standard error of 1986 data.

This comparison indicates that it is possible that the lower 5 grids of the six measured in 2006 (with a total of 243 readings) correspond to approximately the same area that 5 grids and 1 row (with 250 reading) measured in 1986. However since the mean of all six 2006 grids (with 290 readings) results in a more conservative rate the 6 grid mean will be used to calculate the maximum potential corrosion rates between 1986 and 1992 and apparent corrosion rates between 1986 and 2006.

Assuming the material loss occurred continuously from 1986 to 2006 results in an apparent corrosion rate of 0.003055 inches per year. However when considering the aggressive corrosive environment that existed from 1986 to 1992 on the outside, a corrosion rate of 0.0102 inches per year would be expected during this time frame (1986

to 1992). This rate is well within the range (up to 0.0211 inches per year) measured in bay 17 during this period (see assumption/clarification 4). Therefore, it is expected that the material loss occurred between 1986 and 1992.

In addition the minimum 2006 individual reading in this trench was 0.702 inches which is estimated to be located in an area no larger than 4" in diameter. This meets the acceptance of criteria 0.693 inches in an area of 6" by 6" or smaller for at least an additional two years.

**Comparison of external inspection locations correlating to beneath the interior Drywell floor at elevation 10' 3" but above the wetted area at elevation 9' 2".**

The 1992 and 2006 data for 106 external inspections is provided in attachment 4. This attachment includes inspections that were performed above and below the internal concrete floor at elevation 10' 3".

Review of the 106 locations show 18 areas corresponding to elevations of the drywell vessel that are beneath the interior Drywell floor at elevation 10' 3" but above the wetted area at elevation 9' 2" (see attachment 5). The data for the 18 locations is shown in attachment 6. For each of these 18 readings the 2006 value was subtracted from the 1992 value and divided by 14 years (time between 1992 and 2006). Locations with positive rates were re-verified by NDE to be correct during the 2006 inspection. However, since these values would result in positive changes in metal thickness, they were discounted from the computation to maintain conservative results.

The resulting differences in UT readings based on point-to-point comparison in this region vary between 0 and .0065 inches per year. On average the differences for this region, ignoring the described uncertainties, equate to 0.00228 inches per year:

The minimum 2006 reading of all the areas below the concrete floor was 0.669 inches. This meets the local acceptance criteria of 0.49 inches even after deducting the worst case differences including instrument uncertainties.

**Comparison of External Inspection Locations correlating to beneath the wetted elevation of 9' 2" (approximate level at which water was discovered in the Bay 5 trench)**

The 1992 and 2006 data for 106 external inspections is provided in attachment 4. This attachment includes inspections that were performed above and below the internal concrete floor at elevation 10' 3".

Review of the 106 locations show 22 area corresponding to elevations of the drywell vessel at an elevation below 9' 2"; which is the approximate level that water was discovered in the Bay 5 trench (see attachment 5). The data for the 22 locations is shown in attachment 6. For each of these 22 readings the 2006 value was subtracted from the 1992 value and divided by 14 years (time between 1992 and 2006). Locations with positive rates were re-verified by NDE to be correct during the 2006 inspection.



However, since these values would result in positive changes in metal thickness, they were discounted from the computation to maintain conservative results.

The resulting changes based on point to point comparison varied between 0 and .0061 inches per year. On average the changes for this region would equate to 0.00233 inches per year. These values can be conservatively used to demonstrate that even if the rates are not due to the expected uncertainties, there is sufficient margin existing to account for these uncertainties.

#### **Bounding Worse Case**

The maximum worst case point to point difference between 2006 data and 1992 data was found at a single location at an elevation above the wetted region but below the floor at elevation 10' 3". The difference was found at point 5 in Bay 17 from data collected from the external inspection (See attachment 6 sheet 2).

This wall thickness difference was computed by subtracting the 1992 value for this point from the 2006 value without eliminating uncertainties. This point is not located within either of the trench locations. The difference in thickness at this point equates to an apparent rate of 0.0065 inches per year, which is not considered credible given the physical limitations of the UT inspections taken from the exterior surface. These limitations include the roughness of the inspected surfaces, the different UT technologies used between 1992 and 2006, UT Equipment Instrument Uncertainties, and the repeatability due to trying to locate the exact same location over time.

However even when considering this worse case difference which was recorded on a location that is 0.822 inches thick in 2006, and considering it as a loss of wall rate per year at the thinnest location recorded in 2006 for points located below the concrete floor (0.669 inches in Bay 13 point 11), and applying 0.020 inch deduction for instrumentation uncertainty this location would only reduce to 0.636 inches by 2008, which still demonstrates significant margins compared to the acceptance criteria of 0.49 inches. Attachment 6 provides a spreadsheet that illustrates the basis for the above discussion.

Also considering a 0.0065 inches per year rate of change and applying it to the 2006 Bay 17 trench mean value (0.963 inches) and applying .020 inch deduction for instrumentation uncertainty would only reduce this value to 0.930 inches by 2008,

#### **Conclusion:**

The UT measurement taken on the plates exposed by the two trenches exhibit signs of material loss. It is concluded that most of the material loss occurred between 1986 and 1992. Assumed corrosion rates for this mechanism between 1986 and 1992 are consistent with as found measured corrosion rates previously established for these bays prior to removing the sand.

Additional concrete was removed from Bay 5 trench and UT readings taken 6 inches below the previous 1986 and 2006 readings. This newly excavated area represents shell thicknesses of the embedded region (on both sides) of the vessel in Bay 5 of sandbed region. The average Drywell shell thickness measured was 1.113 inches and the minimum reading was 1.052 inches. The UT Data Sheet is Attachment 7 to this evaluation. The shell thickness in this area meets the general uniform thickness criteria of 0.736 inches with considerable margin. This area will be used to repeat these UT measurements in 1R22.

Evaluation of the NDE examination results at and below the elevation 10'3" concrete slab concludes that the Drywell shell has sufficient thickness to withstand all design requirements.

Since there is uncertainty associated with the different instrumentation used in 1986 and 1992 and the instrumentation used in 2006, additional inspection of both trenches will be performed during the 2008 refueling outage.

**References:**

TDR 851, Rev. 0, "Assessment of Oyster Creek Drywell Shell,

TDR 854, Rev. 0, "Drywell Corrosion Assessment"  
Drawing 3E-SK-S-85.

C-1302-187-5320-024, "OC Drywell UT Evaluation in Sandbed"

- Attachment 1 – 1986 and 2006 Trench Inspection Data – 10 pages
- Attachment 2 – Bay 5 Trench Comparison of 1986 and 2006 data – 17 pages
- Attachment 3 – Bay 17 Trench Comparison of 1986 and 2006 data – 20 pages
- Attachment 4 – 1986 and 2006 Sandbed External Inspection Data – 20 pages
- Attachment 5 – Plan and Elevation locations of the External Inspection locations – 8 pages
- Attachment 6 – Comparison of 1986 and 2006 External Data – 2 pages
- Attachment 7 – UT Data Sheet 1R21LR-032 – 2 pages
- Attachment 8 – Third Party Review Documentation – 3 pages
- Attachment 9 – MPR Ass. Independent Review Documentation – 2 pages

Prepared by: Tamburro, P.

*P. Tamburro 11/2/06*

This evaluation was Independently Reviewed by Frank Stulb through out its development which took approximately 7 days.

Comment resolution and incorporation of the Independent Third Party Review comments were discussed with Frank Stulb per a telephone conversation on 11/3/06 at 10:12 AM. He provided authorization for documentation and approval of his Independent Review of this document per this telephone conversation.

Independent Reviewer: P. Tamburro for F. Stulb by telecon on 11/7/06

Manager Comments:

*P. Tal 11/7/06 For F. Stulb per telecon.*  
The preparer and multiple reviewers of this technical evaluation had the appropriate knowledge and experience and are qualified to perform this task. The Independent Third Party Review (ITPR) was performed by MPR who was selected as a subject matter expert based on their expertise and industry experience on this topic. This document has been rigorously challenged and addresses the adequacy of the as-found water conditions and potential impacts to demonstrate the drywell vessel maintains its design and licensing bases requirements to support restart from 1R21.

The ITPR has been completed and comments adequately resolved as documented in Attachment 9.

Manager Approval: F.H. Ray 11/7/2006

*F. H. Ray 11/7/06*

Presented at Start-Up PORC Meeting No. 06-18

PORC Chairman Approval:

*[Signature] 11/7/06*

EXPANDED U.T. AT PT. NO. 5B TRENCH  
 (5 IN. BY 46 IN. MATRIX)  
 (DATA SHT. NO. 86-049-47)

1.156	1.166	1.182	1.172	1.225	1.181	1.171
1.160	43	1.184	1.173	1.175	1.171	1.171
1.165	1.164	1.151	65	419	1.170	1.170
1.145	1.151	1.158	1.162	1.155	1.159	1.159
1.123	1.151	1.148	1.167	456	1.139	1.139
1.128	1.138	1.141	1.157	1.150	1.144	1.144
1.123	1.149	1.130	734	733	NA	NA
1.109	1.121	1.144	1.155	1.156	1.149	1.155
1.064	1.066	1.068	1.115	1.1	1.109	1.124
1.051	1.096	1.041	1.077	1.162	1.078	661
1.043	1.100	1.110	1.048	1.101	1.110	1.113
1.047	1.109	1.149	1.13	1.176	1.179	1.058
1.125	1.123	1.090	1.117	1.182	1.200	1.182
1.135	1.091	1.107	1.080	1.084	1.125	1.103
1.094	1.064	1.067	1.079	446	1.169	1.169
1.043	1.079	1.052	1.079	1.117	1.164	444
1.058	1.055	1.082	1.044	1.071	475	1.137
1.087	1.049	1.058	1.114	1.083	1.053	1.144
1.180	1.118	1.093	1.043	1.062	1.178	1.154
1.138	1.071	1.109	1.137	1.096	N/A	1.194
1.109	1.082	1.158	1.098	1.166	1.134	1.054
1.141	1.128	1.089	1.154	1.144	1.141	1.122
1.159	758	759	1.170	771	1.151	1.185
1.166	1.127	1.165	1.174	1.169	1.105	1.181
1.109	1.148	481	1.166	1.171	1.113	1.141
1.089	1.147	571	1.185	1.128	1.133	1.104
1.124	1.092	1.178	716	1.167	1.124	1.072
1.069	1.054	1.112	1.089	1.146	1.119	1.098
1.076	1.056	1.098	453	1.139	1.098	1.077
1.118	1.054	1.100	1.159	1.060	1.062	1.101
1.167	1.073	1.110	1.205	1.149	1.090	1.117
1.088	1.106	1.171	1.193	1.041	1.134	1.093
1.094	1.119	1.115	1.148	1.092	1.118	1.109
1.128	1.134	1.125	N/A	1.147	1.145	1.112
1.065	1.077	1.128	1.168	1.077	1.068	1.073
1.062	1.101	456	1.088	1.049	1.074	1.047
1.100	1.062	1.141	1.059	1.110	1.076	1.078
1.044	1.052	445	1.045	1.083	1.081	1.074
1.031	788	1.057	1.073	1.059	1.109	1.042
1.035	355	1.076	1.060	1.016	1.074	1.037
1.024	1.103	1.030	1.059	1.041	1.062	1.075
436	1.057	1.021	1.015	1.028	1.089	1.081
1.087	1.110	1.027	1.040	1.070	1.079	1.081
773	1.132	1.049	1.096	1.052	1.093	1.093
1.148	1.112	1.113	1.101	1.056	1.045	1.108
1.271	1.138	1.117	1.103	1.152	1.142	1.105
1.211	1.158	1.099	1.133	1.134	1.145	1.105

From 3E-SK-S-85

Bay 5

Trench 20°

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT L  
 PAGE 1 OF 10

U.T. AT WELD, BAY NO. 5  
 (DATA SHT. NO. 86-049-39)

DOWNCOMER AREA	2.901	2.914
HEAT AFFECTED ZONE AREA	.438	1.206
	1.170	1.175
	.970	.411

EXPANDED U.T. AT PT. NO. 5B  
 3 IN. ABOVE CURB, 5 IN. FROM WE  
 (6 IN. BY 6 IN. MATRIX)  
 (DATA SHT. NO. 86-049-36)

1.173	1.179	468	.44	.498	1.204
1.184	1.181	1.174	1.255	1.15	1.172
1.177	1.184	.465	1.213	1.212	1.184
1.212	1.178	1.177	1.209	1.177	1.18
1.194	1.181	.465	1.22	1.135	1.172
1.174	1.209	1.163	1.16	1.157	1.166
1.155	1.161	1.163	1.221	1.173	1.185

WELD

Note circled values were discounted because these values indicate inclusions.

TDR - 851

EXPANDED U.T. AT PT. NO. 5B  
 11 IN. ABOVE CURB, 30 IN  
 (6 IN. BY 6 IN. MAT  
 (DATA SHT. NO. 86-049)



General Electric	<b>Ultrasonic Thickness Measurement Data Sheet</b>	Report Number:	1R21LR-
Oyster Creek		Date:	10/21/2008
Refueling Outage - 1R21		UT Procedure:	ER-AA-335-004
Page 1 of 2		Specifications:	IS-328227-004

Examiner: Leslie Richter	Level: II	Instrument Type: Panametrics 37DL Plus
Examiner: Matt Wilson	Level: II	Instrument No: 031125009
Transducer Type: DV 508	Serial #: 072581	Size: 0.438" Freq: 5 Mhz Angle: 0°
Transducer Cable Type: Panametrics Length: 5'	Couplant: Soundsafe	Batch No: 19620
Calibration Block Type: C/S Step Wedge	Block Number: CAL-STEP-139	


**SYSTEM CALIBRATION**

INSTRUMENT SETTINGS		Initial Cal. Time	Calibration Checks		Final Cal. Time
Coarse Range:	2.0"	11:01	11:32	12:05	12:38
Coarse Delay:	N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches			
Delay Calib:	N/A	Thermometer: 246647	Comp. Temp: 71°	Block Temp: 68°	
Range Calib:	N/A	W/O Number: C2013479			
Instrument Freq:	N/A	Total Crew Dose	Drywell Containment Vessel Thickness Examination. Internal UT Inspections.		
Gain:	63 db	96 mr			
Damping:	N/A	<b>Trench 1 (Bay 6)</b>			
Reject:	N/A				
Filter:	N/A				

Thickness readings taken at holes located in template.

The UT transducer was positioned in the same orientation at each grid point.

**PASSPORT#**  
**00546049 07**  
**AR# A2152754 E09**  
**ATTACHMENT 1**  
**PAGE 3 OF 10**



**COMMENTS:**

Template was placed at the bottom of the trench and forty-nine (49) points were recorded, then template was relocated above previous location with the centerline of the bottom row 1" +/- 1/16" from previous grid top row. A "V" was stamped next to each side of each template location and above and below top and bottom. A total of 294 readings were taken.

General Electric  
 Oyster Creek  
 Refueling Outage - 1R21  
 Page 2 of 2

**Ultrasonic Thickness Measurement  
 Data Sheet**

File Name: 1R21LR- 25  
 Date: 10/18/2008  
 UT Procedure: ER-AA-335-004  
 Grid Procedure: IS-328227-004

Bottom of Trench							
Location ID	Trench 2			Bay	17	Elev.	10' 3"
	A	B	C	D	E	F	G
1	0.937	0.970	0.927	0.948	0.932	0.918	0.942
2	0.924	1.059	0.934	0.941	0.968	0.924	0.916
3	0.948	0.948	0.963	0.941	0.932	0.937	0.987
4	0.977	0.983	1.032	0.982	0.983	0.997	0.953
5	0.972	0.932	0.977	0.973	1.005	0.959	1.028
6	1.028	1.002	0.968	0.972	0.953	0.964	0.990
7	0.981	1.006	0.967	0.945	0.968	0.943	0.978
8	1.026	0.958	0.958	1.026	0.982	0.988	0.967
9	1.026	0.906	0.915	0.991	1.006	0.984	0.962
10	0.979	0.933	1.027	0.934	0.969	0.958	1.042
11	0.963	1.003	1.016	1.062	0.969	0.987	1.030
12	1.027	0.977	1.039	0.999	0.998	1.027	1.039
13	1.023	1.001	0.959	0.997	0.974	1.003	1.090
14	0.986	1.004	1.009	0.946	1.016	1.023	0.995
15	0.966	1.069	1.014	1.055	0.995	1.002	1.029
16	0.987	0.983	0.942	0.941	1.010	1.023	1.016
17	1.034	1.008	0.971	1.064	0.985	1.022	1.032
18	0.972	1.021	0.985	0.992	1.003	0.997	1.008
19	0.975	0.951	0.985	1.059	1.047	0.935	0.980
20	0.940	0.967	0.995	1.020	1.044	1.075	0.980
21	0.918	0.897	0.934	1.036	1.058	0.998	1.009
22	0.973	0.954	1.004	1.013	1.011	1.043	0.948
23	0.998	0.952	1.007	1.000	0.963	1.006	0.951
24	OBST.	0.878	0.979	0.935	1.014	0.981	1.015
25	1.017	1.074	0.968	0.963	0.968	1.014	1.030
26	1.038	1.053	1.026	1.008	0.983	0.979	1.039
27	0.868	1.028	0.998	1.017	1.004	1.030	1.046
28	1.028	0.950	1.047	1.000	0.977	1.002	1.010
29	0.997	1.023	1.060	1.015	0.964	0.995	0.997
30	1.061	0.958	1.022	1.044	0.991	0.990	1.001
31	1.008	1.021	1.010	1.010	1.003	0.959	0.963
32	0.988	0.991	0.961	0.840	1.029	0.979	0.929
33	1.005	1.014	1.003	0.896	0.944	1.013	0.885
34	0.990	0.976	0.962	0.909	0.905	0.863	0.923
35	0.954	0.954	OBST.	0.885	0.887	0.877	0.930
36	0.963	0.972	0.877	0.835	0.891	0.831	0.894
37	0.897	0.937	0.903	0.893	0.898	0.781	0.841
38	0.855	0.864	0.853	0.850	0.840	0.814	0.788
39	0.802	0.891	0.838	0.790	1.082	OBST.	0.809
40	0.748	0.795	0.776	0.822	0.757	1.042	0.794
41	0.702	0.779	0.811	0.835	0.723	0.738	0.837
42	0.726	0.825	0.878	0.868	OBST.	0.864	0.954

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 1  
 PAGE 4 OF 12

*pcsey*

Tscr.	AVG.
0.660	0.963
Min Reading	Max. Reading
0.702	1.090

Examined by Jeremy Tuttle *Jeremy Tuttle*  
 Examined by N/A  
 Reviewed by: Lee Stone *Lee Stone*



Level II Date 10/21/2008  
 Level N/A Date N/A  
 Level II Date 10/21/2008

Template layout for  
Trench UT data.

IR2ILR-025 P3 of 4  
P3  
MM 10-23-06  
L III


Centerline of bottom row is  
1" +/- 1/16" from previous  
row

1"



Template placed at Bottom  
of Trench





PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 1  
PAGE 6 OF 10

General Electric	<b>Ultrasonic Thickness Measurement Data Sheet</b>	File Name:	1R21LR-25
Oyster Creek		Date:	10/21/2008
Refueling Outage - 1R21		UT Procedure:	ER-AA-335-004
Page 1 of 2		Specification:	IS-328227-004

Examiner: Jeremy Tuttle <i>Jeremy Tuttle 10/21/08</i>	Level: II	Instrument Type: Panametrics 37DL Plus
Examiner: N/A	Level: N/A	Instrument No: 031125009
Transducer Type: DV 508	Serial #: 072362	Size: 0.438" Freq: 5 Mhz Angle: 0°
Transducer Cable Type: Panametrics Length: 5'	Couplant: Soundsafe	Batch No: 19620
Calibration Block Type: C/S Step Wedge	Block Number: CAL-STEP-139	


**SYSTEM CALIBRATION**

INSTRUMENT SETTINGS		Initial Cal. Time	Calibration Checks		Final Cal. Time
Coarse Range:	2.0"	7:17	8:22	N/A	9:05
Coarse Delay:	N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches			
Delay Calib:	N/A	Thermometer:	246672	Comp. Temp:	73° Block Temp: 68°
Range Calib:	N/A	W/O Number:	C2013479		
Instrument Freq:	N/A	Total Crew Dose	Drywell Containment Vessel Thickness Examination. Internal UT Inspections.		
Gain:	51 db	229 mR	<b>Trench 2 Bay 17</b>		
Damping:	N/A				
Reject:	N/A				
Filter:	N/A				

Thickness readings taken at holes located in template.

The UT transducer was positioned in the same orientation at each grid point.

**PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 1  
PAGE 7 OF 10**



**COMMENTS:**  
 Grid Template aligned with V-stamps.  
 Template was placed at the bottom of the trench and forty-nine (49) points were recorded, then template was relocated above previous location with the centerline of the bottom row 1" +/- 1/16" from previous grid top row.  
 A total of 290 readings were taken.

All obstructions due to rough surface conditions. Some readings taken as best effort readings due to rough surface conditions.

General Electric	<b>Ultrasonic Thickness Measurement Data Sheet</b>	File Name:	1R21LR-24
Oyster Creek		Date:	10/21/2008
Refueling Outage - 1R21		UT Procedure:	ER-AA-335-004
Page 2 of 2		Grid Procedure:	IS-328227-004

*m/m L III  
10-23-06*

Bottom of Trench							
Location ID	Trench 1			Bay	Elev.		10' 3"
	A	B	C	D	E	F	G
1	1.059	1.034	1.036	1.106	1.074	1.131	1.078
2	1.061	1.021	1.008	1.051	1.047	1.049	1.024
3	1.062	1.026	1.047	1.026	0.968	1.049	1.032
4	1.016	1.055	1.026	0.959	1.013	1.061	0.987
5	1.027	1.046	1.001	0.993	1.064	1.070	0.993
6	1.035	1.021	1.004	0.985	1.013	1.150	0.957
7	1.032	1.054	1.023	1.033	0.962	0.962	0.991
8	1.065	1.023	1.069	1.043	1.082	1.028	1.030
9	1.111	1.037	1.086	1.071	1.044	0.996	0.976
10	1.061	1.034	1.009	1.099	1.036	0.988	1.105
11	1.014	1.022	1.028	1.142	1.064	1.040	1.041
12	1.125	1.146	1.145	1.125	1.079	1.087	1.089
13	1.101	1.157	1.127	1.155	1.072	1.130	1.049
14	1.116	1.077	1.108	1.094	1.087	1.056	1.051
15	1.127	1.042	1.119	1.126	1.079	1.102	1.075
16	1.109	1.176	1.169	1.112	1.054	1.131	1.113
17	1.106	1.090	1.096	1.079	1.073	1.083	1.030
18	1.094	1.115	1.073	1.068	1.065	1.073	1.091
19	1.045	1.117	1.049	1.114	1.082	1.090	1.095
20	1.111	1.123	1.117	1.086	1.138	1.090	1.091
21	1.151	1.131	1.145	1.091	1.075	1.116	1.114
22	1.126	1.084	1.159	1.058	1.088	1.109	1.134
23	1.129	1.100	1.162	1.023	1.096	1.112	1.070
24	1.089	1.159	1.137	1.109	1.091	1.165	1.124
25	1.135	1.167	1.099	1.075	1.141	1.122	1.050
26	1.054	1.050	1.036	1.074	1.032	1.078	1.070
27	1.134	1.045	1.026	1.082	1.171	1.145	1.178
28	1.069	1.085	1.102	1.142	1.120	1.081	1.116
29	1.020	1.065	1.068	1.021	1.040	1.001	1.066
30	1.085	1.064	1.045	1.033	1.006	1.033	1.056
31	1.047	1.059	0.997	1.083	1.018	1.065	1.030
32	1.084	1.062	1.063	1.105	1.143	1.089	1.048
33	1.107	1.093	1.057	1.050	1.130	1.061	1.064
34	1.099	1.066	1.005	1.027	1.044	1.018	1.073
35	1.059	1.118	1.045	1.023	1.039	1.068	1.087
36	1.067	1.072	1.041	1.035	1.030	1.015	1.047
37	1.093	1.050	1.099	1.039	1.033	0.992	1.033
38	1.142	1.094	1.099	1.086	1.086	1.039	1.048
39	1.151	1.122	1.112	1.074	1.115	1.073	1.049
40	1.132	1.115	1.103	1.106	1.083	1.052	1.047
41	1.137	1.130	1.139	1.119	1.106	1.084	1.087
42	1.113	1.131	1.097	1.122	1.131	1.104	1.063

**PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT L  
PAGE 8 OF 12**

*Page 8*


Tscr.	AVG.
0.660	1.074
Min Reading	Max. Reading
0.967	1.178

*m/m L III  
10-23-06*

Examined by <u>Leslie Richter</u>	Level <u>II</u>	Date <u>10/21/2008</u>
Examined by <u>Matt Wilson</u>	Level <u>II</u>	Date <u>10/21/2008</u>
Reviewed by: <u>Lee Stone</u>	Level <u>II</u>	Date <u>10/21/2008</u>

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 1  
PAGE 2 OF 12

PT





Template layout for  
Trench UT data.

IR21LR-024  
Pg 4 of 4  
7/14/06 L III  
10-23-06

Centerline of bottom row is  
1" +/- 1/16" from previous  
row

1"



Template placed at Bottom  
of Trench.

Attachment 2 - Bay 5 Trench

1986 Data

The data shown below was collected in 1986 in the trench in Bay 5

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-1.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.156	1.166	1.182	1.172	1.225	1.181	1.171
1.16	0	1.184	1.173	1.175	1.171	1.176
1.165	1.164	1.151	0	0	1.17	1.17
1.145	1.151	1.158	1.162	1.155	1.159	1.172
1.123	1.151	1.148	1.167	0	1.139	1.156
1.128	1.138	1.141	1.157	1.158	1.144	1.159
1.123	1.149	1.13	0	0	0	0

XXXX := convert(Points 49, 7)

No DataCells := length(XXXX)

XXXX := deletezero cells(XXXX, No DataCells)

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-2.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.109	1.121	1.144	1.155	1.156	1.149	1.155
1.064	1.066	1.068	1.115	1.1	1.109	1.124
1.051	1.096	1.041	1.077	1.162	1.078	0
1.063	1.1	1.11	1.048	1.101	1.11	1.133
1.047	1.109	1.149	1.13	1.176	1.179	1.058
1.125	1.123	1.09	1.117	1.182	1.2	1.182
1.135	1.091	1.107	1.08	1.084	1.125	1.183

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(XXX, XXXS)

No DataCells := length(Cells 86)

No DataCells = 89

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-3.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.094	1.064	1.067	1.079	0	1.169	1.14
1.043	1.079	1.052	1.079	1.119	1.164	0
1.058	1.055	1.082	1.044	1.071	0	1.137
1.087	1.049	1.058	1.114	1.083	1.053	1.164
1.18	1.118	1.093	1.043	1.062	1.178	1.156
1.138	1.071	1.109	1.137	1.096	0	1.194
1.109	1.082	1.158	1.098	1.166	1.134	1.056

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

No DataCells = 134

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-4.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.141	1.128	1.089	1.154	1.164	1.141	1.122
1.159	0	0	1.17	0	1.151	1.105
1.166	1.127	1.105	1.174	1.169	1.105	1.131
1.109	1.148	0	1.166	1.171	1.113	1.141
1.089	1.167	0	1.18	1.128	1.133	1.106
1.126	1.092	1.178	0	1.167	1.124	1.072
1.069	1.054	1.112	1.089	1.146	1.119	1.098

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

No DataCells = 177

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-5.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.076	1.056	1.098	0	1.139	1.098	1.077
1.118	1.054	1.1	1.159	1.06	1.062	1.101
1.067	1.073	1.11	1.205	1.149	1.09	1.113
1.088	1.106	1.171	1.193	1.041	1.134	1.093
1.094	1.119	1.115	1.148	1.092	1.118	1.109
1.128	1.134	1.125	0	1.147	1.145	1.112
1.065	1.077	1.179	1.168	1.077	1.068	1.073

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)  
No DataCells := length(Cells 86)

No DataCells = 224

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-6.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.062	1.101	0	1.088	1.069	1.074	1.067
1.1	1.062	1.141	1.059	1.11	1.076	1.078
1.044	1.052	0	1.045	1.083	1.081	1.076
1.031	0	1.057	1.073	1.059	1.109	1.062
1.035	0	1.076	1.06	1.016	1.074	1.037
1.024	1.103	1.03	1.059	1.061	1.062	1.076
0	1.057	1.021	1.015	1.028	1.089	1.08

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench5-7.txt")

Points 49 := showcells(page, 7, 0)



Points 49 =

1.087	1.11	1.027	1.04	1.07	1.079	1.081
0	1.132	1.049	1.096	1.052	1.093	1.092
1.168	1.112	1.113	1.101	1.056	1.065	1.108
1.271	1.138	1.117	1.103	1.152	1.142	1.108
1.211	1.158	1.099	1.133	1.134	1.145	1.108
0	0	0	0	0	0	0
0	0	0	0	0	0	0

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX) No DataCells := length(Cells 86)

No DataCells = 302

No DataCells = 302

The thinnest point at this location is shown below

minpoint := min(Cells 86)

minpoint =  $1.015 \cdot 10^3$

### Mean and Standard Deviation

$$\mu_{86 \text{ actual}} := \text{mean}(\text{Cells } 86) \quad \mu_{86 \text{ actual}} = 1.1123 \cdot 10^3 \quad \sigma_{86 \text{ actual}} := \text{Stdev}(\text{Cells } 86) \quad \sigma_{86 \text{ actual}} = 45.002$$

### Standard Error

$$\text{Standard error} := \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Standard error} = 2.59$$

### Skewness

$$\text{Skewness} := \frac{(\text{No DataCells}) \cdot \overline{\sum (\text{Cells } 86 - \mu_{86 \text{ actual}})^3}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\sigma_{86 \text{ actual}})^3} \quad \text{Skewness} = 0.132$$

### Kurtosis

$$\text{Kurtosis} := \frac{\text{No DataCells} \cdot (\text{No DataCells} + 1) \cdot \overline{\sum (\text{Cells } 86 - \mu_{86 \text{ actual}})^4}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3) \cdot (\sigma_{86 \text{ actual}})^4} + \frac{3 \cdot (\text{No DataCells} - 1)^2}{(\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3)} \quad \text{Kurtosis} = -0.534$$

### Normal Probability Plot

In a normal plot, each data value is plotted against what its value would be if it actually came from a normal distribution. The expected normal values, called normal scores, and can be estimated by first calculating the rank scores of the sorted data.

$$j := 0.. \text{last}(\text{Cells } 86) \quad \text{srt} := \text{sort}(\text{Cells } 86)$$

Then each data point is ranked. The array rank captures these ranks .

$$r_j := j + 1$$

$$\text{rank}_j := \frac{\sum_{\text{srt}=\text{srt}_j}^{\text{srt}=\text{srt}_j} r}{\sum_{\text{srt}=\text{srt}_j} \text{srt}_j}$$

$$p_j := \frac{\text{rank}_j}{\text{rows}(\text{Cells } 86) + 1}$$

The normal scores are the corresponding  $p$ th percentile points from the standard normal distribution:

$$x := 1 \quad \text{N\_Score}_j := \text{root}[\text{cnorm}(x) - (p_j), x]$$

**Upper and Lower Confidence Values**

The Upper and Lower confidence values are calculated based on .05 degree of confidence " $\alpha$ "

No DataCells := length(Cells 86)

$\alpha := .05$        $T\alpha := qt\left[\left(1 - \frac{\alpha}{2}\right), \text{No DataCells}\right]$        $T\alpha = 1.968$

Lower 95%Con :=  $\mu_{86 \text{ actual}} - T\alpha \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}}$       Lower 95%Con =  $1.107 \cdot 10^3$

Upper 95%Con :=  $\mu_{86 \text{ actual}} + T\alpha \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}}$       Upper 95%Con =  $1.117 \cdot 10^3$

These values represent a range on the calculated mean in which there is 95% confidence.

**Graphical Representation**

Distribution of the "Cells" data points are sorted in 1/2 standard deviation increments (bins) within +/- 3 standard deviations

Bins := Make bins( $\mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}}$ )

Distribution := hist(Bins, Cells 86)

Distribution =

0
3
14
42
45
54
41
43
45
11
2
1

The mid points of the Bins are calculated

$k := 0..11$        $\text{Midpoints}_k := \frac{(\text{Bins}_k + \text{Bins}_{k+1})}{2}$

The Mathcad function pnorm calculates a portion of normal distribution curve based on a given mean and standard deviation

normal curve<sub>0</sub> := pnorm( $\text{Bins}_1, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}}$ )


normal curve<sub>k</sub> := pnorm( $\text{Bins}_{k+1}, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}}$ ) - pnorm( $\text{Bins}_k, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}}$ )

normal curve := No DataCells · normal curve

**Results For Elevation Sandbed elevation Location Oct. 2006**


The following schematic shows: the the distribution of the samples, the normal curve based on the actual mean and standard deviation, the kurtosis, the skewness, the number of data points, and the the lower and upper 95% confidence values. Below is the Normal Plot for the data.

**Data Distribution**



A Kurtosis value which is less than +/- 1.0 and approaches 0 is indicative of a normal distribution

### Normal Probability Plot



The Normal Probability Plot and the Kurtosis this data is normally distributed.

A Normal Probability Plot which approaches a straight line is indicative of a normal distribution

OCT 2006 Data

The data shown below was collected in 2006 in the trench in Bay 5

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench5-1.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

1.067	1.072	1.041	1.035	1.03	1.015	1.047
1.093	1.05	1.099	1.039	1.033	0.992	1.033
1.142	1.094	1.099	1.086	1.086	1.039	1.048
1.151	1.122	1.112	1.074	1.115	1.073	1.049
1.132	1.115	1.103	1.106	1.083	1.052	1.047
1.137	1.13	1.139	1.119	1.106	1.084	1.087
1.113	1.131	1.097	1.122	1.131	1.104	1.063

XXXX := convert(Points 49, 7)

No DataCells := length(XXXX)

XXXX := deletezero cells(XXXX, No DataCells)

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench5-2.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

1.02	1.065	1.068	1.021	1.04	1.001	1.066
1.085	1.064	1.045	1.033	1.006	1.033	1.056
1.047	1.059	0.997	1.083	1.018	1.065	1.03
1.084	1.062	1.063	1.105	1.143	1.089	1.048
1.107	1.093	1.057	1.05	1.13	1.061	1.064
1.099	1.066	1.005	1.027	1.044	1.018	1.073
1.059	1.118	1.045	1.023	1.039	1.068	1.087

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(XXX, XXXS)

No DataCells := length(Cells 06)

No DataCells = 98

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench5-3.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =	1.126	1.094	1.159	1.058	1.088	1.109	1.134
	1.129	1.1	1.162	1.023	1.096	1.112	1.07
	1.089	1.159	1.137	1.109	1.091	1.165	1.124
	1.135	1.167	1.099	1.075	1.141	1.122	1.05
	1.054	1.05	1.026	1.074	1.022	1.078	1.07



page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench5-5.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.065	1.023	1.069	1.043	1.092	1.028	1.03
1.111	1.037	1.086	1.071	1.044	0.996	0.976
1.061	1.034	1.009	1.099	1.036	0.988	1.105
1.014	1.022	1.028	1.142	1.064	1.04	1.041
1.125	1.146	1.145	1.125	1.079	1.087	1.089
1.101	1.157	1.127	1.155	1.072	1.13	1.043
1.116	1.077	1.108	1.094	1.087	1.056	1.051

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(Cells 06, XXX)

No DataCells := length(Cells 06)

No DataCells = 245

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench5-6.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.059	1.034	1.036	1.106	1.074	1.131	1.078
1.061	1.021	1.008	1.051	1.047	1.049	1.024
1.062	1.026	1.047	1.026	0.968	1.049	1.032
1.016	1.055	1.026	0.959	1.013	1.061	0.987
1.027	1.046	1.001	0.993	1.064	1.07	0.993
1.035	1.021	1.004	0.985	1.013	1.15	0.957
1.032	1.054	1.023	1.033	0.962	0.962	0.991

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(Cells 06, XXX)

No DataCells := length(Cells 06)

No DataCells = 294

minpoint := min(XXX)

minpoint = 957

The thinnest point at this location is shown  
below

minpoint := min(Cells 06)

minpoint = 957

**Mean and Standard Deviation**

$$\mu_{06 \text{ actual}} := \text{mean}(\text{Cells } 06) \quad \mu_{06 \text{ actual}} = 1.0743 \cdot 10^3 \quad \sigma_{06 \text{ actual}} := \text{Stdev}(\text{Cells } 06) \quad \sigma_{06 \text{ actual}} = 45.628$$

**Standard Error**

$$\text{Standard error} := \frac{\sigma_{06 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Standard error} = 2.661$$

**Skewness**

$$\text{Skewness} := \frac{(\text{No DataCells}) \cdot \overline{\sum (\text{Cells } 06 - \mu_{06 \text{ actual}})^3}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\sigma_{06 \text{ actual}})^3} \quad \text{Skewness} = -0.071$$

**Kurtosis**

$$\text{Kurtosis} := \frac{\text{No DataCells} \cdot (\text{No DataCells} + 1) \cdot \overline{\sum (\text{Cells } 06 - \mu_{06 \text{ actual}})^4}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3) \cdot (\sigma_{06 \text{ actual}})^4 + \frac{3 \cdot (\text{No DataCells} - 1)^2}{(\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3)}} \quad \text{Kurtosis} = -0.432$$

### Normal Probability Plot

In a normal plot, each data value is plotted against what its value would be if it actually came from a normal distribution. The expected normal values, called normal scores, and can be estimated by first calculating the rank scores of the sorted data.

$$j := 0 : \text{last}(\text{Cells } 06)$$

$$\text{srt} := \text{sort}(\text{Cells } 06)$$

Then each data point is ranked. The array rank captures these ranks

$$z_j := j + 1$$

$$\text{rank}_j := \frac{\sum_{\text{srt}=\text{srt}_j} \text{srt}}{\sum \text{srt}=\text{srt}_j} \cdot z$$

$$p_j := \frac{\text{rank}_j}{\text{rows}(\text{Cells } 06) + 1}$$

The normal scores are the corresponding  $p$ th percentile points from the standard normal distribution:

$$x := 1 \quad \text{N\_Score}_j := \text{root}[\text{cnorm}(x) - (p_j), x]$$

**Upper and Lower Confidence Values**

The Upper and Lower confidence values are calculated based on .05 degree of confidence "α"

No DataCells := length(Cells 06)

α := .05      Tα := qt(1 - α/2, No DataCells)      Tα = 1.968

Lower 95%Con := μ06 actual - Tα \* (σ06 actual / √No DataCells)      Lower 95%Con = 1.069 \* 10<sup>3</sup>

Upper 95%Con := μ06 actual + Tα \* (σ06 actual / √No DataCells)      Upper 95%Con = 1.08 \* 10<sup>3</sup>

These values represent a range on the calculated mean in which there is 95% confidence.

**Graphical Representation**

Distribution of the "Cells" data points are sorted in 1/2 standard deviation increments (bins) within +/- 3 standard deviations

Bins := Make bins(μ06 actual, σ06 actual)

Distribution := hist(Bins, Cells 06)

Distribution =

2
4
13
28
54
51
48
42
33
14
5
0

The mid points of the Bins are calculated

k := 0..11      Midpoints<sub>k</sub> := (Bins<sub>k</sub> + Bins<sub>k+1</sub>) / 2

The Mathcad function pnorm calculates a portion of normal distribution curve based on a given mean and standard deviation

normal curve<sub>0</sub> := pnorm(Bins<sub>1</sub>, μ06 actual, σ06 actual)


normal curve<sub>k</sub> := pnorm(Bins<sub>k+1</sub>, μ06 actual, σ06 actual) - pnorm(Bins<sub>k</sub>, μ06 actual, σ06 actual)

normal curve := No DataCells \* normal curve

**Results For Elevation Sandbed elevation Location Oct. 2006**


The following schematic shows: the the distribution of the samples, the normal curve based on the actual mean and standard deviation, the kurtosis, the skewness, the number of data points, and the the lower and upper 95% confidence values. Below is the Normal Plot for the data.

**Data Distribution**



A Kurtosis value which is less than +/- 1.0 and approaches 0 is indicative of a normal distribution

### Normal Probability Plot



The Normal Probability Plot and the Kurtosis this data is normally distributed.

A Normal Probability Plot which approaches a straight line is indicative of a normal distribution

Corrosion Rate assuming corrosion occurred between 1986 and 2006

$$\frac{(\mu_{86 \text{ actual}} - \mu_{06 \text{ actual}})}{2006 - 1986} = 1.9$$

Corrosion Rate assuming corrosion occurred between 1986 and 1992

$$\frac{(\mu_{86 \text{ actual}} - \mu_{06 \text{ actual}})}{1992 - 1986} = 6.334$$

Attachment 3 Bay 17 Trench

1986 Data

The data shown below was collected in 1986 in the trench in Bay 17

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-1.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

0.93	0.932	0.943	0.958	0.927	0.889	0.913
1.014	0.953	0.984	0.987	0.973	0.939	0.956
0.991	1.005	0.951	0.968	0.939	0.945	0.956
0.995	0.995	1.038	1.031	0.992	1.003	1.011
1.025	1.011	0.968	1.024	1.004	1.002	1.055
1.017	1.036	1.029	1.031	1.084	1.026	1.05
1.041	1.055	1.044	1.047	1.043	0	0

XXXS := convert(Points 49, 7)

No DataCells := length(XXXS)

XXXS := deletezero cells(XXXS, No DataCells)

Grid Top1986 := XXXS

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-2.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

1.045	1.009	1.024	1.026	1.008	1.07	1.07
0.991	1.012	1.041	1.031	1.017	1.076	1.076
1.031	1.101	1.081	1.077	1.04	1.076	1.072
1.087	1.059	1.069	1.057	1.102	1.088	1.047
0.998	1.065	1.048	1.004	1.014	1.016	1.016
0.964	1.019	0.987	1.055	1.045	1.022	1.061
0.906	1.04	1.019	0.98	1.024	1.01	1.014

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(XXX, XXXS)

No DataCells := length(Cells 86)

No DataCells = 96

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-3.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

0.964	1.105	1.083	1.011	1.047	1.016	1.028
1.063	1.012	1.029	1.047	1.056	0.972	0.907
1.021	1.097	1.071	1.068	1.033	0.911	0.952
1.066	1.023	1.006	1.063	1.045	1.035	0.992
1.052	1.037	1.044	1.078	1.05	1.054	1.051
1.037	1.015	1.026	1.064	1.07	1.056	1.044
1.065	1.059	1.026	1.058	1.047	1.067	1.075

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

No DataCells = 145

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-4.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

1.088	1.046	1.019	1.103	0.993	1.086	1.041
1.056	1.045	0.995	1.044	1.042	1.026	1.116
1.102	1.001	1.044	1.082	1.028	1	1.08
1.106	1.05	1.002	1.017	1.042	1.034	1.037
1.069	0.965	0.988	1.122	1.034	1.032	1.07
1.097	1.028	1.051	0.951	1.059	1.015	1.005
1.135	1.022	1.076	1.058	0.952	0.981	1.023

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

No DataCells = 194



page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-5.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

1.023	1.049	0.987	1.085	1.048	1.072	0.98
1.1	1.017	0.958	1.044	0.991	1.056	1.074
1.053	1.03	1.025	0.987	1.031	1.059	1.087
1.005	1.049	1.006	1.058	1.058	1.011	0.992
0.972	0.985	1.012	1.009	1.067	1.017	0.975
0.985	0.979	0.974	0.961	1.017	1.008	0.982
0.999	0.987	1.021	0.958	0.954	1.064	0.942

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX) No DataCells := length(Cells 86)

No DataCells = 243

page := READPRN("H:\MSOFFICE\Drywell Program data\1986 trenches\Trench17-6.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

0.923	0.981	0.976	0.97	0.964	0.99	1.004
0	0	0	0	0	0	0
0	0	0	0	0	0	0
0	0	0	0	0	0	0
0	0	0	0	0	0	0
0	0	0	0	0	0	0
0	0	0	0	0	0	0

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 86 := stack(Cells 86, XXX)

No DataCells := length(Cells 86)

No DataCells = 250

The thinnest point at this location is shown below

minpoint := min(Cells 86)

minpoint = 889

**Mean and Standard Deviation**

$$\mu_{86 \text{ actual}} := \text{mean}(\text{Cells } 86) \quad \mu_{86 \text{ actual}} = 1.0239 \cdot 10^3 \quad \sigma_{86 \text{ actual}} := \text{Stdev}(\text{Cells } 86) \quad \sigma_{86 \text{ actual}} = 45.019$$

**Standard Error**

$$\text{Standard error} := \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Standard error} = 2.847$$

**Skewness**

$$\text{Skewness} := \frac{(\text{No DataCells}) \cdot \overrightarrow{\Sigma(\text{Cells } 86 - \mu_{86 \text{ actual}})^3}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\sigma_{86 \text{ actual}})^3} \quad \text{Skewness} = -0.387$$

**Kurtosis**

$$\text{Kurtosis} := \frac{\text{No DataCells} \cdot (\text{No DataCells} + 1) \cdot \overrightarrow{\Sigma(\text{Cells } 86 - \mu_{86 \text{ actual}})^4}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3) \cdot (\sigma_{86 \text{ actual}})^4} + \frac{3 \cdot (\text{No DataCells} - 1)^2}{(\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3)} \quad \text{Kurtosis} = -0.033$$

### Normal Probability Plot

In a normal plot, each data value is plotted against what its value would be if it actually came from a normal distribution. The expected normal values, called normal scores, and can be estimated by first calculating the rank scores of the sorted data.

$$j := 0.. \text{last}(\text{Cells } 86) \quad \text{srt} := \text{sort}(\text{Cells } 86)$$

Then each data point is ranked. The array rank captures these ranks

$$r_j := j + 1 \quad \text{rank}_j := \frac{\sum_{\text{srt}=\text{srt}_j} \text{srt}}{\sum \text{srt}=\text{srt}_j}$$

$$p_j := \frac{\text{rank}_j}{\text{rows}(\text{Cells } 86) + 1}$$

The normal scores are the corresponding  $p$ th percentile points from the standard normal distribution:

$$x := 1 \quad \text{N\_Score}_j := \text{root}[\text{cnorm}(x) - (p_j), x]$$

### Upper and Lower Confidence Values

The Upper and Lower confidence values are calculated based on .05 degree of confidence "α"

$$\text{No DataCells} := \text{length}(\text{Cells } 86)$$

$$\alpha := .05 \quad T\alpha := \text{qt}\left(\left(1 - \frac{\alpha}{2}\right), \text{No DataCells}\right) \quad T\alpha = 1.969$$

$$\text{Lower } 95\% \text{Con} := \mu_{86 \text{ actual}} - T\alpha \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Lower } 95\% \text{Con} = 1.018 \cdot 10^3$$

$$\text{Upper } 95\% \text{Con} := \mu_{86 \text{ actual}} + T\alpha \frac{\sigma_{86 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Upper } 95\% \text{Con} = 1.029 \cdot 10^3$$

These values represent a range on the calculated mean in which there is 95% confidence.

### Graphical Representation

Distribution of the "Cells" data points are sorted in 1/2 standard deviation increments (bins) within +/- 3 standard deviations

$$\text{Bins} := \text{Make bins}(\mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}})$$

$$\text{Distribution} := \text{hist}(\text{Bins}, \text{Cells } 86)$$

Distribution =

41
5
13
17
30
47
50
44
28
9
3
0

The mid points of the Bins are calculated

$$k := 0.. 11 \quad \text{Midpoints}_k := \frac{(\text{Bins}_k + \text{Bins}_{k+1})}{2}$$

The Mathcad function pnorm calculates a portion of normal distribution curve based on a given mean and standard deviation


$$\text{normal curve}_0 := \text{pnorm}(\text{Bins}_1, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}})$$

$$\text{normal curve}_k := \text{pnorm}(\text{Bins}_{k+1}, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}}) - \text{pnorm}(\text{Bins}_k, \mu_{86 \text{ actual}}, \sigma_{86 \text{ actual}})$$

$$\text{normal curve} := \text{No DataCells} \cdot \text{normal curve}$$

**Results For Trench 17 1986 Data**

The following schematic shows: the the distribution of the samples, the normal curve based on the actual mean and standard deviation, the kurtosis, the skewness, the number of data points, and the the lower and upper 95% confidence values. Below is the Normal Plot for the data.



Lower 95%Con =  $1.018 \cdot 10^3$

Upper 95%Con =  $1.029 \cdot 10^3$


$\mu_{86}$  actual =  $1.024 \cdot 10^3$

$\sigma_{86}$  actual = 45.019

minpoint = 889

A Kurtosis value which is less than +/- 1.0 and approaches 0 is indicative of a normal distribution

**Normal Probability Plot**



The Normal Probability Plot and the Kurtosis this data is normally distributed.

A Normal Probability Plot which approaches a straight line is indicative of a normal distribution. Therefore the 1986 Bay 17 trench data had a normal distribution.

2006 Data

The data shown below was collected in 2006 in the trench in Bay 17

page := READPRN("H:\MSOFFICEDrywell Program data\2006 trenches\Trench17-1.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

0.963	0.972	0.877	0.835	0.891	0.831	0.894
0.897	0.937	0.903	0.893	0.838	0.781	0.841
0.855	0.884	0.853	0.85	0.84	0.814	0.788
0.802	0.891	0.838	0.79	1.082	0	0.809
0.746	0.795	0.776	0.822	0.757	1.042	0.794
0.702	0.779	0.811	0.835	0.723	0.738	0.837
0.726	0.825	0.878	0.868	0	0.864	0.954

XXXX := convert(Points 49, 7)

No DataCells := length(XXXX)

XXXX := deletezero cells(XXXX, No DataCells)

Grid Top2006 := XXXX

page := READPRN("H:\MSOFFICEDrywell Program data\2006 trenches\Trench17-2.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

0.997	1.023	1.06	1.015	0.964	0.995	0.997
1.061	0.958	1.022	1.044	0.991	0.99	1.001
1.008	1.021	1.01	1.01	1.003	0.959	0.963
0.988	0.991	0.961	0.94	1.029	0.979	0.929
1.005	1.014	1.003	0.896	0.944	1.013	0.885
0.99	0.976	0.962	0.909	0.905	0.863	0.923
0.954	0.954	0	0.885	0.887	0.877	0.93

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(XXX, XXXX)

No DataCells := length(Cells 06)

Grid 2 := XXX

No DataCells = 95

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench17-3.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

0.973	0.954	1.004	1.013	1.011	1.043	0.948
0.998	0.952	1.007	1	0.963	1.006	0.951
0	0.978	0.979	0.935	1.014	0.981	1.015
1.017	1.074	0.968	0.963	0.966	1.014	1.03
1.038	1.053	1.026	1.008	0.983	0.979	1.039
0.968	1.028	0.998	1.017	1.004	1.03	1.046
1.028	0.95	1.047	1	0.977	1.002	1.01

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(Cells 06, XXX)

Grid 3 := XXX

No DataCells := length(Cells 06)

No DataCells = 143

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench17-4.txt")

Points 49 := showcells(page, 7, 0)

Points 49 = 

0.966	1.069	1.014	1.055	0.995	1.002	1.029
0.987	0.983	0.942	0.941	1.01	1.023	1.016
1.034	1.008	0.971	1.064	0.985	1.022	1.032
0.972	1.021	0.985	0.992	1.003	0.997	1.008
0.975	0.951	0.985	1.059	1.047	0.935	0.98
0.94	0.967	0.895	1.02	1.044	1.075	0.98
0.918	0.897	0.934	1.036	1.058	0.998	1.009

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Cells 06 := stack(Cells 06, XXX)

Grid 4 := XXX

No DataCells := length(Cells 06)

No DataCells = 192

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench17-5.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

1.026	0.958	0.958	1.026	0.982	0.988	0.967
1.026	0.906	0.915	0.991	1.006	0.984	0.962
0.979	0.933	1.027	0.934	0.969	0.956	1.042
0.963	1.003	1.016	1.062	0.969	0.987	1.03
1.027	0.977	1.039	0.999	0.998	1.027	1.039
1.023	1.001	0.959	0.997	0.974	1.003	1.09
0.986	1.004	1.009	0.946	1.016	1.023	0.995

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Grid 5 := XXX

Cells 06 := stack(Cells 06, XXX)

No DataCells := length(Cells 06)

No DataCells = 241

page := READPRN("H:\MSOFFICE\Drywell Program data\2006 trenches\Trench17-6.txt")

Points 49 := showcells(page, 7, 0)

Points 49 =

0.937	0.97	0.927	0.946	0.932	0.918	0.942
0.924	1.059	0.934	0.941	0.968	0.924	0.916
0.948	0.948	0.963	0.941	0.932	0.937	0.967
0.977	0.983	1.032	0.982	0.983	0.997	0.953
0.972	0.932	0.977	0.973	1.005	0.959	1.028
1.026	1.002	0.968	0.972	0.953	0.964	0.99
0.981	1.006	0.967	0.945	0.968	0.943	0.978

XXX := convert(Points 49, 7)

No DataCells := length(XXX)

XXX := deletezero cells(XXX, No DataCells)

Grid 6 := XXX

Cells 06 := stack(Cells 06, XXX)

No DataCells := length(Cells 06)

No DataCells = 290

minpoint := min(XXX)

minpoint = 916

The thinnest point at this location is shown below

minpoint := min(Cells 06)

minpoint = 702



**Mean and Standard Deviation**

$$\mu_{06 \text{ actual}} := \text{mean}(\text{Cells } 06) \quad \mu_{06 \text{ actual}} = 962.7897 \quad \sigma_{06 \text{ actual}} := \text{Stdev}(\text{Cells } 06) \quad \sigma_{06 \text{ actual}} = 71.259$$

**Standard Error**

$$\text{Standard error} := \frac{\sigma_{06 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Standard error} = 4.184$$

**Skewness**

$$\text{Skewness} := \frac{(\text{No DataCells}) \cdot \overline{\sum (\text{Cells } 06 - \mu_{06 \text{ actual}})^3}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\sigma_{06 \text{ actual}})^3} \quad \text{Skewness} = -1.252$$

**Kurtosis**

$$\text{Kurtosis} := \frac{\text{No DataCells} \cdot (\text{No DataCells} + 1) \cdot \overline{\sum (\text{Cells } 06 - \mu_{06 \text{ actual}})^4}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3) \cdot (\sigma_{06 \text{ actual}})^4} + \frac{3 \cdot (\text{No DataCells} - 1)^2}{(\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3)} \quad \text{Kurtosis} = 1.587$$

### Normal Probability Plot

In a normal plot, each data value is plotted against what its value would be if it actually came from a normal distribution. The expected normal values, called normal scores, and can be estimated by first calculating the rank scores of the sorted data.

$$j := 0.. \text{last}(\text{Cells } 06) \quad \text{srt} := \text{sort}(\text{Cells } 06)$$

Then each data point is ranked. The array rank captures these ranks

$$z_j := j + 1$$

$$\text{rank}_j := \frac{\sum_{\text{srt}=\text{srt}_j}^{\rightarrow} z}{\sum_{\text{srt}=\text{srt}_j}^{\rightarrow}}$$

$$p_j := \frac{\text{rank}_j}{\text{rows}(\text{Cells } 06) + 1}$$

The normal scores are the corresponding  $p$ th percentile points from the standard normal distribution:

$$x := 1 \quad \text{N\_Score}_j := \text{root}[\text{cnorm}(x) - (p_j), x]$$

### Upper and Lower Confidence Values

The Upper and Lower confidence values are calculated based on .05 degree of confidence, "α"

$$\text{No DataCells} := \text{length}(\text{Cells}_{06})$$

$$\alpha := .05 \quad T\alpha := \text{qt}\left[\left(1 - \frac{\alpha}{2}\right), \text{No DataCells}\right] \quad T\alpha = 1.968$$

$$\text{Lower 95\%Con} := \mu_{06 \text{ actual}} - T\alpha \frac{\sigma_{06 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Lower 95\%Con} = 954.554$$

$$\text{Upper 95\%Con} := \mu_{06 \text{ actual}} + T\alpha \frac{\sigma_{06 \text{ actual}}}{\sqrt{\text{No DataCells}}} \quad \text{Upper 95\%Con} = 971.025$$

These values represent a range on the calculated mean in which there is 95% confidence.

### Graphical Representation

Distribution of the "Cells" data points are sorted in 1/2 standard deviation increments (bins) within +/- 3 standard deviations

$$\text{Bins} := \text{Make bins}(\mu_{06 \text{ actual}}, \sigma_{06 \text{ actual}})$$

$$\text{Distribution} := \text{hist}(\text{Bins}, \text{Cells}_{06})$$

Distribution =

4
8
13
12
18
49
80
74
23
4
0
0

The mid points of the Bins are calculated

$$k := 0..11$$

$$\text{Midpoints}_k := \frac{(\text{Bins}_k + \text{Bins}_{k+1})}{2}$$

The Mathcad function pnorm calculates a portion of normal distribution curve based on a given mean and standard deviation

$$\text{normal curve}_0 := \text{pnorm}(\text{Bins}_1, \mu_{06 \text{ actual}}, \sigma_{06 \text{ actual}})$$


$$\text{normal curve}_k := \text{pnorm}(\text{Bins}_{k+1}, \mu_{06 \text{ actual}}, \sigma_{06 \text{ actual}}) - \text{pnorm}(\text{Bins}_k, \mu_{06 \text{ actual}}, \sigma_{06 \text{ actual}})$$

$$\text{normal curve} := \text{No DataCells} \cdot \text{normal curve}$$

**Results For Trench 17 2006**

The following schematic shows: the the distribution of the samples, the normal curve based on the actual mean and standard deviation, the kurtosis, the skewness, the number of data points, and the the lower and upper 95% confidence values. Below is the Normal Plot for the data.

**Data Distribution**



minpoint = 702

Standard error = 4.184

Skewness = -1.252

Kurtosis = 1.587

minpoint = 702


$\mu_{06}$  actual = 962.79 Lower 95%Con = 954.554

$\sigma_{06}$  actual = 71.259

Upper 95%Con = 971.025

A Kurtosis value which is less than +/- 1.0 and approaches 0 is indicative of a normal distribution. Therefore this distribution may not be completely normal. The data is skewed towards the right.

**Normal Probability Plot**



A Normal Probability Plot indicates the distribution of this data is not completely normal

Review of the 2006 data shows that the first 49 point grid located at the top of the trench is much thinner than the remaining five 49 point grids lower in the trenches

The mean of the top grid is  $\text{mean}(\text{Grid}_{\text{Top}2006}) = 845.128$

While the mean of the remaining five grids are:

$\mu_{06} \text{ grid.actual}_0 := \text{mean}(\text{Grid}_2)$   $\text{mean}(\text{Grid}_2) = 972.583$

$\mu_{06} \text{ grid.actual}_1 := \text{mean}(\text{Grid}_3)$   $\text{mean}(\text{Grid}_3) = 999.75$

$\mu_{06} \text{ grid.actual}_2 := \text{mean}(\text{Grid}_4)$   $\text{mean}(\text{Grid}_4) = 996.51$

$\mu_{06} \text{ grid.actual}_3 := \text{mean}(\text{Grid}_5)$   $\text{mean}(\text{Grid}_5) = 993.816$

$\mu_{06} \text{ grid.actual}_4 := \text{mean}(\text{Grid}_6)$   $\text{mean}(\text{Grid}_6) = 965.102$

$\text{mean}(\mu_{06} \text{ grid.actual}) = 985.552$

Therefore the distribution of each of these set of data were investigated. The following creates an array of the lower 5 grids

$\text{five Cells} := \text{stack}(\text{Grid}_3, \text{Grid}_2)$

$\text{five Cells} := \text{stack}(\text{five Cells}, \text{Grid}_4)$

$\text{five Cells} := \text{stack}(\text{five Cells}, \text{Grid}_5)$

$\text{five Cells} := \text{stack}(\text{five Cells}, \text{Grid}_6)$

$\text{No DataCells} := \text{length}(\text{five Cells})$

$\text{No DataCells} = 243$

**Mean and Standard Deviation**

$$\mu_{5grids.actual} := \text{mean}(\text{five Cells})$$

$$\sigma_{5grids.actual} := \text{Stdev}(\text{five Cells})$$

$$\mu_{5grids.actual} = 985.5473$$

$$\sigma_{5grids.actual} = 41.462$$

**Standard Error**

$$\text{Standard error} := \frac{\sigma_{5grids.actual}}{\sqrt{\text{No DataCells}}}$$

$$\text{Standard error} = 2.66$$

**Skewness**

$$\text{Skewness} := \frac{(\text{No DataCells}) \cdot \overline{\Sigma(\text{five Cells} - \mu_{5grids.actual})^3}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\sigma_{5grids.actual})^3}$$

$$\text{Skewness} = -0.242$$

**Kurtosis**

$$\text{Kurtosis} := \frac{\text{No DataCells} \cdot \overline{\Sigma(\text{five Cells} - \mu_{5grids.actual})^4}}{(\text{No DataCells} - 1) \cdot (\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3) \cdot (\sigma_{5grids.actual})^4} + \frac{3 \cdot (\text{No DataCells} - 1)^2}{(\text{No DataCells} - 2) \cdot (\text{No DataCells} - 3)}$$

$$\text{Kurtosis} = -0.082$$

### Normal Probability Plot

In a normal plot, each data value is plotted against what its value would be if it actually came from a normal distribution. The expected normal values, called normal scores, and can be estimated by first calculating the rank scores of the sorted data.

$$j := 0.. \text{last}(\text{five Cells}) \qquad \text{srt} := \text{sort}(\text{five Cells})$$

Then each data point is ranked. The array rank captures these ranks

$$zz_j := j + 1$$

$$\text{rank}_j := \frac{\sum_{\text{srt}=\text{srt}_j} \text{zz}}{\sum \text{srt}=\text{srt}_j}$$

$$p_j := \frac{\text{rank}_j}{\text{rows}(\text{five Cells}) + 1}$$

The normal scores are the corresponding  $p$ th percentile points from the standard normal distribution:

$$x := 1 \qquad \text{N\_Score}_j := \text{root}[\text{cnorm}(x) - (p_j), x]$$

**Upper and Lower Confidence Values**

The Upper and Lower confidence values are calculated based on .05 degree of confidence "α"

No DataCells := length(five Cells)

No DataCells = 243

α := .05      Tα := qt(1 - α/2, No DataCells)      Tα = 1.97

Lower 95%Con := μ Sgrids.actual - Tα \* (σ Sgrids.actual / √No DataCells)      Lower 95%Con = 980,308

Upper 95%Con := μ Sgrids.actual + Tα \* (σ Sgrids.actual / √No DataCells)      Upper 95%Con = 994,552


These values represent a range on the calculated mean in which there is 95% confidence.

**Graphical Representation**

Distribution of the "Cells" data points are sorted in 1/2 standard deviation increments (bins) within +/- 3 standard deviations

Bins := Make bins(μ Sgrids.actual, σ Sgrids.actual)

Distribution := hist(Bins, five Cells)



The mid points of the Bins are calculated

k := 0..11      Midpoints<sub>k</sub> := (Bins<sub>k</sub> + Bins<sub>k+1</sub>) / 2

The Mathcad function pnorm calculates a portion of normal distribution curve based on a given mean and standard deviation

normal curve<sub>0</sub> := pnorm(Bins<sub>1</sub>, μ Sgrids.actual, σ Sgrids.actual)

normal curve<sub>k</sub> := pnorm(Bins<sub>k+1</sub>, μ Sgrids.actual, σ Sgrids.actual) - pnorm(Bins<sub>k</sub>, μ Sgrids.actual, σ Sgrids.actual)


normal curve := No DataCells \* normal curve



Results For Trehcn 17 ower 5 grids Oct. 2006

The following schematic shows: the the distribution of the samples, the normal curve based on the actual mean and standard deviation, the kurtosis, the skewness, the number of data points, and the the lower and upper 95% confidence values. Below is the Normal Plot for the data.

Data Distribution



minpoint = 702

Standard error = 2.66

Skewness = -0.242


Kurtosis = -0.082

$\mu$  Sgrids.actual = 985.547

$\sigma$  Sgrids.actual = 41.462

A Kurtosis value which is less than +/- 1.0 and approaches 0 is indicative of a normal distribution.

Normal Probability Plot



A Normal Probability Plot indicates the distribution of this data is not completely normal

Therefore when considering the entire 2006 data (all 6 grids) set which is skewed, the corrosion rate from 1986 to 1992 was

$$\frac{(\mu_{86 \text{ actual}} - \mu_{06 \text{ actual}})}{1992 - 1986} = 10.18$$

Therefore when considering the entire 2006 data (all 6 grids) set which is skewed, the apparent corrosion rate from 1986 to 2006 was

$$\frac{(\mu_{86 \text{ actual}} - \mu_{06 \text{ actual}})}{2006 - 1986} = 3.054$$

When considering only the 5 lower grids of the 2006 data set which is normally distributed, the corrosion rate from 1986 to 1992 was

$$\frac{(\mu_{86 \text{ actual}} - \mu_{5 \text{ grids. actual}})}{1992 - 1986} = 6.387$$

This is very consistent with the Bay 5 trench results

When considering only the 5 lower grids of the 2006 data set which is normally distributed, the apparent corrosion rate from 1986 to 2006 was

$$\frac{(\mu_{86 \text{ actual}} - \mu_{5 \text{ grids. actual}})}{2006 - 1986} = 1.916$$

This is very consistent with the Bay 5 trench results



**BAY 1**

	Point	Vertical	Horizontal	1992 value	2006 Value	Comments
	1	D16	R27	0.720	0.710	
	2	D22	R17	0.716	0.690	
	3	D23	L3	0.705	0.665	
	4	D24	L33	0.760	0.738	Very Rough Surface
	5	D24	L45	0.710	0.680	
	6	D48	R19	0.760	0.731	
	7	D39	R7	0.700	0.669	
	8	D48	R0	0.805	0.783	
	9	D36	L38	0.805	0.754	
	10	D16	R23	0.839	0.824	
	11	D23	R12	0.714	0.711	
	12	D24	L5	0.724	0.722	
	13	D24	L40	0.792	0.719	
	14	D2	R35	1.147	1.157	
	15	D8	L51	1.158	1.160	
	16	D50	R40	0.796	0.795	
	17	D40	R16	0.860	0.848	
	18	D38	L2	0.917	0.899	
	19	D38	L24	0.890	0.865	
	20	D18	R13	0.965	0.912	
	21	D24	R15	0.726	0.712	
	22	D32	R13	0.852	0.854	
	23	D48	R15	0.850	0.828	

**PASSPORT#**  
 00546049 07  
**AR# A2152754 E09**  
**ATTACHMENT 4**  
**PAGE 2 OF 2**

Data obtained from  
 NDE Data Sheets 92-072-12 page 1 of 1  
 NDE Data Sheets 92-072-18 page 1 of 1  
 NDE Data Sheets 92-072-19 page 1 of 1  
 All horizontal measurements taken 13" to the right of the centerline of the reinforcement ring (Boss).  
 All vertical measurements taken from bottom of vent nozzle at the 13" reference line.  
 Surface roughness prohibited characterization of all readings.

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

*AR* 10-22-06

IR 21LR-032  
 Pg 2 of 2  
 DATE: III 10-22-06




# BAY 3

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D16	R63	0.795	0.795	N/A
2	D18	R48	1	0.999	
3	D17	R33	0.857	0.850	
4	D13	L5	0.898	0.903	
5	D25	L8	0.823	0.819	
6	D15	L56	0.968	0.972	
7	D29	R4	0.826	0.816	
8	D34	L4	0.78	0.764	

Data obtained from

NDE Data Sheets 92-072-14 page 1 of 1

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.



IR21LR-0012 Pg 2 of 2  
MM' LIII 10:22-06

General Electric	<b>Ultrasonic Thickness Measurement Data Sheet</b>	File Name:	N/A
Oyster Creek		Date:	10/20/2008
Refueling Outage - 1R21		UT Procedure:	ER-AA-335-004
Page 1 of 2		Specification:	IS-328227-004
Examiner: Leslie Richter	Level: II	Instrument Type:	Panametrics 37DL Plus
Examiner: N/A	Level: N/A	Instrument No:	031124909
Transducer Type: D785	Serial #: 104012	Size: 0.200"	Freq: 5 Mhz
Transducer Cable Type: Panametrics	Length: 5'	Couplant: Soundsafe	Batch No: 19620
Calibration Block Type: C/S Step Wedge	Block Number:	CAL-STEP-138	

**SYSTEM CALIBRATION**

INSTRUMENT SETTINGS		Initial Cal. Time	Calibration Checks		Final Cal. Time
Coarse Range:	5.0"	15:38	15:51	16:45	17:28
Coarse Delay:	N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches			
Delay Calib:	N/A	Thermometer:	246647	Comp. Temp:	82°
Range Calib:	N/A	W/O Number:	C2013477	Block Temp:	76°
Instrument Freq:	N/A	Total Crew Dose	Drywell Containment Vessel Thickness Examination, External UT Inspections.		
Gain:	72 db	2 mR			
Damping:	N/A	<b>Bay - 5</b>			
Reject:	N/A				
Filter:	N/A				

BAY	Point Number	Vertical Location	Horizontal Location	Thickness Reading

See Attached for Locations and Thickness Readings

PASSPORT# 00548049 07  
 AR# A2152754 E09  
 ATTACHMENT X  
 PAGE 5 OF 22

COMMENTS: N/A

*manal abul* 10-22-06

Reviewed by: Scott Erickson	<i>Scott R. Erickson</i>	Level	II	Date	10/19/2008
-----------------------------	--------------------------	-------	----	------	------------

1621R-019 Pg 2 of 2  
90-22-013 MAM  
10-22-06

PASSPORT# 00546049 07  
AR# A2152754 E09  
ATTACHMENT Y  
PAGE 6 OF 20


# BAY 5

	Point	Vertical	Horizontal	1992 value	2006 Value	Comments
*		1 D38	R12	0.97	0.948	up .97 dn .97
*		2 D38	R7	1.04	0.955	Rough surface - up .99 dn .99
*		3 D42	R10	1.02	0.989	up 1.0 dn 1.04
*		4 D41	L7	0.97	0.948	Rough surface, also dished
*		5 D42	L11	0.89	0.88	Rough surface
**		6 D47	R5	1.06	0.981	up 1.018 dn 1.014
**		7 D48	L18	0.99	0.974	Rough surface left .99 right N/A
**		8 D46	L31	1.01	1.007	Rough surface

Note: up, dn, left & right readings were taken 1/8" from recorded 2006 value reading.  
Rough surface limited taking additional readings. Reference above.  
\* =Vertical and horizontal measurements taken from top of coating on long seam 62" to right  
\*\* =Vertical and horizontal measurements taken from bottom of nozzle at 6 o'clock position  
Reference NDE Data Sheets 92-072-16 page 1 of 1

- 1 - Reference off the weld 62" to the right of the centerline of the bay.
- 2 The original data sheet is not clear as to whether this point is to the right or left of the weld.  
Therefore NDE shall verify this dimension.

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

 10-20-06





# BAY 7

	Point	Vertical	Horizontal	1992 value	2006 Value	Comments
	1	D21	R39	0.92	N/A	Could not locate area
	2	D21	R32	1.016	N/A	Could not locate area
	3	D10	R20	0.984	0.964	up/dn ranged from 0.956 to 0.980
	4	D10	R10	1.04	1.04	N/A
	5	D21	L6	1.03	1.003	up/dn ranged from 1.000 to 1.049
	6	D10	L23	1.045	1.023	up/dn ranged from 1.020 to 1.052
	7	D21	L12	1	1.003	up/dn ranged from 1.002 to 1.026

Data obtained from  
 NDE Data Sheets 92-072-20 page 1 of 1  
 Note: up, dn readings were taken 1/8" from recorded 2006 value reading.

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT  $\frac{4}{29}$   
 PAGE 2 OF 29

*du Stone*

10-19-2006

IR 21LR-005 Pg 2 of 2  
 2006 LIII  
 10-26-06



# BAY 9

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D29	R32	0.96	0.968	N/A
2	D18	R17	0.94	0.934	
3	D20	R8	0.994	0.989	
4	D27	R15	1.02	1.016	
5	D35	L5	0.985	0.964	
6	D13	L30	0.82	0.802	
7	D16	L35	0.825	0.82	
8	D21	L38	0.791	0.781	
9	D20	L53	0.832	0.823	
10	D30	L8	0.88	0.955	

Data obtained from  
NDE Data Sheets 92-072-22 page 1 of 1

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT  
PAGE 12 OF 20

2/21/07 III  
10-22-06

1K21LR-006 Pg 2 of 2

General Electric		<b>Ultrasonic Thickness Measurement Data Sheet</b>		File Name:	N/A
Oyster Creek				Date:	10/20/2006
Fueling Outage - 1R21				UT Procedure:	ER-AA-335-004
Page 1 of 2				Specification:	IS-328227-004
Examiner: Graham McNabb		Level: II	Instrument Type: Panametrics 37DL Plus		
Examiner: N/A		Level: N/A	Instrument No: 031124909		
Transducer Type: D795	Serial #: 104010	Size: 0.200"	Freq: 5 Mhz	Angle: 0°	
Transducer Cable Type: Panametrics Length: 5'		Couplant: Soundsafe	Batch No: 19620		
Calibration Block Type: C/S Step Wedge		Block Number: CAL-STEP-080			

**SYSTEM CALIBRATION**

INSTRUMENT SETTINGS		Initial Cal. Time	Calibration Checks		Final Cal. Time
Coarse Range:	5.0"	2:15	N/A	N/A	5:15
Coarse Delay:	N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches			
Delay Calib:	N/A	Thermometer: 246534	Comp. Temp: 74°	Block Temp: 72°	
Range Calib:	N/A	W/O Number: C2013477			
Instrument Freq:	N/A	Total Crew Dose: 6 mR	Drywell Containment Vessel Thickness Examination. External UT Inspections.		
Gain:	58 db				
Damping:	N/A				
Reject:	N/A				
Filter:	N/A				

Bay - 11

BAY	Point Number	Vertical Location		Horizontal Location		Thickness Reading

See Attached for Locations and Thickness Readings

PASSPORT# 00546049 07  
 AR# A2152754 E08  
 ATTACHMENT 1/2  
 PAGE 11 OF 11

COMMENTS: N/A

*mm'ad* 10-22-06

Reviewed by: Scott Erickson *Scott R. Erickson* Level II Date 10/20/2008

# BAY 11

	Point	Vertical	Horizontal	1992 value	2006 Value	Comments
	1	D20	R29	0.705	0.700	N/A
	2	D25	R32	0.77	0.760	
	3	D21	L4	0.832	0.830	
	4	D24	L6	0.755	0.751	
	5	D32	L14	0.831	0.823	
	6	D27	L22	0.8	0.756	
	7	D31	R20	0.831	0.817	
	8	D40	R13	0.85	0.825	

Data obtained from  
NDE Data Sheets 92-072-10 page 1 of 1

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

*MM L III 10-22-06*

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT  $\frac{4}{2}$   
PAGE 13 OF 23

1K21R-008 Pg 2 of 2



# BAY 13

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	U1	R45	0.672	N/A	Could not locate area
2	U1	R38	0.729	N/A	Could not locate area
3	D21	R48	0.941	0.923	
4	D12	R36	0.915	0.873	
5	D21	R6	0.718	0.708	
6	D24	L8	0.655	0.658	
7	D17	L23	0.618	0.602	
8	D24	L20	0.718	0.704	
9	D28	R41	0.924	0.915	
10	D28	R12	0.728	0.741	
11	D28	L15	0.685	0.669	
12	D28	L23	0.885	0.886	
13	D18	D40	0.932	0.814	
14	D18	R8	0.868	0.870	
15	D20	L9	0.683	0.666	
16	D20	L29	0.829	0.814	
17	D9	R38	0.807	N/A	Could not locate area
18	D22	R38	0.825	N/A	Could not locate area
19	D37	R38	0.912	0.916	

5  
8  
8  
19

Data obtained from  
NDE Data Sheets 92-072-24 page 1 of 2

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT  $\frac{4}{2}$   
PAGE 14 OF 20

Michael L III 10-22-06

IR21LR-05-03 2 of 2





# BAY 15

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D12	R26	0.786	0.779	0.711 to 0.779
2	D22	R21	0.829	0.798	0.777 to 0.798
3	D33	R17	0.932	0.935	
4	D30	R7	0.795	0.791	
5	D26	L3	0.85	0.855	0.817 to 0.855
6	D6	L8	0.794	0.787	0.715 to 0.787
7	D26	L18	0.808	0.805	
8	D20	L36	0.77	0.760	
9	D36	L44	0.722	0.749	0.720 to 0.749
10	D24	L48	0.86	0.852	0.837 to 0.852
11	D24	L65	0.825	0.843	0.798 to 0.843

Data obtained from  
 NDE Data Sheets 92-072-21 page 1 of 1  
 Note: scanned 0.25" area around recorded 2006 value number - see comments for ranges.

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 4  
 PAGE 16 OF 22

/R21LK-013 19 CURC



10-19-2006  
 Page 2 of 2 021  
 E. Miller 10-22-06

PASSPORT# 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 4  
 PAGE 18 OF 32

# BAY 17

Note: measurement from vent pipe CL to floor 60"

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D12	R50	0.916	0.909	
2	D9	R40	1.150	0.681	up .705 dn .663
3	D16	R26	0.898	0.894	
4	D34	R24	0.951	0.963	
5	D6	R20	0.913	0.822	
6	D17	R7	0.992	0.909	
7	D18	L14	0.970	0.970	
8	D34	L48	0.990	0.960	
9	D21	L29	0.720	0.970	
10	D3	L2	0.830	0.844	
11	N/A	N/A	N/A	N/A	

Note: Down measurements taken from bottom of boss which is 18" below vent line.

Locations 8, 9, & 3 look to be un-prepped flat areas of the original surface.

All left, right measurements taken from 8" left of liner long seam

Data obtained from

NDE Data Sheets 92-072-08 page 1 of 1

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

Matthew E. Winters 10-19-2006

General Electric		<b>Ultrasonic Thickness Measurement Data Sheet</b>			File Name: N/A	
Oyster Creek					Date: 10/22/2006	
Refueling Outage - 1R21					UT Procedure: ER-AA-335-004	
Page 1 of 2					Specification: IS-328227-004	
Examiner: Matt Wilson <i>Matt Wilson</i>		Level: II	Instrument Type: Panametrics 37DL Plus			
Examiner: N/A		Level: N/A	Instrument No: 031124709			
Transducer Type: D795	Serial #: 104010	Size: 0.200"	Freq: 5 Mhz	Angle: 0°		
Transducer Cable Type: Panametrics Length: 5'		Couplant: Soundsafe	Batch No: 19620			
Calibration Block Type: C/S Step Wedge		Block Number: CAL-STEP-088				

**SYSTEM CALIBRATION**

INSTRUMENT SETTINGS		Initial Cal. Time	Calibration Checks		Final Cal. Time
Coarse Range:	5.0"	14:26	15:36	N/A	16:09
Coarse Delay:	N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches			
Delay Calib:	N/A	Thermometer: 246534	Comp. Temp: 82°	Block Temp: 82°	
Range Calib:	N/A	W/O Number: R2088926 <i>SEA</i>			
Instrument Freq:	N/A	Total Crew Dose: 7 mR	C2013477 Drywell Containment Vessel Thickness Examination, External UT inspections.		
Gain:	67 db				
Damping:	N/A				
Reject:	N/A				
Filter:	N/A				

Bay - 19

BAY	Point Number	Vertical Location	Horizontal Location	Thickness Reading

See Attached for Locations and Thickness Readings

PASSPORT# 00546049 07  
 AR# A2152754 E08  
 ATTACHMENT 4  
 PAGE 12 OF 33

COMMENTS: N/A

*Lee Stone* 10-22-06

02  
 Pg. 2 of 2  
 10-22-06  
 M. W. L.

# BAY 19

Point	Vertical	Horizontal	1992 value	2006 Value	Comments
1	D30	R60	0.932	0.904	up .897 dn .867
2	D52	R58	0.924	0.921	up .850 dn .907
3	D33	R40	0.955	0.932	up .894 dn .905
4	D32	R11	0.94	N/A	Could not locate area
5	D31	R3	0.95	0.932	up .883 dn .897
6	D52	L65	0.86	N/A	Could not locate area
7	D54	L10	0.969	0.891	up .821 dn .912
8	D16	R64	0.793/0.953 ***	0.745	up .721 dn .747
9	D18	R12	0.776	0.780	up .728 dn .745
10	D19	R0	0.79	0.791	up .736 dn .846
11	20D	L18	N/A	0.738	up .738 dn .712

*New Value*

Data obtained from  
 NDE Data Sheets 92-072-05 page 1 of 1  
 NDE Data Sheets 92-072-07 page 1 of 1

Note: Per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

\*\*\* - This value is not clear from the original datasheet -NDE to verify this value.

Note: per discussion with Engineering, single point readings were taken in lieu of 6, based on surface curvature.

*Matthew E. Wilton* 10/22/06


PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT ✓  
 PAGE 22 OF 22



PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT  $\frac{5}{8}$   
PAGE 2 OF 8

This sketch is provided  
only to show location of  
points and not the actual values.  
Refer to Attachment 4 for  
1992 and 2000 Thickness  
Readings

SEE DETAIL  
CROSS SECTION AREA  
OF TRENCH




Refer to  
Sheet 5  
for Additional  
Points

**KEY**  
1901



(SCALE)

KEY



△ - DATA POINT LT  
 WITH SHELL THICKNESS  
 FOR EACH INDIVIDUAL  
 BAY

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 5  
 PAGE 3 OF 8

Refer to page  
 8 for additional  
 points


BAY  
 PER F  
 AREA

BAY  
 PER F  
 AREA


BAY 5  
 PER F  
 AREA

BAY 7  
 PER F  
 AREA

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT  
PAGE 1 OF 5




PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 5/8  
PAGE 5 OF 8  
*Page 5 of 8*




SEE DETAIL  
CROSS SECTION AREA  
OF TRENCH

KEY 1  
(SCALE)



PLAN PART II

(NONE)



PASSPORT#  
 00548049 07  
 AR# A2152754 E09  
 ATTACHMENT  
 PAGE 7 OF 8  
 IT 11  
 Page 7 of 8

PLAN

PART II

NONE )

SCALE  
NEL

30°  
11

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 5  
PAGE 8 OF 8

Case 8 of 8

△ - DATA POINT LT  
WITH SHELL THICKNESS  
FOR EACH INDIVIDUAL BAY

BAY 13

FLOOR EL 10'-3"

BAY 15

BAY

PERF

AREA


BAY

PERFC

AREA

9-19

11A, 1



Bay	Point	Vertical	Horizontal	Under Inside Floor	Under Wetted Concrete	1992 value	NDE Data Sheet	2006 Value	Corrosion Rate 1992 to 2006	Corrosion Rate Under floor above Wetted Area	Corrosion Rate in Wetted Area
1	6	D48	R16	Yes	Yes	0.76	IR21LR-022	0.731	2.071		2.071
1	7	D39	R5	Yes	Yes	0.7	IR21LR-022	0.669	2.214		2.214
1	8	D48	R0	Yes	Yes	0.805	IR21LR-022	0.783	1.571		1.571
1	9	D36	L38	Yes		0.805	IR21LR-022	0.734	3.643	3.643	
1	16	D50	R40	Yes	Yes	0.796	IR21LR-022	0.793	0.071		0.071
1	17	D48	R16	Yes	Yes	0.86	IR21LR-022	0.846	1.000		1.000
1	18	D38	L2	Yes		0.917	IR21LR-022	0.899	1.286	1.286	
1	19	D38	L24	Yes		0.89	IR21LR-022	0.863	1.786	1.786	
1	22	D32	R13	Yes		0.832	IR21LR-022	0.834	-0.143		
1	23	D48	R15	Yes	Yes	0.83	IR21LR-022	0.828	1.571		1.571
5	1	D40	R13 *1	Yes	Yes	0.97	IR21LR-019	0.948	1.571		1.571
5	2	D42	R3 *1	Yes	Yes	1.04	IR21LR-019	0.933	6.071		6.071
5	3	D44	R10 *1	Yes	Yes	1.02	IR21LR-019	0.989	2.214		2.214
5	4	D44	R/L7 *1 *2	Yes	Yes	0.97	IR21LR-019	0.948	1.571		1.571
5	5	D46	R/L11 *1 *2	Yes	Yes	0.89	IR21LR-019	0.88	0.714		0.714
5	6	D44	L4	Yes	Yes	1.06	IR21LR-019	0.981	5.643		5.643
13	7	D48	L24	Yes	Yes	0.99	IR21LR-019	0.974	1.143		1.143
5	8	D46	L28	Yes	Yes	1.01	IR21LR-019	1.007	0.214		0.214
9	5	D36	L4	Yes		0.983	92-072-22 Page 1 fo 3	0.964	1.500	1.500	
9	8	D22	L45°	Yes	Yes	0.791	92-072-22 Page 1 fo 8	0.781	0.714		0.714
11	5	D32	L14	Yes		0.831	92-072-10 page 1 of 4	0.823	0.571	0.571	
11	6	D27	L22	Yes		0.8	92-072-10 page 1 of 5	0.736	3.143	3.143	
11	7	D31	R20	Yes		0.831	92-072-10 page 1 of 6	0.817	1.000	1.000	
11	8	D40	R13	Yes	Yes	0.83	92-072-10 page 1 of 7	0.823	1.786		1.786
13	9	D28	R41	Yes		0.924	92-072-24 page 1 of 10	0.915	0.643	0.643	

PASSPORT#  
 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 2  
 PAGE 4 OF 2  
 11/3/03

Bay	Point	Vertical	Horizontal	Under Inside Floor	Under Wetted Concrete	1992 value	NDE Data Sheet	2006 Value	Corrosion Rate 1992 to 2006	Corrosion Rate Under floor above Wetted Area	Corrosion Rate in Wetted Area
13	10	D28	R12	Yes		0.728	92-072-24 page 1 of 11	0.741	-0.929		
13	11	D28	L15	Yes		0.685	92-072-24 page 1 of 12	0.669	1.143	1.143	
15	3	D33	R17	Yes		0.932	IR21LR-015	0.935	-0.214		
15	5	D26	L3	Yes		0.85	IR21LR-015	0.855	-0.357		
15	9	D36	L40	Yes		0.722	IR21LR-015	0.749	-1.929		
17	3	D32	R28	Yes		0.898	IR21LR-021	0.894	0.286	0.286	
17	4	D52	R30	Yes	Yes	0.951	IR21LR-021	0.963	-0.857		
17	5	D36	R12	Yes		0.913	IR21LR-021	0.822	6.500	6.500	
17	6	D52	L6	Yes	Yes	0.992	IR21LR-021	0.909	5.929		5.929
17	7	D36	L26	Yes		0.97	IR21LR-021	0.97	0.000		
17	8	D52	L40	Yes	Yes	0.99	IR21LR-021	0.96	2.143		2.143
									0.000		
19	2	D52	R66	Yes	Yes	0.924	IR21LR-020	0.921	0.214		0.214
19	3	D33	R49	Yes		0.953	IR21LR-020	0.932	1.643	1.643	
19	4	D32	R11	Yes		0.94	IR21LR-020	Not Located			
19	5	D53	R2	Yes	Yes	0.95	IR21LR-020	0.932	1.286		1.286
19	6	D52	L65	Yes	Yes	0.86	IR21LR-020	Not Located			
19	7	D39	L12	Yes	Yes	0.969	IR21LR-020	0.891	5.571		5.571

Minimum Rate	0.286	0.071
Maximum Rate	6.500	6.071
Average Rate	2.280	2.334

Minimum Thickness Recorded in 2006 0.669

Assuming a maximum corrosion rate of 6.5 MPY and an uncertainty of 28 mils the 0.669 location will thin to the following in 2008

0.636

Assuming a Average corrosion rate of 2.3 MPY and an uncertainty of 20 mils the 0.669 location will thin to the following in 2008

0.644

PASSPORT# 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 26 of 31  
 PAGE 2 OF 2




1R21LR-032 19 of 2

General Electric	<b>Ultrasonic Thickness Measurement Data Sheet</b>	Report Number:	1R21LR-32
Oyster Creek		Date:	10/26/2008
Refueling Outage - 1R21		UT Procedure:	ER-AA-335-004
Page 1 of 2		Specification:	IS-328227-004

Examiner: Leslie Richter	Level: II	Instrument Type: Panametrics 37DL Plus
Examiner: N/A	Level: N/A	Instrument No: 031125409
Transducer Type: DV 508	Serial #: 072581	Size: 0.438"
Transducer Cable Type: Panametrics	Length: 5'	Couplant: Soundsafe
Calibration Block Type: C/S Step Wedge	Block Number: CAL-STEP-138	Batch No: 19620

SYSTEM CALIBRATION			
INSTRUMENT SETTINGS	Initial Cal. Time	Calibration Checks	Final Cal. Time
Coarse Range: 2.0"	9:20	9:35 9:38	10:00
Coarse Delay: N/A	Calibrated Sweep Range = 0.500" Inches to 1.500" Inches		
Delay Calib: N/A	Thermometer: 246647	Comp. Temp: 68°	Block Temp: 65°
Range Calib: N/A	W/O Number: G2613478	C3013737-02	
Instrument Freq: N/A	Total Crew Dose: 45 mR	Drywell Containment Vessel Thickness Examination. Internal UT inspections.	
Gain: 55 db	<b>Trench 1 Bay 5 Extended Grid Data</b>		
Damping: N/A			
Reject: N/A			
Filter: N/A			

The UT transducer was positioned in the same orientation at each grid point.



Area extended deeper into Trench								
Location ID	Trench 1	Bay	5	Elev.	10' 3"			
6	1.182	1.145	1.088	1.085	1.088	1.083	1.060	6
5	1.142	1.106	1.070	1.105	1.094	1.077	1.084	5
4	1.147	1.070	1.083	1.085	1.125	1.087	1.059	4
3	1.161	1.133	1.131	1.127	1.094	1.060	1.052	3
2	1.165	1.152	1.148	1.138	1.130	1.113	1.096	2
1	1.151	1.142	1.142	1.125	1.144	1.138	1.148	1
	G	F	E	D	C	B	A	
	Tscr.				AVG.			
	0.660				1.113			
	Min Reading				Max. Reading			
	1.052				1.182			

**COMMENTS:**  
 The removal of concrete from trench exposed six more inches of liner. The template was placed below previous grid location with the centerline of the top row 1" +/- 1/16" from previous grid bottom row. The holes were painted on the liner using the 8"x 8" template, readings were then taken with template removed.  
 An area approximately 14"x 6" of extended trench area was scanned 100% with the minimum reading of 1.047" and a maximum reading of 1.150" recorded.  
 The 100% scan inspection was performed using a D799 (Serial # 104141) transducer and the grid points inspection was performed using a DV 506 transducer.  
 V was stamped above grid point 6D.


Reviewed by: Lee Stone *[Signature]*

PASSPORT# 00546049 07  
 AR# A2152754 E09  
 ATTACHMENT 2  
 PAGE 1 OF 2

10/26  
 8  
 7

IR21LR-032 A3 2072

MM C II 10-26-6



BAY 5 TRENCH 1

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 2  
PAGE 2 OF 2

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 2  
PAGE 1 OF 3

**Exelon.**  
Nuclear

## Memorandum

Asset Management # AM-2006-011  
Revision 3

Date: November 6, 2006

To: Howie Ray  
Peter Tamburro

cc: Roman Gesior  
Richard Hall

From: Steve Leshnoff

Subject: Final Report of the Third Party Independent Review of Oyster Creek  
Drywell Containment Corrosion Evaluation in Bay 5 and Bay 17 Trenches

The purpose of this memo is to document the independent third party review (ITPR) of the Oyster Creek (OC) Drywell Containment Corrosion Evaluation in Bay 5 and Bay 17 Trenches and to provide you with the results related to that review. The review was performed in accordance with Training & Reference Material (T&RM) HU-AA-1212, Revision 1, Technical Task Risk/Rigor Assessment, Pre-job Brief, Independent Third Party Review, and Post-Job Brief.

### Purpose of the Review

Ultrasonic Testing (UT) measurements of the drywell thickness at and below the interior floor at the elevation of the sand bed were obtained during OC 1R21 Refueling Outage. The intent was to complete the assessment of the potential for on-going corrosion both above and below the drywell floor. The purpose of this review is to establish that the appropriate statistical methods were used to evaluate the data and that the correct conclusions were drawn from the statistical evaluation of the data.

### Scope of Review

I performed a detailed review of the statistical methods that were used in the evaluation of the UT measurements. The evaluation included the following steps, each of which was reviewed:

- Establish that the UT data from a measurement template was normally distributed using the kurtosis tests
- Derive the standard deviation and standard error for each of the data distributions
- Derivation of the 95% confidence intervals for the data.

- Determination of the lower range of the calculated mean thickness for which there is 95% confidence.
- Calculation of the apparent corrosion rate on an average basis in the trench in Bay 5 and in the trench in Bay 17.

Limitations

There were no limitations to this review.

Conclusions

All of the statistical tests and steps were appropriate and necessary and were applied correctly. The apparent corrosion rate is minimal. Revision D to Technical Evaluation A2152754 E09 impacts only the narrative description of the UT data collection activities and includes added detailed discussion in the conclusion without modification.

Revision G to Technical Evaluation A2152754 E09 concerns the data collected in the trench in Bay 17. The revision aligns the lower 5 grids of 6 grids, in a single row, taken in 2006 with the 5 grids, in one row, taken in 1986. The alignment develops two comparable normal distributions such that a basis is established to determine an apparent average corrosion rate in the trench in Bay 17.

Comments

Refer to Attachment A for technical comments and resolution to those comments on Revision G of the technical evaluation. The comments did not warrant an Issues Report.

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 8  
PAGE 3 OF 3

ATTACHMENT A

AM-2006-011  
Revision 3 |

REFERENCE DOCUMENT NO. /REV: OC Drywell Containment Corrosion Evaluation in Bay 5 and Bay  
17 Trenches

COMMENTS		RESOLUTION	ACCEPTANCE OF RESOLUTION.	
1	No comments on Revision G to Technical Evaluation A2152754 E09 c			
2				
3				
4				
5				
6				
7				
8				
9				
10				
END				
<u>Leshnoff</u> SUBMITTED BY		<u>Peter Tamburro</u> RESOLVED BY	<u>11/06/06</u> DATE	
DATE				



Privileged and Confidential

November 3, 2006

Mr. F. Howie Ray  
Manager, Mech/Struct Design  
Oyster Creek Generating Station  
AmerGen Energy Company, LLC  
U.S. Route #9  
Forked River, NJ 08751-0388

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 1  
PAGE 1 OF 2

Subject: Third Party Independent Review of Oyster Creek Drywell Water Evaluation

Dear Mr. Ray:

MPR has completed a HU-AA-1212 Independent Third Party Review of the Oyster Creek drywell evaluation concerning standing water found in drywell shell inspection trenches in the 10' 3" concrete floor in the drywell. This review included the following documents:

- Technical Evaluation A/R A2152754 E06, with attachments
- Technical Evaluation A/R A2152754 E09, with attachments
- ECR 06-00879

Based on this review, we generated two comments, one concerning reported local wall thinning in Bay 17 possibly exceeding limiting dimensions for being considered local, and one concerning the relatively low pH value (and possible corrosivity) of trench/drywell gap water during outages when the migration of CRD water through the concrete pad to the inspection trenches and drywell wall occurs. These were transmitted to you via email on November 2. Both comments have been resolved as follows:

- Local wall thinning in Bay 17: Technical Evaluation A/R A2152754 E09 has been revised to include another local thinning acceptance criterion documented in Oyster Creek calculation C-1302-187-5320-024. The UT measurements of concern meet this acceptance criterion and this issue is considered resolved.
- Characterization of the water in the drywell: Section 2.3 of Technical Evaluation A/R A2152754 E06 has been revised to clarify the following points:
  - Any subsequent water (such as reactor coolant) entering the concrete floor to drywell gap will increase in pH due to its migration through and contact with the concrete. This will reduce its corrosivity compared to neutral pH water.

Mr. F. Howie Ray

- 2 -

November 3, 2006

- The corrosion of drywell steel surfaces in contact with gap water is expected to occur only during outages when oxygen is present. Corrosion during operation is expected to be almost nil since the drywell operates inerted and no oxygen is present to drive the corrosion reaction. During outages, shell corrosion losses in the gap are expected to be small since the exposure time is very limited and the water pH is expected to be relatively high.
- The expected low corrosion losses in the concrete-to-drywell gap area have been confirmed by examination of steel surfaces in the trenches which has revealed only superficial corrosion of the drywell shell.

With the resolution of these concerns, we consider that the Technical Evaluations and attachments successfully address:

- The structural integrity of the concrete and drywell shell,
- The adequacy of repairs, and the effect of the repairs on the assumptions or inputs used for safety and other analyses, and
- The impacts of past water migration and current repairs on design and the licensing bases.

We also reviewed the technical bases for the Technical Evaluation and conclude that all inputs are accurate or conservative, assumptions are conservative, chemical analysis results are used appropriately, and corrosion evaluations are correct and results used accurately.

Please let me know if you have any questions about this letter.

Sincerely,



J. E. Nestell, PhD

PASSPORT#  
00546049 07  
AR# A2152754 E09  
ATTACHMENT 5  
PAGE 2 OF 2